10 October 1980

MILITARY SPECIFICATION

DETONATOR, ELECTRIC M100 PARTS FOR AND LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-D-48120A(AR) dated 6 March 1978.

PAGE 13

Paragraph 4.4.2.6: Major Defect 105, delete words "or incorrect" substitute ", deformed or scratched".

PAGE 13

Paragraph 4.4.2.6: Major Defect 105, Para/Ref delete word "Gage" substitute "Visual".

PAGE 13

Paragraph 4.4.2.6: Delete Major 106 in its entirety and substitute "Major Defect 106, Anvil spherical radius verification -- 3.2, Gage/4.5.10"..

PAGE 19

Add new paragraph 4.5.10 Tool control for spherical radius. The contractor shall verify at the beginning and end of each detonator lot produced that the anvil used meets the spherical radius requirements of (Dwg. 9245691). Non-compliance with the above requirements shall result in the rejection of the lot.

PAGE 21

Add the following paragraphs:

6.8 Check test for possible deterioration. The following test is designed to prevent the loading of detonators which have

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

deteriorated, into a major ammunition item. The test shall be performed on detonators from each lot which has been stored under normal conditions for more than two years, or under adverse conditions for any period of time. If the specification for the ammunition item into which the detonators are loaded does not require that the check test be performed, the contracting officer should insert a provision for the performance of the check test in the contract. The contracting officer will arrange for the contractor to be reimbursed for expenses incurred in the performance of the check test for possible deterioration. Two hundred (200) detonators shall be selected from each lot for this test.

6.8.1 Functioning. The detonators shall be selected at random from each lot. The detonators shall be tested in the following sequence:

a. Measure the resistance between electrode and cup as specified in 4.5.7. If two (2) or more detonators fail to comply with the resistance requirement specified in Dwg 9245691 the lot shall be rejected.

b. The detonators that are not classed defective in step "a" shall be functioned as specified in 4.5.2.2 and meet the output requirements of 3.5.2. If any detonator fails to meet the output requirements, it shall be classed defective. If three or more defectives occur, the lot shall be rejected.

Custodian
Army-AR

Preparing Activity
Army-AR

Project No.: 1375-A-214

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.