INCH-POUND

MIL-P-70637(AR)
AMENDMENT 1
30 September 1996

MILITARY SPECIFICATION

PROJECTILE, 20MM, ARMOR PIERCING-TRACER,
M95, METAL PARTS

This amendment forms a part of Military Specification MIL-P-70637(AR), dated 2 March 1988, and is for use by the US Army Armament, Research, Development and Engineering Center and is available for use by all Department and Agencies of the Department of Defense.

PAGE 2

2.1.1, Under Military Standards: Add "MIL-STD-1949 - Inspection, Magnetic Particle".

PAGE 3

2.1.2, Under Inspection Equipment Drawings: Delete "11075203 - Eddy Current Flaw Detector".

PAGE 4

3.5, Delete in its entirety and substitute the following:

"3.5 Soundness. The shot body shall be free of ferrous metal discontinuity that are detectable by magnetic particle inspection.".

PAGE 5

3.9.3, Delete "1000" and substitute "800".

PAGE 8

TABLE I, Make the following changes;

Under Shot Body - Dwg. 12576580 add the following:

"Soundness, 100%, Acc-0/Rej-1, 3.5 4.5.2".

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:50Z
Check the source to verify that this is the current version before use.

Under Body and Windshield Assy - Dwg. 12576579 delete the following:

"Soundness verification, 125, Acc-0/Rej-1, 3.5, 4.5.5" and "Automatic Inspection Effectiveness, 3.5, 4.5.3".

PAGE 15

4.4.2.4, Delete the following:

"1., Metal defect, 100%, 3.5, 4.5.2/11075203 (REF)".

4.4.2.4, Major 108, under paragraph reference/ inspection method column, delete "Visual/Comparator/ 50x 2/" and substitute "comparator/50x".

4.4.2.4, Note 2/, delete Base radius, and".

PAGE 17

4.4.2.5, Make the following changes:

Add Major 108:

"108., Defective metal, 100%, 3.2, Visual 3/".

Add the following note:

"3/ A body, or windshield containing cracks, splits, cold shuts, inclusions or porosity, shall be classed defective."

PAGE 20

TABLE II, Make the following changes:

Delete "Soundness verification (Body & Windshield Assy), 315, 2/, 3.5, 4.5.4" and substitute "Soundness (Shot Body), 500, 2/, 3.5, 4.5.2".

Delete "Automatic inspection effectiveness (PCS No. 1), 3/, 3.5, 4.5.3".

PAGE 21

TABLE II, Make the following changes:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:50Z
Check the source to verify that this is the current version before use.

Delete note 2/ in its entirety and substitute "Rejection of four or more units in the test for shot body soundness shall be cause for rejection of the lot."

Delete note 3/ in its entirety.

PAGE 23

4.5.2, Delete in its entirety and substitute the following:

"4.5.2 Soundness. The method of inspection shall be magnetic particle inspection in accordance with MIL-STD-1949. An electric current of 300-600 amperes shall be used. All shot bodies shall be demagnetized after magnetic particle testing. Shot bodies containing definite indications of cracks as defined below shall be rejected. Imperfections coming under the following definitions shall be considered indication of objectionable cracks:

a. Any cracks or indications of imperfections whatsoever, which run other than parallel to the axis; or

b. Any cracks or indications of imperfections running parallel with the axis which appear in the band seat, crimping groove, or windshield seating surface, or extend into the ogive.

4.5.2.1, Delete in its entirety.

4.5.3, Delete in its entirety.

4.5.3.1, Delete in its entirety.

PAGE 24

4.5.4, Delete in its entirety.

PAGE 25

4.5.10, Line 5, Delete "1000" and substitute "800".

PAGE 26

6.8, Delete in its entirety.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1305-0165)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:50Z
Check the source to verify that this is the current version before use.