MILITARY SPECIFICATION

CONNECTOR, OXYGEN MASK TO REGULATOR CRU-60/F

This amendment forms a part of Military Specification MIL-C-38271A, dated 11 March 1968 and is approved for use by the Department of the Air Force and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

1.1, Delete in its entirety and substitute the following:

*"1.1 Scope. This specification covers one type of connector for connecting aircraft-panel-mounted oxygen regulator delivery tube and emergency oxygen cylinder assemblies to the oxygen demand breathing mask. The connector is designated Type CRU-60/P."

*2.1 Delete in its entirety and substitute the following paragraph 2.1 and 2.1.1:

"2.1 Government documents.

2.1.1 Specifications and standards. Unless otherwise specified (see 6.2), the following specifications and standards of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation, form a part of this specification to the extent specified herein."

*2.1. SPECIFICATIONS:

Federal

Delete title for QQ-Z-325 and substitute "Zinc Coating, Electrodeposited, Requirements For"
Delete "QQ-P-416 Cadmium Plating."

Military

Delete: "MIL-D-1000" and substitute "DOD-D-1000" same title.

"Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be used in improving this document should be addressed to: HQ AFLC CASO/LODS, Federal Center, Battle Creek, Mi 49016 by using the self-addressed Standardization Document Proposal (DD Form 1426) appearing at the end of this document or by letter."

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T12:11Z
Check the source to verify that this is the current version before use.

MILITARY

Add: "MS27796 Connector-Bayonet, Three Pin, Oxygen Mask"
"MS21964 Valve Assembly Emergency Oxygen Cylinder"

* Delete: "MS33586, Metals, Definition of Dissimilar" and substitute "MIL-STD-889 Dissimilar Metals".

* Delete title for MIL-STD-781 and substitute "Reliability Tests Exponential Distribution"

Delete "Air Force-Navy Aeronautical AN6227, Packing O Ring, Hydraulic."

*Paragraph 2.1, Drawings Air Force: Delete "41A2988 Fitting Assembly-Oxygen Mask Coupling" and substitute "MS21964-20 Fitting Assembly".

Paragraph 2.1, under Air Force drawings: Delete "57B3661 Connector-Bayonet, Three Prongs, Oxygen Mask Assembly of."

*Delete parenthetical statement and substitute the following:

"(Copies of specifications and standards required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)"

*Paragraph 2.2 delete in its entirety and substitute the following paragraph:

"2.2 Other Government documents, drawings, and publications. The following other Government documents form a part of this specification to the extent specified herein".

*3.1, delete in its entirety and substitute the following paragraph:

"3.1 Selection of specifications and standards. Specifications and standards for necessary commodities and services not specified herein shall be selected in accordance with MIL-STD-143."

*3.2, delete in its entirety and substitute the following paragraph 3.2:


"3.2 Qualification. The connector furnished under this specification shall be products which are qualified for listing on the applicable qualified products list at the time set for opening of bids (see 4.2 and 6.3)."

*3.3.2. line 3, delete "MS33586" and substitute "MIL-STD-889".

*Add the following new paragraph:

"3.3.5.1 Reclaimed materials. The use of reclaimed materials shall be encouraged to the maximum extent possible."

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T12:11Z
Check the source to verify that this is the current version before use.



EDGES AND FILLETS RADII .010 UNLESS OTHERWISE SPECIFIED.

THE MASK PORT SHALL MATE PROPERLY WITH MS27796.

"O" RING GROOVE FINISH:
SIDES 63 MACHINE FINISH
BOTTOM 32 PER ASA B46.1

UNLESS OTHERWISE SPECIFIED
DIMENSIONS ARE IN INCHES.
TOLERANCE
FRACTION DECIMALS ANGLES
±1/64 ± .005 ±1/2°

FIGURE 6 MASK PORT

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T12:11Z
Check the source to verify that this is the current version before use.

PAGE 5

*3.3.6.2, delete in its entirety and substitute:

"3.3.6.2 Zinc Plating. Unless made of corrosion resisting steel or otherwise protected in accordance with QQ-Z-325."

PAGE 10

*Figure 5: Delete "AN6227" and substitute "MS29513".

PAGE 11

*Figure 6: Delete and substitute Figure 6 as shown on Page 3 of this amendment.

PAGE 12

Figure 7, dimension of retaining groove for 57B3623: Delete ".190 + .002 - .000" and substitute ".190 + .005 - .000".

PAGE 13

*3.4.2, Line 2: Delete "type 41A2988" and substitute "MS21964-20".

*3.5.2.1, Line 3 & 4: Delete "Sierra Engineering Company" and substitute "Scott Aviation".

PAGE 14

3.5.2.2, line 2: Delete "shall be installed over each clamp" and substitute "shall be installed over the clamp at the connector housing end of the tubing".

PAGE 15

*3.6.4, Line 3: Delete "41A2988" and substitute "MS21964-20".

PAGE 16

3.6.12, line 1: Delete "1,000 insertions" and substitute "600 insertions".

PAGE 17

*3.7, line 3: Delete "MIL-D-1000" and substitute "DOD-D-1000".

PAGE 18

*4.1 Responsibility for inspection, delete in its entirety and substitute the following:

4-1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the speci-

Source: https://assist.dla.mil - Downloaded: 2026-10-21T12:11Z
Check the source to verify that this is the current version before use.

cation where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

*4.2 line 1: Delete "Classification of tests" and substitute "Classification of inspection and tests".

PAGE 19

4.5.2.1, line 1: Delete "1,000 connectors" and substitute "4,000 connectors".

PAGE 21

4.6.3, line 5: Delete "57B3361" and substitute "MS27796".
*4.6.5, line 2: Delete "41A2988" and substitute "MS21964-20".

PAGE 22

4.6.7, line 6: Delete "57B3661" and substitute "MS27796".

PAGE 24

4.6.13, line 5: Delete "1,000 cycles" and substitute "600 cycles". Line 9, delete "1,000 cycles" and substitute "600 cycles". Line 13, delete "1,000 insertions" and substitute "600 insertions".

PAGE 25

4.6.19, delete and substitute the following:

"4.6.19 Submerged liquid. The final assembled connector shall be tested for leaks at five psi in a submerged liquid prior to delivery. Total leakage in excess of 0.01 liter per minute shall be cause for rejection".

PAGE 26

* Delete "5. PREPARATION FOR DELIVERY" and substitute "5. PACKAGING".

PAGE 27

*6.3. line 10: delete "Oklahoma City Air Material Area (OCNE), Tinker Air Force Base, Oklahoma" and substitute "San Antonio Air Logistic Center/MMIRCC, Kelly Air Force Base, Texas 78241".

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Air Force - 99
Review Activity
Air Force -11

Preparing Activity:
Air Force - 99
Project No. 1660-F421

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T12:11Z
Check the source to verify that this is the current version before use.