MILITARY SPECIFICATION

RECEIVING SET, LORAN AN/ARN-78

This amendment forms a part of Military Specification
MIL-R-38327B(USAF) dated 23 February 1966.

Pages 1 and 2, paragraph 2.1,
Under "SPECIFICATIONS": Delete:
"MIL-M-26512" and title
"MIL-R-26667" and title.

Under "STANDARDS": Add:

"MIL-STD-470 Maintainability Program Requirements (For Systems and Equipments)
"MIL-STD-471 Maintainability Demonstration
"MIL-STD-781 Reliability Tests, Exponential Distribution
"MIL-STD-785 Requirements for Reliability Program (System and Equipment)"

Page 5, paragraph 3.3.3.3 and all subparagraphs: Delete and substitute:

"3.3.3.3 Reliability, longevity, and maintainability

"3.3.3.3.1 Reliability program. The contractor shall establish and conduct a reliability program in accordance with MIL-STD-785.

"3.3.3.3.2 Reliability and longevity. Reliability and longevity of the AN/ARN-78 receiving set shall be determined in accordance with MIL-STD-785.

"3.3.3.3.2.1 MTBF. The specified mean-time-between failures (MTBF) of the receiving set shall not be less than 30 hours.

"3.3.3.3.2.2 Longevity. The longevity of the receiving set shall not be less than 2000 hours.

"3.3.3.3.3 Maintainability design requirements. Maintainability design requirements shall be in accordance with MIL-STD-470 and MIL-STD-471."

Page 6, paragraph 3.3.3.6: Delete and substitute:

"3.3.3.6 Overload protection. Fuses shall be style F05 or F06 in accordance with MIL-F-15160."

FSC 5826

Source: https://assist.dla.mil -- Downloaded: 202610-21T12:23Z
Check the source to verify that this is the current version before use.

Page 13, figure 2, top of page: Delete "TCA THRU TCD" and substitute "TCE THRU TCH". Delete "TCA", "TCB", "TCC", "TCD" and substitute "TCE", "TCF", "TCG", "TCH", respectively.

Page 19, figure 5: Delete and substitute the attached figure 5. Figure 5 forms page 3 of this amendment.

Page 21, paragraph 3.6.4.11, line 2: Delete "look" and substitute "lock".

Page 21, paragraph 3.6.4.12.1, line 4: Delete "jam" and substitute "gain".

Page 27, paragraph 4.5.2.1: Delete and substitute:

"4.5.2.1 Sampling plan A. Production reliability acceptance tests shall be conducted in accordance with the requirements of test level E of MIL-STD-781. The test program shall be in accordance with table II."

Page 27, table II, line 5: Delete "101 to 2002 2" and substitute "101 to 200".

Page 27, paragraph 4.5.2.1.1, line 2: Delete "table 5.2 of MIL-R-26667" and substitute "test plan I of MIL-STD-781."

Page 33, paragraph 4.6.5: Delete and substitute:

"4.6.5 Reliability demonstration test. The reliability demonstration tests shall be conducted in accordance with test level E of MIL-STD-781. Accept-reject criteria shall be in accordance with test plan I of MIL-STD-781."

Page 33, paragraph 4.6.7, line 2: Delete "MIL-M-26512, including appendix A" and substitute "MIL-STD-471."

Page 35, paragraph 6.3.2.1.1, line 4: After "0 to 100" add "percent".

Page 38, paragraph 6.3.2.10.2: Under "Slave Pulses", delete "S" and substitute "X".

Page 39, paragraph 6.3.2.13 External velocity information.: Renumber paragraph to "6.3.2.14". In line 4, delete "pro-".

Custodian:
Air Force - 11

Preparing activity:
Air Force - 11

Source: https://assist.dla.mil -- Downloaded: 202640-21T12:23Z
Check the source to verify that this is the current version before use.




FIGURE 5. RECEIVER, LORAN R-1298A/ARN-78

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T12:23Z
Check the source to verify that this is the current version before use.