**NOTICE OF VALIDATION**

**INCH-POUND**

**MIL-A-14898**
**NOTICE 3**
**22-Jun-2022**

# DETAIL SPECIFICATION

## Actuator, Rotary 1000-34 Remanufactured Metal Parts Assembly

MIL-A-14898, dated 10-Jul-1999, remains inactive for new design; however, the document is valid for use.

**Custodians:**
Navy - OS

**Preparing Activity:**
Navy - OS

**NOTE:** The activities above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.dla.mil.

**AMSC N/A** **FSC 1377**

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:04Z
Check the source to verify that this is the current version before use.