MIL-C-14909A (PA)
Amendment 2
11 Mar 76
SUPERCEDING
Amendment 1
4 October 1974

MILITARY SPECIFICATION
CARTRIDGE, ILLUMINATING M301A3 WITH FUZE, TIME M84A1 FOR 81MM MORTARS LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-C-14909A (PA) dated 15 March 1971.

* Paragraph 2.1 APPLICABLE DOCUMENTS

1. Military Specification MIL-P-46568 change M71A1E1" to read "M71A2".

2. Drawings 9220705 change "M301A3E1" to read "M301A3".

Paragraph 3.4.2 - Amend paragraph to read:

"3.4.2 Fuze/Separation.-The fuze shall function and the tail cone shall separate from the body tube assembly."

Paragraph 4.2 - Inspection provisions - lot formation

Delete "4.2.1 c. Loaded time fuzes from one interfix lot number from one manufacturer" and substitute: "4.2.1 c. Loaded time fuzes from not more than two serial lots of one lot interfix number from one manufacturer".

* Paragraph 4.2.1.2 Submission of Ballistic Assemblies

Under "b" change "Fourteen" to "Twenty-one".

* Paragraph 4.2.1.4 Cartridge Functioning (First Article Ballistic Testing)

Delete "fifteen: and substitute "fourteen".

Add to end of paragraph:

"The final 7 remaining samples shall be conditioned for a minimum of 4 hours at zero degrees fahrenheit and fired at this temperature, charge 8 increment, with fuze setting to achieve burst height of 300-500 meters. Evaluation shall be made for fuze functioning and candle and parachute performance. No evaluation shall be made for fuze function time per MIL-STD-414.

FSC: 1315

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:06Z
Check the source to verify that this is the current version before use.

* Paragraph 4.2.2.1 Cartridge prior to assembly.

Delete the words "and adapter" in title.

* Paragraph 4.2.2.2 Holder, increment, front.

Delete entire paragraph with no substitution.

* Paragraph 4.2.2.3 - Cartridge Assembly

Delete Critical defect "#4 propellant increment missing" and add under 100% inspection. "Major 102. Propellant increment missing ..... Visual 03004".

Amend Critical Defect #5 to read:

"5. Fin assembly broken or cracked (see 6.11).....Visual/Magnifier 03005"

Add the following new Major defect:

"109 Holder increment finger broken.....Visual 03027".

Paragraph 4.2.2.5 Sealed fiber container prior to wax jungle wrap.

Minor defect 204 add "or improperly oriented".

Paragraph 4.2.2.6 Sealed fiber container after waxing.

Minor defect 201 add "or improperly oriented".

Paragraph 4.2.2.7 Sealed wood packing box (see dwg. 9241849).

Add new Major defect:

"104. Absence of firing table (see dwg. 9241849).....Visual 07008".

Paragraph 4.2.3.3.2 Proving Ground Testing.

Under Table I, change Major defect (Code 03022) to read:

"Major Fuze non-function or non-separation of cartridge
Accept 2 Reject 3"

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:06Z
Check the source to verify that this is the current version before use.

For Note 3 change "03021" and "03022" to "03025" and "03026" respectively.

Add the following new Note 4:

"Note 4: If a cartridge functions properly in all respects with the exception that the "effective illumination" time is less than sixty (60) seconds because the illuminant and parachute assembly hit the ground while still burning and if the burst height, that is, the height above ground level at which the tail cone separated from the tube body was less than 457 meters the performance of the cartridge will not be considered in evaluating the acceptability of the lot for defects 03025 and 03026."

Paragraph 4.3.2 Proving Ground.

Add the following special pre-testing procedure for charge 8 ballistic testing at the end of paragraph 4.3.2.

"Pre-test procedure for charge 8 ballistic testing-(a) Five rounds from each lot submitted for ballistic acceptance shall be fired at approx. 1068 mls (or 60 degrees) quadrant elevation at the 30 second fuze setting. The five spotter rounds are in addition to the normal ballistic sample size. (b) The Proving Ground shall compute the mean burst height for the five rounds. (c) Determine if the mean burst height falls within a 514/782 meter range for the five rounds. (d) Adjust quadrant elevation if necessary to the above mean range of burst height and proceed to test the entire lot ballistic sample at this elevation.

Metro data consisting of air density, temperature and wind velocity, and direction shall be taken up to the maximum height of the trajectory for all of the pre-test and test rounds fired at both 4 and 8 increments of propellants."

Paragraphs 6.10 and 6.11. Add the following new paragraphs:

"6.10 Proving ground.-The proving ground shall make the necessary arrangements to recover all malfunctions which may occur during ballistic test unless otherwise directed by the procuring agency. The terrain in the area specified by the ballistic test conditions from the gun site to down range shall be suitable so that all rounds fired including malfunctions will be accessible for recovery."

Source: https://assist.dla.mil -- Downloaded: 202610-18T05:06Z
Check the source to verify that this is the current version before use.

"6.11 Visual Inspection.-Inspection of the ignition cartridge housing and fin assembly after complete loading and assembly shall be made with the aid of 2-4X magnification. The inspection shall be made just prior to the assembly of propellant increments."

The margins of this Amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodian:
ARMY - PA

Preparing Activity:
ARMY - PA

Project Number: 1315-A097

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:06Z
Check the source to verify that this is the current version before use.