MIL-G-14933B (PA)
23 February 1976
SUPERSEDING
MIL-G-14933A (MU)
27 August 1971

MILITARY SPECIFICATION

GRENADE, HAND, FRAG, DELAY, M67

LOADING, ASSEMBLING AND PACKING

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling an packing for one type of grenade designated as Grenade, Hand, Frag, Delay, M67.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein.

SPECIFICATIONS

FEDERAL

MILITARY

MIL-A-48078	- Ammunition, Standard Quality Assurance Provisions, General Specification For
MIL-I-45607	- Inspection Equipment, Supply and Maintenance of
MIL-P-60312	- Parts, Molded, Plastic Foam Polystyrene (For use with ammunition)

FSC: 1330

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

STANDARDS

FEDERAL

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes

DRAWINGS

PICATINNY ARSENAL

9235492 - Grenade, Hand, Frag, Delay, M67

2.2 Other publications - The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on the date of invitation for bids or request for proposal shall apply.

CODE OF FEDERAL REGULATIONS

TITLE 49 - Transportation, Parts 100-199

(The Code of Federal Regulations is available from the Superintendent of Documents, U.S. Government Printing Office, Washington, D. C. 20402. Orders should specify "49 CFR 100-199 (latest revision)").

AMERICAN SOCIETY FOR TESTING AND MATERIALS

ASTM B 117-73 - Standard Method of Salt Spray (Fog) Testing

(Application for copies should be addressed to: American Society for Testing and Materials, 1916 Race Street, Philadelphia, Pa. 19103)

3. REQUIREMENTS

3.1 Material - Materials shall be in accordance with the applicable drawings and specifications.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

3.2 Parts - The parts shall comply with all requirements specified on Drawing (Dwg.) 9235492, all associated drawings, and with all requirements specified in applicable specifications.

3.3 Loading of high explosive -

3.3.1 The fuze seating surface shall be free of caked explosive. A chemical cleaner shall not be used.

3.3.2 Clean scrap produced in regular operations may be remelted and used provided it complies with the grade of explosive specified except for form and viscosity. Clean scrap is defined as scrap formed in kettles, pails, risers and loading machines used in pouring, casting and drilling operations.

3.4 Workmanship - All parts and assemblies shall be fabricated, loaded and assembled in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, grease, rust and other foreign matter. The cleaning method used shall not be injurious to any parts, nor shall the parts be contaminated by the cleaning agents. Exterior surface coatings shall be continuous; however, a few light scratches not exposing base material may be permitted. All required marking and stamping shall be neat and sharply defined.

3.5 Submission of results of contractor-conducted examinations and tests - The contractor shall forward copies of the results of any of his examinations or tests to the designated address as required by the contract. (See 6.4).

3.6 Functioning of grenade assembly - The grenade assembly shall function high order when tested as specified in 4.5.2.

3.7 Functioning of fuze lots after twleve (12) months of storage (when applicable) - The fuze assembly shall function high order when tested as specified in 4.5.3.

3.8 X-ray examination of M213 Fuze, Grenade, prior to loading in the M67 Hand Grenade - Each assembly shall be x-rayed and its radiograph shall be examined before loading of the fuze in the grenade body for the following defects:

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

a. Missing delay column (Critical Defect)
b. Short delay column (Critical Defect)
c. Variation in column density (Major Defect)
d. Voids at bottom of delay column (Major Defect)
e. Anvil punch penetration at bottom of delay column (Major Defect)
f. Porosity in the fuze body (Major Defect)
g. Broken styphnate and azide in detonator cup (Major Defect)
h. Foreign matter in delay column (Major Defect)

This examination shall be conducted as specified in 4.5.8.

3.9 Verification of fuze to body assembly torque - The assembly torque being applied during the fuze to body assembly operation shall be in accordance with the applicable drawing and shall be measured as specified in 4.5.9.

4. Quality Assurance Provisions

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions - Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of Inspections - The following types of inspection shall be conducted on this item:

a. Quality Conformance Inspection

4.3 First Article Inspection - Not applicable.

4.4 Quality Conformance Inspection

4.4.1 Inspection Lot Formation - Inspection lots shall comply with the lot formation provisions of MIL-A-48078 [illegible].

4.4.2 Examination - See MIL-A-48078 [illegible].

a. Sampling Plans - Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-G-14933B (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Loading Assembly		8810742
			NEXT HIGHER ASSEMBLY
			9235492

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Specific gravity of the charge	2/4 hrs	See Note a	3.2	4.5.1
102	Depth of fuze cavity, maximum		.40%	3.2	8801485
103	Diameter of fuze cavity, max.		.40%	3.2	Gage
Minor					
201	Explosive in threads		.65%	3.2	Visual
202	Explosive on fuze seating surface		.65%	3.3.1	Visual
203	Evidence of poor workmanship		.65	3.4	Visual

NOTES:

a. No defects allowed

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-G-14933B (PA)

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.2	Grenade Assembly		9235492
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Safety pin not properly spread	100%	-	3.2	Visual
2	Safety clip missing or improperly positioned	100%	-	3.2	Visual
3	Either or both level hinge ears missing	100%	-	3.2	Visual
4	Both lever hinge ears not bent away from the body past the vertical centerline of the body hinge bosses	100%	-	3.2	Visual
5	Ends of both lever hinge ears not bent upwards	100%	-	3.2	Visual
Major					
101	Functioning of grenade assembly	See 4.5.2	-	3.6	4.5.2
102	Functioning of grenade assembly, assembled with fuzes from twelve (12) month storage	125	2.5%	3.7	4.5.4
103	Verification of fuze to-body assembly torque	See 4.5.9	-	3.9	4.5.9
104	Pull ring missing		.40%	3.2	Visual
105	Either level hinge ear not bent away from the body past the vertical centerline of the body hinge boss		.40%	3.2	Visual
106	End of either level hinge ear not bent upwards.		.40%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-G-14933B (PA)

PARAGRAPH	TITLE	SHEET 2 OF 2	DRAWING NUMBER
4.4.2.2	Grenade Assembly		9235492
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Total height, max.		.65%	3.2	Gage
202	Protective coating with bare spot		.65%	3.2	Visual
203	Washer or washer retainer missing		.65%	3.2	Visual
204	Marking misleading or unidentifiable		.65%	3.2	Visual
205	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Container for Grenade, Hand, Frag, Delay M67 & M33 prior to Sealing				9254960
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Six (6) grenades orientated improperly		.40%	3.2	Visual
102	Insert missing		.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS MIL-G-14933B (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Container for Grenade, Hand, Frag, Delay M67 & M33				9254960
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Contents loose		.65%	3.2	Visual/Manual
102	Container damaged		.65%	3.2	Visual
103	Container improperly sealed		.65%	3.2	Visual
Minor					
201	Marking misleading or unidentifiable		.65%	3.2	Visual
202	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

MIL-G-14933B (PA)

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	Box, Packing, prior to Sealing		8800492
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Incorrect number of container assemblies		.40%	3.2	Visual
102	Barrier bag improperly sealed		.40%	3.2	Visual
Minor					
201	Fillers missing		.65%	3.2	Visual
202	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4B10

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-G-14933B (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.6	Box, Packing, Sealed		8800492
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Contents loose		.40%	3.2	Manual
102	Strapping insecure		.40%	3.2	Manual/Visual
103	Box damage		.40%	3.2	Visual
104	Box improperly sealed		.40%	3.2	Visual
Minor					
201	Marking misleading or unidentifiable		.65%	3.2	Visual
202	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.7	Retainer Washer				9242622
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Salt spray test of washer retainer	See 4.5.5	-	3.2	4.5.5
Minor					
201	True position of I.D.		.65%	3.2	Gage
202	Length min		.65%	3.2	Gage
203	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-G-14933B (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.8	Fiber Container, prior to Sealing		8800493
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Grenade inverted		.40%	3.2	Visual
Minor					
201	Fillers missing		.65%	3.2	Visual
202	Pad missing on top of grenade		.65%	3.2	Visual
203	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4B10

13

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

MIL-G-14933B (PA)

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Sealed Fiber Container				8800493
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Contents loose		.40%	3.2	Manual
102	Container damaged		.40%	3.2	Visual
103	Container improperly sealed		.40%	3.2	Visual
Minor					
201	Marking misleading or unidentifiable		.65%	3.2	Visual
202	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-G-14933B (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.10	Box Packing, prior to Sealing	1 OF 1	9288720
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Incorrect number of fiber containers		.40%	3.2	Visual
102	Container inverted		.40%	3.2	Visual
Minor					
201	Fillers missing		.65%	3.2	Visual
202	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4B10

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Box, Packing, Sealed		19288720
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Contents loose		.40%	3.2	Manual
102	Strapping insecure		.40%	3.2	Manual/Visual
103	Box damaged		.40%	3.2	Visual
104	Box improperly sealed		.40%	3.2	Visual
Minor					
201	Marking misleading or unidentifiable		.65%	3.2	Visual
202	Evidence of poor workmanship		.65%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-11933B PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.12	M213 Fuze		8822131
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	X-ray examination	100%	-	3.8	4.5.8
102	Functioning of fuze lots after twelve (12) months of storage	80	1.0%	3.7	4.5.3

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9254959
4.4.2.13	Insert				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Moisture content, prior to packing	*	*		4.5.6
102	Static potential test	*	*		4.5.7

NOTES:

* Sampling and rejection shall be in accordance with MIL-P-60312.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

4.4.3 Testing - Testing is described in the Quality Conformance Inspection tables.

4.4.4 Inspection Equipment - The inspection equipment required to perform the examinations and tests prescribed herein is described in the Paragraph Reference/Inspection Method column in the tables starting with Paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 herein.

4.5 Test methods and procedures -

4.5.1 Specific Gravity of the charge - A sample of two (2) Loading Assemblies shall be selected from each [ ] four (4) hours production and subjected to this test. If any unit fails to comply with the requirement specified on the applicable drawing, the [4 hours] production represented by the sample shall be rejected. The Specific Gravity of the charge will be determined using any method acceptable to the Contracting Officer (See 6.6)

4.5.2 Functioning of grenade assembly - One hundred (100) grenade assemblies shall be selected from each lot and divided into two samples of 50 each. The first sample of fifty (50) shall be subjected to this test. The grenade assembly shall be assembled to an approved fixture. The safety clip shall be unlatched, the pull ring pulled and the assembly allowed to function. If all 50 grenade assemblies meet the applicable requirement, the lot is acceptable and the second sample of 50 shall be returned to the lot. If three (3) or more assemblies fail to meet the applicable requirement, the lot shall be rejected. If one (1) or two (2) assemblies fail to meet the applicable requirement, the second sample of 50 shall be subjected to this test. If a total of three (3) or more grenade assemblies from the two samples fail to meet the applicable requirement, the lot shall be rejected. These tests shall be performed at the Load Plant unless otherwise specified by the Contracting Officer.

4.5.3 Functioning of fuze lots after twelve (12) months of storage - Eighty (80) fuzes shall be randomly selected from each fuze lot and subjected to this test. The fuze shall be assembled to an approved fixture and tested for the requirement of 3.7. If three (3) or more fuzes fail to comply with the applicable requirement, the fuze lot represented by the sample shall not be assembled to the grenade lot in which they are to be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

4.5.4 Functioning of grenade assembly, assembled with fuzes from twelve (12) months storage - One hundred twenty-five (125) grenade assemblies shall be selected from each lot and subjected to this test. The grenade assembly shall be assembled to an approved fixture. The safety clip shall be unlatched, the pull ring pulled and the assembly allowed to function. If eight (8) or more assemblies fail to comply with the applicable requirement, the lot shall be rejected. These tests shall be performed at the Load Plant unless otherwise specified by the Contracting Officer.

4.5.5 Salt spray test of washer retainer - The number of parts as specified in the applicable finish specification shall be submitted for this test. Parts shall be tested in accordance with ASTM B 117-73 for the time specified on the drawing. Rejection criteria shall be as specified in the applicable finish specification.

4.5.6 Moisture content of insert prior to packing - Samples shall be selected and tested in accordance with the applicable paragraph of MIL-P-60312. If the sample fails to meet the requirements of MIL-P-60312, the lot shall not be used until dried sufficiently to meet those requirements.

4.5.7 Static potential test of insert prior to packing - Samples shall be selected and tested in accordance with the applicable paragraph of MIL-P-60312. If the sample fails to meet the applicable requirements of MIL-P-60312, the lot shall not be used.

4.5.8 X-ray examination of Fuze Assembly prior to loading in M67 Hand Grenade - Each fuze assembly prior to loading into the M67 Grenade shall be subjected to the x-ray examination. The inspection equipment and the image quality of the radiographs for this examination shall be satisfactory to the Procurement Contracting Officer. The direction of the x-ray beam employed in this inspection shall be perpendicular to the axis of the delay tube. If any fuze shows evidence of any of the defects listed in 3.8, it shall be classed defective and removed from the lot. Definitions of defective fuzes are defined in Para 6.7.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

4.5.9 Verification of fuze to body assembly torque - Prior to the start of production each shift, the assembly torque being applied during the fuze to body assembly operation shall be measured. Any fixture failing to apply the required torque shall not be used for production until it has been calibrated and verified as meeting the requirement.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging -

5.1.1 Level A - The grenade shall be preserved and packaged in accordance with Dwg. 9254960 or Dwg 8800493 as applicable.

5.2 Packing -

5.2.1 Level A - The grenade, preserved and packaged as specified in 5.1.1, shall be packed in accordance with Dwg. 8800492 or Dwg. 9288720 as applicable.

5.3 Marking - Marking shall be in accordance with Dwgs and Code of Federal Regulations, Title 49, Parts 100-199.

5.4 Shipping - When components from more than one lot are shipped as a carload, each lot shall be kept separate and the division between lots clearly indicated to prevent mixing of the lots in transit.

6. NOTES

6.1 Intended Use - This grenade is intended to be the standard tactical hand grenade.

6.2 Ordering Data - See MIL-A-48078 [illegible]

6.3 Submission of Inspection Equipment Designs for Approval - See MIL-A-48078 [illegible] Submit equipment designs as required to Commander, Attn: SARPA-QA-T, Picatinny Arsenal, Dover, NJ 07801.

6.4 Submission of results of contractor-conducted examinations and tests - Unless otherwise specified by the Contracting Officer, the contractor shall forward requested records of examinations or tests to Commander, Picatinny Arsenal, Attn: SARPA-QA-A-S.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

6.5 Submission of test data- In addition to the normal distribution of records, one (1) copy of all ballistic data and ammunition data cards shall be forwarded to: Commander, Picatinny Arsenal, Attn: SARPA-QA-A-S.

6.6 One acceptable method for determining the Specific Gravity of the charge is as follows:

Weigh the empty grenade assembly in grams and record as We. Fill the empty grenade assembly with water at 75 + 10 F, weigh in grams and record weight as Wf. Load the grenade with composition B, drill the fuze cavity when applicable, weigh in grams and record weight as Wl. Determine the volume of the fuze cavity in centimeters and designate as Vc.

Calculate the Specific Gravity as follows:

$$\text{Specific Gravity} = \frac{W_l - W_e}{(W_f - W_e) - V_c}$$

6.7 Definition of critical and major defect for use in x-ray exmination of fuze assembly -

6.7.1 Missing or short delay column (Critical Defect) - This defect is defined as critical when there is no column or when the delay column does not reach the base of the threaded portion of the fuze body.

6.7.2 Variation in column density (Major Defect) - This defect is defined as a Major defect when the image of the column when compared to a standard radiograph indicates a condition which will preclude proper burning or delay time.

6.7.3 Voids at bottom of delay column (Major Defect) - This defect is classed as a Major defect when the void at the bottom of the delay column (detonator end) extends across the entire diameter of the fuze body delay cavity.

6.7.4 Anvil punch penetration at bottom of the delay column (Major Defect) - This defect is classed as a Major Defect when the anvil punch penetration at the bottom of the delay column, including any breakout, extends more than 0.100

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

inch up into the column. (Note: Fuzes without any other defects which have anvil punch penetration, including breakout, which does not extend more than 0.100 inch up into the column are acceptable providing the height of the delay column is at least 0.700 inch when measured from the top of the anvil punch mark or breakout. Measurement is not made from the base of the delay column).

6.7.5 Porosity in the fuze body (Major Defect) - This defect is defined as a major defect when the fuze body, at the intersection of the threaded portion and the delay column, is found to be porous.

6.7.6 Broken styphnate and azide in detonator cup (Major Defect) - This defect is defined as a major defect when any broken, crumbled or loose styphnate and azide is detected in the detonator tube.

6.7.7 Foreign matter in the delay column (Major Defect) - The defect is defined as a major defect when any foreign matter is detected in the delay column which could preclude the proper initiation and propagation of the delay element.

6.8 Disposition of defective fuze assemblies -

6.8.1 Critically defective fuze assemblies - When a critically defective fuze is found, this Arsenal (SARPA-QA-A-S) shall be immediately notified and the fuze held pending disposition and in no instance will the fuze be destroyed without permission of the Procurement Officer.

6.8.2 All defective fuzes culled from each lot should be re-x-rayed to confirm their identity, and the effectiveness of the screening process, in addition this Arsenal will be notified of defects found per lot, so that remedial action may be taken at the fuze contractor's plant.

6.8.3 Data cards - Data cards for all lots of subject fuzes submitted to 100% x-ray screening should be annotated to reflect performance of this inspection.

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number: 1330-A085

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

OMB Approval
No. 22-R255

INSTRUCTIONS: The purpose of this form is to solicit beneficial comments which will help achieve procurement of suitable products at reasonable cost and minimum delay, or will otherwise enhance use of the document. DoD contractors, government activities, or manufacturers/vendors who are prospective suppliers of the product are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity.

DOCUMENT IDENTIFIER AND TITLE

NAME OF ORGANIZATION AND ADDRESS

CONTRACT NUMBER

MATERIAL PROCURED UNDER A

☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?
   A. GIVE PARAGRAPH NUMBER AND WORDING.

   B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY DOCUMENT REQUIREMENT CONSIDERED TOO RIGID

3. IS THE DOCUMENT RESTRICTIVE?

   ☐ YES ☐ NO *(If "Yes", in what way?)*

4. REMARKS

SUBMITTED BY *(Printed or typed name and address - Optional)*

TELEPHONE NO.

DATE

DD FORM 1 JAN 72 1426 REPLACES EDITION OF 1 JAN 66 WHICH MAY BE USED

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:08Z
Check the source to verify that this is the current version before use.