MIL-M-14926B(MI)
AMENDMENT 2
22 August 1988
SUPERSEDING
AMENDMENT 1
17 January 1975

MILITARY SPECIFICATION

MOTOR, ROCKET, LAUNCH, M114
PARTS FOR

This amendment forms a part of MIL-M-14926B(MI), dated 29 March 1974, and is approved for use within the U.S. Army Missile Command, Department of the Army and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

* Under "SPECIFICATIONS - FEDERAL" add:

"PPP-T-76 Tape, Packaging, Paper (For Carton Sealing)"

Delete:

"TT-I-558 Ink, Marking Stencil, Opaque for Nonporous Surfaces (Metals, Glass, Etc.)"

PAGE 2

* Under "MILITARY" delete:

"MIL-I-6868 Inspection Process, Magnetic Particles"

Add:

"MIL-C-5501/7 Caps and Plugs, Protective Dust and Moisture Seal Seal (Plug Tubing)"

AMSC N/A FSC 1336
DISTRIBUTION STATE A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:07Z
Check the source to verify that this is the current version before use.

MIL-I-43553 Ink, Marking, Epoxy Base

MIL-P-46002 Preservative Oil, Contact and Volative Corrosion - Inhibited"

* Under "STANDARDS" delete:

"FEDERAL

FED-STD-151 Metal, Test Methods"

* Under "MILITARY" add:

"MIL-STD-1949 Inspection, Magnetic Particle"

* Under "DRAWINGS - Picatinny Arsenal, Product and Packing Drawings" add:

"9225157 Case Launch Motor

9225158 Nozzle Launch Motor

9225159 Support Propellant"

* Under "DRAWINGS" add:

"U.S. ARMY MISSILE COMMAND

PRODUCT AND PACKING DRAWINGS

13348305 Metal Parts Assembly Tow Launch Motor - M114

13349876 Launch Motor"

* 2.2, delete.

* 3.2, following 9225160, add "or 13348305".

* 3.3, delete.

* 3.5, delete and substitute:

"3.5 Case surface integrity. There shall be no evidence of cracklike indications or surface flaws, including but not limited to laps, slivers, seams, roll-in scale, or tool marks on the case surface."

* 3.5.1, delete "TT-I-558" and substitute "MIL-I-43553".

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:07Z
Check the source to verify that this is the current version before use.

Page 7

* 4.3.2.1, following 9225157, add "or 13349876" and following 9225160, add "or 13348305)."

* 4.3.2.1, Under Categories, Major, 102, delete "True" and capitalize "Position".

Page 8

* 4.3.2.2, following 9225160, add "or 13348305)."

4.3.2.2, under Categories, Major, 103, delete "True" and capitalize "Position".

Page 9

4.3.2.3, following 9225160, add "or 13348305)."

4.3.2.3, under Categories, Major, 109, delete "True" and capitalize "Position".

4.3.2.3, under Categories, Minor, 204, delete "Symmetry" and substitute "Position".

4.3.2.3, under Categories, Minor, 205, delete "Concentricity" and substitute "Position".

* 4.3.3.1.1, delete.

* 4.3.3.1.3, following 9225157, add "or 13349876".

Page 10

* 4.3.3.1.6, following 9225157, add "or 13349876".

* 4.3.3.1.7, following 9225157, add "or 13349876".

* 4.3.3.2.1, delete.

* 4.3.3.2.3, following 9225157, add "or 13349876".

Page 11

* 4.3.3.2.6, following 9225157, add "or 13349876)".

* 4.3.3.2.7, following 9225157, add "or 13349876)".

* 4.4.1, delete.

* 4.4.2, fourth line, following 9225157, add "or 13349876)".

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:07Z
Check the source to verify that this is the current version before use.

Page 12

* 4.4.4, fourth line, delete "MIL-I-6868" and substitute "MIL-STD-1949".

* 4.4.4, add the following sentence:

"Cases showing evidence of crack-like indications on the surface shall be rejected (see 3.5)."

* 5.1, add the following sentence:

"The preservation oil shall meet the requirements of MIL-P-46002. The threads on the head end of the cap shall be protected by cap-plug per MIL-C-5501/7, part number M5501/7-F14."

Page 15

* 6.3.3, fourth line, delete "Picatinny Arsenal, ATTN: SARPA-QA-A-R, Dover, New Jersey 07801" and substitute:

"U.S. Army Missile Command, ATTN: AMSMI-QA-QE-C, Redstone Arsenal, Alabama 35898-5290."

* 6.3.3, tenth line, delete "Picatinny Arsenal" and substitute:

"U.S. Army Missile Command"

* 6.4,

delete:	and substitute:
"Commander Picatinny Arsenal ATTN: SARPA-QA-I-Q Dover, New Jersey 07801"	"Commander U.S. Army Missile Command ATTN: AMSMI-RD-RP-P Redstone Arsenal, Alabama 35898-5249"

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army - MI

Preparing Activity:
Army - MI

(Project No. 1336-A584)

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:07Z
Check the source to verify that this is the current version before use.