MIL-D-2940A
INTERIM AMENDMENT-3(SHIPS)
5 April 1973

USED IN LIEU OF 1/
Amendment-2
5 June 1964

INTERIM AMENDMENT

MILITARY SPECIFICATION

DAMPENERS, FLUID PRESSURE, GAGE PROTECTION

This Interim Amendment is issued for use by the Naval Ship Engineering Center with Military Specification MIL-D-2940A, dated 16 March 1959.

Pages 1 and 2

2.1: Under Military Specifications; Delete reference to "Mil-G-18997 and MIL-F-21467" and substitute:

"MIL-I-18997 - Indicator, Pressure, Panel Mounted or Case Supported, General Specification."

Under Military Standards: Add:

"MS16142 - Boss, Gasket Seal Straight Thread Tube Fitting, Standard Dimensions for."

Page 3

3.3.2: Delete and substitute:

"3.3.2 End connections. The end connections of the dampeners shall be externally threaded on one end and internally threaded on the other end. The size of the end connections shall be in accordance with the following, as specified (see 6.2):

Thread size	Applicable document
9/16-18UNF-3B internal Threaded for "O" ring	MS16142
9/16-18UNF-3A external Threaded for "O" ring	Figure 1 herein"

3.3.3, last sentence: Add "and IV".

Page 4

4.1: Delete and substitute:

"4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements."

1/ THE MARGINS OF THIS DOCUMENT ARE MARKED "#" TO INDICATE WHERE CHANGES (ADDITIONS, MODIFICATIONS, CORRECTIONS, DELETIONS) FROM THE PREVIOUS ISSUE HAVE BEEN MADE. THIS WAS DONE AS A CONVENIENCE ONLY AND THE GOVERNMENT ASSUMES NO LIABILITY WHATSOEVER FOR ANY INACCURACIES IN THESE NOTATIONS. BIDDERS AND CONTRACTORS ARE CAUTIONED TO EVALUATE THE REQUIREMENTS OF THIS DOCUMENT BASED ON THE ENTIRE CONTENT IRRESPECTIVE OF THE MARGINAL NOTATIONS AND RELATIONSHIP TO THE LAST PREVIOUS ISSUE.

FSC 6685

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T15:57Z
Check the source to verify that this is the current version before use.

Page 5

4.4.1, lines 7 and 17: Delete "Mil-G-18997" and substitute "MIL-I-18997".

4.5, lines 3 and 4: Delete "designated by the Bureau of Ships" and substitute "satisfactory to the Naval Ship Engineering Center".

Page 6

Add as paragraph 6.1.1:

"6.1.1 Dampeners with other end connections are intended for use as replacements where acceptable. Dampeners with 9/16-18UNF end connections shall be used on new construction and where the dampener joins 1/4 inch OD tubing."

6.2: Add item (d):

"(d) Size of end connection required (see 3.3.2)."

Page 7

Add the attached figure 1.

Preparing activity:
Navy - SH
(Project 6685-N495)

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T15:57Z
Check the source to verify that this is the current version before use.




Figure 1 - External threaded end connection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T1
Check the source to verify that this is the current version bef