INCH-POUND

MIL-P-3003K
AMENDMENT 1
16 July 1990

MILITARY SPECIFICATION

PONCHO, WET WEATHER, HEAVY DUTY

This amendment forms a part of Military Specification MIL-P-3003K, dated 7 April 1987, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1.1, under Military Specifications: Delete "MIL-C-40039-Cloth, Coated, Nylon, Vinyl Coated" and substitute "MIL-C-43906-Cloth, Coated, Nylon, Polyurethane Double Coated".

PAGE 3

3.2.1, line 2: Delete and substitute "shall be cloth, coated, nylon, polyurethane coated, type I, conforming to MIL-C-43906.".

3.2.2, line 2: after "type I" add "or type II".

PAGE 4

3.2.8: Delete and substitute:

"3.2.8 Seam sealant (see 4.3.1.1). The seam sealant used to seal the seams and allowable needle holes shall be a dull pigmented solvent solution of polyurethane. If plasticization of the sealant is necessary, only a phosphate or phtalate ester plasticizer shall be used (see 4.3.1.1). The sealant shall show no more than number 3 blocking when tested for hydrolytic stability as specified in 4.3.1.2.".

3.4.1, under materials: Delete "Cloth, coated, nylon, vinyl coated" and substitute "Cloth, coated, nylon, polyurethane coated".

PAGES 10 thru 14

Table I, in stitches per inch column: Delete all references to "9-12" and substitute "7-9" in each case.

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T16:00Z
Check the source to verify that this is the current version before use.

PAGE 15

3.9, line 3: Delete "15-1/2 ± 1/2" and substitute "14-1/2 ± 1/2".

PAGE 16

4.3.1.1, line 9, after "Seam sealant": Add "(Plasticizer)".

Add new paragraph:

"4.3.1.2 Seam sealant testing. The seam sealant shall be hydrostatic stability tested as specified in 4.4.4 for conformance to the blocking requirement in 3.2.8. The sample shall be 1 pint of sealant selected at random from the lot. Any failure shall be cause for rejection of seam sealant lot.".

PAGE 19

Table II, third defect on page for Workmanship damages: Delete "2" and "1" and substitute "6" and "2" respectively.

PAGE 23

4.3.3, second defect for Hood: Delete "15" and "16" and substitute "14" and "15" respectively.

4.3.3: Delete Hood drawcord defects entirely.

PAGE 26

4.4.1.3, at the end of the paragraph: Add "A failure of the poncho is defined as a hydrostatic failure in two or more of the seven determinations.".

Add new paragraphs:

"4.4.4 Seam sealant test.

4.4.4.1 Preparation of samples. Three coats of sealant specified in 3.2.8 shall be applied in a 2 inch stripe across an 8 by 8 inch piece of coated cloth specified in 3.2.1. The sealant shall be applied to the heavily coated side of the cloth and shall be allowed to dry at standard conditions for 24 hours prior to testing.

"4.4.4.2 Hydrolytic stability of sealant. Three specimens prepared as specified in 4.4.4.1 shall be laid flat, coated side up, on a supporting plate and the assembly placed in a desiccator containing water in the lower portion. The water level shall be approximately 1 inch below the specimens. The lid of

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T16:00Z
Check the source to verify that this is the current version before use.

the desiccator shall be put in place and the desiccator placed in a circulating air oven having a temperature of 125°F ± 2°F for a period of 7 days. At the end of the aging period, the specimens shall be removed from the desiccator, folded in such a manner that a strip of sealant is in complete contact across the specimen, and placed under a load of 4 pounds evenly distributed over the specimens for 5 minutes. The load shall be removed and the specimens opened up and laid flat. Failure to meet the blocking requirement in 3.2.8 shall be classified as a test failure.".

PAGE 27

5.2.1 and 5.2.2: Delete "Towards the end of the contract or when there are less than the required amount per container of the same size, mixed sizes may be packed within the same container.".

5.3, lines 6, 7, 8, and 9: Delete and substitute in accordance with bonding means C and D or film bonding means F or G. Pallet pattern shall be number 32 in accordance with the appendix of MIL-STD-147.".

PAGE 28

5.4.1: Delete.

Custodians:

Army - GL
Navy - NU

Review activities:

Army - MD
Navy - MC
DLA - CT

User activities:

Navy - SH

Preparing activity:

Army - GL

(Project 8405-0123)

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T16:00Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T16:00Z
Check the source to verify that this is the current version before use.