INCH-POUND

MIL-C-60315A(AR)
AMENDMENT 5
20 June 1990

SUPERSEDING
AMENDMENT 4
21 February 1990

MILITARY SPECIFICATION
CHARGE, PROPELLING, M67 FOR 105MM HOWITZER LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-C-60315A (PA) dated 2 February 1973, and is approved for use within the US Army Armament Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1, Standard, Military: Delete "MS 63053 - Drum, Metal Shipping and Storage, 15 and 19 Gallon" and substitute "MS 27683 - Drums, Metal - Shipping and Storage, 16 to 80 Gallons."

PAGE 2

2.1, Drawing, Army:

Add: "9288695 - Charge, Propelling, M67 Assembly"

Add: "9283001 - Cover Assembly"

3.2, line 3: After "9205472" add "or 9288695."

(Note: This change corrects a typographical error in Amend 2)

PAGE 4

4.2.2.1:

Line 1: Add after 9205470, "or 9288697"

(Note: This change corrects a typographical error in Amend 2)

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

PAGE 4

Line 2: Add after 9205472, "or 9288695"

Major: Delete "None defined" and substitute "AQL 0.40 percent"

Major: Add "101. Foil missing or improperly assembled (applicable to increment 5 only) when applicable... Visual"

PAGE 5

4.2.2.1, Minor 203: Delete in its entirety.

4.2.2.2:

Line 1: Add after 9205471, "or 9288696"

(Note: This change corrects a typographical error in Amend 2)

Line 2: Add after 9205472, "or 9288695"

4.2.2.3:

Line 1: Add after 9205472, "or 9288695"

Critical Defect: Delete "None defined" and add "1. Incorrect increment(s), incorrect sequence or missing increment(s)...100%...Visual."

Minor 203: Delete in its entirety.

4.2.2.4:

Line 1: Delete "MS 63053" and substitute "MS 27683-2."

* Major: Add "102 Inspection of gasket.....4.2.5"

PAGE 6

4.2.2.5:

Line 1: Delete "MS 63053" and substitute "MS 27683-2."

* Major Defect 101: Delete in its entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

PAGE 7

4.2.3.3, line 7: Add "(The following applies only with lead foil bag)" to the end of the sentence.

PAGE 8

Add the following new paragraph:

* "4.2.5 Gasket inspection. Container lid will be inspected 100% for cut, dried-out, cracked, abraded or improperly affixed gasket or excessive adhesive used for affixing the gasket. If any gasket is found with any of the conditions listed above, the lid shall be rejected and removed from the lot."

Add the following new paragraph:

* "5.1.1.1 Reworked containers. In addition to meeting the requirements of MS 27683, the gaskets of all reworked containers shall be replaced in accordance with 9283001 prior to reuse."

5.1.3: Delete paragraph 5.1.3 in its entirety and substitute the following:

"5.1.3 Air pressure test of container. Immediately after packing, all containers shall be tested with compressed air at an internal air pressure of 2 to 3 psi. The container shall withstand the specific pressure for one minute minimum without apparent leakage as defined in paragraph 4.3.1."

The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
ARMY-AR

Preparing activity:
ARMY-AR

(Project 1315-AC40)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.