MIL-P-63430(AR)
AMENDMENT 4
30 April 1984
SUPERSEDING
AMENDMENT 3
16 November 1983

MILITARY SPECIFICATION

PROJECTILE, 155MM, TEST, NON-HAZ, M718/M741 TYPES LOADING, ASSEMBLING AND PACKING OF

This Amendment forms a part of Military Specification MIL-P-63430(AR), dated 1 December 1980, and is approved for use by the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 5

Add paragraph 3.12 as follows:

"3.12: Shorting bar resistance. There shall be no more than one (1) ohm resistance to the shorting bar loop when measured between the output terminal to ground.".

PAGE 9

4.4.1: Inspection lot formation. Subparagraph b., change wording to read:

"Expulsion charge assemblies from one lot interfix, from one manufacturer."

Subparagraph e., add:

"-1 and -2 after "Electronic Assemblies".

PAGE 11

4.4.2.2: Electronic and primer assembly (M718). Major defect 102, change to read:

"Bushing missing"

FSC 1320

PAGE 12

4.4.2.3: Electronic and primer assembly (M741). Major defect 102, change to read:

"Bushing missing".

PAGE 13

4.4.2.4: Battery check and insulator test point installation. Add major defect 104:

"Resistance of shorting bar, improper, 100%, 3.12, 4.5.6".

PAGE 17

4.4.2.7: Mine, test, non-haz (during assembly) (M741). Major defect 113, change to read:

"Retaining ring height improper".

PAGE 18

4.4.2.8: Mine, test, non-haz (during assembly) (M718). Major defect 113, change to read:

"Retaining ring height improper".

PAGE 20

4.4.2.9: Projectile, 155MM, M718/M741 Metal Parts Assy.(Prior to loading mines).

Delete Drawing Number: "9282848".
Add Drawing Number: "10542902".

PAGE 21

4.4.2.10: Projectile, 155MM, test, non-haz, M741 type (prior to inserting mines into projectile).

Critical defect 1, change to read:

"...being assembled into projectile...".

Critical defect 2, change to read:

"...being assembled into projectile...".

Critical defect 3, change to read:

"mine color code improper, or HE mine with non-haz color code".

PAGE 23

4.4.2.12: Projectile, 155MM, test, non-haz, M741 type (prior to assembling lifting plug).

Major defect 108: Delete defect in its entirety.

PAGE 24

4.4.2.13: Projectile, 155MM, test, non-haz, M741 type.

Critical defect 1, change wording

from: "Nomenclature on body, letter in triangle and stamped number on base not consistent"

to: "Nomenclature on body and letter in triangle not consistent".

Major defect 102, change to read:

"Lifting plug missing or improper".

Major defect 103, change as follows:

No. of sample units, delete: "See 4.4.3.5" AQL, add: "0.40%".

* Major 104: Delete in its entirety and substitute:

"Major 104, Lifting plug or gasket missing or damaged
100% 3.2 Visual".

Minor defect 201, change to read:

"...1/4 square inch".

PAGE 26

4.4.2.14: Projectile, 155MM, test, non-haz, M718 type (prior to inserting mines into projectile).

Critical defect 1, change to read:

"...being assembled into projectile...".

Critical defect 2, change to read:

"...being assembled into projectile...".

Critical defect 3, change to read:

"Mine color code improper, or HE mine with non-haz color code".

PAGE 29

4.4.2.17: Projectile, 155MM, test, non-haz, M718 type.

Critical defect 1, change wording

from: "Nomenclature on body, letter in triangle and stamped number on base not consistent"

to: "Nomenclature on body and letter in triangle not consistent".

Major defect 102, change to read:

"Lifting plug missing or improper".

Major defect 103, change as follows:

No. of sample units, delete: "See 4.4.3.5"

AQL, add: "0.40%"

* Major 104: Delete in its entirety and substitute:

"Major 104, Lifting plug or gasket missing or damaged
100% 3.2 Visual".

Minor defect 201, change to read:

"...1/4 square inch".

PAGE 31

4.4.2.18: Pallet (loaded).

* Major 106: Add the following:

"Major 106, Cover support missing 100% 3.2 Visual (8 places)".

Major defect 201: Delete in its entirety.

PAGE 33

4.4.3.5: Lifting plug torque. Delete paragraph in its entirety.

4.4.3.7: Expulsion charge assembly. Delete paragraph in its entirety.

PAGE 35

4.5.5: Radiographic examination of test mines. Change title to read:

"Radiographic examination of test mines and projectiles".

Change, "DRDAR-QAT-M" to "DRSMC-QAT-M(D).".

Add paragraph 4.5.6 as follows:

"4.5.6: Shorting bar resistance. The resistance of each shorting bar circuit shall be measured between the test points E3 and TP9, using an approved ohmmeter. Observation shall be made for compliance with the requirement of 3.14."

PAGE 36

6.3: Submission of designs for approval.

Change "DRDAR-QAT-I" to "DRSMC-QAT-I(D)".

6.4: Submission of test data and data cards.

Change, "DRDAR-QAT-M" to "DRSMC-QAT-M(D)".

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only, and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:	Preparing activity:
Army-AR	Army-AR
	(Project 1320-A772)

QUALITY CONFORMANCE INSPECTION

MIL-P-63430(AR)
AMENDMENT 4

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH 4.4.2.10	**TITLE** Projectile, 155MM, Test, Non-Haz, M741 Type	**SHEET** 1 **OF** 1	**DRAWING NUMBER** 9317598 **NEXT HIGHER ASSEMBLY** --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Nomenclature on body, letter in triangle and stamped number on base not consistent		100%	3.2	Visual
2	"M" missing from body		100%	3.2	Visual
Major					
101	Grease missing from lifting plug threads (prior to installing)		0.40%	3.2	Visual
102	Lifting plug improper		0.40%	3.2	Visual
103	Lifting plug torque improper	See 4.4.3.5		3.2	Torquewrench
104	Lifting plug or gasket missing or damaged		100%	3.2	Visual
105	Max. diameter forward of grommet improper (Applicable after retouching paint)		100%	3.2	Gage
106	Stamped letter "A" missing from base		100%	3.2	Gage
107	Rotating band damaged (Applicable if grommet has been removed)		0.40%	32.	Visual
108	Obturator missing or damaged (Applicable if grommet has been removed)		0.40%	3.2	Visual

NOTES: 1. Data item description DI-R-1721 applies for all critical defects. Submission of the report shall be whenever defects are found. Immediate notification of technical agency required for critical defects.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

QUALITY CONFORMANCE INSPECTION

MIL-P-63430(AR)
AMENDMENT 4

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH 4.4.2.17	**TITLE** Projectile, 155MM, Test, Non-Haz, M718 Type	**SHEET** 1 **OF** 1	**DRAWING NUMBER** 9317597 **NEXT HIGHER ASSEMBLY** --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Nomenclature on body, letter in triangle and stamped number on base not consistent		100%	3.2	Visual
2	"M" missing from body		100%	3.2	Visual
Major					
101	Grease missing from lifting plug threads (prior to installing)		0.40%	3.2	Visual
102	Lifting plug improper		0.40%	3.2	Visual
103	Lifting plug torque improper	See 4.4.3.5		3.2	Torquewrench
104	Lifting plug or gasket missing or improper		100%	3.2	Visual
105	Max. diameter forward of grommet improper (Applicable after retouching paint)		100%	3.2	Gage
106	Stamped letter "A" missing from base		100%	3.2	Visual
107	Rotating band damaged (Applicable if grommet has been removed)		0.40%	3.2	Visual
108	Obturator missing or damaged (Applicable if grommet has been removed)		0.40%	3.2	Visual

NOTES: 1. Data item description DI-R-1721 applies for all critical defects. Submission of the report shall be whenever defects are found. Immediate notification of technical agency required for critical defects.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)
AMENDMENT 4

PARAGRAPH 4.4.2.18	**TITLE** Pallet (loaded)	**SHEET** 1 **OF** 1	**DRAWING NUMBER** 8837839
			NEXT HIGHER ASSEMBLY --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major					
101	Projectile lifting plug missing		0.40%	3.2	Visual
102	Projectile grommet assembly missing, damaged, or improperly assembled		0.40%	3.2	Visual
103	Board broken or split		0.40%	3.2	Visual
104	Projectile(s) of different zones on the same pallet		0.40%	3.2	Visual
105	DOT symbol missing or unidentifiable		0.40%	3.2	Visual
106	Cover support missing		100%	3.2	Visual (8 places)
Minor					
201	Strap width incorrect		0.65%	3.2	Visual/Gage
202	Strapping improperly assembled		0.65%	3.2	Visual
203	Marking missing, incorrect or unidentifiable		0.65%	3.2	Visual

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.