MIL-STD-1270A(WC)
Notice 1
26 August 1966

MILITARY STANDARD

PATCHING OF WOOD STOCKS FOR THE 7.62MM, M14, AND M14E2 RIFLES

TO ALL HOLDERS OF MIL-STD-1270A (WC)

1. MIL-STD–1270A (WC), 18 March 1966 is changed as follows:

2. Remove old pages and insert new pages as indicated below.

Old pp	*New pp*	*Superseded pp*
v, v i	v, vi	v, vi
13, 14	13, 14	13
15, 16	15, 16	15
17, 18	17, 18	17
21, 22	21, 22	22
25, 26	25, 26	25
31, 32	31, 32	31, 32
33, 34, 35	33, 34, 35	33, 34, 35

3. Retain this notice and insert before the table of contents.

4. Holders of MIL-STD-1270A (WC) will verify that page changes indicated above have been entered. The latest notice (notice page) will be retained as a check sheet. This issuance, together with appended pages, is a separate publication. Each notice is to be retained by stocking points until the Military Standard is completely revised or cancelled.

Custodian:

Army—WC

Preparing activity:

Army—WC

Project No. 1005-A378

FSC 1005

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.

CONTENTS

		Page
1	SCOPE	1
2	REFERENCED DOCUMENTS	1
3	DEFINITIONS	1
4	GENERAL REQUIREMENTS	1
5	DETAIL REQUIREMENTS	2
5.1	Materials	2
5.2	Storage and Preparation of Adhesive	2
5.3	Patches	2
5.4	Fillers	3

FIGURES

1.	Stock areas	5
1A.	Pistol grip area, M14E2 rifle stock	6
2.	Edge split defect	7
2A.	Edge split defect, patched	8
3.	Split defect	9
3A.	Split defect, patched	10
4.	Knothole defect	11
4A.	Knothole defect, patched	12
5.	Scant material defect	13
5A.	Scant material defect, patched	13
6.	Edge split defect	14
6A.	Edge split defect, patched	14
7.	Knothole defect	15
7A.	Knothole defect, patched	15
8.	Cutter marks and edge split defects	16
8A.	Cutter marks and edge split defects, patched	16
9.	Edge split defect	17

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.

FIGURES–(cont'd)

9A. Edge split defect, patched 17
10. Edge split defect 18
10A. Edge split defect, patched 18
11. Edge split defect 19
11A. Edge split defect, patched 19
12. Knot defect 20
12A. Knot defect, patched 20
13. Edge split defect 21
13A. Edge split defect, patched 22
14. Corner split 23
14A. Corner split, patched 23
15. Crack, front end 24
15A. Crack, front end, patched 24
15B. Front end and forearm area M14E2 25
16. Workmanship defect, patched 26
17. Knothole defect 26
17A. Knothole defect, filled 27
18. Open defect 27
18A. Open defect, filled 28
19. Small knothole defect 28
19A. Small knothole defect, filled 29
20. Small knothole defect 30
20A. Small knothole defect, filled 30
21. Not acceptable patch 31
22. Not acceptable patch 31
23. Not acceptable patch 32
24. Not acceptable patch 33
25. Not acceptable patch 33
26. Not acceptable patch 34
27. Not acceptable patch 34
28. Not acceptable patch 35

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.





FIGURE 5. *Scant material defect*



Patching permitted on right side only

FIGURE 5A. *Scant material defect, patched.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.





FIGURE 6. *Edge split defect.*



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.





FIGURE 7. *Knothole defect.*




Patching permitted on right side only

FIGURE 7A. *Knothole defect, patched.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.



FIGURE 8. *Cutter marks and edge split defect.*



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.





FIGURE 9. *Edge split defect.*



Patching permitted on right side only

FIGURE 9A. *Edge split defect, patched.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.




FIGURE 10. *Edge split defect.*




FIGURE 10A. *Edge split defect, patched.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.





FIGURE 13. *Edge split defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.




Patching permitted on right side only

FIGURE 13A. *Edge split defect, patched.*

Supersedes page 22 of 18 March 1966

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.



A. Maximum length of front end patch illustrated in figure 15A. A equals ¼ inch.

B. No patches permitted on bottom surface of forearm area. B extends to receiver opening.

FIGURE 15B. *Front end and forearm area, M14E2.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.




FIGURE 16. *Workmanship defect, patched.*






FIGURE 17. *Knothole defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.



Patch exceeds size limits and extends into area where patching is not permitted

FIGURE 21. *Not acceptable patch.*



Length of patch exceeds the 1 inch permitted in this area.

FIGURE 22. *Not acceptable patch.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.






FIGURE 23. *Not acceptable patch.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.



Patch extends into area where patching is not permitted


FIGURE 24. *Not acceptable patch.*



Patch exceeds size limits and extends into area where patching is not permitted


FIGURE 25. *Not acceptable patch.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.



Patch exceeds size limits and extends into area where patching is not permitted.


FIGURE 26. *Not acceptable patch.*



Workmanship defect. Patch has poor mechanical fit and wide glue line

FIGURE 27. *Not acceptable patch.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.



Patch applied to where patching is not **permitted.**

FIGURE 28. ***Not acceptable patch.***

* U . S. GOVERNMENT PRINTING OFFICE: 251–069—1966—(X–106)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:42Z
Check the source to verify that this is the current version before use.