ADOPTION NOTICE

SAE AMS2590 “Rotary Flap Peening of Metal Parts” was adopted on 23 April 2012 for use by the Department of Defense (DoD). Proposed changes by DoD activities must be submitted to the DoD Adopting Activity: Naval Air Systems Command (Naval Air Warfare Center Aircraft Division, Code 4L8000B120-3, Highway 547, Lakehurst, NJ 08733-5100). Copies of this document may be purchased from SAE International, 400 Commonwealth Drive, Warrendale, PA 15096-0001 or www.sae.org.

SAE AMS2590 should be used instead of MIL-R-81841(AS), which was cancelled on 23 April 2012.

Custodians:
Army – MR
Navy – AS

Preparing activity:
Navy – AS

(Project MFFP-2012-003)

Review activity:
Navy – OS

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.daps.dla.mil.

AMSC N/A

AREA MFFP

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T16:12Z
Check the source to verify that this is the current version before use.