INCH-POUND

MIL-F-48172(AR)
AMENDMENT 5
29 August 1995
SUPERSEDING
AMENDMENT 4
25 April 1990

MILITARY SPECIFICATION

FUZE, PD, M935
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of MIL-F-48172 (AR), dated 17-January 1977, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1: Add the following:

9381686 - Packing and Marking of Container, M548 for Fuze, M935 or M936.

9272193 - Packing and Marking for Box Fiberboard, Inner, for Fuze, PD, M567 less Boosters, or Fuze, M935 Less Boosters or Body Assembly, Front, M935.

9272194 Packing and Marking for Box Fiberboard, Outer, for Fuze, PD, M567 less Booster or Body Assembly, Front, M935."

PAGE 3

4.3.1: Delete "188" and substitute "203."

AMSC N/A **FSC 1390**
DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

PAGE 5

TABLE I: Delete "124" (two (2) places) and substitute "154."

PAGE 8

* 4.4.2.2, Delete Major 104 in its entirety.

PAGE 13

4.4.2.7: Add Major 108 and Note (b):

"108 Sealant missing or improperly applied ...25 (b) ...3.2 ...Visual

Note (b) 25 samples shall have the booster cup disassembled and inspection performed for proper application of sealant or sealant missing. If one or more samples are classed defective, the lot shall be rejected."

4.4.2.7: Add Major 109 which reads:

"109 Distance from base of front body assembly to top booster cup, max. ...0.40% ...3.2 ...Gage.

PAGE 14

4.4.2.8, Critical 3: Change "124" to "80."

Majors 101 and 102: Delete in their entirety and substitute:

"101	Ballistic test SQ	60	(a)	3.5.2	4.5.5
102	Ballistic test delay	10	(b)	3.5.2	4.5.5
103	Transportation vibration firing phase non-function	10	(c)	3.5.2	4.5.2.

(a) Two (2) or more duds shall cause the lot to be rejected. After three (3) consecutive lots have been accepted according to this criteria, a special double sampling plan shall be used (see 4.5.5.1.3).

(b) Five (5) fuzes from the charge zero quantity shall be tv-conditioned prior to ballistic test. Results for information only except for premature functioning.

(c) Two (2) or more duds shall cause the lot to be rejected."

Add pages "14A and 14B (included).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.9	Packing and Marking of Container, M548 for Fuze, PD, M935 (Unsealed)	1 OF 1	9381686
			NEXT HIGHER ASSEMBLY 9395584

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Any material containing condensate or surface moisture	40%	5.1	Visual
102	Bottom support or separators missing	40%	5.1	Visual
103	Partition missing or incomplete	40%	5.1	Visual
104	Top filler missing or insufficient (contents loose)	40%	5.1	Visual/Manual
105	Incorrect number of assemblies	Level III	5.1	Visual
106	Fuze supports missing	Level III	5.1	Visual
Minor	None defined			

NOTES:

Source: https://assist.dla.mil (-14A) Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

MIL-F-48172 (AR)
AMENDMENT 5

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.10	Packing and Marking of Container, M548 for Fuze, PD, M935 (Sealed)	1 OF 1	9381686
			NEXT HIGHER ASSEMBLY 9395584

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major 101	Air leakage test	100%	5.1	4.5.7
Minor 201	Marking missing or unidentifiable	0.65%	5.1	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89

Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- (Downloaded: 2026-10-22T19:16Z)
Check the source to verify that this is the current version before use.

4.5.2, line 10: Delete the sentence, "If the x-rays indicate" in its entirety and substitute:

"If the x-rays indicate the fuzes safe and operable, then they shall be assembled to 60mm, M720 rounds and fired at charge 0 set SQ, as detailed in paragraph 4.5.5."

4.5.5, line 10: Delete in its entirety and substitute:

"4.5.5 Performance test (proving ground ballistic).

4.5.5.1 Functioning test. The sample fuzes shall be assembled to 60mm, HE, M720 cartridges and fired from an appropriate mortar between 45 degrees and 75 degrees elevation. If any fuze fails to cause the shell to function high order, that fuze shall be classified as defective. If any fuze in either SQ or delay setting mode causes the round to function prematurely, that fuze shall be classified as having critical defect. The proving ground shall utilize a geophonic sensing device to differentiate superquick and delay functionings at maximum charge.

4.5.5.1.1 SQ phase. The sample fuzes shall be divided into two (2) equal groups. The groups shall be fired at charge 0 set SQ and maximum charge set SQ.

4.5.5.1.2 Delay phase. The sample fuzes shall be divided into two (2) equal groups. The groups shall be fired at charge 0 set delay and maximum charge set delay, respectively. Sample fuzes required to be tv-tested shall be conditioned in accordance with 4.5.2 except that the fuzes shall be set delay after conditioning. This test is for informational purposes only and shall not be considered for lot acceptance purposes except for premature functions.

4.5.5.1.3 Double sample SQ. After three (3) consecutive lots have met the ballistic requirements of paragraph 4.4.2.8 a special double sample for the ballistic, SQ phase shall be employed. Thirty (30) sample fuzes shall be fired in accordance with 4.5.5.1.1. If no (0) duds result, the lot shall be accepted. If two (2) or more duds are found, the lot shall be rejected. If one (1) dud results, another sample of thirty (30) shall be fired. If one (1) additional dud results, the lot shall be rejected and testing shall revert to 4.4.2.8 again until three (3) consecutive lots have been accepted. If only the first sample is required, the premature burst sample size shall be reduced to fifty (50)."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

Add new paragraph 4.5.7 as follows:

"4.5.7 Air leakage test (see drawing 9381686). The sealed metal ammunition container shall be tested in accordance with the procedures of 9246386."

5.1: Add to end of paragraph the following:

"For interplant shipment, packaging, packing, and marking shall be in accordance with the requirements and quality assurance provisions specified in drawings 9272193, 9272194 and MIL-P-60412."

6.4 Delete in its entirety and substitute:

"6.4 Performance test summary.

6.4.1 Quality conformance test.

FUNCTIONING

Weapon	Cartridge	Charge	Fuze Setting	Quantity
60MM MORTAR	60MM, HE, M720	0	SQ	30(a)
		0	Delay	5(b)
		4	SQ	30(a)
		4	Delay	5(b)

(a) Quantity reduced to fifteen (15) per test phase as required when employing special double sample.

(b) Results for information purposes only except for premature functionings. Charge zero quantity shall be tv-conditioned prior to functioning test.

ARMING DELAY

Weapon	Cartridge	Charge	Fuze Setting	Quantity
60MM MORTAR	M720 INERT	0	SQ	12

TRANSPORTATION VIBRATION

Weapon	Cartridge	Charge	Fuze Setting	Quantity
60MM MORTAR	M720, HE	0	SQ	10

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:16Z
Check the source to verify that this is the current version before use.

6.4.2 First article inspection test.

FUNCTIONING

Weapon	Cartridge	Charge	Fuze Setting	Quantity
60MM MORTAR	M720, HE	0	SQ	62
		0	Delay	15(a)
		4	SQ	62
		4	Delay	15(a)

(a) Results for information only except for premature functioning. Five (5) fuzes of the charge zero quantity shall be tv-conditioned prior to functioning test.

ARMING DELAY

Weapon	Cartridge	Charge	Fuze Setting	Quantity
60MM MORTAR	M720 INERT	0	SQ	12

TRANSPORTATION VIBRATION

Weapon	Cartridge	Charge	Fuze Setting	Quantity
60MM MORTAR	M720, HE	0	SQ	10

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (modifications, additions, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in this notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1390-0832)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.