MIL-F-14890A(MU)
16 June 1972
SUPERSEDING
MIL-F-14890(MU)
28 February 1969

MILITARY SPECIFICATION
FUZE, ROCKET, MT, M421, ASSEMBLY

1. SCOPE

1.1 This specification covers Fuze, Rocket, MT, M421, Assembly.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposals form a part of this specification to the extent specified herein.

STANDARDS
Military

MIL-STD-105	- Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-109	- Quality Assurance Terms and Definitions
MIL-STD-331	- Fuze and Fuze Components Environmental and Performance Test For
MIL-STD-414	- Sampling Procedures and Tables for Inspection by Variables for Percent Defective
MIL-STD-1167	- Ammunition Data Card

DRAWINGS
Munitions Command

F8595903	- Fuze, Rocket, MT, M421, Assembly
F8595907	- Container, Ammunition, Metal, for Fuze, Rocket MT, M421, Assembly
F8595908	- Box, Packing Assembly
F8596046	- Fuze Setter Assembly
IEL-8595903	- Inspection Equipment List for Fuze, Rocket, MT, M421

(Copies of specifications, standards, and drawings required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

2.2 Other Publication.-The following document forms a part of this specification to the extent specified herein. Unless otherwise indicated the issue in effect on date of invitation for bids or request for proposal shall apply.

ASA-B46.1 Surface Texture

(Application for copies should be addressed to the American National Standards Institute (ANSI), 1430 Broadway, New York, NY 10018.)

3. REQUIREMENTS

3.1 General.-Materials, parts and assemblies shall comply with the requirements specified on the applicable drawings, referenced standards and specifications, except as provided in 6.1.

3.2 Regulation.-The movement assembly shall be regulated to the frequency specified on Drawing F8595808. The accumulated error shall not exceed 0.04 percent for either of two consecutive runs of 120 seconds.

3.3 Movement and timing disc assembly.

3.3.1 Arming.-When subjected to an acceleration of 15G, maximum, the safety lever release shall release and the movement shall run.

3.3.2 Non-arming.-When subjected to an acceleration of 10G, minimum, for two seconds minimum, the safety lever release shall not release.

3.4 Base assembly.

3.4.1 Arming.-When subjected to an acceleration of 15G, maximum, the delay arming mechanism shall commit the base assembly to arm within 0.6 to 1.0 second. Upon removal of acceleration, the firing arm release shall release.

3.4.2 Non-arming.-When subjected to an acceleration of 10G, minimum, for two seconds, minimum, the firing arm release shall not release.

3.5 Timer assembly.-The timer assembly shall function within the accuracy limits specified in Table I.

3.6 Fuze assembly.

3.6.1 Safety.-The fuze shall be incapable of functioning at any time setting from 0 to 3.0 seconds and shall not function prematurely (see 6.5).

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

3.6.2 Non-function.-When subjected to an acceleration of 10G, minimum, for two seconds, minimum, the fuze shall not function within the temperature range of minus 40 degrees to plus 160 degrees Fahrenheit (^{o} F).

3.6.3 Function and accuracy.-When subjected to an acceleration of 15G, maximum, and upon removal of acceleration the fuze shall function within the setting range of 4 to 120 seconds and temperature range of minus 40° to plus 160° F and shall comply with the accuracy requirements in Table I, as applicable.

TABLE I - Simulated Ballistics

Temp. ^{o}F.		Upper timer	Timer setting	Lower timer	Timer setting
Ambient	UL	115.89	115 seconds	110.89	110 seconds
	LL	114.33		109.33	
-40°F	UL	116.05	115 seconds	111.21	110 seconds
	LL	113.63		108.63	
+160°F	UL	116.05	115 seconds	111.05	110 seconds
		114.47		109.47	

3.7 Environmental.

3.7.1 Jolt.-The fuze shall comply with MIL-STD-331, Test No. 101.1 with the following exceptions:

a. Inert lead tube assemblies.

b. Not required that all arms of the machine are operated in the test.

c. Random radial orientation in the horizon position. Longitudinal axis of the fuze to be perpendicular to the arm.

3.7.2 Jumble.-The fuze shall comply with MIL-STD-331, Test No. 102.1 with the following exceptions:

a. Inert lead tube assemblies.

b. Jumbled in the metal shipping container.

3.7.3 Transportation-Vibration.-The fuze shall comply with MIL-STD-331, Test No. 104 Procedure II, and the requirements of 3.6.2 and 3.6.3 when functioned at ambient temperature (see 4.2.6) with the following exceptions:

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

3.7.3 (Cont'd)

a. Inert lead tube assemblies.

b. Vibrated in the metal shipping container.

c. Sequence of testing (see 4.4.11.3).

3.7.4 Forty-foot drop.-The fuze shall comply with MIL-STD-331, Test No. 103, with the following exceptions:

a. Inert lead tube assemblies.

b. Dropped in the metal shipping container in lieu of a warhead.

c. Lateral orientation shall be a random selection.

3.8 Workmanship.-The requirements for workmanship are as specified on the applicable drawings, referenced specifications and the following:

3.8.1 Metal defects.-All components shall be free from cracks, splits, cold shuts, inclusions, porosity, or any similar defect.

3.8.2 Threads.-Threads shall be full and undamaged for the entire minimum length or depth as required on the applicable drawing.

3.8.3 Burr.-No part shall have a burr which might interfere with the assembly or function of the item or which might be injurious to personnel handling the item.

3.8.4 Protective finish.-Protective finish shall be in accordance with the applicable specifications and drawings and shall apply to all surfaces of the component regardless of contour configuration.

3.8.5 Foreign matter.-No part or assembly shall contain chips, dirt, grease, rust, corrosion or other foreign matter. The method and agents used in process and cleaning shall not adversely affect the finish or contaminate the parts.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsiblity for inspection.-Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.1 (Cont'd)

disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.1.1 Quality assurance terms and definitions.-Reference is made to MIL-STD-109 to define quality assurance terms used.

4.1.2 Lot formation.-Each inspection lot of fuzes shall be comprised of components (except explosive components) each produced by one manufacturer by one process in accordance with the same drawing and revision and specifications and revisions, as applicable, and assembled on one assembly line. Each explosive component within a lot of assembled fuzes shall be limited to one manufacturer and one interfix number.

4.2 First article sample.-When required, the first article sample shall be as specified in the contract and shall consist of the following:

280 component parts as delineated in 4.2.2 (aggregate)
325 subassemblies as delineated in 4.2.3 (aggregate)
29 fuze assemblies as delineated in 4.2.5 and 4.2.6 (aggregate)

The sample shall be manufactured using the same materials, equipment, processes and procedures as will be used in regular production. All parts and materials, including packaging and packing, shall be the same as used for regular production and shall be obtained from the same source of supply.

4.2.1 Examination and test.-After inspection by the contractor and provisional acceptance at source by the Government, sixteen (see 4.2.6) fuze assemblies with inert lead tube assemblies, in containers shall be forwarded to Aberdeen Research and Development Center (ARDC), Aberdeen, Maryland, ATTN: AMXRD-XSR. Two hundred and eighty (280 component parts, 325 subassemblies and 17 fuze assemblies with inert lead tube assemblies (see 4.2.5) shall be inspected, as provided herein, at a Government laboratory or such other facility as specified in the contract.

4.2.2 Components.

4.2.2.1 Twenty (20) of each of the 12 components listed shall be tested as in 4.3.3.2 (Hardness) and 4.3.3.3 (Bend).

4.2.2.2 Twenty (20) of each of the two components listed shall be tested as in 4.3.3.4 (Load).

4.2.3 Subassemblies.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.2.3.1 Twenty-five (25) of each of the 11 subassemblies listed shall be tested as in 4.3.3.5.1 (Static load).

4.2.3.2 Twenty-five (25) of each of the two subassemblies listed shall be tested in 4.3.3.5.2 (Torque).

4.2.4 Acceptance criteria.-Failure of any component or subassembly to comply with the requirements of the applicable drawing shall be cause for rejection of the first article sample.

4.2.5 Environmental - Fuze assembly with inert lead assembly.-Seventeen (17) fuze assemblies shall be subjected to the following MIL-Standard tests, with the fuze set on safe "S".

Test	Quantity	Requirement	Method	Criteria
Jolt	4	3.7.1	4.4.11.1	4.2.5.1
Jumble	4	3.7.2	4.4.11.2	4.2.5.1
Forty-foot drop	5	3.7.4	4.4.11.4	4.2.5.1
*Transportation-Vibration	4	3.7.3	4.4.11.3	4.2.5.2

*Units subjected to transportation-vibration shall be tested in accordance with 4.2.5.2 and 4.2.6.

4.2.5.1 Acceptance criteria.-The criteria of the applicable MIL-STD shall apply as determined by disassembly and examination in accordance with the procedure in 4.4.11. Where the accept/reject decision is based on engineering judgement, concurrence by the responsible Technical Agency must be obtained.

4.2.5.2 Post transportation-vibration.-Units subjected to transportation-vibration test shall be immediately subjected to the simulated ballistics test. Units that fail the function test shall be disassembled and examined in order to determine whether or not the failure is attributable to the vibration.

4.2.6 Simulated ballistics.-Sixteen (16) fuzes with inert lead tube assemblies from the first article sample including those subjected to transportation-vibration shall be subjected to a simulated ballistic test (see 4.2.1). The fuzes shall be conditioned and tested in the following phases:

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.2.6 (Cont'd)

Phase	Temperature Conditioned	Quantity	Requirement	Method
Post Transportation-Vibration	Ambient	4	3.7.3	4.4.11.3
Non-Function	Ambient	-	3.6.2	
Function and Accuracy	Ambient	-	3.6.3	4.4.13
Non-Function	-40 to -45°F.	5	3.6.2	
Function and Accuracy	-40 to -45°F.	-	3.6.3	4.4.13 and 4.4.16
Non-Function	+160 to +165°F.	5	3.6.2	
Function and Accuracy	+160 to +165°F.	-	3.6.3	4.4.13 and 4.4.16
Non-Function	Ambient	2	3.6.2	
Function and Accuracy	Ambient	-	3.6.3	4.4.13

4.2.6.1 Acceptance criteria.-The occurrence of any of the following shall be cause for rejection of the first article sample:

a. A premature function in any phase (see 6.5)

b. One or more movements or base assemblies function in the non-function phases.

c. More than one timer fails to function in the combined function phases.

d. The estimated lot percent defective for any time setting and temperature phase exceeds the appropriate value in Table II (see 4.4.13.3 and 6.5.2)

e. More than one outlier-offtime in the combined function phases (see 6.5.1)

f. One or more unsettable timers in the ballistic sample.

TABLE II

Sample Size	Allowable % Defective
6	3.43
5	3.32
4	1.53

4.3 Inspection provisions.

4.3.1 Submission of product.-The product shall be presented in accordance with MIL-STD-105.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2 Examination.-One hundred percent examination shall be performed for all critical defects. Examination for major and minor defects shall be performed on a single defect basis in accordance with MIL-STD-105. For each classification of defects contained herein, the AQL given shall be applied to each major and minor defect listed. All nonconforming material shall be rejected. The roughness comparison specimens prescribed in ASA-B46.1 shall be used as a basis of comparison for surface roughness determination. Four (4X) magnification may be used in performing visual examination for such defects as burr and foreign matter.

4.3.2.1 Housing, lower.-Drawing F8595901 covering a detail of Drawing F8595903.

	Defect	Method of Inspection
CRITICAL		
	None defined	
MAJOR	AQL = 0.40%	
101.	Datum diameter at dial end below min.	Gage
102.	Internal diameter at dial end below min.	Gage
103.	Eccentricity of internal diameter with datum "A"	Gage
104.	Surface finish on internal diameter improper	Visual
105.	Markings missing, incorrect or illegible	Visual

4.3.2.2 Housing, upper.-Drawing F8595902 covering a detail of Drawing F8595903.

CRITICAL		
	None defined	
MAJOR	AQL = 0.40%	
101.	Datum diameter at dial end below min.	Gage
102.	Internal diameter at dial end below min.	Gage
103.	Eccentricity of internal diameter with datum A	Gage
104.	Surface finish on internal diameters improper	Visual
105.	Markings missing, incorrect or illegible	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2.3 Rotor.-Drawing C8595925 covering a detail of Drawing F8595903.

Defect	Method of Inspection
CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Location of rotor cavity with pivot hole	Gage
102. Depth of cavity exceeds max.	Gage
103. Centerline of tab incorrect	Gage
104. Surface finish on working radius of tab (dents, flats, etc.)	Visual

4.3.2.4 Dial.-Drawing D8595937 covering a detail of Drawing F8595903.

CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Location of "S" line with respect to "0" line	Gage
102. Cumulative error of time scale exceeds max. (to be checked from zero line, 30, 60, 90 and 115 second lines)	Gage
103. Protective finish improper	Visual
104. Marking missing, incorrect or illegible	Visual

4.3.2.5 Body, dial.-Drawing F8595858 covering a detail of Drawing F8595903.

CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Diameter of Datum A exceeds max.	Gage
102. Diameter of shoulder exceeds max.	Gage
103. Eccentricity of shoulder with datum A	Gage
104. Solid film lubricant missing	Visual
105. Surface finish improper (teeth, shoulder, datum A)	Visual
106. Damaged teeth	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2.6 Cover plate assembly.-Drawing D8595941 covering a detail of Drawing F8595903.

Defect	Method of Inspection
CRITICAL	
1. Fracture of upright bend of either firing arm or firing arm release	Visual
MAJOR AQL = 0.40%	
101. Spring broken or missing	Visual
102. Improper assembly	Visual

4.3.2.7 Pinion, setting.-Drawing B8595974 covering a detail of Drawing F8595903.

CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Diameter across teeth exceeds max.	Gage
102. Solid film lubricant missing	Visual
103. Surface finish improper (teeth, datum A)	Visual
104. Diameter of datum A incorrect	Gage
105. Damaged teeth	Visual

4.3.2.8 Base assembly.-Drawing C8595904 covering a detail of Drawing F8595903 (Prior to testing).

CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Movement not engaged by both locating pins	Manual
102. Gap between delay rotor pin and lever, incorrect	Gage
103. Misalignment of firing pin and detonator cavity in rotor (to be checked after the function and accuracy test - see 4.4.10.2)	Gage

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2.9 Movement assembly.-Drawing F8595808 covering a detail of Drawing F8595903.

Defect	Method of Inspection
CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Arbor not prewound properly	Visual
102. Staking of arbor stop pin, inadequate	Visual
103. Foreign matter	Visual

4.3.2.10 Movement and timing disc assembly.-Drawing F8595805 covering a detail of Drawing F8595903.

CRITICAL	
1. Timing disc bushing loose on arbor (check prior to assembly of timing disc safety and torque to be applied in a counterclockwise direction)	Gage
2. Timing disc safety missing	Visual
3. Timing disc safety assembled incorrectly	Visual
4. Safety release spring missing	Visual
MAJOR AQL = 0.40%	
101. Staking of arbor nut inadequate	Visual
102. Burr or irregularities which prevent proper seating of movement in the dial body	Visual

4.3.2.11 After in-process testing.

NOTE: The following inspections shall be performed on each timer assembly produced after subjection to the function and accuracy tests (see 4.3.3.10.2) disassembly, rewinding and reassembly of the timer, as applicable.

4.3.2.11.1 Timer assemblies No. 1 and No. 2 (less base assembly after testing and rewind of the movement.-Drawings F8595905 and 8595906 covering a detail of Drawing F8595903.

CRITICAL	
1. Release lock plate missing or loose	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2.11.1 (Cont'd)

Defect	Method of Inspection
MAJOR AQL = 0.40%	
101. Movement not fully wound (see 8595808)	Visual
102. Escapement gear not locked by exit pallet	Visual
103. Burr	Visual
104. Foreign matter	Visual
105. Movement not identified	Visual
106. Damaged teeth	Visual

4.3.2.11.2 Base assembly (after testing).-Drawing F8595904 covering a detail of Drawing F8595903.

CRITICAL	
1. Movement delay mechanism not set	Visual
2. Firing arm upright fractured or bent	Visual
MAJOR AQL = 0.40%	
101. Base assembly not in the cocked position	Visual
102. Part missing or broken (spring, firing pin lever, etc.)	Visual
103. Base assembly and rotor not identified with housing	Visual
104. Foreign matter	Visual
105. Burr	Visual

4.3.2.11.3 Timer assemblies No. 1 and No. 2.-Drawings F8595905 and F8595906 (after testing and reassembly, less welsh plugs) covering a detail of Drawing F8595903.

CRITICAL	
1. Safety screw missing (after assembly of plugs)	Visual
MAJOR AQL = 0.40%	
101. Pullring missing	Visual
102. Rotor not in the cocked position (after assembly of the safety screw)	Visual
103. Marking missing, incorrect or illegible (decals, base assembly, movement, rotor)	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2.11.3 (Cont'd)

Defect	Method of Inspection
* 104. Internal zero setting incorrect	Visual

* NOTE: Inspection to be performed on a 100 percent basis.

4.3.2.12 Loading and Packing.

4.3.2.12.1 Long lead assembly.-Drawing C8595909 covering a detail of Drawing F8595903.

CRITICAL

1. Flash tube disc missing	Visual

MAJOR AQL = 0.40%

101. Gap between tubes exceeds maximum allowable	Gage
102. Crimp improper	Visual
103. Foreign matter	Visual

4.3.2.12.2 Short lead and base plate assembly, loading assembly.-Drawing C8595913 covering a detail of Drawing F8595903.

CRITICAL

1. Flash tube disc missing	Visual

MAJOR AQL = 0.40%

101. Charge below maximum allowable (check prior to assembly of the discs)	Gage
102. Crimp improper	Visual
103. Foreign matter	Visual

4.3.2.12.3 Upper-half loaded assembly.-Drawing B8595949 covering a detail of Drawing F8595903.

CRITICAL

1. Change over flush	Visual

MAJOR AQL = 0.40%

101. Charge below maximum allowable	Gage
102. Burr	Visual
103. Foreign matter	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2.12.4 Lower-half loaded assembly.-Drawing B8595950 covering a detail of Drawing F8595903.

Defect	Method of Inspection
CRITICAL	
1. Charge over flush	Visual
MAJOR AQL = 0.40%	
101. Charge below maximum allowable	Gage
102. Burr	Visual
103. Foreign matter	Visual

4.3.2.12.5 Timer assembly No. 1 and No. 2 (less base assembly).-Drawing F8595905 and F8595906 covering a detail of Drawing F8595903.

CRITICAL	
1. Safe set (external) "S" and "O", improper	Visual
* 2. Release lock pin not confined behind release lock plate when set on safe	Visual
3. Base assembly not properly identified with timer serial number	Visual

* Rejected unit (timer assembly) shall be resubmitted and reworked for internal zero setting and safe setting.

MAJOR AQL = 0.40%	
101. Foreign matter	Visual

4.3.2.12.6 Rotor assembly.-Drawing C8595910 covering a detail of Drawing F8595903.

CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Detonator installed improperly (red end not at crimp end)	Visual
102. Detonator missing	Visual
** 103. Crimp missing or inadequate	Visual
104. Detonator above flush	Visual

** See paragraph 4.3.3.12 pushload.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2.12.7 Base assembly (after assembly of loaded rotor assembly). -Drawing F8595904 covering a detail of Drawing F8595903.

Defect	Method of Inspection
CRITICAL	
1. Gap between firing pin and top of rotor, incorrect (see Drawing 8595904)	Gage
2. Safety screw missing	Visual
MAJOR AQL = 0.40%	
101. Lever assembly not engaging delay mechanism (8595928)	Visual
102. Pin not engaging firing arm release (8595904, #4)	Visual
103. Firing arms not in cocked position	Visual
104. Rotor not in cocked position	Visual
105. Detonator installed improperly (red end at bottom)	Visual
106. Crimp surface on detonator above max. (8595910)	Visual
107. Part missing or broken (spring, firing pin lever, rotor or detonator)	Visual
108. Foreign matter	Visual

4.3.2.12.8 Timer assembly No. 1 and No. 2 (after assembly of loaded base assembly).-Drawing F8595905 and F8595906 covering a detail of Drawing F8595903.

CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Safety screw(s) not removed (prior to assembly of base plate)	Visual
102. Pull ring(s) missing	Visual
103. Base screw(s) missing	Visual
104. Lead charge(s) missing	Visual
105. Base plate(s) missing	Visual
106. Improper assembly (short head and base plate assembly on #1 timer)	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2.12.9 Fuze, Rocket, M421 assembly (after loading).-Drawing F8595903.

Defect	Method of Inspection
CRITICAL	
* 1. Fuze (2 timers) not set on safe, setting (check immediately prior to packaging)	Visual

* Rejected unit shall be resubmitted for internal zero and safe setting (remove welsh plugs).

MAJOR AQL = 0.40%

101.	Total length	Gage
102.	Decal missing or loose	Visual
103.	Improper assembly (#2 timer on top)	Visual
104.	Marking, missing, incorrect or illegible	Visual
105.	Pull wire missing	Visual
106.	Retainer wire not through small loop of pull wire	Visual
107.	Retainer wire cut off less than minimum	Visual
108.	Tape missing	Visual
109.	Mounting bolt(s) loose	Manual/Visual

4.3.2.13 Fuze setting assembly.-Drawing C8596046.

CRITICAL

None defined

MAJOR AQL = 0.40%

101.	Improper assembly (operates clockwise or both directions)	Visual

4.3.2.14 Container, Ammunition, Metal for Fuze, Rocket, MT, M421 Assembly.-Drawing F8595907.

CRITICAL

None defined

MAJOR

None defined

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.2.14 (Cont'd)

Defect	Method of Inspection
MINOR AQL = 2.5%	
201. Contents loose	Manual
202. Strip improperly assembled	Visual
203. Key missing	Visual
204. Container cut or damaged	Visual
205. Marking missing, incorrect or illegible	Visual

4.3.2.15 Box, Packing Assembly.-Drawing F8595908.

CRITICAL	
None defined	
MAJOR	
None defined	
MINOR AQL = 2.5%	
201. Contents loose	Manual
202. Hardware missing, broken or loose	Visual
203. Hardware improperly engaged	Visual
204. Strapping missing, broken or loose	Visual
205. Car seal missing, unsealed or improperly positioned (when applicable)	Visual
206. Box damaged	Visual
207. Containers placed wrong side up in box	Visual
208. Marking missing, incorrect or illegible	Visual
209. Quantity incorrect	Visual
210. Rope handles, insecure or damaged	Visual.
211. Strapping improperly assembled	Visual.

4.3.2.16 Process control.-Periodic unscheduled monitoring shall be conducted for the following process operations to determine compliance with the requirements of the applicable drawing. Bending adjustment of the firing arm upright is not permitted at any time.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

Solid lubricant (body, dial)	F8595858
Arbor prewound	F8595808
Movement assembly and housing assembly (torque)	F8595905-06
Nylok pellets (screws)	8596039-42-43-44
Nylock pellets (screws)	8595969

4.3.3 Inspection testing.-The following tests shall be performed in accordance with the provisions of 4.4.

4.3.3.1 Protective finish.-The number of specimens or samples (as applicable) and acceptance criteria for protective finish tests shall be in accordance with the applicable standards or specifications listed on the drawings.

4.3.3.2 Hardness (destructive).-Twenty (20) samples from each lot of the following components shall be subjected to the hardness test. Failure of any component to comply with the requirements specified on the applicable drawing shall be cause for rejection of the lot. Where plating is required, the sample parts submitted shall be unplated (see 4.4.2).

Components	Drawing Number
Guide, Adjusting	C8594273
Arbor, Escapement	C8594298
Lever, Escapement	F8594400
Gear, Escapement	C8595790
Washer, Spring Timing Disc Safety	B8595811
Lever, Firing Arm	C8595921
Release, Firing Arm (see 4.3.3.3)	D8595943
Spring, Lock Plate	B8595970
Arm, No. 1 Firing (see 4.3.3.5.1 and 4.3.3.3)	B8595971 (reference)
Arm, No. 2 Firing (see 4.3.3.5.1 and 4.3.3.3)	B8595972 (reference)
Washer	C8595975
Gear No. 1	C8596015
Gear No. 2	C8596017
Gear, Annular (Delay Mechanism)	D8596023

4.3.3.3 Bend (destructive).-The same firing arms (static load and hardness) and releases (8595943) used in 4.3.3.2 and 4.3.3.5.1 from each lot that complies with the hardness requirements shall be subjected to the bend test. Evidence of fracture after bending shall be cause for rejection of the lot, as applicable (see 4.4.3).

4.3.3.4 Load (destructive).-Twenty (20) samples from each lot of the following components shall be subjected to the load test. Failure of any spring to comply with the requirements specified on the applicable drawing shall be cause for rejection of the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.3.4 (Cont'd)

Component	Drawing Number
Spring, Firing Pin	D8595957
Spring, Plunger	B8595983

4.3.3.5 Static load and torque.

4.3.3.5.1 Static load.-Twenty-five (25) samples from each lot of the following subassemblies shall be subjected to the static load test. Failure of any subassembly to comply with the requirements specified on the applicable drawing shall be cause for rejection of the lot of subassemblies, as applicable (see 4.4.5.1 and 6.6).

Static Load	Drawing Number
No. 1 Gear and Pinion Assembly	C8594280
No. 2 Gear and Pinion Assembly	C8594283
No. 3 Gear and Pinion Assembly	C8594286
No. 4 Gear and Pinion Assembly	C8595158
Escapement Lever Assembly	C8595156
Escapement Gear and Pinion Assembly (movement)	C8595735
Escapement Gear and Pinion Assembly (delay mechanism)	C8596010
No. 1 Gear and Pinion Assembly (delay mechanism)	C8596013
No. 2 Gear and Pinion Assembly (delay mechanism)	C8596016
*Cover Plate Assembly (reference only)	D8595941
*No. 1 Firing Arm 8595971, No. 1 "D" Shaft 8595919 (destructive)	
*No. 2 Firing Arm 8595972, No. 2 "D" Shaft 8595920 (destructive)	

*No. 1, No. 2 Firing Arms and "D" Shafts only shall be assembled for static load test sample using the same assembly methods and equipment that shall be used in production of Cover Plate Assembly (see 4.3.3.2 and 4.3.3.3).

4.3.3.5.2 Torque.-Twenty-five (25) samples from each lot of the following subassemblies shall be subjected to the torque test. Failure of any subassembly to comply with the requirement specified on the applicable drawing shall be cause for rejection of the lot of subassemblies, as applicable (see 4.4.5.2 and 6.6).

Torque	Drawing Number
Escapement Lever Assembly	C8595156
Mainspring Arbor Assembly	C8595861

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.3.6 Timing Disc Safety Torque (nondestructive).-After tightening and staking the arbor nut, each movement and timing disc assembly produced shall be subjected to the torque specified on Drawing F8595805. Failure of the assembly to comply with the requirement shall be cause for rejection of the movement assembly (see 4.4.6).

4.3.3.7 Regulation - Movement Assembly (nondestructive).-After adjusting and rewinding, each movement assembly produced shall be subjected to two consecutive runs for 120 seconds each. The tapes of each movement shall be inspected to determine compliance with requirement of 3.2. If the accumulated error is exceeded on either tape, the unit shall be rejected (see 4.4.7).

4.3.3.8 Movement and timing disc assembly.

4.3.3.8.1 Nonarming (nondestructive).-Each movement and timing disc assembly produced shall be tested to determine compliance with the requirement of 3.3.2. Failure to comply with the requirement shall be cause for rejection of the unit (see 4.4.8.1).

4.3.3.8.2 Arming (nondestructive).-Each movement and timing disc assembly produced shall be tested to determine compliance with the requirement of 3.3.1. Failure of any movement to run after release of the safety lever shall be cause for rejection of the movement (see 4.4.8.2).

4.3.3.9 Base assembly.

4.3.3.9.1 Nonarming (destructive).-Each base assembly produced shall be tested to determine compliance with the requirement of 3.4.2. Failure to comply with the requirement shall be cause for rejection of the base assembly (see 4.4.9.1).

4.3.3.9.2 Arming (nondestructive).-Each base assembly produced shall be tested to determine compliance with the requirement of 3.4.1. Failure to comply with the requirement shall be cause for rejection of the base assembly (see 4.4.9.2).

4.3.3.10 Timer assembly, inert (No. 1 and No. 2), in-process testing.

4.3.3.10.1 Setting torque (nondestructive).-Each inert timer assembly produced shall be tested to determine compliance with the setting torque requirement of Drawing F8595905 or F8595906. Failure to comply with the requirement after being subjected to three (3) complete revolutions of the dial and movement assembly shall be cause for rejection of the timer assembly (see 4.4.10.1).

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.3.10.2 Function and accuracy (ambient temperature) (nondestructive).- Each inert timer assembly produced shall be tested for function and accuracy using control limits specified for simulated ballistic test in Table I. Failure to meet the established control limits shall be cause for rejection of the timer (see 4.4.10.2).

4.3.3.10.3 Nonfunction (ambient temperature) (nondestructive).-Each inert timer assembly produced shall be tested to determine compliance with the requirement of 3.6.2. Failure to comply with the requirement shall be cause for rejection of the timer (see 4.4.10.3).

4.3.3.11 Environmental (lots) fuze assembly with inert lead tube assemblies (destructive).-Eight (8) fuze assemblies from each production lot shall be subjected to the following MIL-STD tests, with the timers set on safe "S".

Test	Quantity	Requirement	Method	Criteria
Jolt	2	3.7.1	4.4.11.1	4.2.5.1
Jumble	2	3.7.2	4.4.11.2	4.2.5.1
*Transportation-Vibration	4	3.7.3	4.4.11.3	4.2.5.2

4.3.3.11.1 Acceptance criteria.-Lot acceptance criteria shall be as specified in 4.2.5.1.

*Units subjected to transporation-vibration shall be tested in accordance with 4.2.5.2 and 4.3.3.13.

4.3.3.12 Pushload (nondestructive).-Twenty-five (25) rotor assemblies from each fuze lot shall be subjected to a static pushload on the detonator. Failure of any unit to comply with the requirements of Drawing 8595910 shall be cause for rejection of the lot of fuzes (see 4.4.12).

4.3.3.13 Simulated ballistics (destructive).-Sixteen (16) fuzes with inert lead tube assemblies from each production lot shall be subjected to the simulated ballistics of paragraph 4.2.6 applying the same criteria as in paragraph 4.2.6.1 (see 4.4.13).

4.3.3.14 Air pressure test, container (nondestructive).-Each sealed container shall be tested to determine compliance with the requirement of Drawing F8595907. Failure to comply with the requirement shall be cause for rejection (see 4.4.14).

4.3.3.15 Salt spray container (destructive).-One specimen or panel from each production lot of containers shall be tested to determine compliance with

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.3.3.15 (Cont'd)

the requirement of Drawing F8595907. The duration of the test shall be six (6) hours. Evidence of red rust shall be cause for corrective action in the process (see 4.4.15).

4.3.4 Inspection equipment.-The examinations and tests shall be made using equipment listed in IEL-8595903. Equipment design shall be in accordance with the code designation on the applicable IEL.

4.4 Test methods and procedures.

4.4.1 Protective finish.-Test procedures for protective finish shall be in accordance with the applicable specification or MIL-STD referenced on the component drawing.

4.4.2 Hardness.-Samples shall be tested in an area which is solidly supported in order to obtain valid readings. The median value of 3 hardness readings taken on each sample unit shall be used as the individual value.

4.4.3 Firing arm bend.-The test shall be performed on the upright as specified on the applicable drawing. All firing arms and firing arm releases that have been subjected to the bend test shall be scrapped.

4.4.4 Load.-The springs shall be compressed to the height and the load applied as specified on the applicable drawing. All springs that have been subjected to the load tests shall be scrapped.

4.4.5 Static load and torque.

4.4.5.1 Static load.-Escapement lever assemblies shall be tested prior to insertion of the escapement lever. The test shall be performed using the values as specified on the applicable drawing. All samples tested shall be scrapped.

4.4.5.2 Torque.-Escapement lever assemblies shall be tested prior to insertion of the escapement lever. The test shall be performed using the values as specified on the applicable drawing. All samples tested shall be scrapped.

4.4.6 Timing disc safety torque.-The torque test shall be performed after assembly of the timing disc assembly to the movement and staking of the locknut on the arbor. The highest and lowest readings will be taken in one complete uninterrupted counterclockwise revolution of the timing disc safety for determination of compliance with the requirement of Drawing F8595805.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.4.7 Regulation.-The movement shall be regulated using the operational procedure furnished with the regulation equipment. Timekeeping and performance shall be checked over a period of not less than 120 seconds. No adjustment shall be made on the escapement during the two consecutive 120-second check runs.

4.4.8 Movement and timing disc assembly.

4.4.8.1 Nonarming.-The nonarming test shall be performed on completely wound assemblies. The assembly shall be rotated on a centrifuge and auxiliary equipment capable of giving required "G" as specified in 3.3.2. The nonarming test shall be performed prior to the arming test.

4.4.8.2 Arming.-The arming test shall be performed on completely wound assemblies. The assembly shall be rotated on a centrifuge and auxiliary equipment capable of giving required "G" as specified in 3.3.1. After completion of the test, each mechanism shall be rewound.

4.4.9 Base assembly.

4.4.9.1 Nonarming.-The completely cocked assembly shall be rotated on a centrifuge and auxiliary equipment capable of giving required "G" as specified in 3.4.2. Upon completion of the test, the assembly shall be examined to determine that the "D" shaft is not released and the firing arm release remains in the cocked position. The nonarming test shall be performed prior to the arming test.

4.4.9.2 Arming.-The completely cocked assembly shall be rotated on a centrifuge and auxiliary equipment capable of giving required "G" as specified in 3.4.1. An electric pickup shall by used to determine complete downward movement (delay time) of the lever assembly. After completion of the test, the assembly shall be examined to determine that the "D" shaft and firing arm release have released.

4.4.10 Timer assembly, inert (No. 1 and No. 2) in process testing.

4.4.10.1 Setting torque.-The test shall be performed using the values as specified on the applicable drawing. The highest and lowest readings will be taken on each of three (3) complete uninterrupted revolutions of the dial assembly for determination of compliance with the requirement.

4.4.10.2 Function and accuracy.-The base assembly, the movement assembly and the rotor shall be timed with the housing assembly. Do not interchange these parts with parts from other housing assemblies (see Drawings 8595905 and 8595906). The lever and firing arm assembly and the rotor from the original assembly shall be used for the test, no substitution shall be made. The timers

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.4.10.2 (Cont'd)

shall be modified for testing as follows: An insulated soft core electrical contact with appropriate wire leads shall be inserted into the detonator cavity of the rotor. The timer shall be set for 115 seconds (record setting torque) and rotated on a centrifuge to the specified acceleration which shall be removed within five seconds to complete the arming phase. Function time will be recorded by utilizing a timing device capable of recording milliseconds.

4.4.10.2.1 Upon completion of the test, the timer shall be disassembled, the electrical contact removed and examined to determine proper alignment of the firing pin with the center of the electrical contact and visual evidence of penetration of the firing pin. Reassembly inspection shall be as specified in paragraphs 4.3.2.11.1 through 4.3.2.11.3. The movement shall be rewound, base assembly completely cocked, reassembled into the timer and subjected to a non-function test.

4.4.10.3 Nonfunction.-Upon completion of assembly and inspection, the timer shall be set for five (5) seconds, minimum, and rotated on a centrifuge to the specified acceleration. After the nonfunction tests have been completed the timer shall be examined to determine nonfunction as follows:

a. Rotor remained in the cocked position.

b. Firing arm release pin withdrawn (see Drawing 8595904, hole No. 4).

c. Reset timer from 5 seconds to zero "0" by rotating the setting gear in the opposite direction of the indicating arrow, if binding or tightness occurs (do not force) this is an indication that the safety lever has released.

d. After completion of the nonfunction test and assembly of the welsh plugs, inspection shall be as specified in paragraph 4.3.2.11.4.

4.4.11 Environmental tests.-The procedures used shall be as set forth in the following subparagraphs, as applicable. Where testing is required, the nonarming or nonfunction test shall be performed prior to the arming or function test. The components of the disassembled fuzes shall be scrapped. All adverse conditions observed shall be reported to the responsible engineering element.

4.4.11.1 Jolt.-The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 101.1, except as specified herein. The final orientation of each fuze tested shall be the base up position.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.4.11.1.1 The fuze shall be disassembled and inspected as follows:

a. Prior to disassembly, check position of "S" line relative to zero line.

b. Remove base plates and base assemblies. Check for rotor not in the unarmed position (see 6.4) and check for firing pin not in the cocked position.

c. Remove base assembly, check position of firing arms, check delay mechanism for function, check internal safe setting (pin not under the release lock plate) and check if movement ran.

d. Remove movement, check for separation of movement plates and check timing disc safety torque.

e. Disassemble major subassemblies to the extent that all critical parts can be examined, such as gears and pinion assemblies, etc., for security of assembly, broken or bent pivots and teeth, fractured or bent firing arm or shaft or other part which might allow accidental function of the base assembly or the movement. Check condition of all explosive elements.

4.4.11.2 Jumble.-The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 102.1, except as specified herein. The fuze shall be disassembled and examined for the conditions as defined in 4.4.11.1.1.

4.4.11.3 Post transportation-vibration.-The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 104, Procedure II, except as specified herein and with the fuze orientations in the following sequence:

a. Parallel to longitudinal axis, top of can up.

b. Parallel to longitudinal axis, top of can down.

c. Horizontal, random orientation.

4.4.11.4 Forty foot drop.-The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 103, except as specified herein.

4.4.11.4.1 The fuze shall be disassembled and inspected as follows:

a. Remove base and base plates. Check for rotor not in the unarmed position (see 6.4) and check condition of all explosive elements.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.4.12 Loading.-Rotor assembly, base assembly or housing shall not be interchanged, Drawings 8595905 and 8595906.

4.4.12.1 Pushload.-The rotor assembly shall be identified with the base assembly and housing. The test shall be performed using the value specified on the applicable drawing.

4.4.13 Simulated ballistics.-The sample fuzes selected for simulated ballistic test shall be forwarded to designated proving ground and tested in accordance with procedure and equipment approved by Frankford Arsenal.

4.4.13.1 Set times.-The upper timers shall be set at 115 seconds and the lower timers shall be set at 110 seconds.

4.4.13.2 Nonfunction.-The nonfunction test shall be performed prior to the function and accuracy test. Remove pull wire during the test.

4.4.13.3 Lot percent defective.-The estimate of the lot percent defective shall be calculated for each temperature and time setting phase using the method prescribed in Example B3, MIL-STD-414 (see 6.5.2). Lot percent defective values for sample size 6 shall be determine by interpolating between the values given in Table B5, MIL-STD-414 for sample sizes 5 and 7. A minimum of 4 statistically normal values are required for each phase (see 6.5.2). All values of the sample shall be used to initially calculate the mean ($\overline{X}$) and standard deviation (s). The standard deviation value obtained shall then be used in the determination of statistical outliers (non-normal values) by using the criteria $\overline{X}$ plus or minus 2.88 times the standard deviation. A value judged to be an outlier shall be excluded and the remaining values in the sample used to recalculate $\overline{X}$ and s (see 6.5.1).

4.4.13.4 Fuze setter.-All fuze settings shall be made using the fuze setter, Drawing C8596046, utilizing the vernier scale on the housing for accurate setting.

4.4.14 Container, air leakage.-The equipment and procedure shall be in accordance with IEL-8595903.

4.4.15 Salt spray.-The test shall be conducted in accordance with the specifications referenced on the applicable drawing.

4.4.16 Temperature conditioning.

4.4.16.1 High temperature (+160° F).

4.4.16.2 Low temperature (-40° F).

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

4.4.16.3 Conditioning (-40° F and +160° F).-The test chambers shall be at ambient temperature at the start of the test and the chamber maintained at a temperature of minus 40 F or plus 160 F as applicable, until stabilization of the fuze temperature is reached (see 6.3). After stabilization, the fuze shall be saturated at minus 40 F or plus 160 F as applicable, for one hour, minimum.

5. PREPARATION FOR DELIVERY

5.1 Packing and marking - Level A.-Packing and marking shall be in accordance with Drawings F8595907 and F8595908.

5.1.1 Salt spray and air leakage.-The metal container shall comply with the salt spray and air leakage requirement as specified on Drawing F8595907.

6. NOTES

6.1 Dimensions.

6.1.1 Compliance with tests (proving ground, ballistic performance, and shop) required by the specifications and drawings is mandatory. The contractor will not assume, nor does the government guarantee, that all possible combinations permitted by the tolerance limits of the specifications and drawings will consistently satisfy the test requirements. Therefore, the manufacturer is obligated to choose those combinations of tolerances and fits within the limits of the specifications and drawings that best suit his process needs and still satisfy the testing rquirements.

6.1.2 Dimensions which are specifically referred to in the classification of defects, as listed in Section 4, are mandatory. Pertaining to other dimensions, it is recognized that current mass production methods may occasionally produce parts which are not in full compliance with all dimensional requirements, but which may provide adequate fuze performance. Therefore, the contractor, at his own risk, may utilize these parts provided there is no adverse effect on fuze functionability. This relaxation of requirements applies to "after the fact" deviations only, to dimensions only, and does not constitute authority to establish new dimensions or to relax efforts to achieve the required sizes within the specified limits. The procedure for accomplishing dimensional changes is available under the established engineering change system. Nothing above is to be construed as relieving the contractor of any responsibility in connection with performance of the fuze.

6.1.3 The contractor shall maintain records showing deviations from dimensional requirements, the extent of such deviations, the amount of material involved, and the date the material is introduced into the assembly line. Copies of these records shall be forwarded to the agency assigned custody of the technical data.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

6.2 Ambient as defined herein is room temperature 70° F plus or minus 10° F.

6.3 Temperature stabilization timers may be checked by a thermal measuring device in good thermal contact with the largest centrally located internal mass.

6.4 Examination (bottom view of timer assembly with base plate removed).
Safe - Rotor assembly cocked toward the "V" cutout in the base casting leaving the cocked firing pin clearly exposed. The firing arm release pin 1/8 inch, min, below the surface (see Drawing F8595904, hole No. 4).

6.5 Premature function.-Premature function is when the fuze -

a. Set for 4 seconds, functions at less than 3.5 seconds.

b. Set for 5 to 20 seconds, functions at less than 75% of the set time.

c. Set for 21 to 120 seconds, functions at less than the set time minus 5 seconds.

6.5.1 Outlier-offtime.-An outlier which is also outside the time limits of Table I, except where it is a premature function.

6.5.2 Where less than four (4) time values are obtained in any test phase and the lot is not rejected for other reasons, the disposition of the lot shall be referred to the responsible procuring activity. The Government reserves the right to require the contractor to submit additional test samples. The number of additional test samples shall be sufficient to obtain a combined total of six (6) values in ambient and five (5) in either extreme temperature phase in order that the occurrence of outliers will not reduce the number of normal values to less than the minimum required. All normal values obtained in the combined tests shall be used to determine lot acceptance or rejection. Attribute characteristic failures, e.g. duds occuring in the additional samples shall not be used to reject the lot.

6.5.3 Defective fuzes.-Where sample fuzes are found to be defective as received at the ballistic test facility, all tests of the lot sample shall be held in abeyance pending investigation by the responsible procuring activity.

6.6 Screening of lots.-Caution shall be exercised so no damage occurs to components during static load and torque testing.

6.7 Data cards.-Data card information shall be as specified in MIL-STD-1167.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

6.8 Informational:

Procedure for manual operations for:

Explosive function.-(Note: This fuze is loaded with two detonators and two lead assemblies. Extreme care must be used in the preparation of the timer assembly and the preparation of the assembled fuze for firing.) The test procedure is as follows:

a. Prepare the fuze for the Explosive Train Functioning Test by first separating timers No. 1 and 2 and then performing the following operations to the timers:

(1) Check dial setting. Must be "Safe"

(2) Insert safety screw into base assembly

(3) Remove pull wire pin

(4) Remove base assembly

(5) Loop a piece of string over the setback weight and behind the pull wire pin stud and permit it to fall through the access section of the base assembly.

(6) Assemble the base assembly into the housing.

(7) Insert the pull wire pin.

(8) Remove the safety screw.

(9) Carefully remove the pull wire pin partly and pull down string which will cause the setback weight to fully travel in the downward direction. Immediately thereafter reinsert the pull wire pin. It will now be over the pull wire pin stud in the setback weight which will prevent the setback weight from moving in an upward direction.

(10) Insert retainer wire and add pressure sensitive tape to pull ring.

b. Assemble the prepared timer No. 1 and the prepared timer No. 2 to the base with two screws.

c. The following procedure can be used to fire the fuze:

(1) Prepare for firing in a barricaded area that has a small access hole between the control section and the barricaded section.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

6.8 (Cont'd)

(2) Securely attach a piece of pressure sensitive tape over the top of the fuze to act as a handle.

(3) Tie a string to the handle and suspend the fuze over a rod, with the string through the access hole tied to a rigid part in the control section.

(4) Place a solid platform (cinder block) approximately 12" below the fuze.

(5) Place a 12" long pipe with an I.D. to permit passage of the fuze on the platform.

(6) Support the fuze for setting.

(7) Tie a string to both pull rings.

(8) Remove the tape from the pull rings.

(9) Set both dials of the fuze to the same setting (20 seconds).

(10) Cut the retainer wire.

(11) Remove the support.

(12) Remove the two pull wire pins with the strings from behind a barricade. This will permit both firing arms to rest on the timing disc.

(13) Order all personnel to move behind barricade and into the control section.

(14) Cut the string that is tied in the control section. This will permit the fuze to hit the platform which will start both timers running.

(15) At the set time, both timers will fire.

(16) Wait an additional two minutes before inspection to insure that the fuze is inactive.

6.9 Statement of Safety Requirements

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.

6.9.1 Safety Limitations and Precautions Relating to Production Equipment and Facilities:

Assembly of explosive elements into fuzes shall be performed under protective hoods with static electricity controls. Protective barrier should be used when performing the MIL-standard tests.

6.9.2 Hazards Presented by Materials:

Possible injury (burns or dismemberment) to limbs and body from flash or detonation of explosive elements.

6.9.3 Known Hazards or Hazardous Areas:

All areas in which explosive elements are used in assembly operations or stored.

6.9.4 Specific Instructions Relative to Manufacture, Handling, Storage and Shipment of Material: The number of persons exposed to explosive operations and the quantities of explosive materials should at all times be the minimum consistent with safety and the efficiency of of operation. Signs setting forth personnel and explosive limits also should be posted. Prior to starting operations including any of the hazardous materials or items described herein, a standard operating procedure should be developed and approved by the contractor outling the specific requirements to safely perform the particular operation. All personnel concerned should be cognizant of SOP contents. Applicable portions of the approved procedure should be conspicuously posted convenient to all stations involved in the operation for guidance of all personnel.

6.9.5 Explosive Hazard Classification of Materials:

Assembled fuzes - Class 1, Detonators in Storage - Class 7.

6.10 Ordering data.-Procurement documents should specify the title, number and date of this specification.

Custodian:

Army - MU

Preparing activity:

Army - MU(FA)

Project No. 1390 - A102

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:03Z
Check the source to verify that this is the current version before use.