MIL-P-11386G
12 February 1985
SUPERSEDING
MIL-P-11386F(ME)
26 April 1973

MILITARY SPECIFICATION

PONTON FLOAT: PNEUMATIC, THREE-TUBE HALF FLOAT, 12-TON CAPACITY

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers an three-tube, pneumatic ponton half float, 12-ton capacity, complete with halter assembly and emergency repair items.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. Unless otherwise specified, the following specifications and standards of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation, form a part of this specification to the extent specified herein.

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: USA Belvoir Research and Development Center, ATTN: STRBE-DS, Fort Belvoir, VA 22060-5606 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

FSC 5420

Source: https://assist.dla.mil -- Downloaded: 202610-17T15:59Z
Check the source to verify that this is the current version before use.

SPECIFICATIONS

FEDERAL

L-P-378	- Plastic Sheet and Strip, Thin Gauge, Polyolefin.
QQ-S-781	- Strapping, Steel, and Seals.
PPP-B-601	- Boxes, Wood, Cleated-Plywood.
PPP-B-621	- Boxes, Wood, Nailed and Lock-Corner.

MILITARY

MIL-P-116	- Preservation, Methods of.
MIL-A-5540	- Adhesive, Polychloroprene.
MIL-C-14505	- Cloth, Nylon, Polychloroprene-Coated (for Pneumatic Floating Equipment).
MIL-G-20241	- Gasket Material, Wool Felt, Impregnated, Adhesive, Pressure-Sensitive.
MIL-S-81733	- Sealing and Coating Compound, Corrosion Inhibitive.

STANDARDS

FEDERAL

FED-STD-601	- Rubber: Sampling and Testing.

MILITARY

MIL-STD-105	- Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-129	- Marking for Shipment and Storage.
MIL-STD-889	- Dissimilar Metals.

2.1.2 Government drawings. The following Government drawings form a part of this specification to the extent specified herein.

DRAWINGS

ME

TA13212E3020	- Ponton Float: Pneumatic, Three-Tube Half Float, 12-Ton Capacity.
TA13212E3035	- Halter Assembly, Pneumatic Half Float.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T15:59Z
Check the source to verify that this is the current version before use.

(Copies of specifications, standards, and drawings required by contractors in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

2.2 Other publications. The following document(s) form a part of this specification to the extent specified herein. The issues of the documents which are indicated as DoD adopted shall be the issue listed in the current DoDISS and the supplement thereto, if applicable.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

D 3951-Standard Practice for Commercial Packaging

(Application for copies should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103.)

(Industry association specification and standards are generally available for reference from libraries. They are also distributed among technical groups and using Federal agencies.)

2.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence.

3. REQUIREMENTS

3.1 Description. The ponton half float shall be in accordance with Top Assembly TA13212E3020 and as specified herein, and shall be furnished with a halter assembly in accordance with Top Assembly TA13212E3035.

3.1.1 Drawings. The drawings forming a part of this specification are end product drawings. No deviation from the prescribed dimensions or tolerances is permissible without prior approval of the contracting officer. Where tolerances could cumulatively result in incorrect fits, the contractor shall provide tolerances within those prescribed on the drawings to insure correct fit, assembly, and operation of the ponton half float. Any data (e.g. shop drawings, layouts, flow sheets, processing procedures, etc.) prepared by the contractor or obtained from a vendor to support fabrication and manufacture of the production item shall be made available, upon request, for inspection by the contracting officer or the designated representative.

3.2 First article. When specified (see 6.2), a sample shall be subjected to first article inspection (see 4.3 and 6.3).

3.3 Materials. Materials shall be as specified herein and on the applicable drawings. Materials not specified shall be selected by the contractor and shall be subject to all provisions of this specification. All material shall be new and unused.

Source: https://assist.dla.mil -- Downloaded: 202640-17T15:59Z
Check the source to verify that this is the currenversion before use.

3.3.1 Material deterioration and control. The ponton half float shall be fabricated from compatible materials, inherently corrosion and deterioration resistant or treated to provide protection against the various forms of corrosion and deterioration that may be encountered in any of the applicable storage and operating environment to which the item may be exposed.

3.3.1.1 Dissimilar metals. Dissimilar metals, as defined in MIL-STD-889, shall be electrically insulated from one another to minimize or prevent galvanic corrosion. Insulation may be provided by an insulating barrier such as a corrosion inhibiting sealant conforming to MIL-S-81733 or chromate tape conforming to MIL-G-20241. Protection against any galvanic corrosion could also be obtained by exclusion of the electrolyte if feasible.

3.3.1.2 Identification of materials and finishes. The contractor shall identify the specific material, material finish or treatment for use with components and sub-components, and shall make information available, upon request, to the contracting officer or designated representative.

3.3.2 Coating compound. The coating compound shall be as specified in MIL-C-14505.

3.3.3 Coated cloth. The uncured coated cloth used in fabrication of the ponton half float shall conform to MIL-C-14505, class as specified on the drawings.

3.3.4 Gum sheeting and strips. Gum sheeting shall be fabricated from coating compound specified in 3.3.2, thickness as specified on the drawings. The required gum strips, cut from the sheeting, width as specified on the drawings, shall be used to cover all seaming tape and other exposed fabric edges. When joining two sections of gum stripping, the ends shall overlap not less than 1/2-inch.

3.3.5 Seaming and hinge tapes. Tapes used as seam overlaps and as hinge tape shall be cut from coated fabric specified in 3.3.3, class and width as specified on the drawings. When joining two sections of the tape, the ends shall overlap not less than 1-inch.

3.3.6 Adhesive. The adhesive required in the fabrication of the ponton half float shall conform to MIL-A-5540, class 1, color black.

3.4 Seams. When tested as specified in 4.5.2.1 the cured seams shall evidence breaking strength equivalent to that of the coated fabric. Slippage of the cured seams, when tested as specified in 4.5.2.1, shall not exceed 1/8 inch.

Source: https://assist.dla.mil -- Downloaded: 202610-17T15:59Z
Check the source to verify that this is the currentversion before use.

3.5 Tubes. Each tube of the ponton half float shall be fabricated from uncured coated cloth specified in 3.3.3. Not more than three longitudinal seams shall be allowed in each tube. All air chamber and bulkhead seams shall have an overlap of not less than 2 inches. Overlap (splices) of seaming and hinge tapes shall be not less than 1 inch and the overlap (splices) of gum strips shall be not less than 1 inch and the overlap (splices) of gum strips shall be not less than 1/2-inch. The stern end cap of the tube shall be fabricated of either the baseball or gore type pattern; the bulkheads shall be the baseball or two-piece (half sphere) type construction; and the bow end cap shall be the baseball pattern of construction. Not more than one longitudinal and one circumferential seam shall intersect at one point. Each tube shall be vulcanized as a complete unit in a steam-pressure-type autoclave. Swashing of the inner walls of inflatable compartments with latex or any other sealing compound shall not be permitted either before or after vulcanization. After vulcanization of the tube, the seams of the tube shall not be opened. When inflated to an air pressure of 2-pounds per square inch (psi), helical distortion of the finished tubes shall be not more than .9 degrees rotational displacement of the periphery in 15 feet of tube length.

3.5.1 Valve patch assemblies. When tested as specified in 4.5.2.2.2, the valve patch assemblies shall show no evidence of separation of the valve core or base from the tube, or permanent deformation of any part of the valve patch assembly.

3.5.2 Tubes. When tested as specified in 4.5.2.3.1, the tubes shall show no evidence of permanent distortion, rupture of material, or slippage of seams; the retained air pressure shall be not less than 2 psi.

3.5.2.1 Tube folding. When tested as specified in 4.5.2.5, repeated folding and inflation of the half float shall not cause damage to the half float or show a decrease in pressure more than 0.3 psi below the final pressure reading obtained during the initial 24-hour air retention period specified in 4.5.2.3.1.

3.5.3 Alternate tube compartments. When tested as specified in 4.5.2.3.2, the tubes shall show no evidence of permanent distortion, rupture of material, or slippage of seams; each inflated compartment shall retain an air pressure of not less than 2 psi. After passing the test, three tubes shall be laced together to form a complete ponton half float with all accessories attached in accordance with the applicable drawings.

3.6 Components. Components of the ponton half float not an integral bonded part of the tube, and fabricated from uncured coated cloth conforming to MIL-C-14505, class as specified on the drawings, shall be vulcanized, after fabrication, in a steam-pressure-type autoclave.

Source: https://assist.dla.mil -- Downloaded: 202640-17T15:59Z
Check the source to verify that this is the currentversion before use.

3.7 Anchor patch assemblies. When tested as specified in 4.5.2.2.1, the anchor patch assemblies for the webbing straps shall show no evidence of rupture of material, permanent distortion, or separation of the anchor patches from the ponton tubes or from the bow or side filler panels.

3.8 Dimensions. Dimensions subject to variation with air pressure shall be taken with the ponton tube inflated to a pressure of 2 psi.

3.9 Markings. Identification and instructional markings shall be as specified on the drawings, and shall be legible. The repair items specified in the drawings shall be identified by name and by applicable National Stock Number or manufacturer's code and part number.

3.10 Repairs. The first article ponton half float shall not contain any repair patches. Production ponton half floats may be patched with patches prepared from coated cloth conforming to MIL-C-14505, class 7, applied with adhesive specified in 3.3.6 and vulcanized with the local application of heat and pressure. The edge of any repair patch shall extend not less than 3 inches beyond the extremity of the defect. Gum strips as specified in 3.3.4 shall be used on the periphery of all repair patches. Covering or overlapping of patches shall not be permitted. Any applied patch shall not adversely affect the strength or serviceability of the ponton half float. Any injury or damage that exposes the base fabric (nylon) of the ponton half float's air chamber cloth shall be repaired with patch material as specified above. Exposed base fabric of non-air-retaining ponton cloth shall be repaired with gum sheeting, cemented, and cured by applying local heat and pressure. Any nonadhering surfaces of cemented material shall be repaired by recementing and curing by applying local heat and pressure.

3.11 Workmanship. The fabricated and assembled ponton half float, complete with all specified bonded and attached components, shall be free from folds, wrinkles, blisters, puckers, defective or missing parts, or any other defect that could impair serviceability of the ponton half float. Surfaces to be cemented shall be wiped clean with a cleaning solvent before applying cement; the surfaces shall be free from grease, grit, dirt, oil, excess material used in fabrication, and any other foreign materials that could harmfully affect the application of the cement and the bonding of cemented surfaces. The halter assembly shall be free of defects that could impair serviceability.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified

Source: https://assist.dla.mil -- Downloaded: 202640-17T15:59Z
Check the source to verify that this is the current version before use.

herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.1.1 Component and material inspection. The contractor is responsible for insuring that component and materials used are manufactured, examined, and tested in accordance with referenced specifications and standards.

4.1.2 Parts and components. Parts and components detailed on the drawings shall be inspected in accordance with the quality assurance provisions (QAP) shown on the drawings. The drawings specify the characteristics requiring QAP inspection, the sampling plan, and the basis for acceptance and rejection (see 6.4 and 6.5).

4.2 Classification of inspection. Inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).

b. Quality conformance inspection (see 4.4).

c. Inspection of packaging (see 4.6).

4.3 First article inspection.

4.3.1 Examination. The first article ponton half floats, complete with all components, lacings, repair items, and halter assembly, shall be examined as specified in 4.5.1. Presence of one or more defects shall be cause for rejection.

4.3.2 Tests. The first article ponton half floats shall be tested as specified in 4.5.2. Samples for lap seam strength tests shall be fabricated identically to seams in the first article from coated cloth representative of that used to fabricate the ponton half float, and shall be vulcanized identically to one of the ponton half float, and shall be vulcanized identically to one of the ponton half float tubes represented. Failure of any test shall be cause for rejection.

4.4 Quality conformance inspection.

4.4.1 Sampling.

4.4.1.1 For examination. Sampling for examination shall be in accordance with MIL-STD-105.

Source: https://assist.dla.mil -- Downloaded: 202610-17T15:59Z
Check the source to verify that this is the current version before use.

4.4.1.2 For tests.

4.4.1.2.1 Lap seams. Samples for lap-seam tests shall be fabricated identically to seams in the ponton half float, from coated cloth representative of the ponton half floats, and vulcanized simultaneously with, and identically to, one of the ponton half float tubes represented. Width of the overlap shall not exceed the minimum overlap used in any seam in the ponton half float. The sample shall contain not less than 13 inches of linear seam and shall have not less than 3 inches of coated cloth extending on each side of the seam overlap. No gum strips or tapes shall be applied to sample seam edges. One sample shall be furnished for each 25 ponton half floats.

4.4.1.2.2 Pull resistance. For the pull resistance tests, one ponton half float shall be selected at random from each 25 ponton half floats.

4.4.2 Examination. Samples selected in accordance with 4.4.1.1 shall be examined for the major and minor defects specified in 4.5.1. AQL shall be 2.5 percent defective for major defects, and 4.0 percent defective for minor defects.

4.4.3 Tests.

4.4.3.1 Individual. Each ponton half float tube shall be tested as specified in 4.5.2.3.1, 4.5.2.3.2 and 4.5.2.4. Failure of a test shall be cause for rejection. Rejected tubes having repairable defects (see 3.10), may be repaired and resubmitted for all tests specified in 4.5.2.3.1 and 4.5.2.3.2. Failure of a test of a repaired tube shall be cause for rejection.

4.4.3.2 Samples.

4.4.3.2.1 Lap seam. Samples fabricated in accordance with 4.4.1.2.1 shall be tested as specified in 4.5.2.1. Failure of any test shall be cause for rejection of the ponton half floats represented.

4.4.3.2.2 Pull resistance. Ponton half floats selected in accordance with 4.4.1.2.2 shall be tested as specified in 4.5.2.2. Failure of any test shall be cause for rejection of the ponton half floats represented.

4.5 Inspection procedure.

4.5.1 Examination. The ponton half float, complete with all components, lacings, repair items, and halter assembly, shall be examined as specified herein for the following defects:

Source: https://assist.dla.mil -- Downloaded: 202610-17T15:59Z
Check the source to verify that this is the current version before use.

Major

101. Material not as specified.
102. Materials are not resistant to corrosion and deterioration or treated to be resistant to corrosion and deterioration for the applicable and operating environments.
103. Dissimilar metals as defined in MIL-STD-889 are not effectively insulated from each other.
104. Contractor does not have documentation available for identification of material, material finishes or treatment.
105. Any part (or component) not in accordance with the QAP requirements as shown on the drawings.
106. More than three longitudinal seams in each tube.
107. More than one longitudinal and one circumferential seam intersecting at one point.
108. Swashing of inner walls of tube compartments with sealing compound.
109. Seam overlap of air chamber or bulkhead fabric less than 2 inches.
110. Seaming tape required to cover seam edges of air chamber fabric and bulkhead fabric either missing or not as specified.
111. Overlap of seaming tape splices less than 1 inch and of gum strip splices less than 1/2-inch.
112. Gum strips required to cover exposed fabric edges and seaming tape edges either missing or not as specified.
113. Installation of inflation valves not as specified.
114. Rope work incorrect or not secured as specified.
115. Repairs other than as specified.
116. Nonadhering cemented surfaces.
117. Repair items not as specified or missing.
118. Components incorrectly attached, missing, or damaged.
119. Halter assembly not as specified.
120. Fittings and fastening devices not as specified.
121. Hardware finish incorrect.
122. Workmanship not as specified.

Minor

201. Any dimension other than those identified on the QAP requirements shown on the drawings not as specified.
202. Identification and instruction markings incorrect, illegible, or missing.
203. Color of materials not as specified.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T15:59Z
Check the source to verify that this is the current version before use.

4.5.2 Tests.

4.5.2.1 Lap seam strength. Prepare six test specimens by cutting the seam sample into 2-inch widths. Test three of the test specimens to failure in accordance with FED-STD-601, method 8311. Rupture of the seam before rupture of the coated cloth shall constitute failure of this test. Record and report breaking strength values regardless of failure mode. Test the remaining three specimens as follows: Subject each specimen to a tensile load (dead weight) of 80 pounds (40 pounds per inch width) at a temperature of 200° F. for a period of 24 hours with the seam running horizontally, and examine the seam for slippage. Nonconformance to 3.4 shall constitute failure of these tests.

4.5.2.2 Pull resistance.

4.5.2.2.1 Anchor patch assemblies. Apply a pulling force of 1,000 pounds to each anchor patch assembly as follows: On two of the four anchor patches on each side filler panel; on the bow filler panel; and on the stern connector. Apply the pull through the webbing strap and square link attachment in the direction for which the anchor patch is designed to resist, and hold the pulling force not less than 10 seconds. Nonconformance to 3.7 shall constitute failure of this test.

4.5.2.2.2 Valve patch assemblies. Apply a pulling force of 200 pounds to one valve patch assembly of each tube of the ponton half float. Apply the pulling force to either the valve core (with the valve cap assembly removed) or to the valve cap (with the valve cap assembly installed), in a direction perpendicular to the plane of the valve base. Hold the pulling force for not less than 10 seconds. Nonconformance to 3.5.1 shall constitute failure of this test.

4.5.2.3 Air retention.

4.5.2.3.1 Tubes. After vulcanization, inflate all compartments of each tube with air to a pressure of 5 psi at ambient temperature. After not less than 2 hours, adjust the pressure in all compartments as closely as possible to 2.5 psi. After adjustment of the pressure, seal the valve caps in such a manner that the tube cannot be re-inflated without breaking the seals. After 24 hours, take a final pressure reading of each compartment. To compensate for any temperature or barometric change during the test period, calculate the final pressure on the basis of a 0.3 psi change in pressure per 10° F. change in temperature, and of 0.49 psi change per inch (mercury) change in barometric pressure. Nonconformance to 3.5.2 shall constitute failure of these tests.

Source: https://assist.dla.mil -- Downloaded: 202610-17T15:59Z
Check the source to verify that this is the currentversion before use.

4.5.2.3.2 Alternate tube compartments. Inflate alternate compartments of each tube to a pressure of 3 psi. After not less than 1 hour, adjust the pressure as closely as possible to 2.5 psi. After a period of 4 hours inflation at this pressure, take a final pressure reading of the inflated compartments. Calculate the final pressure as specified in 4.5.2.3.1 to compensate for temperature and barometric changes during the test period. Nonconformance to 3.5.3 shall constitute failure of these tests.

4.5.2.4 Rotational distortion. With all air compartments inflated to an air pressure of 2 psi, measure the helical distortion of the finished tubes. Nonconformance to 3.5 shall constitute failure of this test.

4.5.2.5 Folding and air retest. Deflate all tube compartments of the ponton half float, fold the half float (to a size to fit the box specified in 5.2), unfold it, and inflate all compartments to not less than 2.5 psi. Repeat this cycle 25 times. After completion of the 25 folding cycles, inflate all tubes to 2.5 psi and test for air retention, after 24 hours, as specified in 4.5.2.3.1. Nonconformance to 3.5.2.1 shall constitute failure of this test.

4.6 Inspection of packaging.

4.6.1 Quality conformance inspection of pack.

4.6.1.1 Unit of product. For the purpose of inspection, a completed pack prepared for shipment shall be considered a unit of product.

4.6.1.2 Sampling. Sampling for examination shall be in accordance with MIL-STD-105.

4.6.1.3 Examination. Samples selected in accordance with 4.6.1.2 shall be examined for the following defects. AQL shall be 2.5 percent defective.

123.	Materials, methods, and containers not as specified for level A or B. Each incorrect material, method, or container shall be considered one defect.
124.	Repair kit items not preserved, placed in the pockets, and the pockets closed and secured as specified.
125.	Ponton floats not dusted, folded or rolled as specified.
126.	Box not lined as specified for level A or B.
127.	Strapping not as specified for level A.
128.	Packing not in accordance with the referenced document specified for commercial.
129.	Marking missing, illegible, incorrect, or incomplete for level A, B, or commercial.

Source: https://assist.dla.mil -- Downloaded: 202610-17T15:59Z
Check the source to verify that this is the currentversion before use.

5. PACKAGING

5.1 Preservation (see 6.6).

5.1.1 Repair kit items. Each of the repair kit items shall be individually preserved in accordance with MIL-P-116, method IC-1 or IC-3. The items shall then be placed in the repair kit pocket of the ponton float and the pocket closed and secured.

5.1.2 Ponton float. The ponton float shall be completely deflated, dusted with soapstone or talc, then carefully folded or rolled to a size to fit the box specified in 5.2.

5.2 Packing. Packing shall be level A, B, or commercial as specified (see 6.2).

5.2.1 Level A. Each complete ponton float, preserved as specified in 5.1, and with the halter assembly placed on top of the float, shall be packed in a close-fitting box conforming to PPP-B-601, overseas type, grade B, style optional or to PPP-B-621, class 2, style 2. Prior to placing the components in the box, the box shall be loosely lined with polyethylene material conforming to L-P-378, type I, class 1, with a minimum thickness of .0060 inch to prevent abrasion. Box closure and strapping shall be in accordance with the appendix to the applicable box specification. Strapping shall conform to QQ-S-781, class 1, types I or IV, size as applicable. Unless otherwise specified (see 6.2), strapping shall be finish B. When specified (see 6.2), strapping shall be finish A.

5.2.2 Level B. Packing shall be as specified in 5.2.1 for level A, except that the box shall be domestic type or class as applicable. Box closure and strapping shall be in accordance with the appendix to the applicable box specification.

5.2.3 Commercial. Each complete ponton float, preserved as specified in 5.1, shall be packed in accordance with ASTM D 3951.

5.3 Marking (see 6.6).

5.3.1 Military. Marking for military levels of protection (level A or B) shall be in accordance with MIL-STD-129.

5.3.2 Commercial. Marking for commercial packaging shall be in accordance with ASTM D 3951.

Source: https://assist.dla.mil -- Downloaded: 202640-17T15:59Z
Check the source to verify that this is the currenversion before use.

6. NOTES

6.1 Intended use. The ponton half float is intended for use as a floating support for floating bridges and bridge rafts.

6.2 Ordering data. Acquisition documents should specify the following:

a. Title, number, and date of this specification.

b. When a first article is required for inspection and approval and the number of units required (see 3.2, 4.3 and 6.3).

c. Degree of preservation and packing required (see 5.1 and 5.2).

d. When other than finish B strapping is required (see 5.2.1).

6.3 First article. When a first article inspection is required, the item to be tested should be a first produced item. The first article should consist of one or more units. The contracting officer should include specific instructions in acquisition documents regarding arrangements for examinations, test, and approval of the first article.

6.4 Quality assurance provisions (QAP) record. The contracting officer should require the contractor to maintain records of all QAP inspections. A suggested paragraph is as follows:

"The contractor shall maintain complete records of all examinations and tests performed to verify the requirements of classified QAP characteristics. The records shall include, as a minimum, lot size, sample size, drawing requirements, actual measurements, number and type of deficiencies found, quantity approved, quantity rejected, and corrective action taken when applicable."

6.5 Definitions.

6.5.1 Quality assurance provisions (QAP). A QAP is a contractual requirement that supplements section 4 of the specification. QAP indicates the minimum requirements which must be inspected on the product drawings to verify the design objectives of the product and assure interchangeability of repair parts.

6.6 Preservation. Levels of preservation have not been included as the requirements specified are the minimum acceptable for any level of protection. For purposes of preservation/packing level marking, the preservation shall be marked level A.

Custodian:
Army - ME
Navy - MC

Preparing activity:
Army - ME

Project 5420-0151

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T15:59Z
Check the source to verify that this is the current version before use.

INSTRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in submitting comments and suggestions for improvements. All users of military standardization documents are invited to provide suggestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and mailed. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was too rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the problems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an acknowledgement will be mailed to you within 30 days to let you know that your comments were received and are being considered.

NOTE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

DEPARTMENT OF THE ARMY

USA Belvoir R&D Center
STRBE-DS
Fort Belvoir, VA 22060-5606

NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.

POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
USA Belvoir R&D Center
STRBE-DS
Fort Belvoir, VA 22060-5606

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T15:59Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-P-11386G	Ponton Float: Pneumatic, Three-Tube Half Float, 12-Ton Capacity

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR ☐ USER ☐ MANUFACTURER ☐ OTHER *(Specify)*: _____
b. ADDRESS *(Street, City, State, ZIP Code)*	

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION (YYMMDD)

DD FORM 82 MAR 1426 PREVIOUS EDITION IS OBSOLETE.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T15:59Z
Check the source to verify that this is the current version before use.

NOTICE OF CANCELLATION

INCH-POUND

MIL-P-11386G
NOTICE 1
03 June 1996

MILITARY SPECIFICATION

PONTON FLOAT: PNEUMATIC, THREE-TUBE HALF FLOAT, 12-TON CAPACITY

MIL-P-11386G, dated 12 February 1985, is hereby canceled without replacement.

Custodians:
Army - AV
Navy - MC

Preparing activity:
Army - AV

Review activities:
DLA - CS

AMSC N/A

FSC 5420

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-17T15:59Z
Check the source to verify that this is the current version before use.