ADOPTION NOTICE

EIA-364-32, "Connectors and Sockets, Electrical, Thermal Shock (Temperature Cycling) Test Procedure for", was adopted on 22-OCT-2004 for use by the Department of Defense (DoD). Proposed changes by DoD activities must be submitted to the DoD Adopting Activity: Commander, Naval Air Warfare Center, Aircraft Division, Code 4L8000B120-3, Highway 547, Lakehurst, NJ 08733-5100. Copies of this document may be purchased from the Electronic Components Association, 2500 Wilson Boulevard, Arlington, Virginia 22201. http://ec-central.org

EIA-364-32 should be used instead of MIL-STD-1344A, method 1003.1, which was canceled on October 22, 2004.

Custodians:
Army - CR
Navy - AS
Air Force - 85
DLA - CC

Adopting Activity:
Navy - AS

Reviewer Activities:
Air Force - 99
Army - MI, AR
Navy - SH, MC, EC

NOTE: The activities above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.daps.dla.mil.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T15:48Z
Check the source to verify that this is the current version before use.