MIL-M-48119(MU)
February 6, 1973
SUPERSEDING
(See 6.6)

MILITARY SPECIFICATION

MINE, APERS, PRACTICE: M35

1. SCOPE

1.1 This specification covers the parts assembling and packing for one type of practice mine designated as M35.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein:

SPECIFICATIONS

MILITARY

MIL-A-2550 - Ammunition and Special Weapons, General Specification for

MIL-I-45607 - Inspection Equipment, Acquisition, Maintenance and Disposition of

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes (ABC-STD-105)

MIL-STD-109 - Quality Assurance Terms and Definitions

FSC: 1345

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

MIL-STD-1168 - Lot Numbering of Ammunition

MIL-STD-1235 - Single and Multilevel Continuous Sampling Procedures and Tables for Inspection by Attributes

DRAWINGS

U.S. Army Munitions Command

F-9212294 - Mine, Apers, Practice: M35
9218489 - Box, Packing, Ammunition, For Mine, Apers, Practice, M35 W/or W/o Maintenance Kit
9218490 - Carton, Packing, and Bag, Packing, for Maintenance Kit, for Mine, Apers, Practice, M35
9218491 - Container, Fiber, Ammunition, M406A2, for Mine, Apers, Practice, M35

PUBLICATIONS
ARMY
ET-9212294 - Equipment Tabulation

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the Contracting Officer).

2.2 Other publications.-The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on the date of invitation for bids or request for proposal shall apply.

CODE OF FEDERAL REGULATIONS

. Title 49 - Transportation, Parts 0-190

(The Code of Federal Regulations is available from the Superintendent of Documents, U. S. Government Printing Office, Washington, D. C. 20402. Orders should specify, "49 CFR 0-190 (latest revision)".)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

AMERICAN SOCIETY FOR TESTING AND MATERIALS

ASTM B 117-64 - Standard Method of Salt Spray (Fog) Testing

ASTM E 18-67 - Standard Methods of Test for Rockwell Hardness and Rockwell Superficial Hardness of Metallic Materials

(Application for copies should be addressed to: American Society for Testing and Materials, 1916 Race Street, Philadelphia, Pa. 19103)

3. REQUIREMENTS

3.1 Material.-Materials shall be in accordance with the applicable drawings and specifications.

3.2 Parts.-The parts shall comply with all requirements specified on Drawing (Dwg.) F-9212294, all associated drawings, and with all requirements specified in applicable specifications.

3.3 Mechanical properties.-Cold-working or heat-treating (including quenching-and-tempering, normalizing, normalizing-and-tempering, annealing, and stress-relieving) operations, shall be performed in such a manner as to produce the specified properties uniformly throughout the entire lot. The contractor shall determine the detailed procedures to produce parts meeting the required mechanical properties. These procedures shall be documented and submitted with the first article sample to the Contracting Officer. Changes in these procedures shall also be documented and submitted to the Contracting Officer.

3.4 Workmanship.-All parts and assemblies shall be fabricated and finished in a thorough, workmanlike manner. They shall be free of burrs, chips, sharp edges, cracks, unblended radii, surface defects, dirt, grease, rust, corrosion products, and other foreign matter. The cleaning method used shall not be injurious to any parts, nor shall the parts be contaminated by the cleaning agents. All marking and stamping shall be neat and sharply defined.

3.5 Submission of results of contractor-conducted examinations and tests.-The contractor shall forward copies of the results of any of his examinations or tests to the designated address as required by the contract. (See 6.5).

3.6 First article testing.-This specification makes provisions for first article testing. Submission of first article quantity by the contractor shall be as specified in the contract.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

3.7 Functioning.-The mine shall eject a visible signature plune when tested as specified in 4.4.18.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection.-Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Reference shall be made to MIL-STD-109 to define terms used herein. The provisions of MIL-A-2550 shall apply.

4.1.1 Submission of product.-At the time the completed lot of items deliverable under the contract is submitted to the Government for acceptance, the contractor shall supply the following information accompanied by a certificate which attests that the information provided is correct and applicable to the product being submitted:

a. A statement that the lot complies with all the quality assurance provisions specified in this specification.
b. Drawing and specification number and date, together with identification and date of changes thereto.
c. A statement that all material purchased by the contractor meets requirements, when such material is controlled by Government or commercial specifications referenced in any of the contractual documents, and that certificates of conformance are on file and available for review.
d. Number of items in the lot.
e. Date submitted.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Substantiation of the agent's authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization.

4.2 First article inspection.-

4.2.1 Submission.-The contractor shall submit a first article quantity as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.2.2. (See 6.1)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

The first article sample shall consist of the following:

a. Twenty-five (25) each of every component
b. Fifty (50) each of every assembly
c. Fifty (50) completely assembled mines

All parts and completed assemblies submitted shall have been produced by the contractor (or furnished by a supplier) using the same production processes, procedures and equipment as will be used in fulfilling the contract. All parts and materials, including packaging and packing, shall be obtained from the same sources of supply as will be used in regular production. The sample shall be accompanied by certificates of conformance. A first article quantity, or portion thereof, as directed by the Contracting Officer, shall also be submitted whenever there is a lapse in production for a period in excess of 90 days, or whenever a change occurs in manufacturing process (including heat treatment procedures and equipment, material used, drawing specification or source of supply as to significantly affect product uniformity as determined by the Government. Prior to submission, the contractor shall inspect the sample to the degree necessary to assure that it conforms to the requirements of the contract and submit a record of this inspection with the sample. A sample containing known defects will not be submitted unless specifically authorized by the Contracting Officer.

4.2.2 Inspection to be performed.-All parts and assemblies shall be subjected by the Government to any or all the examinations or tests specified in this specification and any or all requirements of the applicable drawings. In addition, the following tests shall be performed:

4.2.2.1 Internal air pressure of body (See Dwg. 9278250).-The twenty-five (25) bodies shall be subjected to this test.

4.2.2.2 Body porosity (See Dwg. 9278250).-The twenty-five (25) bodies shall be subjected to this test.

4.2.2.3 Internal air pressure of cover and arming latch assembly (See Dwg. 9212552).-The fifty (50) cover and arming latch assemblies shall be subjected to this test.

4.2.2.4 Trip lever pull test of cam on cover and arming latch assembly (See Dwg. 9212552).-The fifty (50) cover and arming latch assemblies shall be subjected to this test.

4.2.2.6 Security of take-up ring on cover and arming latch assembly (See Dwg. 9212552).-The fifty (50) cover and arming latch assemblies shall be subjected to this test.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.2.2.7 Security of crimp of firing pin on firing pin assembly (See Dwg. 8840306) .-The fifty (50) firing pin assemblies shall be subjected to this test.

4.2.2.8 Security cold test of trip wire tape (See Dwg. 8840352).-The fifty (50) trip wire assemblies shall be subjected to this test.

4.2.2.9 Pull test of wire and loop of trip wire (See Dwg. 8840352).-The fifty (50) trip wires shall be subjected to this test.

4.2.2.10 Static load test of actuating lever on spring housing assemblies (See Dwg. 9211794).-The fifty (50) firing spring housing assemblies shall be subjected to this test.

4.2.2.11 Min deflection at point of release of firing pin on spring housing assembly (See Dwg. 9211794).-The fifty (50) spring housing assemblies shall be subjected to this test.

4.2.2.12 Non-tripping test of actuating lever (See Dwg. 9211794).-The fifty (50) spring housing assemblies shall be subjected to this test.

4.2.2.13 Security of stake of actuating lever on spring housing assembly (See Dwg. 9211794).-The fifty (50) firing pin, lever and housing assemblies shall be subjected to this test.

4.2.2.14 Load test of trip lever (See Dwg. 8840351).-The twenty-five (25) trip levers shall be subjected to this test.

4.2.2.15 Load test of cover ring lugs (See Dwg. 9212116).-The twenty-five (25) cover rings shall be subjected to this test.

4.2.2.16 Salt spray.-Ten (10) each of the following parts shall be subjected to this test.

PART	DWG. NO.
Retainer, spool	8840292
Ring	8840296
Body	9278250
Retainer, spring housing	9212307
Pin, firing	8840309
Ring, take-up	9278210
Ring, cover	9278834
Cover	9212116

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

PART	DWG. NO.
Cam	8840324
Latch, arming	8840325
Handle, arming latch	8840350
Lever, trip	8840351

4.2.2.17 Hardness.-Fifteen (15) each of the following parts shall be subjected to this test.

a. Extraction tool (Dwg. 9211705)
b. Installation tool (Dwg. 9211706)
c. Reset tool (Dwg. 9219054)
d. Ring, take-up (Dwg. 9278210)
e. Retainer, spool (Dwg. 8840292)
f. Ring (Dwg. 8840296)
g. Spring, firing pin (Dwg. 8840310)
h. Latch, arming (Dwg. 8840325)

4.2.2.18 Functioning of Mine, Apers, Practice: M35 (See Dwg. F-9212294).-Fifty (50) mines shall be subjected to this test. If four (4) or more mines fail to eject a visible signature plume the first article quantity shall be rejected.

4.2.3 Rejection.-If any assembly or component fails to comply with any of the applicable requirements, the first article quantity shall be rejected. The Government reserves the right to terminate its inspection upon any failure of any primer. In the event of rejection, the Government reserves the right to require the contractor to take corrective action and submit a new first article quantity or portion thereof. Until a first article quantity is accepted, the contractor is in no way authorized by the Government to resume regular production unless otherwise directed by the Contracting Officer.

4.3 Inspection provisions.-

4.3.1 Lot formation.-The term "inspection lot" as used in this specification is defined as an essentially homogeneous collection of units of product from which a representative sample is drawn and inspected to determine conformance with applicable requirements. The sample selected shall represent only that quantity of units from which the sample was drawn and shall not be construed to represent any prior or subsequent quantities presented for inspection. Homogeneity shall be considered to exist provided the inspection lot has been produced by one manufacturer, in one unchanged process, in accordance with the same drawing, same drawing revision, same specification and same specification revision, and complies with the provisions for submission of product as specified in MIL-STD-105. Changes to process, specification, or drawing not affecting safety, perform-

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

ance, interchangeability, or storage, as determined by the Government, shall not be deemed to alter the homogeneity of an inspection lot. All material submitted for inspection in accordance with this specification shall comply with the homogeneity criteria specified herein regardless of the type of sampling procedure which is being applied to determine conformance with requirements. Lot numbering, as required, shall be in accordance with MIL-STD-1168. Each inspection lot shall contain:

a. Parts of one lot interfix number from one manufacturer.
b. Cartridges of one lot interfix number from one manufacturer.

4.3.2 Examination.-The examinations listed in the following subparagraphs shall be performed on inspection lots (See 4.3.1) of the components or assemblies designated in the applicable paragraph headings. Inspection for critical defects (and major defects, when so specified) shall be 100 percent. Sampling plans for major and minor defects shall be in accordance with MIL-STD-105 except that continuous sampling plans in accordance with MIL-STD-1235 may be used if approved by the Government. Individual defects will have an AQL of 0.40 Percent for each major defect and an AQL of 0.65 percent for each minor defect. Equipment necessary for the performance of the inspections listed shall be in accordance with 4.3.4.

4.3.2.1 Reset tool (See Dwg. 9219054)

Categories	Defects	Method of Inspection	Defect Code (See 6.2)
Critical: None defined			
Major: None defined			
Minor			
201.	Large diameter, min.	Gage	01001
202.	Small diameter, min.	Gage	01002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

203.	Length of tip	Gage	01003
204.	Evidence of poor workmanship (See 3.4)	Visual	01004

4.3.2.2 Extraction tool (See Dwg. 9211705).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major:	None defined		
Minor			
201.	Length of bar, min.	Gage	02001
202.	Finish improper	Visual	02002
203.	Tool damaged impairing its function (end slot damaged part deformed, etc)	Visual	02003
204.	Evidence of poor workmanship (See 3.4)	Visual	02004

4.3.2.3 Installation tool (See Dwg. 9211706).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Outside diameter at open end, min., (second largest outside diameter)	Gage	03001
102.	Outside diameter at face of open end, min.(smallest outside diameter)	Gage	03002
103.	Diameter of cavity	Gage	03003
Minor			
201.	Finish improper	Visual	03004
202.	Evidence of poor workmanship (See 3.4)	Visual	03005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.2.4 Barrel (See Dwg. 9211800 covering a detail of Dwg. 9212294).

Categories		Defects	Method of Inspection	Defect Code
Critical:		None defined		
Major				
	101.	Diameter of largest hole	Gage	04001
	102.	Location of largest hole	Gage	04002
	103.	Location of lugs for spring housing assembly	Gage	04003
	104.	Location of side wall cutout	Gage	04004
	105.	Runout of center hole with outside diameter of body	Gage	04005
	106.	Diameter of center hole, max.	Gage	04006
	107.	Diameter of bottom of cavity, open end, min.	Gage	04007
	108.	Diameter top of cavity, open end, max.	Gage	04008
	109.	Diameter of simulator recess	Gage	04009
	110.	Depth of simulator recess	Gage	04010
	111.	Dry lubricant missing	Visual	04011
	112.	Pitch diameter of screwhole(3)	Gage	04012
	113.	Location of screw holes(3)	Gage	04013
	114.	Cold shuts or porosity below or within safety tab	Visual	04014
	115.	Projections or depressions on lug bearing surface for spring housing	Visual	04015
	116.	Incomplete fill in any area	Visual	04116
Minor				
	201.	Distance from bottom of simulator recess to open end surface	Gage	04017
	202.	Outside diameter at datum	Gage	04018
Minor				
	203.	Evidence of poor workmanship (See 3.4)	Visual	04019

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.2.5 Ring, Take-up (See Dwg. 9278210 covering a detail of Dwg. 9212552).

Categories	Defects	Method of Inspection (See 4.3.3.2)	Defect Code
Critical:	None defined		
Major			
101.	Outside diameter, min.	Gage	05001
102.	Location of guide teeth (6)	Gage	05002
103.	Wall thickness	Gage	05003
104.	Angle of bend improper	Gage	05004
105.	Location of cut out on inside diameter	Gage	05005
106.	Distance from cut out to opposite diameter	Gage	05006
Minor			
201.	Width of guide teeth (6)	Gage	05007
202.	Color improper	Visual	05008
203.	Cut out radius, max.	Gage	05009
204.	Evidence of poor workmanship	Visual	05010

4.3.2.6 Housing, spring (See Dwg. 9211798 covering a detail of Dwg. 9211794).

Categories	Defects	Method of Inspection (See 4.3.3.1)	Defect Code
Critical:	None defined		
Major			
101.	Concentricity of diameter of post with diameter of body	Gage	06001
102.	Diameter of flange	Gage	06002
103.	Diameter of post	Gage	06003
104.	Diameter of hole in cartridge cavity	Gage	06004
105.	Diameter of body	Gage	06005
106.	Height of setting lug	Gage	06006
107.	Distance between outside of projections on spring housing for positioning in body	Gage	06007

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

	108.	Location of projections on spring housing for positioning spring in body	Gage	06008
	109.	Depth of cartridge cavity	Gage	06009
	110.	Diameter of cartridge cavity	Gage	06010
Major				
	111.	Weight, max.	Balance	06011
	112.	Incomplete fill in any area	Visual	06012
Minor				
	201.	Evidence of poor workmanship (See 3.4)	Visual	06013

* Combined AQL for Major defects 101-112 inclusive, is as follows: AQL 1.50 Percent (See 4.3.2.)

4.3.2.7 Simulator (See Dwg. 9211819 covering a detail of Dwg. 9212294).

Categories		Defects	Method of Inspection	Defect Code
Critical:		None defined		
Major				
	101.	Total length	Gage	07001
	102.	Length to flange from roll pin end	Gage	07002
	103.	Diameter of dye capsule cavity	Gage	07003
	104.	Location of dye capsule cavity	Gage	07004
	105.	Location of large (cartridge) cavity in barrel end	Gage	07005
	106.	Length of barrel recess, min.	Gage	07006
	107.	Barrel diameter, min.	Gage	07007
	108.	True position of barrel diameter	Gage	07008
	109.	Sleeve cavity and dye capsule cavity blocked from each other	Visual	07009
Minor		AQL 1.50 Percent		
	201.	Diameter of cartridge cavity, max.	Gage	07010
	202.	Diameter of flange, min.	Gage	07011
	203.	Evidence of poor workmanship (See 3.4)	Visual	07012

4.3.2.8 Sleeve, cartridge (See Dwg. 9211793 covering a detail of Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Length	Gage	08001
102.	Inside diameter	Gage	08002
103.	Outside diameter	Gage	08003
104.	Concentricity of outside diameter with inside diameter	Gage	08004
Minor			
201.	Evidence of poor workmanship (See 3.4)	Visual	08005

4.3.2.9 Simulator and barrel assembly (See Dwg. 9211820 covering a detail of Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Length from simulator face to bottom of barrel cavity	Gage	09001
102.	Distance between simulator face and roll pin (4 places)	Gage	09002
103.	Machine screw in barrel missing	Visual	09003
104.	Machine screw above flush	Visual	09004
105.	Roll pin missing or damaged (bent) (4)	Visual	09005
Minor	AQL 0.65 Percent		
106.	Evidence of poor workmanship (See 3.4)	Visual	09006

4.3.2.10 Cover (See Dwg. 9212116 covering a detail of Dwg. 9212552).

Categories	Defects	Method of Inspection (See 4.3.3.1)	Defect Code
Critical:	None defined		
Major			
101.	Width of o-ring grooves	Gage	10001
102.	Diameter of o-ring grooves	Gage	10002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

103.	Location of first o-ring groove from large open end	Gage	10003
104.	Large outside diameter	Gage	10004
105.	Concentricity of o-ring grooves with large outside diameter	Gage	10005
106.	Location of second o-ring groove from large open end	Gage	10006
107.	Location of sphere lug cavities	Gage	10007
108.	Location of lug (for cover ring slot)	Gage	10008
109.	Diameter of cam o-ring groove, max.	Gage	10009
Minor			
201.	Width of large sphere lug cavity	Gage	10010
202.	Width of small sphere lug cavity	Gage	10011
203.	Depth of sphere lug cavities	Gage	10012
Minor			
204.	Evidence of poor workmanship (See 3.4)	Visual	10013

4.3.2.11 Cover and arming latch assembly (See Dwg. 9212552 covering a detail of Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Stake of seal retainer in cover missing or incomplete	Visual	11001
102.	Seal retainer missing	Visual	11002
103.	Cam missing or inverted	Visual	11003
104.	Gap between cover and cover ring	Visual	11004
105.	Two angled lugs on arming latch not in alignment with arrow on cover ring	Visual	11005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection	Defect Code
Minor			
201.	Evidence of poor workmanship (See 3.4)	Visual	11006
202.	Assembly damaged (chipped edges, crack, raised metal, etc)	Visual	11007
203.	O-ring seal missing from lower groove of cover assembly	Visual	11008

4.3.2.12 Spring Housing Assembly (in tripped position) (See Dwg. 9211794 covering a detail of Dwg. 9211797).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Length between firing pin spring and flange with lever tripped, max.	Gage	12001
102.	Concentricity of firing pin with hole in bottom of primer-delay cavity	Gage	12002
103.	Stake of actuating lever in housing missing (2 places)	Visual	12003
Minor:	None defined		

4.3.2.13 Cam (See Dwg. 9219050 covering a detail of Dwg. 9212552).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Pitch diameter of thread, max.	Gage	13001
102.	Minor diameter of thread, max.	Gage	13002
103.	Length of thread, min.	Gage	13003
104.	Spherical diameter	Gage	13004
Minor			
201.	Finish improper	Visual	13005

4.3.2.14 Ring, cover (See Dwg. 9278334 covering a detail of Dwg. 9212552).

Categories	Defects	Method of Inspection (See 4.3.3.1)	Defect Code

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Categories		Defects	Method of Inspection	Defect Code
Major	101.	Thickness of shear lugs, min. (2)	Gage	14001
	102.	Distance from top of shear lugs to underside of ring cover lugs (6)	Gage	14002
	103.	Location of cover lug slot on outside diameter	Gage	14003
	104.	Location of arrow	Gage	14004
Minor	201.	Evidence of poor workmanship (See 3.4)	Visual	14005

4.3.2.15 Spring housing and body assembly (See Dwg. 9211797) covering a detail of Dwg. 9212294).

Categories		Defects	Method of Inspection	Defect Code
Critical:		None defined		
Major	101.	Spring housing assembly not free to adjust to alignment	Manual	15001
	102.	Spring housing turns out of body slot	Manual	15002
	103.	Actuating lever not in armed position	Visual	15003
	104.	Firing pin missing (not visible in cartridge cavity)	Visual	15004
Minor	201.	Evidence of poor workmanship (See 3.4)	Visual	15005

4.3.2.16 Retainer, spring housing (See Dwg. 9212307 covering a detail of Dwg. 9211794).

Categories		Defects	Method of Inspection (See 4.3.3.2)	Defect Code
Critical:		None defined		
Major	101.	Thickness	Gage	16001
	102.	Radius of curved surface	Gage	16002
	103.	Location of holes (2)	Gage	16003
	104.	Diameter of holes (2)	Gage	16004

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Minor			
201.	Diameter, min.	Gage	16005
202.	Evidence of poor workmanship (See 3.4)	Visual	16006

4.3.2.17 Body, (See Dwg. 9278250 covering a detail of Dwg. 9211797).

Categories	Defects	Method of Inspection (See 4.3.3.1)	Defect Code
Critical:			
1.	None		
Major			
101.	Diameter of barrel cavity	Gage	17001
102.	Depth of notch for spring housing assembly	Gage	17002
103.	Width of notch for spring housing assembly, retaining screw end	Gage	17003
104.	Diameter of simulator cavity	Gage	17004
105.	Concentricity of inside diameter for the spring housing with the inside diameter for barrel	Gage	17005
106.	Location of small notch in flange	Gage	17006
107.	Location of letter "S"	Gage	17007
108.	Location of letter "A"	Gage	17008
109.	O-ring seal diameter	Gage	17009
110.	Concentricity of o-ring seal diameter with diameter of simulator cavity including perpendicularity with flange face	Gage	17010
111.	Location of cotter pin hole	Gage	17011
112.	Depth to seating surface for spring housing assembly	Gage	17012
113.	Thickness of flange	Gage	17013
114.	Location of vent hole	Gage	17014
115.	Scratches, nicks or porosity on large o-ring seal surface	Visual	17015
116.	Incomplete fill in any area	Visual	17016

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Minor				
	201.	Location of letter "S" less than 5 degrees toward arming position	Gage	17017
	202.	Width of ribs	Gage	17018
	203.	Location of body ribs	Gage	17019
	204.	Diameter of body under flange, min.	Gage	17020
	205.	Inside diameter, bottom	Gage	17021
	206.	Outside diameter, bottom	Gage	17022
	207.	Distance between notches in flange, max.	Gage	17023
	208.	Width of small notch in flange, max.	Gage	17024
	209.	Width of large notch in flange, max.	Gage	17025
Minor				
	210.	Width of cover groove, max.	Gage	17026
	211.	Diameter of cover groove, max.	Gage	17027
	212.	Inside diameter of flange, max.	Gage	17028
	213.	Total height	Gage	17029
	214.	Diameter of hole for cotter pin	Gage	17030
	215.	Pitch diameter hole for set screw	Gage	17031
	216.	Location of set screw hole	Gage	17032
	217.	Excess paint in bottom of body (when applicable)	Visual	17033
	218.	Angle on cover groove missing	Visual	17034
	219.	Flash on flange end	Visual	17035
	220.	Exterior protective coating with bare spot	Visual	17036
	221.	Evidence of poor workmanship (See 3.4)	Visual	17037

4.3.2.18 Retainer, Seal (See Dwg. 9219048 covering a detail of Dwg. 9212552).

Categories	Defects	Method of Inspection	Defect Code

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Outside diameter, min.	Gage	18001
102.	Inside diameter, max.	Gage	18002
103.	Distance from bottom of notch to opposite outside diameter, min.	Gage	18003
104.	Thickness of seal	Gage	18004
Minor			
201.	Evidence of poor workmanship (See 3.4)	Visual	18005

4.3.2.19 Dye Capsule Assembly (See Dwg. 9219051 covering a detail of Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Diameter, min.	Gage	19001
102.	Total weight, min.	Balance	19002
103.	Heat seal of closure, incomplete	Visual	19003
Minor			
201.	Evidence of poor workmanship (See 3.4)	Visual	19004

4.3.2.20 Capsule, Dye (See Dwg. 9219052 covering a detail of Dwg. 9219051).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Thickness of capsule bottom	Gage	20001
102.	Inside diameter	Gage	20002
Minor			
201.	Outside diameter, min.	Gage	20003
202.	Total height, min.		20004
203.	Evidence of poor workmanship (See 3.4)	Visual	20005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.2.21 Closure (See Dwg. 9219053 covering a detail of Dwg. 9219051).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major:	None defined		
Minor:			
201.	Thickness	Gage	21001
202.	Diameter	Gage	21002
203.	Evidence of poor workmanship (See 3.4)	Visual	21003

4.3.2.22 Case, Cartridge, and Sleeve Assembly (See Dwg. 9219073 covering a detail of Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major:			
101.	Total length, max.	Gage	22001
102.	Gap between cartridge case and sleeve	Gage	22002
Minor:			
201.	Evidence of poor workmanship (See 3.4)	Visual	22003

4.3.2.23 Retainer, Spring Housing (See Dwg. 8840300 covering a detail of Dwg. 8840288).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major:			
101.	Outside diameter, min.	Gage	23001
102.	Inside diameter, max.	Gage	23002
103.	Thickness	Gage	23003
Minor:			
201.	Angle of bend	Gage	23004
202.	Evidence of poor workmanship (See 3.4)	Visual	23005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.2.24 Lever, actuating (See Dwg. 8840305 covering a detail of Dwg. 9211794).

Categories	Defects	Method of Inspection (See 4.3.3.1)	Defect Code
Critical:	None defined		
Major			
101.	Total length	Gage	24001
102.	Distance from center of shaft to firing pin spring surface of lever	Gage	24002
103.	Distance from center of shaft to barrel surface of lever	Gage	24003
104.	Radius from center of shaft to firing pin spring surface of lever	Gage	24004
105.	Perpendicularity of shaft (both ends)	Gage	24005
Minor			
201.	Total length of shaft	Gage	24006
202.	Diameter of shaft	Gage	24007
203.	Dry lubricant missing	Visual	24008
204.	Evidence of poor workmanship (See 3.4)	Visual	24009

4.3.2.25 Firing pin assembly (See Dwg. 8840306 covering a detail of Dwg. 9211794).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Diameter of firing pin point	Gage	25001
102.	Profile of firing pin point	Gage	25002
Minor:	None defined		

4.3.2.26 Firing pin spring (See Dwg. 8840310 covering a detail of Dwg. 8840306).

Categories	Defects	Method of Inspection (See 4.3.3.2)	Defect Code

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Critical: None defined

Major			
101.	Thickness of material, min.	Gage	26001
102.	Width of lever tab, min.	Gage	26002
103.	Total width	Gage	26003
104.	Location of firing pin hole	Gage	26004
105.	Location of screw holes (2)	Gage	26005
106.	Width of screw holes (2), max.	Gage	26006
107.	Length of screw holes (2), max.	Gage	26007
108.	Distance from tab to center of firing pin hole	Gage	26008
109.	Tab angle	Gage	26009
Minor			
201.	Thickness of material, max.	Gage	26010
202.	Diameter of firing pin hole	Gage	26011
203.	Width of slot	Gage	26012
204.	Evidence of poor workmanship (See 3.4)	Visual	26013

4.3.2.27 Latch, arming (See Dwg. 8840325 covering a detail of Dwg. 9212552).

Categories	Defects	Method of Inspection (See 4.3.3.1)	Defect Code
Major			
101.	Height of formed edge, min.	Gage	27001
102.	Total width	Gage	27002
103.	Distance between latch arms	Gage	27003
104.	Width of cam slot	Gage	27004
105.	Distance from the cam locking surface to the latch arms, max.	Gage	27005
106.	Diameter of cotter pin hole	Gage	27006
Minor			
201.	Evidence of poor workmanship	Visual	27007

4.3.2.28 Handle, arming latch (See Dwg. 8840350 covering a detail of Dwg. 8840291).

Categories	Defects	Method of Inspection (See 4.3.3.2)	Defect Code
Critical:	None defined		
Major			
101.	Distance from small slot to large slot	Gage	28001

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Minor			
201.	Width of smaller latch hole	Gage	28002
202.	Width of large latch hole	Gage	28003
203.	Length of smaller latch hole	Gage	28004
204.	Length of larger latch hole	Gage	28005
Minor			
205.	Evidence of poor workmanship (See 3.4)	Visual	28006

4.3.2.29 Trip lever (See Dwg. 8840351 covering a detail of Dwg. 8840291).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Pitch diameter of thread	Gage	29001
102.	Major diameter of thread	Gage	29002
103.	Length of thread, min.	Gage	29003
Minor			
201.	Diameter of eye	Gage	29004
202.	Length from thread end to center of eye	Gage	29005
203.	Evidence of poor workmanship (See 3.4)	Visual	29006

4.3.2.30 Retainer, spool (See Dwg. 8840292 covering a detail of Dwg. 9212294).

Categories	Defects	Method of Inspection (See 4.3.3.2)	Defect Code
Critical:	None defined		
Major			
101.	Small inside diameter, max.	Gage	30001
102.	Thickness, before plating	Gage	30002
Minor			
201.	Outside diameter, min.	Gage	30003
202.	Large inside diameter, max.	Gage	30004
203.	Color improper	Visual	30005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.2.31 Spool, trip wire (See Dwg. 8840349 covering a detail of Dwg. 8840291).

Categories	Defects	Method of Inspection (See 4.3.3.2)	Defect Code
Critical:	None defined		
Major			
101.	Location of slots	Gage	31001
102.	Width of slots	Gage	31002
103.	Width of wrench slot	Gage	31003
104.	Small diameter of trip lever hole, max.	Gage	31004
105.	Inside diameter, max.	Gage	31005
106.	Body outside diameter	Gage	31006
107.	Length from top to seat	Gage	31007
Minor			
201.	Total length	Gage	31008
202.	Large outside diameter	Gage	31009
203.	Color improper	Visual	31010
204.	Crack in arming latch handle slot	Visual	31011
205.	Evidence of poor workmanship (See 3.4)	Visual	31012

4.3.2.32 Spool assembly (See Dwg. 8840291 covering a detail of Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Number of trip wires incorrect	Visual	32001
102.	Color of trip wires incorrect	Visual	32002
103.	Hole or cutouts (2) missing from arming latch handle	Visual	32003
Minor:	None defined		

4.3.2.33 Spring housing assembly (prior to inserting in body) (See Dwg. 9211794 covering a detail of Dwg. 9211797).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Actuating lever incorrectly positioned (not under firing pin spring)	Visual	33001
102.	Firing pin spring screw (2) missing or not fully seated	Visual	33002
103.	Firing pin point damaged	Visual	33003
104.	Assembly damaged (cracked, chipped or distorted)	Visual	33004
105.	Spring retainer missing	Visual	33005
Minor			
201.	Evidence of poor workmanship (See 3.4)	Visual	33006

4.3.2.34 Mine assembly (prior to inserting simulator and barrel assembly) (See Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Cartridge sleeve assembly missing	Visual	34001
Minor			
201.	Evidence of poor workmanship in body or on housing assembly (See 3.4)	Visual	34002

4.3.2.35 Mine assembly (prior to inserting cover and arming latch assembly) (See Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Simulator and barrel assembly missing	Visual	35001

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

102.	Simulator and barrel assembly incorrectly positioned	Visual	35002
103.	Roll pin missing or damaged	Visual	35003
104.	Dye capsule assembly missing	Visual	35004
Minor			
201.	Evidence of poor workmanship (See 3.4)	Visual	35005

4.3.2.35.1 Mine assembly (after inserting cover and arming latch assembly) (See Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Torque required to rotate cover assembly, max.	Test	35005
Minor:	None defined		

4.3.2.36 Mine assembly (See Dwg. 9212294).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Arming latch missing	Visual	36001
102.	Cover and arming latch assembly incorrectly positioned (latch arms not seated under cam flange; or latch arms, arrow on cover ring and letter "S" on body not in alignment	Visual	36002
103.	Arming instruction tag missing or damaged	Visual	36003
104.	Instructions on instruction tag missing, illegible or incorrect	Visual	36004

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

105.	Spool assembly or spool retainer missing or incorrectly assembled	Visual	36005
106.	Spool assembly damaged (Tape peeling, wire loosening, lug broken or cracked)	Visual	36006
107.	Cam damaged (cracked or chipped)	Visual	36007
108.	Trip lever missing from spool assembly	Visual	36008
109.	Arming latch handle missing from spool assembly	Visual	36009
110.	Set screw missing	Visual	36010
111.	Paint color incorrect	Visual	36011
Minor			
201.	Painting of body inadequate or damaged (bare spot)	Visual	36012
202.	Marking on body misleading or unidentifiable	Visual	36013
203.	Evidence of poor workmanship (See 3.4)	Visual	36014
204.	Cotter pin legs inadequately spread	Visual	36015

4.3.2.37 Fiber container (prior to closing) (See Dwg. 9218491).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Number of mines incorrect	Visual	37001
102.	Mine inverted	Visual	37002
103.	Contents loose (insufficient fillers)	Visual	37003
104.	Container damaged	Visual	37004
Minor			
201.	Spacer tub missing	Visual	37005
202.	Evidence of poor workmanship (See 3.4)	Visual	37006
203.	Marking of container misleading or unidentifiable	Visual	37007

4.3.2.38 Carton (Maintenance kit-prior to sealing of carton) (See Dwg. 9218490).

Categories	Defects	Method of Inspection	Defect Code

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Critical: None defined

Major			
101.	Replacement parts missing or incomplete	Visual	38001
102.	Maintenance tools missing or incomplete	Visual	38002
103.	Expendable materials missing or incomplete	Visual	38003

Minor: None defined

4.3.2.39 Sealed carton (prior to inserting into wooden box) (See Dwg. 9218490).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Box damaged	Visual	39001
102.	Sealing strip incomplete, badly wrinkled, or missing	Visual	39002
Minor			
201.	Contents loose	Manual	39003
202.	Label missing or badly wrinkled (where applicable)	Visual	39004

4.3.2.40 Sealed barrier bag (See Dwg. 9218490).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Waterproofness destroyed by separation of heat seal or rip, tear, or puncture	Visual	40001
Minor			
201.	Marking misleading or unidentifiable	Visual	40002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.2.41 Sealed wooden packing box (See Dwg. 9218489).

Categories	Defects	Method of Inspection	Defect Code
Critical:	None defined		
Major			
101.	Strapping missing, broken or loose	Visual	41001
102.	Contents exposed	Visual	41002
103.	Board broken or split	Visual	41003
104.	Protruding nail	Visual	41004
Minor			
201.	Contents loose (when box is tilted)	Manual	41005
202.	Strapping improperly assembled	Visual	41006
203.	Car seal missing, unsealed or improperly positioned	Visual	41007
204.	Marking misleading or unidentifiable, including incorrect color code	Visual	41008

4.3.3 Testing.

4.3.3.1 Dimensional control of cast parts.-In place of the normal sampling associated with the Classification of Defects, and with the approval of the Contracting Officer, a sample of at least three (3) parts (as cast) from each cavity may be dimensionally inspected to qualify a new or reworked cavity for use in production or as a control of the cavity during production. Inspection for control of each cavity during production shall be performed on the above quantities from each cavity after production of 5000 parts. Individual cavity identification must be provided.

If any defective parts are found during qualification of the cavity, the cavity producing the defective part will not be used in production. If any defective parts are found when inspection is performed for control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for corrective action.

All cavities formerly removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test specified above. The contractor may request a change of inspection frequency providing he presents objective evidence to substantiate the request to the Contracting Officer.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.3.2 Dimensional control of stamped parts.-In place of the normal sampling associated with the Classification of Defects, and with the approval of the Contracting Officer, a sample of at least ten (10) parts may be dimensionally inspected to qualify the tool used in he stamping process for use in production. In addition, a random sample of five (5) parts shall be selected from the last portion of each hour's production for dimensional inspection as a control of the tool during production.

If any defective parts are found during qualification of the tool, the tool producing the defective part shall not be used in production.

If any defective parts are found when inspection is performed for control of the tool, the tool producing the defective part shall be removed from production. Further, that portion of production since the last tool control check shall be returned to the contractor for corrective action.

All tools removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the Contracting Officer to substantiate the request.

4.3.3.3 Dimensional control of molded parts.-In place of the normal sampling associated with the Classification of Defects, and with the approval of the Contracting Officer, and after a curing time for the parts has been approved (See Note 1), a sample of three (3) parts (as molded) from each cavity may be dimensionally inspected to qualify a new or reworked cavity for use in production or as a control of each cavity during production.

The inspection of the parts shall be performed only when the curing time for the parts has been reached. The inspection for control of each cavity during production shall be performed on the above quantities from each cavity after production of each 5000 parts or at the end of each shift, providing the number of parts produced during that shift is less than 5000 parts. Of the three (3) samples, one (1) sample shall be the last part produced.

NOTE 1: In establishing a curing time, dimensionally check ten(10) parts from each cavity at fifteen (15)-minute intervals until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. The inspection data used in determining the curing time shall be sent to Picatinny Arsenal, SMUPA-QA-A-S. If any new change in material, cycle time, a reworked cavity, or new cavity is used, a new curing time shall be established and approved.

4.3.3.4 Internal air pressure of body (See Dwg. 9278250) Major Defect (Code Number 42001).-One-hundred and twenty-five (125) bodies shall be selected from each lot and subjected to this test. If two

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

(2) or more bodies fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.1 using equipment in accordance with 4.3.4.

4.3.3.5 Internal air pressure of cover and arming latch assembly (See Dwg. 9212552) Major Defect (Code Number 43001).-One-hundred and twenty-five (125) cover and arming latch assemblies shall be selected from each lot and subjected to this test. If two (2) or more assemblies fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.2 using equipment in accordance with 4.3.4.

4.3.3.6 Trip lever pull test of cam on cover and arming latch assembly (See Dwg. 9212552) Major Defect (Code Number 44001).-Eighty (80) cover and arming latch assemblies shall be selected from each lot and subjected to this test. If two (2) or more cams fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.3 using equipment in accordance with 4.3.4.

4.3.3.7 Security of stake of seal retainer on cover and arming latch assembly (See Dwg. 9212552) Major Defect (Code Number 45001).-Eighty (80) cover and arming latch assemblies shall be selected from each lot and subjected to this test. If two (2) or more seal retainers fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.4 using equipment in accordance with 4.3.4.

4.3.3.8 Security of take-up ring on cover (See Dwg. 9212552) Major Defect (Code Number 46001).-Eighty (80) cover assemblies shall be subjected to this test. If two (2) or more take-up rings fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.5 using equipment in accordance with 4.3.4.

4.3.3.9 Security of crimp of firing pin on firing pin assembly (See Dwg. 8840306) Major Defect (Code Number 47001).-Eighty (80) firing pin assemblies shall be selected from each lot and subjected to this test. If two (2) or more firing pins fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.6 using equipment in accordance with 4.3.4.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.3.10 Security cold test of trip wire tape (See Dwg. 8840352) Major Defect (Code Number 48001).-Fifty (50) trip wires shall be selected from each lot and subjected to this test. If two (2) or more trip wires fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.7 using equipment in accordance with 4.3.4.

4.3.3.11 Pull test of wire and loop of trip wire (See Dwg. 8840352) Major Defect (Code Number 49001).-One-hundred twenty-five (125) trip wires, twenty-four (24) inches long, shall be selected from each lot and subjected to this test. If two (2) or more trip wires fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.8 using equipment in accordance with 4.3.4.

4.3.3.12 Static load test of actuating lever on Spring Housing Assembly (See Dwg. 9211794) Major Defect (Code Number 50001).-Eighty (80) firing pin, lever and housing assemblies shall be selected from each lot and subjected to this test. If two (2) or more assemblies fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.9 using equipment in accordance with 4.3.4.

4.3.3.13 Min deflection at point of release of firing pin on firing pin, lever and housing assembly,(See Dwg. 9211794) Major Defect, (Code Number 51001).-Eighty (80) firing pin, lever and housing assemblies shall be selected from each lot and subjected to this test. If two (2) or more assemblies fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.10 using equipment in accordance with 4.3.4.

4.3.3.14 Non-tripping test of actuating lever (See Dwg. 9211794) Major Defect (Code Number 52001).-This test shall be performed 100 percent. Any assembly which fails to comply with the requirement specified on the applicable drawing shall be classed defective and removed from the lot. The test shall be performed as specified in 4.4.11 using equipment in accordance with 4.3.4.

4.3.3.15 Security of stake of actuating lever on Spring Housing Assembly (See Dwg. 9211794) Major Defect, (Code Number 53001).-Eighty (80) firing pin, lever and housing assemblies shall be selected from each lot and subjected to this test. If two (2) or more assemblies fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.12 using equipment in accordance with 4.3.4.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.3.16 Load test of trip lever (See Dwg. 8840351) Major Defect, (Code Number 54001).-Fifty (50) trip levers shall be selected from each lot and subjected to this test. If any trip lever fails to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.13 using equipment in accordance with 4.3.4.

4.3.3.17 Load test of cover ring lugs (See Dwg. 9278834) Major Defect (Code Number 55001).-One hundred twenty-five (125) cover rings shall be selected from each lot and subjected to this test. If two (2) or more cover rings fail to comply with the requirement specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.14 using equipment in accordance with 4.3.4.

4.3.3.18 Salt spray, Major Defect, Code Number 56001).

4.3.3.18.1 Batch-type process.-When the parts are produced in a batch-type process, ten (10) of each part specified in Table I shall be selected from each batch and subjected to the salt spray test as specified on the applicable drawing. If any part fails to comply with the specified requirement, the batch represented by the failing part shall be rejected. The test shall be performed as specified in 4.4.15.

4.3.3.18.2 Continuous-type process.-When the parts are produced in a continuous-type process, five (5) of each part specified in Table I shall be selected from each four (4) hours of production, or portion thereof, and subjected to the salt spray test as specified on the applicable drawing. If any part fails to comply with the specified requirement, the quantity represented by the failing part shall be rejected. The test shall be performed as specified in 4.4.15.

4.3.3.18.3 Lot plan.-Ten (10) each of the following parts shall be selected from each lot and subjected to the salt spray test as specified on the applicable drawing. If any part fails to comply with the specified requirement, the lot represented by the failing sample shall be rejected. The test shall be performed as specified in 4.4.15.

TABLE I

PART	DWG. NO.
Retainer, Spool	8840292
Ring	8840296
Body	9278250
Retainer, spring housing	9212307
Pin, firing	8840309
Ring, take-up	9278210
Ring, cover	9278834

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

Cover	9212116
Cam	9219050
Latch, arming	8840325
Handle, arming latch	8840350
Lever, trip	8840351

4.3.3.19 Hardness, Major Defect, (Code Number 57001).-Five (5) each of the following parts shall be selected from each heat-treatment batch and subjected to this test. If any part fails to comply with the requirement specified on the applicable drawing, the batch represented by the failing part shall be rejected. The test shall be performed as specified in 4.4.16 using equipment in accordance with 4.3.4.

PART	DWG. NO.
Installation Tool	9211706
Reset Tool	9219054
Extraction Tool	9211705
Retainer, spool	8840292
Ring	8840296
Retainer, spring housing	9212307
Spring, firing pin	8840310
Ring, take-up	9278210
Latch, arming	8840325

4.3.3.20 Body porosity (See Dwg. 9278250) Major Defect, (Code Number 58001).-Twenty (20) bodies shall be selected from each casting lot and subjected to this determination. If two (2) or more bodies fail to comply with the requirements specified on the applicable drawing, the lot shall be rejected. The test shall be performed as specified in 4.4.17.

4.3.3.21 Functioning (See 3.7) Major Defect, Code Number 58002 (ambient temperature) (See Dwg. F-9212294).-One hundred and twenty-five (125) mines shall be selected from each lot and subjected to this test. If eight (8) or more mines fail to function as evidenced by a visible signature plume, the lot shall be rejected. The test shall be performed as specified in 4.4.18.

4.3.4 Inspection equipment.-Equipment Tabulation (ET) number 9212294 and Equipment Lists (EL's) referenced thereon identify the inspection equipment required to performed the examinations and and tests prescribed in this section. The contractor shall design inspection equipment in accordance with the instructions in 6.3. Supply and maintenance of the equipment listed on the EL's shall be in accordance with MIL-I-45607.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.3.4.1 Government rights to documentation.-Inspection equipment drawings and lists provided and revised in accordance with the requirements of this specification may be used by DOD activities for design, procurement, manufacture, testing, evaluation, production and receiving inspection, overhaul, shipping, storage, identification of stock, ordering and storage of replacement parts, inspection of items at overhaul, general maintenance of equipment, construction, survey, and whenever inspection equipment drawings are needed.

4.4 Test methods and procedures.

4.4.1 Internal air pressure of body.-The body shall be placed in a fixture shown on the Equipment List and the required pressure specified on Dwg. 9278250 shall be applied. This test is a non-destructive test. Parts so tested may be returned to the lot.

4.4.2 Internal air pressure of cover and arming latch assembly.-The cover and arming latch assembly shall be placed in a fixture shown on the Equipment List and the required pressure specified on Dwg. 9212552 shall be applied. This test is a non-destructive test. Parts so tested may be returned to the lot.

4.4.3 Trip lever pull test of cam on cover and arming latch assembly.-The cover and arming latch assembly shall be placed in a fixture shown on the Equipment List and the load specified on Dwg. 9212552 shall be applied. This test is a non-destructive test. Parts so tested may be returned to the lot.

4.4.4 Security of stake of seal retainer on cover and arming latch assembly.-The cover and arming latch assembly shall be placed in a fixture shown on the Equipment List and the force specified on Dwg. 9212552 shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.4.5 Security of take-up ring on cover.-The cover, with staked take-up ring, shall be placed in a fixture shown on the Equipment List and the load specified on Dwg. 9212552 shall be applied. This test is a destructive test. Parts so tested shall be returned to the lot.

4.4.6 Security of crimp of firing pin on firing pin assembly.-The firing pin assembly shall be placed in a fixture specified on the Equipment List and the force specified on Dwg. 8840306 shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.4.7 Security cold test of trip wire tape.-The trip wire shall be placed in an approved chamber and the temperature of the chamber shall be lowered to that specified on Dwg. 8840352. This test is a non-destructive test. Trip wires so tested without visible signs of tape looseness may be returned to the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.4.8 Pull test of wire and loop of trip wire.-The wire shall be placed in a fixture specified on the Equipment List and the load specified on Dwg. 8840352 shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.4.9 Static load test of actuating lever on Spring housing assembly.-The spring housing assembly shall be placed in a fixture specified on the Equipment List and the static load specified on Dwg. 9211794 shall be applied. This test is a non-destructive test. Parts so tested may be returned to the lot.

4.4.10 Min deflection at point of release of firing pin on Spring, housing assembly.-The spring housing assembly shall be placed in a fixture specified on the Equipment List and observation shall be made for the amount of deflection specified on Dwg. 9211794. This is a non-destructive test. Parts so tested may be returned to the lot.

4.4.11 Non-tripping test of actuating lever.-The spring housing assembly shall be placed in a fixture specified on the Equipment List and observation shall be made for the amount of travel of lever specified on Dwg. 9211794. This is a non-destructive test. Actuating levers that trip the firing pin prior to attaining the max dimension specified on the drawing shall be classed defective.

4.4.12 Security of stake of actuating lever on spring housing assembly.-The firing pin, lever and housing assembly shall be placed in a fixture specified on the Equipment List and the force specified on Dwg. 9211794 shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.4.13 Load test of trip lever.-The trip lever shall be placed in a fixture specified on the Equipment List and the load specified on Dwg. 8840351 shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.4.14 Load test of cover ring lugs.-The cover ring shall be placed in a fixture specified on the Equipment List and the load specified on Dwg. 9212116 shall be applied. This is a destructive test. Parts so tested shall not be returned to the lot.

4.4.15 Salt spray.-The parts selected shall be subjected to the salt spray test in accordance with ASTM Test Method B 1 -64. (Part 7). This is a destructive test. Parts so tested shall not be returned to the lot.

4.4.16 Hardness.-The parts shall be tested for hardness in accordance with ASTM E 18-67 (Part 31).

4.4.17 Body porosity.-Each body selected for this determination shall be selected longitudinally in four (4) places, 90° apart. The cross sectioned area of each segment shall be examined for voids or pits that exceed drawing requirements.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

4.4.18 Functioning.-

Pull force.-The mine shall be mounted in an approved fixture. The trip lever shall be threaded into the cam on the cover assembly of the unarmed mine. Attach a lanyard to the end of the arming latch handle. The lanyard will extend approximately fifteen (15) feet. From the end of the arming latch handle measure four (4) feet along the lanyard and attach a six or seven foot nylon cord. Attach the opposite end of the cord to the top of the installed trip lever. The arming latch handle will then be assembled to the lugs on the arming latch. The mine cover shall then be rotated to the armed position by using the arming latch handle to rotate the cover assembly in a clockwise direction, approximately 100 degrees to a fixed stop (slightly past "A" position).

CAUTION: The mine is now in the functioning position. The mine shall be positioned so that the attached arming latch handle now is in the same direction as the lanyard to permit the arming latch to be easily withdrawn from the mine. This procedure is such that a pull on the lanyard will, first, pull the arming latch off the mine and then exert the required force on the trip lever to function the mine. If the mine does not function due to breakage of the lanyard or trip lever cord, or due to other causes not attributed to the mine, as determined by the Government Representative, it shall be declared, "No-test". If the mine does not function after the required force has been exerted on the trip lever, it shall be classed as a dud.

NOTE: WARNING: An armed mine with arming latch in place will function if dropped 2 inches. Read arming instructions on Arming Tag P/N 9219657, prior to conducting functioning test.

The mine functioning test is a destructive test for the cartridge sleeve assembly and dye capsule assembly. Mines tested may be returned to the lot providing the following operations are performed:

a. Wipe clean the inside of the mine body, the simulator-barrel assembly and the cover assembly.

b. Clean and visually inspect the cover o-ring. If damaged it must be replaced.

c. Replace cartridge sleeve assembly.

d. Replace dye capsule assembly.

e. Reassemble per drawing 9212294.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging.

5.1.1 Level A.-The mine, apers, practice, XM35 shall be preserved and packaged in accordance with Dwg. 9218491.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

5.1.2 Level A.-The maintenance kit shall be preserved and packaged in accordance with Dwg. 9218490.

5.2 Packing.

5.2.1 Level A.-The mine, apers, practice, M35, preserved and packaged as specified in 5.1.1, shall be packed in accordance with Dwg. 9218489.

5.2.2 Level A.-The maintenance kit, preserved and packaged as specified in 5.1.2, shall be packed in accordance with Dwg. 9218489.

5.3 Marking.-Marking shall be in accordance with Dwgs. 9218489, 9218490, 9218491 and Code of Federal Regulations, Title 49 Parts 171-179.

5.4 Shipping.-When components from more than one lot are shipped as a carload, each lot shall be kept separate, and the division between lots clearly indicated to prevent mixing of the lots in transit.

6. NOTES

6.1 Ordering data.-Procurement documents shall specify the following:

a. Title, number and date of this specification.
b. Data cards shall be prepared for each lot in accordance with the information specified in Standard MIL-STD-1167.
c. Provisions for submission of first article samples.

6.2 Inspection code numbers.-The five-digit code numbers assigned to the inspections herein are to facilitate future data collections and analysis by the Government. These code numbers are also used to correlate the characteristics cited on Equipment Lists with the inspections listed in this specification. These code numbers shall be listed on drawings of equipment designs submitted by the contractor (See 6.3.5).

6.3 Inspection equipment.-The contractor shall design inspection equipment as required by the referenced Equipment Lists (EL) in accordance with the instructions of paragraphs 6.3.1 through 6.3.5.

6.3.1 Equipment lists.-Equipment lists indicate the availability of inspection equipment designs by showing in the "Part Number" column of the list of inspection equipment (Form SMUPA 1010)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

the numbers of drawings or Federal Stock numbers of existing equipment designs, or codes as indicated in paragraph 6.3.2. Design action required of the contractor is described in paragraphs 6.3.3 and 6.3.4. The contractor will be required to prepare detailed drawings in accordance with 6.3.4 for all the equipment coded as "Contractor Design" in the "Part Number" column. These contractor designs must be approved by the Government prior to fabrication or procuring of the equipment. Designs shall be submitted for approval as specified in 6.3.5.

6.3.2 Equipment list codes.-The inspection equipment as defined in 6.3.3 and 6.3.4 will be designated in the EL by the following codes:

CD - Contractor design on controlled contractor format and/or commercial equipment.
MU - Army design, mandatory for use.

6.3.3 Army designs.-Army designs are reflected on detailed drawings which completely depict all the information necessary for the fabrication of the item of inspection equipment. The contractor need provide no design when an Army design is listed for an item of inspection equipment. Army designs fall into two basic classifications: Mandatory (designated "MU") and non-mandatory (indicated by drawing or Federal Stock Number). When an equipment list references mandatory Army Designs, the contractor shall comply with, and use these designs accordingly. The contractor may, however, in connection with non-mandatory designs, with the approval of the Government, design alternate inspection equipment to facilitate his operations. Such contractor-prepared designs (See 6.3.4) or commercial equipment selections must be approved by the Government prior to fabrication or procuring of the equipment. Designs shall be submitted for approval as specified in 6.3.5.

6.3.4 Contractor designs.-Contractor designs are designs of inspection equipment for which the Government has assigned design responsibility to the contractor. Contractor designs shall be supported by detailed drawings which depict all information necessary to completely fabricate, calibrate and operate an item of inspection equipment. This requires that the necessary views, dimensions, materials, finishes, notes and operating and calibration instructions be properly depicted in accordance with approved practices to the extent that further calculation or clarification will not be required. Unless otherwise specified,

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.

contractor designs may be developed on the format the contractor normally employs in his equipment design procedure provided such format reflects the detail and information specified above, subject to Specification MIL-D-1000, Category A, Form 3. Legibility and reproducibility shall permit conventional making of clearly understandable, high-contrast reproductions. Contractors shall submit three copies of final designs as a flat set. Designs shall be submitted for approval as specified in 6.3.5.

6.3.5 Submission of contractor design.-All submitted designs shall contain a reference to the applicable 5-digit code number contained in Section 4 of this specification and the appropriate component or assembly drawing number and revision letter to which the specific design applies. Unless otherwise specified on the EL, all designs of equipment for inspection of defects classified as critical and major shall be submitted for approval to the Commanding Officer, Picatinny Arsenal, ATTN: SMUPA-QA-A-S. All other designs of inspection equipment shall be approved by the inspection element of the agency administering the contract. Submission shall be as directed by the contracting officer. Partial submission of inspection equipment designs is permissible and encouraged. However, the Arsenal completion date for design review will be based on the date of the final submission of designs. Picatinny Arsenal design review will be accomplished, normally, within one month after receipt.

6.5 Submission of results of contractor-conducted examinations and tests.-Unless otherwise specified by the Contracting Officer, the contractor shall forward requested records of examinations or tests to Commanding Officer, Picatinny Arsenal, ATTN: SMUPA-QA-A-S.

6.6 Supersession data.-This specification includes the requirements of , and supersedes, Purchase Specification AEI-397, dated 16 September 1966.

Custodian:
Army-MU

Preparing Activity:
Army-MU

Project Number: 1345-A005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:14Z
Check the source to verify that this is the current version before use.