MIL-P-63188(AR)
25 June 1982
SUPERSEDING
(see 6.6)

MILITARY SPECIFICATION

PROJECTILE ASSEMBLY, NUCLEAR 8 INCH TRAINING: M173

This specification is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense

1. SCOPE

1.1 Scope. This specification covers requirements, quality assurance provisions and the preparation for delivery criteria for 8 Inch nuclear training projectiles (see 6.1).

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. Unless otherwise specified (see 6.2), the following specifications and standards of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DODISS) specified in the solicitation form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078 Ammunition, Standard Quality Assurance Provisions, General Specification for

Beneficial comments (recommendations, additions, deletions), and any pertinent data which may be of use in improving this document, should be addressed to: Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAN-Q, Dover, New Jersey 07801, by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426), appearing at the end of this document, or by letter.

FSC 1110

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

STANDARDS

MILITARY

MIL-STD-1167	Ammunition Data Cards
MS16556	Pin, Headless
MS19062	Ball Bearing, Nonferrous, Brass
MS29513	Packing, Preformed, Hydrocarbon Fuel Resistant, O Ring
MS35206	Screw, Machine, Pan Head, Cross Recessed, Carbon Steel, Cadmium Plated
MS35649	Nut, Plain, Hexagon, Machine Screw, UNC-2B
MS51982	Setscrew, Hexagon-socket, Oval Point, Alloy, Cadmium Plated UNC-3A

2.1.2 Other Government documents, drawings and publications. The following other Government documents, drawings, and publications form a part of this specification to the extent specified herein.

DRAWINGS (see 6.7)

US ARMY ARMAMENT RESEARCH & DEVELOPMENT COMMAND

9270723	Grommet Assembly
9287943	Warhead Section, Aft
9287954	Warhead Section, Forward
9287956	Ring, Shear Seal
9287971	Motor Body
9287972	Housing, Delay
9287983	Obturator
9288040	Cap Assembly, Rocket-Off
9295701	Plate, Mounting
9295750	Inert Rocket Motor Assembly M754
9295751	Warhead Section, Aft-Modified
9295752	Warhead Section, Forward-Modified
9295753	Adapter Assembly
9295754	Adapter
9295755	Projectile, 8 Inch Trainer, M754
9313677	8 Inch Stop Ring
9313682	Delay Column, Dummy
9313683	Delay Housing Assembly, Dummy

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

9317756	Packing and Marking for Projectile Assembly, 8 Inch, Training, M173
9317900	Shipping and Storage Container, M613
9326217	Connector, Trainer
9327698	Stud, Adapter
9340536	Projectile Assembly, Nuclear, 8 Inch Training: M173
11725080 (HDL)	Nose Section, M754, Type X

(Copies of specifications, standards, handbooks, drawings and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

2.2 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence.

3. REQUIREMENTS

3.1 Assembly. The training projectile assembly shall comply with all requirements specified on drawing (dwg.) 9340536 with the requirements of all applicable subassembly dwgs., with all requirements specified herein, and with the requirements of all applicable specification to the extent specified on the dwg. and herein.

3.2 Components and materials. The contractor shall provide objective evidence (see 6.4) that components and materials comply with all dwg. and specification requirements.

3.3 Government furnished material. The following items will be Government furnished subject to the conditions specified:

Description	Drawing	Quantity
Shipping and Storage Container, M613	9317900	as req'd
Wrench, Spanner H4278	9322213	as req'd
Disable Module, MC3395 TRA (Kit)	211707 REF (DOE)	as req'd

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

Description	Drawing	Quantity
Control Module, MC3138 TRA (Kit)	316577 REF (DOE)	as req'd
Fuze Forward Assembly, Training	11725080	as req'd
M650 Projectile Components	as applicable	as req'd by contract

3.4 Data cards. Data cards shall be provided for each assembly in accordance with MIL-STD-1167.

3.5 First article inspection. This specification contains technical provisions for first article inspection (see 4.3). Requirements for submission of first article samples shall be as specified in the contract.

3.6 Workmanship

3.6.1 Plastic and metal characteristics. All components shall be free from cracks, splits, cold flow, shrinkage, cold shuts, inclusions, porosity, or any similar characteristic.

3.6.2 Threads. Threads shall be full and undamaged for the entire minimum length or depth as required on the applicable drawing.

3.6.3 Burrs. Parts shall be free from burrs.

3.6.4 Foreign matter. Parts shall be free from chips, dirt, grease, rust, corrosion, or any embedded foreign material.

3.6.5 Cleaning. The cleaning method shall not be injurious to any of the parts, nor shall the parts be contaminated by the cleaning agent. Primary coats, when applicable shall be thoroughly dry before application of finished coats.

3.6.6 Protective finish. Protective finishes shall be smooth and even and shall completely cover the finished area with no bare spots or other defects exposing base material.

3.6.7 Marking. Marking shall be as specified on dwgs. and shall be neat and sharply defined.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise spexcified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Unless otherwise specified herein or in the contract or purchase order, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspection. The inspections specified herein are classified as follows:

1. First article inspection (see 4.3)
2. Quality conformance inspection (see 4.4).

4.3 First article inspection.

4.3.1 Submission. When the contract requires first article inspection (see 3.5), the contractor shall submit a first article sample as designated by the contracting officer for evaluation in accordance with 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawing	Quantity
Stud, Adapter	9327698	1
Plate, Mounting	9295701	1
Warhead Section, Aft-Modified	9295751	1
Warhead Section, Forward-Modified	9295752	1
Adapter	9295754	1
8 Inch Stop Ring	9313677	1
Delay Column, Dummy	9313682	1

4.3.2 Inspections to be performed. The first article quantity submitted in accordance with 4.3.1 shall be subjected to any or all of the requirements of the applicable drawings and the first article inspection table herein, subject to the conditions of 4.3.2.1.1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.3.2.1	Projectile Assembly, Nuclear, 8 Inch Training: M173 (see note)	1 OF 1	9340536 & 9317756
			NEXT HIGHER ASSEMBLY: NA

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Classification of defects for parts (see 4.3.2.1.1)	1 ea.		3.1	4.4.2.3 thru 4.4.2.9
	Classification of defects for subassemblies	1 ea.		3.1	4.4.2.10 thru 4.4.2.12
	Classification of defects for completely assembled M754 Training Projectile assembly	1		3.1	4.4.2.13
	Classification of defects for M173 Training Projectile in Shipping and Storage Container	1		3.1	4.4.2.14

NOTES:

First article inspections and tests are non-destructive. Items may be delivered as part of production quantity when specified in the contract.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

4.3.2.1.1 Assembly procedure. Following preliminary Government acceptance of M754 Training Projectile parts in accordance with 4.4.2.3 thru 4.4.2.9 the contractor shall assemble these parts into subassemblies for inspection in accordance with 4.4.2.10 thru 4.4.2.12. Following preliminary Government acceptance of these subassemblies the contractor shall assemble the subassemblies into a complete M754 Training Projectile for inspection in accordance with 4.4.2.13 (including assembly of a Government furnished Training Forward Fuze Assembly). Following preliminary Government acceptance of the M754 Training Projectile, the contractor shall use the projectile and other Government furnished material (see 3.3) to assemble a complete M173 Trainer in the Shipping and Storage container for inspection in accordance with 4.4.2.14.

4.3.3 Inspection equipment. The inspections and tests specified in 4.3.2 shall be accomplished with the gages and test equipment specified in 4.4.4.

4.3.4 Rejection. See MIL-A-48078.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. Inspection lots shall comply with lot formation provisions of MIL-A-48078.

4.4.2 Examinations. See MIL-A-48078 and Quality Conformance Tables herein.

a. Major defect sampling plans. Unless otherwise specified, inspection for major defects shall be sampled in accordance with Table I.

b. Minor defect sampling plans. Unless otherwise specified, inspection for minor defects shall be sampled in accordance with Table II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.1	Verification of MIL-SPEC and Commercial Items	1 OF 1	See Below
			NEXT HIGHER ASSEMBLY: See Below

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Objective evidence not available for the following items in accordance with applicable Drawing, Specification or Standard.		--	3.2	Visual (6.4)

Description	Spec or Strd	Dwg Used on dwg
Pin, Headless	MS 16556-641	9295755
"O" Ring Packing	MS 29513-019	9295750
Screw, Machine, Pan Head	MS 35206-206	9295753
Screw, Machine, Pan Head	MS 35206-263	9295753
Nut, Hexagon	MS 35649-222	9295753
Connector	9326217	9295753
Ball Bearing	MS 19062-2005	9295755
Set Screw	MS 51982-41	9295755

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.2	Verification of M650 Rocket Motor, Projectile, Fuze Forward Assembly and M613 Container Components	1 OF 1	See Below
			NEXT HIGHER ASSEMBLY: See Below

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Objective evidence not available for the following items in accordance with applicable specifications.		--	3.2	Visual (6.4)

Dwg. No.	Description	Used on Dwg.
9287971	Motor Body	9295750
9287972	Housing, Delay	9313683
9287956	Ring, Shear Seal	9295750
9288040	Cap Assy - Rocket Off	9295750
9287954	Warhead Section, Fwd	9295752
9287983	Obturator	9295755
9270723	Grommet Assembly	9295755
11725080	Fuze Forward Assy, Training	9295755
9317900	Shipping and Storage Container, M613	9340536
9326217	Connector, Trainer	9295753
9287943	Warhead Section, Aft	9295751

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.3	Stud, Adapter	1 OF 1	9327698
			NEXT HIGHER ASSEMBLY: 9295755

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Overall length		Table I	3.1	Gage
102.	Pitch diameter of thread		Table I	3.1	Gage
103.	Major diameter of thread		Table I	3.1	Gage
104.	Location of undercut		Table I	3.1	Gage
105.	Width of undercut		Table I	3.1	Gage
106.	Outside diameter bottom of undercut		Table I	3.1	Gage
107.	Radius bottom of undercut		Table I	3.1	Gage
108.	Outside diameter of stud head		Table I	3.1	Gage
109.	Width of slot		Table I	3.1	Gage
110.	Depth of slot		Table I	3.1	Gage
Minor:					
201.	Poor workmanship		Table II	3.6	Visual
202.	Material		--	3.2	Visual (6.4)

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Document is restricted. Downloaded: 2026-02-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Plate, Mounting				9295701
					NEXT HIGHER ASSEMBLY
					9295753
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Outside diameter		Table I	3.1	Gage
102.	Overall width		Table I	3.1	Gage
103.	Diameter 4 large holes		Table I	3.1	Gage
104.	Location 4 large holes		Table I	3.1	Gage
105.	Diameter 6 small holes		Table I	3.1	Gage
106.	Location 6 small holes		Table I	3.1	Gage
107.	Length 3 slots		Table I	3.1	Gage
108.	Location length of 3 slots		Table I	3.1	Gage
109.	Width of 3 slots		Table I	3.1	Gage
110.	Location width of 3 slots		Table I	3.1	Gage
Minor:					
201.	Surface finish 125		Table II	3.1	Visual
202.	Protective finish missing or bare spots present		Table II	3.1	Visual
203.	Poor workmanship		Table II	3.6	Visual
204.	Material		Table II	3.2	Visual (6.4)

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
4.4.2.5	Warhead Section, Aft-Modified		1 OF 1	9295751
				NEXT HIGHER ASSEMBLY: 9295755

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Overall length (max.)		Table I	3.1	Gage
102.	Knurl not removed		Table I	3.1	Visual
103.	Inert fill missing		Table I	3.1	Visual
104.	Improper weight of assembly		Table I	3.1	Gage
Minor:					
201.	Surface finish 125		Table II	3.1	Visual
202.	Marking missing or improper		Table II	3.1	Visual
203.	Poor workmanship		Table II	3.6	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9295752
4.4.2.6	Warhead Section, Forward-Modified				NEXT HIGHER ASSEMBLY 9295755
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Length		Table I	3.1	Gage
102.	Chamfer missing		Table I	3.1	Visual
103.	Pitch diameter external thread		Table I	3.1	Gage
104.	Major diameter external thread		Table I	3.1	Gage
105.	Inside diameter cavity		Table I	3.1	Gage
106.	Exterior paint removed		Table I	3.1	Visual
Minor:					
201.	Surface finish 125		Table II	3.1	Visual
202.	Marking missing or improper		Table II	3.1	Visual
203.	Poor workmanship		Table II	3.6	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assistdraw.mil -- Downloaded: 2020-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.7	Adapter				9295754
					NEXT HIGHER ASSEMBLY
					9295753
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR /100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Outside diameter (4.20-.02)		Table I	3.1	Gage
102.	Outside diameter undercut (3.748-.002)		Table I	3.1	Gage
103.	Inside diameter (2.75+.03)		Table I	3.1	Gage
104.	Face to end of adapter (.71+.02)		Table I	3.1	Gage
105.	Length face to face (2.01-.02)		Table I	3.1	Gage
106.	Outside diameter undercut (3.045-.010)		Table I	3.1	Gage
107.	Major diameter small thread		Table I	3.1	Gage
108.	Pitch diameter small thread		Table I	3.1	Gage
109.	Runout small thread		Table I	3.1	Gage
110.	Width of undercut (.140+.005)		Table I	3.1	Gage
111.	Face to end of adapter		Table I	3.1	Gage
112.	Inside diameter (2.580+.005)		Table I	3.1	Gage
113.	Depth of cavity (1.320+.010)		Table I	3.1	Gage
114.	Face to end of hole (1.740+.020)		Table I	3.1	Gage
115.	Parallelism face and bottom of hole		Table I	3.1	Gage
116.	Outside diameter (3.455-.010)		Table I	3.1	Gage
117.	Outside diameter (3.47-.01)		Table I	3.1	Gage
118.	Angle of taper (69°+2°)		Table I	3.1	Gage
119.	Center to side of rectangular hole, 2 places (.535+.010)		Table I	3.1	Gage
120.	Diameter 3 holes (.136+.005 -.001)		Table I	3.1	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2024-10-28 10:22:32Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.7 (cont)	Adapter				9295754
					NEXT HIGHER ASSEMBLY 9295753
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major: (cont'd)					
121.	Depth 3 holes (.37+.03)		Table I	3.1	Gage
122.	Location 3 holes		Table I	3.1	Gage
123.	Center to end rectangular hole, 2 places (1.215+0.10)		Table I	3.1	Gage
124.	Pitch diameter 4 threaded holes		Table I	3.1	Gage
125.	Minor diameter 4 threaded holes		Table I	3.1	Gage
126.	Location 4 threaded holes		Table I	3.1	Gage
127.	Any chamfer or radius missing		Table I	3.1	Gage
Minor:					
201.	Surface finish 125		Table II	3.1	Visual
202.	Protective finish missing or bare spots present		Table II	3.1	Visual
203.	Marking missing or incorrect		Table II	3.1	Visual
204.	Poor workmanship		Table II	3.6	Visual
205.	Material		-	3.2	Visual (6.4)

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
4.4.2.8	8 Inch Stop Ring		1 OF 1	9313677
				NEXT HIGHER ASSEMBLY: 9295750

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Inside radius of ring		Table I	3.1	Gage
102.	Thickness of ring		Table I	3.1	Gage
103.	Length of ring		Table I	3.1	Gage
104.	Width of ring		Table I	3.1	Gage
105.	Any radius missing		Table I	3.1	Visual
Minor:					
201.	Surface finish 125		Table II	3.1	Visual
202.	Poor workmanship		Table II	3.6	Visual
203.	Material		-	3.2	Visual (6.4)

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.9	Delay Column, Dummy	1 OF 1	9313682
			NEXT HIGHER ASSEMBLY 9313683

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Outside diameter		Table I	3.1	Gage
102.	Length		Table I	3.1	Gage
103.	Any chamfer missing		Table I	3.1	Visual
Minor:					
201.	Surface finish 125		Table II	3.1	Visual
202.	Poor workmanship		Table II	3.6	Visual
203.	Material		-	3.2	Visual (6.4)

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.10	Adapter Assembly	1 OF 1	9295753
			NEXT HIGHER ASSEMBLY: 9295755

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Improper assembly, any part missing		100%	3.1	Visual
102.	Mounting plate not securely fastened to adapter		100%	3.1	Manual
Minor:					
201.	Marking missing or improper		Table II	3.1	Visual
202.	Poor workmanship		Table II	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.11	Delay Housing Assembly, Dummy	1 OF 1	9313683
			NEXT HIGHER ASSEMBLY: 9295750

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Improper assembly, any component missing		100%	3.1	Visual
102.	Dummy delay column(s) not securely bonded in delay housing		100%	3.1	Manual
Minor:					
201.	Marking missing, illegible, incomplete or in improper location(s)		Table II	3.1	Visual
202.	Poor workmanship		Table II	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
4.4.2.12	Inert Rocket Motor Assembly		1 OF 1	9295750
				NEXT HIGHER ASSEMBLY: 9295755

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Knurl not removed		Table I	3.1	Visual
102.	Overall length (max.)		Table I	3.1	Gage
103.	Length rear face to stop rings (2 places)		Table I	3.1	Gage
104.	Location 2 stop rings (2.50+.03)		Table I	3.1	Visual
105.	Outside diameter (8.75 max)		Table I	3.1	Gage
106.	Any weld missing or improper		100%	3.1	Visual
107.	Delay housing not securely seated in motor body after shear seal installation		100%	3.1	Visual/Manual
108.	Improper Rocket Off Cap Assembly torque		100%	3.1	Gage
109.	Inert filler missing		100%	3.1	Visual
110.	Improper weight loaded rocket motor		100%	3.1	Gage
111.	Inside diameter at bottom of small cavity in inert fill		Table I	3.1	Gage
112.	Depth of small cavity in inert fill		Table I	3.1	Gage
113.	Angle of wall of small cavity in inert fill		Table I	3.1	Gage
Minor:					
201.	Surface finish 125		Table II	3.1	Visual
202.	Poor workmanship		Table II	3.6	Visual

NOTES:

Check the source to verify that this is the current version before use.
Downloaded from https://assist.dla.mil - Document is valid as of 2026-04-13T02:29:27

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.13	Projectile, 8 Inch Trainer, M754	1 OF 3	9295755
			NEXT HIGHER ASSEMBLY 9340536

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Location of adapter stud hole		Table I	3.1	Gage
102.	Pitch diameter of adapter stud hole thread		Table I	3.1	Gage
103.	Minor diameter of adapter stud hole thread		Table I	3.1	Gage
104.	Inside diameter of adapter stud hole counterbore		Table I	3.1	Gage
105.	Depth of adapter stud hole counterbore		Table I	3.1	Gage
106.	.04 x 45° countersink present on adapter stud hole		Table I	3.1	Visual
107.	152° location ball bearing hole		Table I	3.1	Gage
108.	5° location adapter stud hole		Table I	3.1	Gage
109.	14° location threaded hole		Table I	3.1	Gage
110.	Pitch diameter threaded hole		Table I	3.1	Gage
111.	Major diameter threaded hole		Table I	3.1	Gage
112.	Depth of threaded hole (min.)		Table I	3.1	Gage
113.	Height of adapter stud (.236 Max)		Table I	3.1	Gage
114.	Adapter stud not coated with sealing compound		Table I	3.1	Visual
115.	Setscrew plug not firmly seated		Table I	3.1	Visual
116.	Improper assembly; any component or subassembly missing		Table I	3.1	Visual
117.	Overall length (max.)		Table I	3.1	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 3		DRAWING NUMBER 9295755
4.4.2.13 (cont)	Projectile, 8 Inch Trainer, M754				NEXT HIGHER ASSEMBLY 9340536
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major: (cont)					
118.	Thread and bearing surfaces not clean prior to assembly		Table I	3.1	Visual
119.	Sealing compound missing from fwd whd/ aft whd threads		100%	3.1	Visual
120.	Improper fwd whd/aft whd torque		100%	3.1	Gage
121.	Sealing compound missing from aft/whd rocket motor threads		100%	3.1	Visual
122.	Improper aft whd/rocket motor torque		100%	3.1	Gage
123.	Inside diameter headless pin holes (3)		Table I	3.1	Gage
124.	Location headless pin holes (3)		Table I	3.1	Gage
125.	Headless pin missing or not flush with surface (3)		100%	3.1	Visual/Manual
126.	Grommet assembly not provided over rotating band		100%	3.1	Visual
127.	Orientation mark improper or missing (Sect. A-A)		100%	3.1	Visual
*128.	Improper fit of Training Fuze Forward Fuze Assembly		100%	3.1	Visual/Manual
Minor:					
201.	Protective finish(s) missing, improper or bare spots present		Table II	3.1	Visual
202.	Marking missing, illegible, improper or in incorrect location		Table II	3.1	Visual

NOTES:
*This test to be performed with a Government furnished Training Forward Fuze Assembly. Improper fit to be reported to the procuring agency.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
4.4.2.13 (cont)	Projectile, 8 Inch Trainer, M754		3 OF 3	9295755
				NEXT HIGHER ASSEMBLY 9340536

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor: (cont)					
203.	Poor workmanship		Table II	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE		SHEET 1 OF 4		DRAWING NUMBER
4.4.2.14	Projectile Assembly, Nuclear, 8 Inch Training: M173 (Packing and Marking)				9340536 & 9317756
					NEXT HIGHER ASSEMBLY N.A.
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
101.	Interior surfaces of shipping container not clean and free of dirt, grease, rust, loose particles or other foreign matter		100%	5.1	Visual
102.	Mating surfaces of MC3138 TRA Control Panel and module mounting bracket not clean and free of dirt and foreign matter		100%	5.1	Visual
103.	Improperly assembled, damaged or missing EMR gasket or MC3138 TRA Control Panel		100%	5.1	Visual
104.	MC3138 TRA Control Panel mounting screws improper, missing or improperly torqued		100%	5.1	Visual/Gage
105.	Improperly assembled or missing bonding strap		100%	5.1	Visual
106.	Bonding strap screws improper, missing or improperly torqued.		100%	5.1	Visual
107.	CF 2456 TRA Cable missing or improperly assembled to MC3138 TRA Control Panel		100%	5.1	Visual
108.	CF2455 Cable missing or improperly assembled to MC3138 TRA Control Panel		100%	5.1	Visual
109.	CF2455 or CF2456 TRA Cables improperly routed or not tied down		100%	5.1	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.14 (cont)	Projectile Assembly, Nuclear 8 Inch Training: M173 (Packing and Marking)	2 OF 4	9340536 & 9317756
			NEXT HIGHER ASSEMBLY N.A.

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major: (cont)					
110.	Mating surfaces of MC3395 TRA Disable Module and container not clean and free of dirt and foreign matter		100%	5.1	Visual
111.	Improperly assembled, damaged or missing MC3395 TRA Disable Module		100%	5.1	Visual
112.	MC3395 TRA Disable Module mounting screws improper, missing or improperly torqued		100%	5.1	Visual/Gage
113.	CF2455 Cable improperly or insecurely assembled to MC3395 TRA Disable Module		100%	5.1	Visual/Manual
114.	Paint marker or paint marker bracket improper missing or improperly assembled		100%	5.1	Visual
115.	Paint marker or paint marker bracket mounting screws improper, missing or improperly torqued		100%	5.1	Visual/Gage
116.	Interconnection block missing or improperly assembled on projectile		100%	5.1	Visual
117.	Cables (3) to interconnecting block improper, missing or improperly assembled		100%	5.1	Visual
118.	Cables (3) to interconnecting block not clamped to container		100%	5.1	Visual
119.	Cables (3) improperly assembled to MC3395 TRA Disable Module		100%	5.1	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
4.4.2.14 (cont)	Projectile Assemby, Nuclear, 8 Inch Trainer: M173 (Packing and Marking)		3 OF 4	9340536 & 9317756
				NEXT HIGHER ASSEMBLY: N.A.

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major: (cont)					
120.	Cable tie-down at shock mount improper or missing		100%	5.1	Visual
121.	CF2456 TRA Cable Connector improperly or insecurely assembled to projectile nose		100%	5.1	Visual/Manual
122.	CF2456 TRA Cable Connector Cover missing or improperly assembled on container side		100%	5.1	Visual/Gage
123.	CF2456 TRA Restraining Cable improperly assembled or missing		100%	5.1	Visual
124.	Container cover adapter or plug improper, missing or improperly assembled		100%	5.1	Visual
125.	Improper container cover adapter torque		100%	5.1	Gage
126.	Web lifting strap missing		100%	5.1	Visual
127.	Lifting device missing, improperly assembled or improperly oriented on projectile		100%	5.1	Visual
128.	Projectile improperly oriented in container		100%	5.1	Visual
129.	Projectile not butted up against rear plate		100%	5.1	Visual
130.	Hold down clamps improperly adjusted or do not secure projectile		100%	5.1	Visual/Manual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63188(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.14 (cont)	Projectile Assembly, Nuclear, 8 Inch Training: M173 (Packing and Marking)	4 OF 4	9340536 & 9317756
			NEXT HIGHER ASSEMBLY: N.A.

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major (cont)					
131.	Fuze assembly (in fuze container) improper, missing or improperly assembled		100%	5.1	Visual
132.	T-bolt or fuze spanner wrench improper, missing or not secured		100%	5.1	Visual/Manual
133.	Desiccant improper or missing		100%	5.1	Visual
134.	Humidity indicator card improper or missing		100%	5.1	Visual
135.	Maintenance log missing (when applicable)		100%	5.1	Visual
136.	Any T-bolt improperly torqued		100%	5.1	Gage
137.	Seals (4) missing		100%	5.1	Visual
138.	Assembly improper or incomplete (check before and after assembly of container covers)		100%	5.1	Visual
139.	Marking (including name plate) missing, incorrect, illegible or in incorrect location		100%	5.1	Visual
140.	Data cards missing		100%	3.6	Visual
141.	Poor workmanship		100%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

Table I. Sampling plan for major defects.

LQ = .05 Acceptance No. = 0 Consumers Risk = .10

Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size
1-16	all	28-29	23	52-56	31	132-156	39
17	16	30-31	24	57-62	32	157-191	40
18	17	32-34	25	63-69	33	192-244	41
19-20	18	35-36	26	70-76	34	245-334	42
21	19	37-40	27	77-86	35	335-519	43
22-23	20	41-43	28	87-97	36	520-1120	44
24-25	21	44-47	29	98-112	37	over 1120	45
26-27	22	48-51	30	113-131	38		

Table II. Sampling plan for minor defects.

LQ = .10 Acceptance No. = 0 Consumers Risk = .10

Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size
1-9	all	14-16	12	28-33	16	77-121	20
10	9	17-18	13	34-41	17	122-273	21
11	10	19-22	14	42-54	18	over 273	22
12-13	11	23-27	15	55-76	19		

4.4.3 Testing. Testing is described in the first article and quality conformance inspection Tables.

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the "Paragraph Reference/Inspection Method" column in the tables starting with 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract (see MIL-A-48078 and 6.3 herein).

5. PACKAGING

5.1 Packing and marking. Unless otherwise specified in the contract, M173 projectile assemblies shall be packed and marked in accordance with the requirements of dwgs. 9340536 and 9317756.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

6. NOTES

6.1 Intended use. The items covered by this specification are intended for use as M753 Projectile training items. The M173 Projectile assembly consists of the M754 Training Projectile mounted in the M613 Shipping and Storage Container with DOE Training Modules and ancillary equipment simulating a complete M753 Projectile in its shipping and storage configuration.

6.2 Ordering data.

6.2.1 Acquisition requirements. Acquisition documents should specify the following:

a. Title, number and data of this specification.
b. Government furnished property (see 6.5).
c. First article inspection, when required (see 3.5)

6.2.2 Data requirements. When this specification is used in an acquisition which incorporates a DD1423, Contract Data Requirements List (CDRL) the data requirements identified below shall be developed as specified by an approved Data Item Description (DD Form 1664) and delivered in accordance with the approved CDRL incorporated into the contract. When the provisions of DAR 7-104.9 (n) (2) are invoked and the DD Form 1423 is not used, the data specified below shall be delivered by the contractor in accordance with the contract or purchase order requirements. Deliverable data required by this specification is cited in the following paragraphs.

Paragraph no.		Data requirements	Applicable DID no.
(a)	3.4	Data cards	DI-L-1410
(b)	4.4.4	Inspection equipment approval	DD-R-1714 (Tailored)

(Copies of DID's required by contractors in connection with specific acquisition functions should be obtained from the Naval Publications and Forms Center or as directed by the contracting officer.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.

6.3 Equipment design approval. Submit equipment designs as required to commander US Army Armament Research and Development Command, ATTN: DRDAR-QAN-I, Dover, New Jersey 07801.

6.4 Objective evidence.

6.4.1 M650 Rocket Motor and Projectile Components, Fuze Forward Assembly Training Components and M613 containers. Ammunition data cards or other documentary evidence of Government Acceptance of these items in accordance with applicable drawings and specification.

6.4.2 Commercial and MIL-SPEC components. A certificate of conformance from the supplier certifying that the item complies with applicable dwg. and specification requirements.

6.4.3 Materials. A statement (certification) supported by test data that the material meets all applicable dwg. and specification requirements.

6.5 Government furnished property. The contracting officer should arrange to have the items specified in 3.3 furnished, as required.

6.6 Supersession data. This specification includes the requirements of AR-PD-53 dated 6 February, 1981.

6.7 Drawings and specifications. Drawings and specifications listed in Section 2 of this specification under the heading US Army Armament Research and Development Command may also include dwgs. and specifications prepared and identified as Frankford Arsenal, Edgewood Arsenal, Rock Island Arsenal or Picatinny Arsenal dwgs. and specifications. Technical data originally prepared by these activities is now under the cognizance of ARRADCOM.

Custodian:

Army - AR

Preparing activity:

Army - AR

(Project 1110-A168)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:23Z
Check the source to verify that this is the current version before use.