MIL-STD-1256A(WC)
4 June 1971

SUPERSEDING
MIL-STD-1256(WC)
2 December 1963
SA STD-101
28 November 1960

MILITARY STANDARD

RUBBER COATED PARTS

FOR

MACHINE GUN, 7.62MM, M60

FSC 1005

Source: https://assist.dla.mil -- Downloaded: 202640-23T23:34Z
Check the source to verify that this is the current version before use.

DEPARTMENT OF THE ARMY

U.S. ARMY MATERIEL COMMAND

WASHINGTON, D.C.

Rubber Coated Parts for Machine Gun, 7.62MM, M60 — 4 June 1971

MIL-STD-1256A(WC)

1. This standard has been approved by the Department of the Army and is published to provide standards for rubber coated parts for the 7.62MM, M60 machine gun.

2. Recommended corrections, additions, or deletions should be addressed to the Commanding General, U.S. Army Weapons Command, Attn: SWERR-E-SE, Rock Island, Illinois 61201.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.

CONTENTS

		Page
1	SCOPE	1
2	REFERENCED DOCUMENTS	2
3	DEFINITIONS	3
4	GENERAL REQUIREMENTS	4
5	DETAIL REQUIREMENTS	5
5.1	Standard comparison gages	5
5.2	Rubber coated parts	5
5.2.1	Cam bumper assembly - B7269126	5
5.2.2	Cheek pad assembly - D7269138	5
5.2.3	Forearm shell assembly - F7269190	6
5.2.4	Housing assembly, trigger - F7269203	6
5.2.5	Carrying handle assembly - D7269231	6
5.2.6	Butt stock shell assembly - F11686712	6

FIGURES

1-1	Flash	7
1-2	Flash	7
1-3	Flash	8
1-4	Flash	9
1-5	Flash	9
1-6	Flash	10
2-1	Trim	11
2-2	Trim	11
2-3	Trim	12
3-1	Flash and trim	13
3-2	Flash and trim	14
3-3	Flash and trim	14
3-4	Flash and trim	15
3-5	Flash and trim	15
3-6	Flash and trim	16
3-7	Flash and trim	16
3-8	Flash and trim	17
4-1	Radial flash	18
5-1	Ripple and trim	19
6-1	Surface nick	20
6-2	Surface nick	21
6-3	Surface nick	22
6-4	Surface nick	23
6-5	Surface nick	24

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.

1. SCOPE

1.1 This document establishes standard comparison gages for workmanship type defects for rubber coated parts for the 7.62MM, M60 Machine Gun.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.

2. REFERENCED DOCUMENTS

2.1 The issues of the following documents in effect on the date of the invitation for bids form a part of this standard to the extent specified herein:

GOVERNMENTAL
DRAWINGS

U.S. ARMY WEAPONS COMMAND

B7269126 - Bumper Assembly, Cam.
D7269138 - Pad Assembly, Cheek.
D7269231 - Handle Assembly, Carrying.
F7269190 - Shell Assembly, Forearm.
F7269203 - Housing Assembly, Trigger.
F11686712 - Shell Assembly, Butt Stock.

Source: https://assist.dla.mil -- Downloaded: 202640-23T23:34Z
Check the source to verify that this is the currenversion before use.

3. DEFINITIONS

Not applicable.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.

4. GENERAL REQUIREMENTS

4.1 The standard comparison gages established in this standard are in the form of photographs depicting borderline acceptable conditions for workmanship type defects commonly occurring in rubber coated parts for the M60 machine gun.

4.1.1 The application of these gages for acceptance inspection of the rubber coated parts is contained in Section 5 herein.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.

5. DETAIL REQUIREMENT

5.1 STANDARD COMPARISON GAGES.

5.1.1 For the purpose of this standard and convenience in referencing, the comparison gages are grouped by the type of defect as follows:

Type of defect	Figure No.
Flash	1-1 through 1-6.
Trim	2-1 through 2-3.
Flash and trim	3-1 through 3-8.
Radial flash	4.1.
Ripple and trim	5-1.
Surface nicks	6-1 through 6-5.

5.1.2 The borderline acceptable conditions permitted on specific surfaces or areas of weapon parts are specified in 5.2. Parts containing defects which exceed the borderline acceptable condition depicted in the specified standard comparison gage or which occur on surfaces or areas other than specified for that part shall be rejected.

5.2 RUBBER COATED PARTS.

5.2.1 Cam bumper assembly - B7269126.

5.2.1.1 Figure 1-1 represents flash and loose flash conditions at the plate junction.

5.2.2 Cheek pad assembly - D7269138.

5.2.2.1 Figure 2-1 represents trim condition at the mold parting line.

5.2.2.2 Figure 2-2 represents trim condition on the two longitudinal edges of this assembly.

5.2.2.3 Figure 4-1 represents radial flash at the front surface of the large and small ends.

5.2.2.3.1 A thin tightly adhering flash is permitted on the inside of the large end provided it will not cause interference at assembly to the cover. A thin tightly adhering flash is permitted on the inside radius of the small end.

5.2.2.4 Figure 1-2 represents loose flash condition on the inside of the longitudinal edges.

5.2.2.5 Figure 6-1 represents surface nick condition on the large end of the assembly.

Source: https://assist.dla.mil -- Downloaded: 202610-23T23:34Z
Check the source to verify that this is the current version before use.

5.2.2.6 Flash is permitted on the inside edge of all holes provided there is no interference at assembly.

5.2.3 Forearm shell assembly - F7269190.

5.2.3.1 Figures 3-1, 3-2, and 3-3 represent flash and trim conditions for the longitudinal edges.

5.2.3.2 Figures 2-3 and 5-1 represent trim conditions at the mold parting line.

5.2.3.3 Figure 5-1 also represents ripple condition caused when flash is removed from the square hole in the center of the bottom surface.

5.2.3.4 Figures 6-4 and 6-5 represent surface nick conditions applicable to this assembly.

5.2.3.5 A thin tightly adhering flash is permitted on the outside of the two U-shaped edges provided the flash will not cause interference at the assembly of the end caps.

5.2.4 Housing assembly, trigger - F7269203.

5.2.4.1 Figures 1-3, 1-4, 3-4, 3-5, 3-6 and 3-7 represent flash and trim conditions at the rivet holes, at the top edges, in the trigger opening and in the channel opening of this assembly.

5.2.4.2 Figures 6-2 and 6-3 represent surface nick conditions near the lower rear section of the trigger guard.

5.2.4.3 A thin tightly adhering coating is permitted at the bottom of the holes in each end of this assembly.

5.2.5 Carrying handle assembly - D7269231.

5.2.5.1 Figure 1-5 represents flash condition at the forward end of the rubber handle. This flash must be tight and adhering.

5.2.5.2 Figure 3-8 represents flash and trim condition at the mold parting line.

5.2.6 Butt stock shell assembly - F11686712.

5.2.6.1 Figure 1-6 represents flash conditions at the front section of the cheek pad radius.

5.2.6.2 Figures 6-4 and 6-5 represent surface nick condition at the lower rear section of this assembly.

5.2.6.3 All loose flash in the inside edge of the small end (receiver opening) must be removed. Buffing is not necessary for this flash removal.

5.2.6.4 A thin tightly adhering rubber coating is permitted on the butt plate surface provided the flash will not cause interference at assembly.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 1-1, Flash




Figure 1-2, Flash

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 1-3, Flash

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 1-4, Flash




Figure 1-5, Flash

Source: https://assist.dla.mil -- Downloaded: 202610-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 1-6, Flash

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 2-1, Trim



Figure 2-2, Trim

Source: https://assist.dla.mil -- Downloaded: 2026l0-23T23:34Z
Check the source to verify that this is the currentversion before use.




Figure 2-3, Trim

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 3-1, Flash and Trim

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 3-2, Flash and Trim




Figure 3-3, Flash and Trim

Source: https://assist.dla.mil -- Downloaded: 202610-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 3-4, Flash and Trim




Figure 3-5, Flash and Trim

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.



Figure 3-6, Flash and Trim



Figure 3-7, Flash and Trim

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 3-8, Flash and Trim

Source: https://assist.dla.mil -- Downloaded: 202610-23T23:34Z
Check the source to verify that this is the currentversion before use.




Figure 4-1, Radial Flash

Source: https://assist.dla.mil -- Downloaded: 202640-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 5-1, Ripple and Trim

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.



Figure 6-1, Surface Nick

Source: https://assist.dla.mil -- Downloaded: 202640-23T23:34Z
Check the source to verify that this is the current version before use.



Figure 6-2, Surface Nick

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.



Figure 6-3, Surface Nick

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 6-4, Surface Nick

Source: https://assist.dla.mil -- Downloaded: 202610-23T23:34Z
Check the source to verify that this is the current version before use.




Figure 6-5, Surface Nick

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.

(When required for use in a contract, the applicable photographs as depicted in Figures contained herein, may be obtained from U.S. Army Weapons Command, Attn: SWERR-E-SE, Rock Island, Illinois 61201.)

Custodian:
Army - WC

Preparing activity:
Army - WC

Project number:
1005-A410

☆ U. S. GOVERNMENT PRINTING OFFICE: 1971-714-156/12238

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:34Z
Check the source to verify that this is the current version before use.