MIL-STD-1372A(EC)
NOTICE - 1
18 January 1973

MILITARY STANDARD

PROCESS FOR SOLDERING ACCIDENT

DOSIMETER TO FILM BADGE HOLDER FOR

RADIAC DETECTING ELEMENT

TO ALL HOLDERS OF MIL-STD-1372A(EC)

1. THE FOLLOWING PAGES OF MIL-STD-1372A(EC) HAVE BEEN REVISED AND SUPERSEDE THE PAGES LISTED:

NEW PAGE	DATE	SUPERSEDED PAGE	DATE
5	18 January 1973	5	12 October 1972
6	12 October 1972		Reprinted without change

2. RETAIN THIS NOTICE PAGE AND INSERT BEFORE THE TABLE OF CONTENTS.

3. Holders of MIL-STD-1372A(EC) will verify that page changes indicated above have been entered. The notice page will be retained as a check sheet. This issuance, together with appended pages, is a separate publication. Each notice is to be retained by stocking points until the Military Standard is completely revised or cancelled.


Preparing activity:


Navy - EC

(Project THJM-N049)

FSC THJM

Source: https://assist.dla.mil -- Downloaded: 2026-10-24T00:10Z
Check the source to verify that this is the current version before use.





Outside diameter of the Dosimeter Tubular Housing shall be flush with the front or back or may be centered on the Film Badge Holder.

Figure 2. Positioning of outer case of film badge holder and metal tubular housing of dosimeter for soldering.

Source: https://assist.dla.mil -- Downloaded: 2026-10-24T00:10Z
Check the source to verify that this is the current version before use.




Fig. 3

Completed assembly of Film Badge Holder with attached Dosimeter showing orientation of plastic capsule in housing.

Source: https://assist.dla.mil -- Downloaded: 2026-10-24T00:10Z
Check the source to verify that this is the current version before use.