MIL-B-63299A(AR)
AMENDMENT 3
24 January 1985
SUPERSEDING
AMENDMENT 2
20 September 1984

MILITARY SPECIFICATION

BODY ASSEMBLY
MINE, ANTI-PERSONNEL: HE, M74

This Amendment forms a part of Military Specification MIL-B-63299A(AR), dated 15 December 1983, and is approved for use by the US Army Armament, Munitions and Chemical Command is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

* 2.1.2, Drawings: Delete "(See 6.7)" and substitute "(See 6.8)".

* PRODUCT AND PACKAGING DRAWING: Delete "... DRAWING" and substitute "...DRAWINGS".

PAGE 4

* 3.6d: Delete "Presence of shorting eyelet." and substitute "Presence of detonator and micropiston actuator flex cable shunts."

PAGE 8

Delete "Insert (Dwg. 9292629)" and substitute "Insert, Bushing (Dwg. 9381375)".

PAGE 18

4.4.2.4: Delete present Page 18 and substitute included Page 18.

PAGE 53

* 4.4.2.34, Critical 4: Delete "Shorting eyelet missing" and substitute "Flex cable shunts missing or improper".

FSC 1345



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:35Z
Check the source to verify that this is the current version before use.

PAGE 54

4.4.2.34: Delete Major 109 in its entirety.

PAGE 56

4.4.2.35 Cont'd: Add "Major 110, Shim missing or incorrect, 0.40%, 3.2, Visual".

PAGE 62

* 4.4.2.40:

Criticals 1 thru 4: Delete "0-1".

Critical 2: Delete "(See Note c)" and substitute "(See Note b)".

Critical 4: Delete "(b)".

Major: Delete "RESISTANCE OF EED's AFTER T-V, (a)" and substitute "RESISTANCE AFTER T-V".

PERFORMANCE/FUNCTION: Delete "(b)".

NOTES: Delete (a), (b) and (c) in their entirety and substitute "(a) See sheet 2; (b) Acoustic sensor or adequate alternate shall be used for monitoring".

FOLLOWING PAGE 63

Add Page 63A, 4.4.2.41 included herein.

PAGE 65

* 4.5.1, line 30: Delete "DRSMC-QAT-I(D)" and substitute "AMSMC-QAT-I(D)".

PAGE 66

* 4.5.1 CONT., line 3: Delete "DRSMC-QAT-M(D)" and substitute "AMSMC-QAT-M(D)".



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:35Z
Check the source to verify that this is the current version before use.

PAGE 73

* 6.3, line 3: Delete "DRSMC-QAT-I(D)" and substitute "AMSMC-QAT-I(D)".

* 6.4, line 3: Delete "DRSMC-QAT-M(D)" and substitute "AMSMC-QAT-M(D)".

* 6.6, line 4: Delete "DRSMC-QAT-M(D)" and substitute "AMSMC-QAT-M(D)".



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

MIL-B-63299A(AR)
AMENDMENT 3

## CLASSIFICATION OF DEFECTS & TESTS

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER 9381375 |
|---|---|---|---|---|---|
| 4.4.2.4 | Insert, Bushing | | | | NEXT HIGHER ASSEMBLY 9292680 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | None defined | | | | |
| Minor | | | | | |
| 201 | Length | | 0.65% | 3.2 | Gage |
| 202 | Outside diameter | | 0.65% | 3.2 | Gage |
| 203 | Diameter of hole | | 0.65% | 3.2 | Gage |
| 204 | Location of hole | | 0.65% | 3.2 | Gage |
| 205 | Evidence of poor workmanship | | 0.65% | 3.11 | Visual |

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63299A(AR)
AMENDMENT 3

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.41 | Shim, Shorting Bar | | | | 9381374 |
| | | | | | NEXT HIGHER ASSEMBLY 9292680 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | None defined | | | | |
| Minor | | | | | |
| 201 | Length | | 0.65% | 3.2 | Gage |
| 202 | Length of legs, 2 places | | 0.65% | 3.2 | Gage |
| 203 | Width | | 0.65% | 3.2 | Gage |
| 204 | Diameter of hole | | 0.65% | 3.2 | Gage |
| 205 | Evidence of poor workmanship | | 0.65% | 3.11 | Visual |

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:35Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1345-A332)



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:35Z
Check the source to verify that this is the current version before use.