INCH-POUND

MIL-M-70742 (AR)
AMENDMENT 1
14 JUNE 1991

MILITARY SPECIFICATION

MOUNT, TELESCOPE AND QUADRANT: P/N 12599166

This amendment forms a part of Military Specification MIL-M-70742 (AR), dated 30 September 1988, and is approved for use by the U.S. Army Armament, Munitions, and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

TITLE: Change from "MOUNT, TELESCOPE AND QUADRANT: P/N 12599166" to "MOUNT, TELESCOPE AND QUADRANT: M187"

PAGE 2

2.1, DRAWINGS: Change "12599166 MOUNT, TELESCOPE AND QUADRANT: P/N 12599166"

to "12599166 MOUNT, TELESCOPE AND QUADRANT: M187"

2.1, PACKAGING DATA SHEET: Change "12599166 PACKAGING OF MOUNT TELESCOPE AND QUADRANT: P/N 12599166"

to "12599166 PACKAGING OF MOUNT TELESCOPE AND QUADRANT: M187"

PAGE 3

3.5.2, change "-80" to "-50"

3.5.3, second sentence, delete and substitute:

"Each shock impulse shall be 100 g's half sine wave with a time duration of 3 +/-1 milliseconds."

PAGE 12

4.6.1.5, last sentence: Change "3.5.6" to "3.5.5"

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 20261O-23T03:57Z
Check the source to verify that this is the current version before use.

4.6.2.7, delete and substitute:

"4.6.2.7 Elevation error and backlash. With the fixture and mount positioned as outlined in 4.6.2.1 and with the auxiliary telescope's sighting device assembled to the mount, insert an elevation into the mount from low to high thus excluding backlash. Rotate the fixture handwheel until the mount elevation level vial bubble is centered. Using a gunners quadrant (inspection aid) on the fixture quadrant seat assembly, measure the actual elevation. The difference between the whole number mount elevation and the actual reading form the gunners quadrant shall not exceed the limit outlined in 3.6.4.2. Place the gunners quadrant on the auxiliary telescope's sighting device and center the quadrant level vial bubble. Record this gunners quadrant reading. Rotate the mount elevation knob approximately one revolution beyond the elevation. Rotate the knob in the reverse direction back to the original whole number elevation, making sure not to override this position. Center the gunners quadrant level bubble. Record this gunners quadrant reading. The difference between the first gunners quadrant reading and the second is considered backlash and shall not exceed the limit outlined in 3.6.4.3.1."

Custodian:
Army-AR

Preparing Activity:
Army–AR

(Project 1240-AB22)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:57Z
Check the source to verify that this is the current version before use.