INCH-POUND
A-A-60024A
24 June 2024
SUPERSEEDING
A-A-60024
08 June 2022

COMMERCIAL ITEM DESCRIPTION

AUTOMATED MANUFACTURING MACHINE, COMPUTER NUMERIC CONTROL LATHE, SLANT BED, HORIZONTAL-SPINDLE

The General Services Administration has authorized the use of this commercial item description (CID) for all federal agencies.

1 SCOPE. (CID) covers computer numeric control (CNC), horizontal-spindle, slant-bed lathes and turning centers intended for turning, boring, drilling, reaming, tapping, and facing of workpieces of cast iron, steel, titanium, aluminum, brass, graphite epoxy, and composite materials, for use in Aircraft Metals Technology Shops across the Air Force. The equipment identified herein shall be manufactured in the United States of America.

CNC milling is an automated machine process used to manufacture engineering parts by selectively and progressively removing material from a workpiece. Material removal (milling) occurs via use of a rotating multi-point cutting tool and computerized controls (i.e., CNC). Parts manufactured via CNC milling are most practical via use of Computer-Aided Design (CAD) and Computer-Aided Manufacturing (CAM) software. CAD enables development and design of a part. CAM programs are used to generate manufacturing tool paths and to automate the manufacturing processes; CAM converts the CAD model into an executable CNC program (.NC) for machine use. This results in CNC manufacturing (machine control), instructing (via "G-code") the machine to execute the job in order to manufacture a physical part.

G-code, per Electronic Industries Alliance (EIA) SAE RS-274D, is required as the programming language; it describes geometric paths using a simple command structure of the letter "G" followed by a numeric value.

Beneficial comments, recommendations, additions, deletions, clarifications, etc., and any data that may improve this document should be sent to: AFLCMC/EZSS, Bldg. 28, 2145 Monahan Way, Wright-Patterson AFB, OH 45433-7017 or email engineering.standards@us.af.mil. Since contact information can change, you should verify the currency of this information using the ASSIST Online database at https://assist.dla.mil.

AMSC/NA FSC 3416

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

2. CLASSIFICATION. The slant-bed lathes and turning centers shall be of the sizes specified in Table I. The size is the maximum cutting length (also referred to as the center-to-center distance) as shown in Table I. The size to be furnished shall be as specified (see 7.4(b).

TABLE I. Sizes Slant-bed Lathes and Turning Centers.

Size	Chuck Size	Max Speed	Max Spindle Rating
16.0 in	6.5 in	6000 rpm	15 hp
22.5 in	8.3 in	4000 rpm	20 hp
32.5 in	10.0 in	4000 rpm	20 hp

3. SALIENT CHARACTERISTICS.

3.1 General requirements. The lathe or turning center shall be new and one of the manufacturer's current models capable of operation in accordance with the requirements herein. The lathe or turning center shall be constructed from materials with sufficient mass and strength and configured in a shape and size that shall support the workpiece and machine components while minimizing element deflections and initiated and/or transmitted vibration during operation. The rotational axis of the workpiece shall be horizontal. The longitudinal axes of machineways supporting the carriage, tailstock, steady rests, or tool rests shall lie in a horizontal plane and shall be parallel to the rotational axis of the workpiece. All parts subject to wear, breakage, or distortion shall be accessible for adjustment, replacement, and repair. Access doors or removable panels shall be provided for servicing all components located within the lathe or turning center.

The machining center and CNC system shall be shipped to the AF ready to operate pending training and installation. The term "ready to operate" is defined herein as a minimum set of tooling and accessories, internal and external hardware and software, and components required for installation to operate the machining center and CNC systems to perform milling operations.

3.2 Components. The lathe or turning center shall include, as a minimum, the following components:

3.2.1 Base. The base shall support the lathe or turning center bed and all components mounted thereon. The base shall provide a means for leveling and anchoring the machine. A swarf collection area shall be provided to collect and retain turning chips and coolant fluid either adjacent to or within the base.

3.2.2 Base Anchoring. The lathe or turning center shall be delivered with fasteners, adapters, clamps, or other hardware required to affix the base to the floor. Maximum diameter for each hole required in the shop floor shall be 1 inch.

3.2.3 Bed. The bed shall support the machine ways upon which the carriage, tailstock, and tool or workpiece rests travel. The bed shall be configured to allow the chip swarf to either pass through openings in the bed or be diverted to the collection area.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

3.2.4 Spindle and Spindle Drive.

3.2.4.1 Spindle. The spindle shall be fabricated from alloy steel, then hardened and ground. The spindle shall be supported on preloaded, antifriction roller or ball bearings within the headstock. All spindle bearings shall be sealed and lubricated for life, or by centralized lubricating system. The spindle shall be dynamically balanced both before and after assembly. The spindle shall be thermally isolated from the headstock and spindle drive. The spindle nose shall conform to American Society of Mechanical Engineers (ASME) B5.9. Spindles shall be compatible with provided chucks (see section 3.2.5) listed in Table I. Spindles shall conform to the requirements listed in Table II.

TABLE II: Spindle Requirements.

Size	Max Speed	Bar Capacity	Chuck Size	Drive Type	Peak Power[1]
16.0 in	6000 rpm	1.75 in	6.5 in	Belt	75 ft-lb @ 1300 rpm
22.5 in	4000 rpm	2.50 in	8.3 in	Belt	300 ft-lb @ 500 rpm
32.5 in	4000 rpm	2.50 in	10.0 in	Belt	300 ft-lb @ 500 rpm

Note 1: Peak power equates to 200 percent spindle load for three (3) minutes, 150 percent spindle load (75 percent of shown value) for 15 minutes, or 100 percent spindle load (50 percent of shown value) continuously.

3.2.4.2 Spindle Orientation System. The spindle shall contain encoder(s) allowing the spindle to be positioned to a specific, programmed angle within 0.1 degrees.

3.2.5 Chuck. The lathe or turning center shall have a chuck provided in the size noted in Table 1. The chuck shall be a 3-jaw chuck featuring serrated jaws and clamping force necessary to hold the workpiece during turning operations. Adapters and hardware necessary to mount the chuck must be included. Lathes and turning centers shall include a hydraulic operated chuck. Chucks shall conform to American Society of Mechanical Engineers (ASME) B5.8.

3.2.6 Machine ways. Machine ways shall be standard design of the manufacturer. A means shall be provided to prevent coolant and chip swarf from accumulating on machine ways and becoming lodged between sliding parts. Machine ways shall be machined/ground smooth to allow continuous, uninterrupted movement of carriages, guides, and slides for machining operations. Machine ways shall not corrode or degrade under normal operations and maintenance and/or storage for no less than fifteen (15) years from the date of procurement.

3.2.7 Carriage. Carriage(s) shall be mounted on the bed machine ways and shall move parallel to the rotational axis of the workpiece. Carriages shall support movement and operation of the tool turret assembly (see section 3.2.9). Carriages shall be a configuration allowing the movement of the cross-slide or tool turret assembly to be on a plane parallel to the spindle axis. Carriages shall be capable of programmable, hands-free movement.

3.2.8 Cross-slide and Tool Turret Assembly. The lathe or turning center shall have a tool turret assembly mounted on the carriage. The tool turret assembly shall allow for tool travel

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

perpendicular to the rotating axis of the workpiece and shall support the functionality of the applicable tool turret (see section 3.2.9). Cross-slide and tool turret shall be capable of programmable, hands-free movement.

3.2.9 Tool turret(s). A tool turret shall be provided with a minimum of twelve (12) stations for automated tool changing and indexing for unattended operations. The lathe or turning table shall be operable with the tool turret installed or removed. Tool turrets shall have the capability of programmable, hands-free changing between installed tools.

3.2.10 Axis drive mechanisms. Each motion control axis of the lathe or turning center shall be actuated by an independent axis drive. Each axis drive shall have a brushless servomotor coupled directly onto a balls crew anchored at both ends and a closed-loop feedback control system to position the driven component.

3.2.11 Tailstock. The lathe or turning center shall have a tailstock located on the bed opposite the spindle. The centerline of the tailstock shall be coincident with the centerline of the spindle. The tailstock shall be equipped with a moveable quill with a minimum 4” of travel for manual tailstocks and 6” of travel for programmable tailstocks and shall accommodate various material-holding centers and cutting tools. The tailstock shall have a locking device to hold it in position after adjustment.

3.2.12 Safety devices. An emergency stop switch/button shall be provided that when pressed will instantly stop all motion of the machine, servomotors, the tool changers, and coolant pump. The system shall allow the operator to define the maximum allowable tool load, in percent, and the resulting action when that load is exceeded including system alarm. Limit switches shall be provided at both ends of each axis of travel to prevent overtravel. Automatic machine-actuated safety warnings, trips, and/or stoppages shall activate an indicator light(s) on the operator control panel and produce a visual alarm. Torque-limiting capabilities shall be included on all axis drives. The lathe or turning center shall have a protective enclosure with locking doors that prevent access to the workpiece and tools when in locked operation. When in unlocked operation, the rapid motion shall be limited to 25 percent of normal rapid operations, spindle rotation shall be limited to 50 rpm, and tool change shall not be allowed. The enclosure shall be configured to afford easy operator access to the workpiece when doors are open and clear observation when the lathe or turning center is in use.

3.2.13 Control system. The lathe or turning center shall be capable of manual control from a local operator station, semiautomatic control from manual data input (MDI) devices, and automatic control from programs stored in the memory of the CNC system or external drives. The control system components shall be industrial grade, and enclosures shall be type 12 in accordance with National Electrical Manufacturers Association (NEMA) 250. The control system shall have the capability to perform a screen capture to save an image of the current control screen to the hard drive or external USB drive. The lathe or turning center shall be capable of operating in the following modes:

a. Manual operation mode.

b. Manual data input (MDI) mode.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

c. Programming mode.

d. Automatic mode.

e. Background editing mode.

f. Machine diagnostic/maintenance/monitoring modes.

g. Remote monitoring using an Android or iOS device.

h. Wireless file transfer using an Android or iOS device.

i. Display of media files (PDF, videos, images) from memory both independently and during program runs.

j. The ability to program machine functions using a graphic interface allowing the creation of G-code outputs without the need for G-code programming inputs.

3.2.13.1 Machine status indicators. The lathe or turning center shall include, as a minimum, the following machine status indicators:

a. Power on indicator.

b. Operational mode indicator.

c. Spindle power indicator.

d. Spindle speed indicator.

e. Axis movement direction indicators.

f. Axis movement speed indicators.

g. Accessory system (e.g., air, hydraulic, coolant, lubrication) status indicator(s).

h. Overload and/or trouble indicator(s).

i. Overload and/or trouble alarm.

3.2.13.2 Manual controls. The lathe or turning center manual controls shall include, as a minimum, the following functions:

a. Emergency stop.

b. Key-actuated system lock.

c. Power on/off.

d. Spindle start/stop.

e. Spindle speed override.

f. Spindle incremental angular indexing.

g. Carriage motion.

h. Cross-slide motion.

i. Tailstock motion.

j. Tool station indexing.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

k. Feed hold.

l. Feed rate override.

m. Jog motion and jog direction.

n. CNC system start/stop (cycle start/stop).

3.2.13.3 Foot, and Pendant Controls. The lathe or turning center shall have separate foot controls for chuck and tailstock operations. A remote jog control with LCD, touchscreen display shall be included. The remote shall allow for part setup, changeover, and inspection while maintaining control of the machine including precise jogging speed control, setting work and tool offsets, command tool changes, cycle start and feed hold programs, and operator override of the CNC system.

3.2.13.4 Computer numeric control. The lathe or turning center shall have a CNC system that is a completely integrated, functional unit. The CNC system shall operate as a continuous path system providing full contouring capability. The term "full contouring", as used herein, shall be defined as a closed-loop control system having simultaneous control of position, direction, and rate of movement of all controlled axes. The CNC system shall always be active when electric power is supplied to the lathe or turning center. The CNC system shall, as a minimum, automatically control the following functions:

a. Spindle speed.

b. Spindle incremental angular indexing, when a live-tooling spindle is provided.

c. Carriage motion.

d. Tool turret assembly motion.

e. Tool station indexing.

f. Tailstock motion.

g. All accessory systems (e.g., air, hydraulic, coolant, lubrication).

h. Other machine functions considered by the manufacturer as standard.

3.2.13.5 Hardware features. The CNC system shall include, as a minimum, the following hardware features:

a. Minimum of three (3) 32-bit microprocessor having a minimum operating speed of 1000 blocks per second.

b. Buffer storage capacity sufficient to allow continuous program execution without non-programmed stops, delays, or pauses.

c. A USB port capable of reading external, USB devices formatted in FAT 32.

d. A minimum 15 inch, full-color, LCD touchscreen allowing screen navigation, data entry, and full operational control.

e. Minimum 1 GB internal memory for program/operational storage.

f. Standard Ethernet port for network connectivity.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

g. WiFi connectivity.

3.2.13.6 Software features. The CNC system shall include, as a minimum, the following programming software and control features:

a. SAE RS-274D variable data block programming format (standard G-codes).

b. Decimal point programming.

c. Conversational mode programming.

d. Inch/metric programming.

e. Programmable zero-point reference.

f. Absolute and incremental motion control programming.

g. Simultaneous control of all motion axes.

h. Linear, circular, and helical motion interpolation.

i. Constant surface speed capability.

j. Manufacturer's standard suite of preprogrammed machine operational cycles.

k. Workpiece graphic display.

l. Tool path graphic display.

m. Tool length compensation.

n. Tool offsets.

o. Scale feedback compensation.

p. Drive backlash compensation.

q. Maintenance monitoring package.

r. Diagnostics assistance.

3.2.13.7 Data Package. The CNC system shall have an external data package with maintenance and technical support shall include, as a minimum, the following hardware and software:

a. Three (3) year multi-user subscription and/or license to most current version of MasterCAM software. Three (3) year subscription and/or license to most current version of SOLIDWORKS Professional design and modeling software.

b. Personal computer (PC) with Windows 10 operating system or higher. Multiple core 64-bit processor, 16GB RAM, 2GB OpenFL 2.0 complaint graphics card, 1920 x 1200 screen resolution, 16GB disk space.

c. All hardware and software shall be capable and compatible with machine controllers and post-processors.

3.2.14 Lubrication System. An automatic lubrication system shall be provided to direct lubricant from a central reservoir to all machine components requiring continuous lubrication. The automatic lubrication system shall include all components required to ensure full system operation on one fill of lubricant for one year of operation. A means shall be provided for

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

determining the oil level in the reservoir. Oil low pressure and low-level alarms shall be provided. Components requiring periodic manual lubrication shall be readily accessible through doors or removable panels. When a spindle gear-drive transmission is provided, a separate lubrication system for the gears shall be furnished.

3.2.15 Coolant system. An automatic cutting tool flood coolant system shall be provided. The coolant system shall direct a selectable, controlled flow rate of coolant to the cutting tool. The cooling system shall include a reservoir, piping, valves, pump, motor, and a cleanable or replaceable filter. A means shall be provided for determining the coolant level in the reservoir.

3.2.15.1 Coolant Oil Skimmer. For systems greater than 20 inches in size (reference Table I), a removable coolant tank oil skimmer that removes oil from the surface of the coolant in the coolant reservoir. Oil removed via the skimmer shall be stored in a removable, reusable storage container. The oil skimmer shall be powered via 120VAC power.

3.2.16 Hydraulic System. A hydraulic system shall be provided for applicable operations. The hydraulic system shall conform to the requirements of the National Fluid Power Association (NFPA) T2.24.1. The hydraulic system shall include a reservoir, piping, valves, pumps, motor, strainer, heat exchanger, and a cleanable or replaceable filter. A means shall be provided for determining the fluid level in the reservoir. Hydraulic oil high-pressure gauge shall be provided. An identification plate or chart shall be attached to the lathe or turning center stating the type and Society of Automotive Engineers (SAE) identification number of the hydraulic fluid used.

3.2.17 Compressed air system. A compressed air system connected either to shop air or to a dedicated air compressor and tank shall be provided. Connection ports to and from the compressed air system shall be 3/8 inch supplied at 80 psi. The compressed air system shall include piping, valves, fittings, dryers, cleanable or replaceable filter, and other appurtenances necessary for the operation of the pneumatic components. The compressed air system shall conform to the requirements of NFPA T2.25.1M.

3.2.18 Electrical system. The electrical system shall conform to the National Fire Protection Association (NFPA) 79. The system shall have multiple electrical connectivity options per Table III.

TABLE III: Power Requirements.

Size	Power Option 1	Power Option 2
16.0 in	220 VAC 40 A Three Phase	440 VAC 20 A Three Phase
22.5 in	220 VAC 40 A Three Phase	440 VAC 20 A Three Phase
32.5 in	220 VAC 70 A Three Phase	440 VAC 35 A Three Phase

3.2.19 Electric motors. The spindle drive motor and motion control motors shall be brushless, sealed, and permanently lubricated ball or roller bearings, shall be energy efficient, and shall conform to NEMA MG 1 and NEMA ICS 16, respectively. The spindle drive motor shall have an

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

open drip-proof enclosure. Motion and position control motors and controls shall conform to NEMA ICS 1 and NEMA ICS 3.

3.2.20 Tooling, Attachments, and Accessories. All tooling, attachments, accessories, and hardware required to render the machine usable shall be included. At a minimum, this includes:

3.2.20.1 Toolholders. A minimum of two (2) removable toolholders shall be provided. Toolholders shall be functional with the lathe or toolholder provided and able to be fully integrated with the CNC and software. The toolholder shall be capable of holding C-style inserts for external machining and facing via top and hole clamping, though not simultaneously. The toolholder shall be in a right-handed, external tool orientation and have a 95-degree angle. The toolholder shall conform to ISO 13399 standards.

3.2.20.2 Standard Boring Bar. A removable boring bar shall be provided that is functional with the lathe or toolholder provided and able to be fully integrated with the CNC and software. The boring shall be capable of holding C-style inserts for external machining and facing via top and hole clamping. The toolholder shall be in a right-handed, external tool orientation and have a 95-degree angle. The toolholder shall conform to ISO 13399 standards. The boring bar shall have a length of 8 inches and a minimum machining diameter of 1.2 inches.

3.2.20.3 Extended Boring Bar. For systems greater than 20 inches in size (reference Table I), an additional boring bar shall be provided that meets the same specifications as the other with the exception that the length shall be 12 inches and a minimum machining diameter of 2.0 inches.

3.2.20.4 Fine Finish Inserts. A minimum of ten (10) C-style inserts shall be provided with the appropriate grade for fine finishing of steel and cast iron. Inserts shall be compatible with the toolholder specified in 3.2.20.1 via top and hole clamping, though not simultaneously. Insert sizes shall be 0.5 inches with a maximum thickness of 0.19 inches.

3.2.20.5 Medium Finish Inserts. A minimum of ten (10) C-style inserts shall be provided with the appropriate grade for medium-light finishing of steel and cast iron. Inserts shall be compatible with the toolholder specified in 3.2.20.1 via top and hole clamping, though not simultaneously. Insert sizes shall be 0.5 inches with a maximum thickness of 0.19 inches.

3.3 Equipment Training. A complete overview of the machine controller, graphics display, and machine function and operation shall be provided at the installation location. Training shall be coordinated with the training point of contact (POC) at the installation location no later than seven (7) calendar days after setup/commissioning at the installation location. The training POC will be provided by the government at the time of order. Training shall follow installation of the equipment and last no more than three (3) days for a maximum of five (5) technicians. Training shall provide the necessary skills and knowledge to operate the machine safely, execute manual data-input functions, manually operate the machinery, load tooling into tool changer, conduct tooling offsets, and importing manufacturing files. Electronic versions of training materials shall be accessible to training participants for a minimum of three (3) years after completion of the training.

3.4 Warranty. A minimum one (1) year warranty shall be provided to protect against defects, breaks, or component failures during normal operations. The warranty shall include the

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

replacement and installation of components/assemblies at the installation location by an OEM-certified technician. The warranty does not cover consumable items such as tooling identified in 3.2.20.2 through 3.2.20.5. For equipment located in austere operating environments, an OEM-certified technician may oversee the repair by a government representative; however, replacement components will still be provided as part of the warranty.

3.5 Support. Technical support for the equipment and software shall be provided for a period of three (3) years after the date of purchase. Technical support shall be accessible, at a minimum, via phone and email.

3.6 Performance. When tested in accordance with sections 5.3, the lathe or turning center shall meet either the precision or standard performance category requirements shown in Table IV.

Table IV. Performance requirements.

Test	Parameter	Performance category	
		Precision	Standard
Linear displacement accuracy	All X, Y, and Z directions	0.0003 inch/10 inches	0.001 inch/10 inches
Bidirectional repeatability	All X, Y, and Z directions	□0.0002 inch	□0.0005 inch
Maximum parallelism error between spindle C-axis and each Z-axis		0.0003 inch	0.0005 inch
Spindle dynamic error	Radial error-average	0.0003 inch	0.0005 inch
Spindle thermal growth		0.0015 inch	0.0025 inch
Spindle C-axis indexing accuracy		□1.8 arc seconds	□3.6 arc seconds
Spindle C-axis indexing repeatability		□1.0 arc second	□1.8 arc seconds
Turret indexing accuracy		□3 arc seconds	□5 arc seconds
Turret indexing repeatability		□1.5 arc seconds	□2.5 arc seconds
Contouring performance-ball bar test	100□, 190□ and 360□	0.0005 inch	0.0015 inch

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

3.7 Safety and health requirements. The machine shall be designed and manufactured in accordance with ANSI B11.6. The manufacturer shall ensure that the machine and all equipment and accessories used on the machine comply with Occupational Safety and Health Administration (OSHA) 29 CFR PART 1910. If a conflict arises between the ANSI B11.6 and OSHA standards, the OSHA standards shall apply.

3.8 System of units. The U.S. Customary System of Units (US) or the International System of Units (SI) shall be used to graduate measuring and indicating devices. Measuring and indicating devices shall be graduated in both the US and SI system ofmeasurements.

3.9 Nameplate. A nameplate shall be securely attached to the machine and shall contain the following information:

a. Nomenclature.

b. Manufacturer's name.

c. Serial number.

d. Machine model designation.

e. Power input (volts, total amperes, phase, frequency).

f. Short-circuit/overcurrent rating.

g. Contract number or order number.

h. Applicable National stock number.

i. Date of manufacture.

3.10 Lubrication plate or chart. A lubrication plate or chart shall be attached to the machine. The information provided on the plate or chart shall include:

a. Points of lubricant application.

b. Servicing interval.

c. Type of lubricant(s) with SAE number or lubricant identifier.

4. REGULATORY REQUIREMENTS.

4.1 Recovered materials. The offeror/contractor is encouraged to use recovered materials to the maximum extent practicable, in accordance with paragraph 23.403 of the Federal Acquisition Regulation (FAR).

4.2 Environmental protection. The item shall meet all applicable Environmental Protection Agency (EPA) restrictions in effect on the date of the contract. These regulations apply to the emission of materials hazardous to the environment or the user's health and shall be adhered to during the manufacturing, service, transportation, storage, and operation/use of the item.

5. PRODUCT CONFORMANCE.

5.1 Product conformance. The products shall meet the salient characteristics of this commercial item description; conform to the manufacturer's own drawings, specifications, standards, and

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

quality assurance practices; and be the same product offered for sale in the commercial market. The Government reserves the right to require proof of such conformance.

5.2 Inspection. The lathe or turning center shall be inspected to determine compliance with all requirements specified in this CID.

5.3 Testing. The lathe or turning center shall be tested in accordance with sections 5.3.1 through 5.3.3. Should a malfunction or a failure occur during any test, the problem shall be corrected and the test shall be rerun from the beginning.

5.3.1 Test setup and conditions. The manufacturer shall be responsible for supplying all tooling and materials and shall conduct all tests required by the Government. The manufacturer shall provide test instruments and equipment with calibration traceable to the National Institute of Standards and Technology (NIST) and shall provide certification of calibration. The machine shall be tested in the environmental conditions considered by the manufacturer as standard for machine performance verification.

5.3.2 Operational test. The lathe or turning center shall be operated in accordance with the manufacturer's standard operating procedures. The lathe or turning center shall be operated for not less than 4 hours in which proper operation of all controls and features shall be verified.

5.3.3 Performance tests. The performance tests shall be conducted in accordance with procedures considered by the manufacturer as standard for machine performance verification.

5.4 Acceptance. Preliminary and final acceptance tests shall be conducted at the manufacturer's site. The results of the performance tests shall be compared with the performance requirements shown in table IV. Failure of the machine to meet the performance category requirements shown in table IV shall be cause for rejection.

6. PACKAGING. Preservation, packing, and marking shall be as specified in the contract or purchase order.

7. NOTES.

7.1 Part identification number (PIN). The following part identification numbering procedure is for Government purposes and does not constitute a requirement for the contractor.

A-A-60024A-XXX

- Size: Reference Table I
  - 160 = 16.0 inches
  - 225 = 22.5 inches
  - 325 = 32.5 inches
- CID number

7.2 Sources of referenced documents.

7.2.1 The American Society of Mechanical Engineers (ASME). Copies of ASME documents may be obtained at https://www.asme.org/.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

7.2.2 Federal Acquisition Regulation (FAR). Copies of FARS may be obtained at https://www.acquisition.gov/browse/index/far.

7.2.3 American National Standards Institute (ANSI). Copies of ANSI documents may be obtained at https://www.ansi.org.

7.2.4 Electronic Industries Association (EIA). Copies of SAE documents may be obtained at https://www.sae.org/.

7.2.5 Environmental Protection Agency (EPA). Copies of EPA documents may be obtained at https://www.epa.gov/.

7.2.6 National Electrical Manufacturers Association (NEMA). Copies of NEMA standards may be obtained at https://www.nema.org/standards.

7.2.7 National Fire Protection Association (NFPA). Copies of NFPA documents may be obtained at https://www.nfpa.org/.

7.2.8 National Fluid Power Association (NFPA). Copies of NFPA documents may be obtained at https://www.nfpa.com/.

7.2.9 International Organization for Standardization (ISO). Copies of ISO documents may be obtained at https://www.iso.org/home.html.

7.2.10 Occupational Safety and Health Administration (OSHA). Copies of OSHA documents may be obtained at https://www.osha.gov.

7.2.11 Society of Automotive Engineers (SAE) Copies of SAE documents may be obtained at https://www.sae.org/standards.

7.3 Applicable National Stock Numbers (NSNs). The following NSNs are established to meet the requirements of the associated PINs.

PIN	NSN
A-A-60024A-160	3416-10-698-9412
A-A-60024A-225	3416-01-698-8832
A-A-60024A-325	3416-01-698-9411

7.4 Ordering data. Acquisition documents must specify the following:

a. Title, number, and date of this document.

b. Size of lathe or turning center required (see 2)

c. Point of contact for training coordination at installation location (name, address, email, and telephone numbers).

7.5 Key Words:

Bed, Slant

CNC, Computer, Numerically, Controlled

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.

Lathe

Turning

MILITARY INTERESTS:

Custodians:

Air Force – 184

Reviewer

GSA – FAS

Preparing Activity:

Air Force – 184

Agent:

Air Force – 110

(Project 3416-2024-002)

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.dla.mil.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:32Z
Check the source to verify that this is the current version before use.