MIL-R-55054-A(SigC)
Amendment 3
5 April 1965
Superseding
Amendment 2
16 October 1961

MILITARY SPECIFICATION

RECEIVER, RADIO R-392( )/URR

(This amendment forms a part of Military Specification (MIL-R-55054A(SigC), dated 3 April 1961

1. Sheet 2, paragraph 2.1: Under "STANDARDS" "MILITARY", delete "MIL-STD-129" "Marking for Shipment and Storage."

2. Sheet 10, paragraph 3.10.7, Internal signals, Change "2.927" to read "2.727 mc".

3. Sheet 11, paragraph 3.10.10, Overall gain, Change from "----------and not less than 1 microvolt" to "------and not less than 0.5 microvolt."

4. Sheet 12, paragraph 3.10.15 Overall audio response, Change "-------to 3500 cps." Change to read"---------to 2500 cps."

5. Sheet 12, paragraph 3.10.21, Backlash - Change "Backlash between the kilocycle and the frequency indicating----------", Change to read "Backlash the up-frequency and the DOWN-frequency tuning shall not exceed 100 cps as read by the EPUT meter". Delete the sentence "Backlash between the kilocycle knob and the variable frequency oscillator shall not exceed 50 cps."

6. Sheet 13, paragraph 3.10.27, Densensitization - Delete entire paragraph.

7. Sheet 16, table II, Preproduction inspection: In column 2, change "3.9.3" to read "3.9.2".

8. Sheet 16, paragraph 4.5: Delete and replace with the following:

"4.5 Acceptance inspection of equipment before preparation for delivery. The contractor shall perform the inspection specified in 4.4 and 4.5.1 through 4.5.3.2. Each unit which will be subjected to group A, group B, or group C inspection shall be preconditioned after final assembly. (See 3.11) Test equipment, when required for Government verification inspection shall be made available by the contractor."

FSC 5820

Source: https://assist.dla.mil -- Downloaded: 202610-22T22:19Z
Check the source to verify that this is the current version before use.

9. Sheet 17, table III, Group A inspection: In column 2, change "3.10.6" to read "3.10.36".

10. Sheet 20, paragraph 4.6, Bounce preconditioning:- In line 2, change "Package Tester" to: Package Tester, Type 1000 SC.

11. Sheet 22, paragraph 4.8.7, - Internal signals, - Change "2.927" to read "2.727 mc."

12. Sheet 25, paragraph 4.8.16 Overall audio response, - Delete"------- to 3500 cps". Change to read"---------to 2500 cps".

13. Sheet 25, paragraph 4.8.17, - Hum level - Change "Adjust the AF gain control on the receiver for 200 milliwatts----------". Change to read "Adjust the AF gain control on the receiver for 1 watt----------".

14. Sheet 27, paragraph 4.8.22, Backlash -Change this paragraph to read "set the kilocycle dial to 500 KC on any convenient megacycle band. Set the AGC to CAL and BFO to ON. Adjust BFO to 1000 cps. audio output. Move the kilocycle control below 500 KC and then return up-frequency to 500 KC. Measure audio output frequency with an eput meter. Move kilocycle knob above 500 KC and then return down-frequency to 500 KC. Measure audio output frequency with eput meter.

15. Sheet 28, paragraph 4.8.28, Desensitization - Delete entire paragraph.

16. Sheet 29, paragraph 4.8.32, Blocking -Change "Audio output shall be ----------". Change to read "Diode load voltage shall be----------".

17. Sheet 29, paragraph 4.8.31, Carrier level meter - Change 500,000 microvolts to read 200,000 microvolts.

18. Sheet 30, paragraph 4.10.1, - Test conditions: Delete subparagraph (c) and replace with:

(c) Test the equipment with the chassis removed from the enclosure."

19. Sheet 31, paragraph 4.10.2 Test Method:- In line 1 of subparagraph (d), change "fifteen" to: five.

20. Sheet 35, paragraph 4.18, - Air seal test - Change sentence"-------- the ensuing period of 1 minute. During this 1 minute period the vacuum shall not exceed .01 pound. The gage used-------- a difference of .01 pound can be determined readily.:

Source: https://assist.dla.mil -- Downloaded: 202610-22T22:19Z
Check the source to verify that this is the current version before use.

Change to read: "------the ensuing period of 2 minutes. During this 2 minute period the vacuum shall not exceed .005 point. The gage used ----------a difference of .005 pound can be determined readily."

21. Sheet 36, paragraph 4.22,- Operational inspection:- In line 1, change "3.10.10" to read "3.10.36".

22. Sheets 38 and 39, paragraph 6.7, - Verification inspection:- Delete this paragraph.

CUSTODIAN:
ARMY-EL

PREPARING ACTIVITY
ARMY-EL

Project No. 5820-A288

FSC 5820

Source: https://assist.dla.mil -- Downloaded: 202610-22T22:19Z
Check the source to verify that this is the current version before use.