MIL-W-50931 (MU)
AMENDMENT 1
23 January 1973

MILITARY SPECIFICATION

WARHEAD SECTION, GUIDED MISSILE,

PRACTICE: XM-198

This Amendment forms a part of Military Specification MIL-W-50931(MU), dated 29 April 1971.

A. Paragraph 3.3 - Delete "Single and".

B. Paragraph 4.2.1g - Delete in its entirety and substitute: "g. Two (2) - Ring, Fuze (9267729)."

C. Paragraph 4.2.1q and s - Delete in their entirety.

D. Paragraph 4.3.2.5 - Delete in its entirety.

E. Paragraph 4.3.2.6 - Delete in its entirety.

F. Paragraph 4.3.2.9 - Change "(See Dwg. 9212740)" to "(See Dwg. 9267739)".

G. Paragraph 4.3.2.10 - Change "(See Dwg. 9208257)" to "(See Dwg. 9267729)".

H. Paragraph 4.3.2.25 - Delete in its entirety.

I. Paragraph 4.3.2.27 - Delete in its entirety.

J. Paragraph 4.3.2.29 - Delete in its entirety and substitute: "4.3.2.29 Cord, detonating (See Dwg. 9208251).-

Categories	Defects	Method of Inspection	Code No.
Critical:			
1.	Open ends of detonating cord not sealed	Visual	29002
Major:	AQL 0.40 Percent		
101.	Total length	Gage	29005
102.	Evidence of poor workmanship (See 3.8)	Visual	29007
Minor:	None defined"		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.

K. Paragraph 4.3.2.32, Critical 1 - Delete in its entirety.

L. Paragraph 4.3.2.32, Critical 2 - Delete in its entirety and substitute: "2. Detonating cord(s) or lead cup(s) damaged to the extent explosive is exposed Visual 32002".

M. Paragraph 4.3.2.32, Major 101 - Delete in its entirety and substitute: "101. Maximum gap between double lead cup assembly and .250 diameter pin (2 places) Gage 32009".

N. Paragraph 4.3.2.32, Major 116 - Delete in its entirety.

O. Paragraph 4.3.2.32 - Under "Minor" delete "AQL 4.00 Percent" and substitute "AQL 2.50 Percent".

P. Paragraph 4.3.2.32, Minor 207 - Delete in its entirety.

Q. Paragraph 4.3.3.3 - Delete the following:
Detonator Assembly (9208409) 41001
*Single Lead Cup Assembly (9208251) 41003

R. Paragraph 4.3.3.4 - Delete the following:
Single Lead Cup Assembly (9208251) 42001

Project No. 1340-A394

Custodian:
Army-MU

Preparing Activity:
Army-MU

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.