MILITARY SPECIFICATION

BISTABLE MULTIVIBRATOR ASSEMBLY

LD 546989

(For Guidance Control Test Set Mk 443 Mod 0 and Mod 1)

This amendment forms a part of Military Specification MIL-B-82564(OS) of 12 September 1968 and has been approved by the Naval Ordnance Systems Command, Department of the Navy.

Wherever it appears in specification delete "Bureau of Naval Weapons" and substitute "Naval Ordnance Systems Command"; also delete "BuWeps" and substitute "NAVORD".

Page 1, paragraph 2.1, under SPECIFICATIONS, Military: Delete "MIL-S-901" and associated title.

Page 2, paragraph 2.1, under STANDARDS, Military. Add:

"MIL-STD-202 Test Methods for Electronic and Electrical Component Parts"

* Page 2, paragraph 2.1, under DRAWINGS: Delete "DL 2452605" and substitute "LD 547003".

Page 4, paragraph 3.3.4, line 2: Delete "mc test circuit" and substitute "rc test circuit".

Page 4, paragraph 3.4.2. Delete and substitute:
"3.4.2 Shock (see 6.3.2). The assembly shall be capable of withstanding shock as specified in MIL-STD-202, Method 213A, test condition J."

Page 5, paragraph 4.1. Delete and substitute:
"4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or

FSC 1355

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:14Z
Check the source to verify that this is the current version before use.

any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements."

Page 7, paragraph 4.5.2.2. Delete and substitute:
"4.5.2.2 Shock. Subject the assembly to shock tests as specified in MIL-STD-202, Method 213A, test condition J."

Page 10, Table III. Change bottom section of table as follows:

From:

Circuit Symbol	Part	Designation	Quantity
J1	Connector	Amphenol 57-20140	1
R1, R2, R3	Resistor, 1000 ohm, 1/2w	RC20GF102J	3
R4, R5	Resistor, 100 k, 1/2w	RC20GF104J	2

To:

Circuit Symbol	Part	Designation	Quantity
J1	Connector	Amphenol 57-20140	1
R1	Resistor, 1000 ohm, 1/2w	RC20GF102J	1
R2, R3, R4, R5	Resistor, 100 k, 1/2w	RC20GF104J	4

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:14Z
Check the source to verify that this is the current version before use.

Page 10, Table III. Change bottom section of table (last two lines) as follows:

From:

S1, S3	Switch, SPDT	MS35058-23	2
S2	Switch, SPDT, Center OFF	MS35058-21	1

To:

S2, S3	Switch, SPDT	MS35058-23	2
S1	Switch, SPDT Center OFF	MS35058-21	1

Page 11, Figure 2: Change value of Resistors R2 and R3 from "1 K" to "100 K".

Page 12, paragraph 4.7.3. Add note under paragraph as follows:
"NOTE: All time measurements are to be performed with digital voltmeter disconnected from TP1."

Page 12, paragraph 4.7.3.1.1: Under "Limits (vdc)" column delete "+9.5 ± 0.5" and substitute "+9.6 ± 0.5".

Page 13, paragraph 4.7.3.2.3 (b) (1): Delete "with a time of 5μ sec" and substitute "with a fall time 5μ sec".

Page 14, Table IV: Delete "

TP1, TP4	14

" and substitute "

TP1 (+), TP4 (+)	14 (-)

".

Page 16, paragraph 6.2 (f): Delete "additonal " and substitute "additional".

APPENDIX page (2), paragraph 10.3.2.1, under "Positive stop" test: Delete "Voltage rise time" and substitute "Voltage fall time".

APPENDIX page (3), paragraph 10.3.2.1, under "Negative stop" test: Delete "Voltage rise time" and substitute "Voltage fall time".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:14Z
Check the source to verify that this is the current version before use.

APPENDIX page (3), paragraph 10.3.2.3:

delete "TP1, TP4 to P1-14 — 9,000 to 11,000 ohms"

substitute: "TP1 (+) to P1-14 (-) — 9K to 11K ohms
TP4 (+) to P1-14 (-) — 9K to 11K ohms"

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccurracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodian:
Navy - OS

Preparing Activity:
Navy - OS
Project No. 1355-N303

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:14Z
Check the source to verify that this is the current version before use.