MILITARY SPECIFICATION

FIRE CONTROL ASSEMBLY

LD 546992

(For Guidance Control Test Set Mk 443 Mod 0 and Mod 1)

This amendment forms a part of Military Specification MIL-F-82566(OS) of 12 September 1968 and has been approved by the Naval Ordnance Systems Command, Department of the Navy.

Wherever it appears in specification delete "Bureau of Naval Weapons" and substitute "Naval Ordnance Systems Command"; also delete "BuWeps" and substitute "NAVORD".

Page 1, paragraph 2.1, under "SPECIFICATIONS, Military": Delete "MIL-S-901" and associated title.

Page 2, paragraph 2.1, under "STANDARDS, Military". Add:

"MIL-STD-202 Test Methods for Electronic and Electrical Components Parts"

* Page 2, paragraph 2.1, under "DRAWINGS": Delete "DL 2452605" and substitute "LD 547003".

Page 3, paragraph 3.3.2.3, lines 4 and 5: Delete "less than 2.5 vdc" and substitute "less than 3.5 vdc".

Page 3, paragraph 3.3.2.4: Delete "voltage of 0.5 to 2.5 vdc" and substitute "voltage of 0.5 to 3.5 vdc".

Page 3, paragraph 3.3.3, output voltage readings for P1-16: Delete "+16.40 to +17.23" and substitute "+16.37 to +17.23".

Page 4, paragraph 3.4.1. After paragraph, add note as follows:

"NOTE: The quality assurance tests of 4.7.3.2.2 and 4.7.3.2.4 shall not be performed during vibration."

FSC 1355

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:14Z
Check the source to verify that this is the current version before use.

Page 4, paragraph 3.4.2. Delete and substitute:
"3.4.2 Shock (see 6.3.2). The assembly shall be capable of withstanding shock as specified in MIL-STD-202, Method 213A, test condition J."

Page 5, paragraph 4.1. Delete and substitute:
"4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements."

Page 7, paragraph 4.5.2.2. Delete and substitute:
"4.5.2.2 Shock. Subject the assembly to shock tests as specified in MIL-STD-202, Method 213A, test condition J."

Page 12, paragraph 4.7.3.2.2 (b). After paragraph, add note as follows:

"NOTE: If lamp DS2 extinguishes when S1 is switched to position 1, slowly increase the output voltage of power supply No. 2 (not to exceed 2.5 vdc) until DS2 illuminates."

Pages 12 and 13, paragraph 4.7.3.2.4 (a) and (b): Delete "between 0.5 and 3.2 vdc" and substitute "between 0.5 and 3.5 vdc".

Page 13, paragraph 4.7.3.2.4 (b). After paragraph, add note as follows:

"NOTE: If lamp DS1 extinguishes when S1 is switched to position 2, slowly increase the output voltage of power supply No. 2 (not to exceed 3.5 vdc) until DS1 illuminates."

APPENDIX page (2), paragraph 10.3.2.1, "Reference" paragraph 4.7.3.2.2 (b): Delete "(b) Remains illuminated" and substitute "(b) Illuminated".

APPENDIX page (3) paragraph 10.3.2.1, "Reference" paragraph 4.7.3.2.4 (a) and (b): Delete "0.5 to 3.2 vdc" and substitute "0.5 to 3.5 vdc" in two places.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:14Z
Check the source to verify that this is the current version before use.

APPENDIX page (3), paragraph 10.3.2.1, "Reference" paragraph 4.7.3.2.4(b): Delete "(b) Remains illuminated" and substitute "(b) Illuminated".

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodian:
Navy - OS

Preparing Activity:
Navy - OS
Project No. 1355-N300

☆ U. S. GOVERNMENT PRINTING OFFICE: 1972 - 714-539/2377

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:14Z
Check the source to verify that this is the current version before use.