MILITARY SPECIFICATION

LIGHT CIRCUIT ASSEMBLY

LD 546991

(For Guidance Control Test Set Mk 443 Mod 0 and Mod 1)

This amendment forms a part of Military Specification MIL-L-82565(OS) of 12 September 1968 and has been approved by the Naval Ordnance Systems Command, Department of the Navy.

Wherever it appears in specification delete "Bureau of Naval Weapons" and substitute "Naval Ordnance Systems Command"; also delete "BuWeps" and substitute "NAVORD".

Page 1, paragraph 2.1, under "SPECIFICATION, Military": Delete "MIL-S-901" and associated title.

Page 2, paragraph 2.1, under "STANDARDS, Military". Add:

"MIL-STD-202 Test Methods for Electronic and Electrical Component Parts"

Page 2, paragraph 2.1, under "DRAWINGS": Delete "LD 2540800" and substitute "DL 2540800".

Page 2, paragraph 2.1, under "DRAWINGS": Delete "DL 2452605" and substitute "LD 547003".

Page 5, paragraph 3.4.2. Delete and substitute:
"3.4.2 Shock (see 6.3.2). The assembly shall be capable of withstanding shock as specified in MIL-STD-202, Method 213A, test condition J."

Page 5, paragraph 4.1. Delete and substitute:
"4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified

FSC 1355

Source: https://assist.dla.mil - Downloaded: 2026-10-23T07:14Z
Check the source to verify that this is the current version before use.

herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements."

Page 8, paragraph 4.5.2.2. Delete and substitute:
"4.7.2.2 Shock. Subject the assembly to shock tests as specified in: MIL-STD-202, Method 213A, test condition J."

Page 11, Table II, under "Designation" column: Delete "MS35038-26" and substitute "MS 35058-22".

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodian:
Navy - OS

Preparing Activity:
Navy - OS
Project No. 1355-N302



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:14Z
Check the source to verify that this is the current version before use.