MIL-C-46952 (MU)
AMENDMENT 3
30 October 1963
SUPERSEDING
AMENDMENT 2
16 September 1963

MILITARY SPECIFICATION

CHARGE, PROPELLING, 155MM, XM115 (WHITE BAG) LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-C-46952(MU), dated 26 February 1963.

Page 1, paragraph 1.1: Delete and substitute:

"This specification covers the loading, assembling and packing for one type of propelling charge designated as Charge, Propelling, XM115 (White Bag) for Howitzer, SP, M109 for use with Projectile, HE, M470".

Page 1, paragraph 1.2, Standards, Military: Add "MIL-STD-1235 - Single and Multilevel Continuous Sampling Procedures and Tables for Inspection by Attributes."

Page 1, paragraph 2.1, Drawings, Ordnance Corps: Delete reference to Drawing 119154 and substitute "8865264 - Increment 1-4 Load Assembly."

Page 2, paragraph 2.1, Drawings, Ordnance Corps: Delete reference to Drawing 119249 and substitute "8865262 - Charge, Propelling, 155MM: XM115 (White Bag) For Projectile, HE, M470 For Howitzer, SP, M109."

*Page 2, paragraph 2.1, Drawings, Ordnance Corps; Delete reference to Drawing 8800640 and substitute "76-5-85 - Container, Metal, Propelling Charge Assembly."

Page 2, paragraph 2.1, Drawings, Ordnance Corps: Delete reference to Drawing 8800641 and substitute "7548187 - Packing and Marking of Metal Containers for Propelling Charges, Assembly and Detail."

FSC: 1320

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T07:24Z
Check the source to verify that this is the current version before use.

Page 2, paragraph 2.1, Publications, Ordnance Corps: Delete "ORD-M608-11- Procedures ... Attributes."

Page 2, paragraph 3.2, line 2: Delete "119154 and 119249" and substitute "8865262 and 8865264."

Page 4, paragraph 4.2.2., line 4: Delete "Handbook ORD-M608" and substitute "Standard MIL-STD-1235."

*Page 5, paragraph 4.2.2.2, line 1: Delete "119154" and substitute "8865264".

Page 6, paragraph 4.2.2.3, line 2: Delete "119155 and 119249" and substitute "8865263 and 8865262".

Page 6, paragraph 4.2.2.4, line 1: Delete "119249" and substitute "8865262".

Page 6, paragraph 4.2.2.5, line 1: Delete "119249" and substitute "8865262".

*Page 6, paragraph 4.2.2.6: Delete and substitute:

"4.2.2.6 Container prior to sealing (see dwg. 76-5-85 and 7548187)

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major: None defined			
Minor:	AQL 1.50 percent		
201.	Any packing component missing	Visual	06001
202.	Cover cannot be removed by hand	Manual	06002
203.	Charge cannot be removed by hand	Visual	06003"

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T07:24Z
Check the source to verify that this is the current version before use.

*Page 6, paragrph 4.2.2.7: Delete and substitute:

"4.2.2.7 Container sealed (see dwg. 76-5-85 and 7548187).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major: None defined			
Minor:	AQL 1.00 percent		
201.	Cover incompletely engaged.....	Manual	07001
202.	Marking misleading or unidentifiable.....	Visual	07002"

Page 8, paragraph 4.2.3.2, line 3: Delete "119176" and substitute "8865270, a detail of dwg. 8865264".

*Page 8, paragraph 5.1: Delete in its entirety.

*Page 8, paragraph 5.1.1: Delete in its entirety.

*Page 9, paragraph 5.2.1: Delete and substitute:
"5.2.1 Level A.-The propelling charges shall be packed in containers complying with dwg. 75-5-85 and marked in accordance with dwg. 7548187".

*Asterisk indicates changes in addition to, or differing from, Amendment 2.

Custodian:
Army-MU

Preparing activity:
Army-MU

Project Number 1320-A058

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T07:24Z
Check the source to verify that this is the current version before use.