MIL-B-63094B(AR)
24 July 1978
SUPERSEDING
MIL-B-63094A(AR)
30 November 1977

MILITARY SPECIFICATION

BLASTING MACHINE, 50 CAP, M34

This specification is approved for use by the U.S. Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification contains requirements not normally covered by the drawings and provides quality assurance provisions for the fabrication inspection, test and packing for a generator blasting machine designated as the Blasting Machine, M34.

2. APPLICABLE DOCUMENTS

2.1 Issues of documents. - The following documents of the issue in effect on date of invitation for bids or request for proposals, form a part of this specification to the extent specified herein.

SPECIFICATIONS

FEDERAL

PPP-T-45 - Tape, Gummed, Paper, Reinforced and Plain, for Sealing and Securing
PPP-B-621 - Boxes, Wood, Nailed and Lock-corner
PPP-B-636 - Box, Fiberboard

MILITARY

MIL-P-116 - Preservation, Methods of
MIL-B-117 - Bag, Sleeve and Tubing - Interior Packaging
MIL-S-4473 - Shielding Magnetron Tubes and Magnets for Air Shipment

FSC: 1375

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

MIL-B-46506 - Box, Ammunition Packing Wood, Wirebound
MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification for
MIL-F-50449 - Filler Sheet For (For use in Ammunition Containers)

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes (ABC-STD-105)
MIL-STD-129 - Marking for Shipment and Storage
MIL-STD-331 - Fuze and Fuze Components, Environmental and Performance Tests for
MIL-STD-1169 - Packaging, Packing and Marking for Shipment of Inert Ammunitions Components

DRAWINGS

U.S. ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

9312773 - M34 Blasting Machine

(Copies of specifications, standards and drawings required by contractors in connection with specific procurement functions should be obtained from the procuring activity or as directed by the Contracting Officer).

3. REQUIREMENTS

3.1 Materials. - Materials shall be in accordance with the applicable drawings and specifications.

3.2 Components and assemblies. - The components and assembly shall comply with all requirements specified in drawing (Dwg) 9312773, all associated drawings and with all requirements specified in applicable specifications and standards.

3.3 Output capacity. - The blasting machine shall produce a minimum output of one and five tenths (1.5) amperes for a period not less than one and five tenths (1.5) milliseconds when tested as specified in 4.5.1.

3.4 Drop test. - The blasting machine shall comply with the requirements of 3.3 when tested as specified in 4.5.2.

3.5 Waterproofness. - The blasting machine shall comply with requirements of 3.3 and shall show no evidence of leakage when tested as specified in 4.5.3.

3.6 Transportation vibration. - The blasting machine shall comply with the requirements of 3.3 when tested in accordance with 4.5.4.

3.7 Service life cycle. - The blasting machine shall comply with the requirements of 3.3 for a minimum five thousand (5000) firing functions when tested in accordance with 4.5.5 and without any component replacement or repair.

3.8 Extreme temperature performance. - The blasting machine shall comply with the requirements of 3.3 when tested at minus forty five degrees Centigrade minus five degrees Centigrade to plus fifty two degrees Centigrade plus five degrees Centigrade ($-45^{\circ}C$ $-5^{\circ}C$ to $52^{\circ}C$ $+5^{\circ}C$) and in accordance with 4.5.6.

3.9 Temperature storage. - The blasting machine shall be capable of functioning and complying with the requirements of 3.3 after seventy two (72) hours of storage and testing as specified in 4.5.7.

3.10 Insulation resistance. - The blasting machine shall comply with the requirements of 3.3 after having five hundred volts alternating current (500 VAC) applied between case and each output terminal. The voltage shall be applied for a minimum of ten (10) seconds and there shall be no evidence of current leakage in excess of ten (10) microamperes.

3.11 Humidity. - The blasting machine shall operate within the requirements of 3.3 after exposure to twenty (20) hours of relative humidity between ninety two (92) and ninety seven (97) percent at air temperatures from twenty seven degrees Centigrade plus five degrees Centigrade (27°C + 5°C), followed by four (4) hours plus one (1) hour of one hundred (100) percent relative humidity with condensation at twenty five degrees Centigrade plus five degrees Centigrade (25°C + 5°C).

3.12 Unactivated voltage. - The output voltage across the output terminals shall be one tenth (0.1) volt or less within ten (10) seconds after the device has complied with the requirements of 3.3 and it is tested in accordance with 4.5.10.

3.13 Test temperature. - All testing shall be performed at a temperature of twenty five degrees centigrade plus or minus five degrees centigrade (25°C ± 5°C) unless specified otherwise.

3.14 Data requirements. - Data as required by test method paragraphs 4.5 shall be retained as specified in 4.5.16.

3.15 Workmanship. - All parts and assemblies shall be fabricated and finished in a thorough workmanlike manner and all manufacturing, processing, and assembly operations shall be correctly performed. They shall be free of burrs, chips, sharp edges, cracks, unblended radii, porosity, warpage, burn marks, checks, chipped edges, blisters, excess flash, dirt, grease, rust, salt deposits, visible raised cement seams, solder splash, corrosion products, and other defects and foreign matter which would affect their serviceability. The cleaning method used shall not be injurious to any part or assembly nor shall the parts be contaminated by the cleaning agent. All required markings shall be neat, legible and sharply defined. All required packing shall be dry.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. - Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this specification.

4.2 Classification of inspections. - The following types of inspection shall be conducted on this item:

a. First article inspection.
b. Quality conformance inspections.

4.3 First article inspection

4.3.1 Submission. - The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of twenty five (25) sets of all components, sub-assemblies and assemblies.

4.3.2 Inspections to be performed. - See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. - See MIL-A-48078.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
	Blasting Machine, 50 Cap, M34	1 OF 9	See Below
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Plate, Bearing (Dwg. 9235514) Examination for defects	25		3.2	4.4.2.1
	Mechanical Housing Assembly (Dwg. 9235532) Examination for defects	25		3.2	4.4.2.2
	End Bell, Drive (Dwg. 9235517) Examination for defects	25		3.2	4.4.2.3
	Sleeve, Rotor (Dwg. 9232516) Examination for defects	25		3.2	4.4.2.4
	End, Bell (Dwg. 9235520) Examination for defects	25		3.2	4.4.2.5
	Gear, Pinion Rotor (Dwg. 9235518) Examination for defects	25		3.2	4.4.2.6

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

TABLE I - FIRST ARTICLE INSPECTION

MIL-B-63094B(AR)

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 9		DRAWING NUMBER
	Blasting Machine, 50 Cap, M34				See below NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Stator Assembly (Dwg. 9235519) Examination for defects	25		3.2	4.4.2.7
	Shaft, Shouldered (Dwg. 9235542) Examination for defects	25		3.2	4.4.2.8
	Standoff (Dwg. 9235528) Examination for defects	25		3.2	4.4.2.9
	Gear, Pinion (Dwg. 9235530) Examination for defects	25		3.2	4.4.2.10
	Gear, Spur (Dwg. 9235531) Examination for defects	25		3.2	4.4.2.11
	Gear Rack Assembly (Dwg. 9235535) Examination for defects	25		3.2	4.4.2.12

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

TABLE 1 - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 3 OF 9		DRAWING NUMBER
	Blasting Machine, 50 Cap, M34				See below NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Spring, Helical Compression (Dwg. 9235539)				
	Examination for defects	25		3.2	4.4.2.13
	Deflection Test	25		3.2	4.5.15
	Housing, Mechanical Drive (Dwg. 9235533)				
	Examination for defects	25		3.2	4.4.2.14
	Gear, Pinion (Dwg. 9235537)				
	Examination for defects	25		3.2	4.4.2.15
	Gear Assembly (Dwg. 9235534)				
	Examination for defects	25		3.2	4.4.2.16
	Gear Sub-Assembly (Dwg. 9235529)				
	Examination for defects	25		3.2	4.4.2.17
	Blaster Assembly (Dwg. 9235504)				
	Examination for defects	25		3.2	4.4.2.18

NOTES:

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 4 OF 9		DRAWING NUMBER
	Blasting Machine, 50 Cap, M34				See below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Barrel, Clutch (Dwg. 9235547)				
	Examination for defects	25		3.2	4.4.2.19
	Gear, Spur (Dwg. 9235546)				
	Examination for defects	25		3.2	4.4.2.20
	Spring, Leaf (Dwg. 9328277)				
	Examination for defects	25		3.2	4.4.2.21
	Deflection Test	25			4.5.15
	Capacitor, Fixed, Electrolytic (Dwg. 9328271)				
	Capacitance	25		3.2	4.5.11.1
	Leakage Current	25		3.2	4.5.11.2
	Capacitance, Fixed Electrolytic (Dwg. 9328281)				
	Capacitance	25		3.2	4.5.11.1
	Leakage Current	25		3.2	4.5.11.2

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 5 OF 9		DRAWING NUMBER
	Blasting Machine, 50 Cap, M34				See below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Resistor (Dwg. 9328275)				
	Resistance (Each value)	25		3.2	4.5.12
	Lamp, Trigger (Dwg. 9328280				
	Examination for defects	25		3.2	4.4.2.25
	Aging	25(a)(b)		3.2	45.13.1
	Breakdown Voltage	25(a)		3.2	4.5.13.2
	Service Cycle	25(b)		3.2	4.5.13.3

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

TABLE I - FIRST ARTICLE INSPECTION

MIL-B-63094B(AR)

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 6 OF 9		DRAWING NUMBER
	Blasting Machine, 50 Cap, M34				See below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Magnet, Permanent (Dwg. 9235515)				
	Examination for defects	25		3.2	4.4.2.26
	Flux Density	25		3.2	4.5.14
	Printed wiring Board Assembly (Dwg. 9328275)				
	Examination for defects	25		3.2	4.4.2.27
	Internal Assembly (Dwg. 9328276)				
	Examination for defects	25		3.2	4.4.2.28
	Resistor R3-R6 Resistance	25		3.2	
	Blasting Machine, 50 Cap, M34 (Dwg. 9312773)				
	Examination for defects	25		3.2	4.4.2.29
	TESTS				
	Output capacity	25(c)		3.3	4.5.1
	Insulation resistance	25(c)		3.10	4.5.8
	Extreme temperature performance	10(d)		3.8	4.5.6
	Temperature storage	10(d)		3.9	4.5.7
	Drop test	10(e)		3.4	4.5.2
	Transportation vibration	20(f)		3.6	4.5.4
	Waterproofness	5 (f)		3.5	4.5.3.1
	Service life cycle	5(g)		3.7	4.5.5

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 7 OF 9		DRAWING NUMBER
	Blasting Machine, 50 Cap, M34				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Humidity	10		3.11	4.5.9
	Unactivated Voltage	25(h)		3.12	4.5.10
	Housing, Electrical (Dwg. 9235541) Examination for defects	5(i)		3.2	4.4.2.30
	Housing, Mechanical Drive (Dwg. 9235533) Examination for defects	5(i)		3.2	4.4.2.31
	Case, Molded (Dwg. 9328278) Examination for defects	5(i)		3.2	4.4.2.32
	Lever (Dwg. 9235508) Examination for defects	5(i)		3.2	4.4.2.33
	Box, Fiberboard Prior to Closing Examination for defects	5		5.1.1	4.4.2.34
	Box, Fiberboard Examination for defects	5		5.1.1	4.4.2.35

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 8 OF 9		DRAWING NUMBER
	Blasting Machine, 50 Cap, M34				See below NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Sealed Packed Barrier Bag, Prior to Packing In Box Examination	5		5.1.1	4.4.2.36
	Box, Wood, Prior to Closing Examination for defects	5		5.1.1	4.4.2.37
	Box, Wood Examination for defects	5		5.1.1	4.4.2.38
	Notes a. Aging cycle must be completed on test samples prior to performing service cycle test. b. Aging cycle must be completed on test samples prior to performing breakdown voltage test. c. Output capacity and insulation resistance test shall be performed on all samples prior to any other test sequence. d. Five (5) samples shall be tested for the high temperature requirement and five (5) samples shall be tested for the low temperature requirement. e. Ten (10) samples shall be tested for the drop test requirements. f. The samples from the extreme temperature performance and temperature storage tests shall be used for the transportation vibration and waterproofness tests and in the sequence shown. g. The remaining five (5) samples shall be used for the service life cycle test group.				

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

TABLE I - FIRST ARTICIE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
	Blasting Machine, 50 Cap, M34		9 OF 9	See below
				NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	H. The unactivated voltage test shall be performed at the end of each test above, in notes c through g. I. The five (5) samples are required on a per mold basis.				

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. - Inspection lots shall comply with the lot formation provisions of MIL-A-48078.

4.4.2 Examination. - See MIL-A-48078.

a. Sampling plans. - Unless otherwise specified in the classification of defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105.

QUALITY CONFORMANCE INSPECTION

MIL-B-63094B(AR)

CLASSIFICATION OF DEFECTS & TESTS

		SHEET 1 OF 1		DRAWING NUMBER 9235514
				NEXT HIGHER ASSEMBLY 9235509
T DST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
si le diameter with		0.40%	3.2	Gage
		0.40%	3.2	Gage
		0.40%	3.2	Gage
		0.65%	3.2	Visual
		0.65%	3.2	Gage
ir		1.00%	3.15	Visual

QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235532
4.4.2.2	Mechanical Housing Assembly				NEXT HIGHER ASSEMBLY 9235509
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Component missing		0.40%	3.2	Visual
102	Lubrication missing		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235517
4.4.2.3	End Bell, Drive				NEXT HIGHER ASSEMBLY 9235513
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of rotor sleeve diameter with small inside diameter		0.40%	3.2	Gage
102	True position of bearing cavity diameter with small inside diameter		0.40%	3.2	Gage
103	True position of small outside diameter with small inside diameter		0.40%	3.2	Gage
104	Rotor sleeve diameter		0.40%	3.2	Gage
105	Diameter of bearing cavity		0.40%	3.2	Gage
106	Small inside diameter		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.4	Sleeve, Rotor		9235516
			NEXT HIGHER ASSEMBLY 9235513

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of inside diameter with outside diameter		0.40%	3.2	Gage
102	Inside diameter		0.40%	3.2	Gage
Minor					
201	Outside diameter		0.65%	3.2	Gage
202	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER 9235520
4.4.2.5	End Bell		NEXT HIGHER ASSEMBLY 9235513

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of outside diameter with bearing diameter		0.40%	3.2	Gage
102	True position of large inside diameter with bearing diameter		0.40%	3.2	Gage
103	Large inside diameter		0.40%	3.2	Gage
104	Bearing diameter		0.40%	3.2	Gage
Minor					
201	Length		0.65%	3.2	Gage
202	Thickness of bottom		0.65%	3.2	Gage
203	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.6	Gear, Pinion Rotor				9235518
					NEXT HIGHER ASSEMBLY 9235513
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter		0.40%	3.2	Gage
102	Face width of pinion, max.		0.40%	3.2	Gage
103	Total length		0.40%	3.2	Gage
104	Total composite error of gear		0.40%	3.2	Gage
105	Tooth to tooth composite error		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.7	Stator Assembly				9235519
					NEXT HIGHER ASSEMBLY 9235513
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of outside diameter of stator assembly to shoulder of shaft		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.8	Shaft, Shouldered				9235542
					NEXT HIGHER ASSEMBLY
					9235519
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of small outside diameter with intermediate outside diameter		0.40%	3.2	Gage
102	Intermediate outside diameter		0.40%	3.2	Gage
103	Inside diameter		0.40%	3.2	Gage
104	Small outside diameter		0.40%	3.2	Gage
105	Outside diameter of spline		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Standoff				9235528
					NEXT HIGHER ASSEMBLY 9235523
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Width across flats		0.40%	3.2	Gage
102	Small outside diameter		0.40%	3.2	Gage
103	Small inside diameter		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235530
4.4.2.10	Gear,Pinion				NEXT HIGHER ASSEMBLY 9235529
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of small outside diameter with large outside diameter		0.40%	3.2	Gage
102	Total composite error of gear		0.40%	3.2	Gage
103	Large outside diameter		0.40%	3.2	Gage
104	Small outside diameter		0.40%	3.2	Gage
105	Tooth to tooth composite error		0.40%	3.2	Gage
Minor					
201	Total Length		0.65%	3.2	Gage
202	Face width of pinion		0.65%	3.2	Gage
203	Length from small end to end of pinion		0.65%	3.2	Gage
204	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235531
4.4.2.11	Gear, Spur				NEXT HIGHER ASSEMBLY 9235529
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Inside diameter		0.40%	3.2	Gage
102	Total composite error of gear		0.40%	3.2	Gage
103	Tooth to tooth composite error		0.40%	3.2	Gage
104	Thickness		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.12	Gear Rack Assembly				9235535
					NEXT HIGHER ASSEMBLY 9235532
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of outside diameter of plunger		0.40%	3.2	Gage
102	Outside diameter of plunger		0.40%	3.2	Gage
103	Outside diameter of gear rack		0.40%	3.2	Gage
104	Diameter over gage pin		0.40%	3.2	Gage
Minor					
201	Number of teeth		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.13	Spring, Helical Compression				9235539
					NEXT HIGHER ASSEMBLY
					9235532
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Deflection Test	10(a)	--	3.2	Test 4.5.15
102	Outside diameter		0.40%	3.2	Gage
103	End not closed, ground or squared		0.40%	3.2	Visual
104	Improper number of coils		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:
(a) Ten (10) samples shall be randomly selected from each heat treat batch Composing the lot. The heat treat batch shall be rejected if one (1) or more samples are classed defective.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235533
4.4.2.14	Housing, Mechanical Drive				NEXT HIGHER ASSEMBLY 9235532
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None Defined				
Major					
101	Pitch diameter of threads, max		0.40%	3.2	Gage
102	Minor diameter of threads, max		0.40%	3.2	Gage
103	Crack or split		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235537
4.4.2.15	Gear, Pinion				NEXT HIGHER ASSEMBLY 9235532
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of small outside diameter with large outside diameter		0.40%	3.2	Gage
102	Total composite error of gear		0.40%	3.2	Gage
103	Small outside diameter		0.40%	3.2	Gage
104	Large outside diameter		0.40%	3.2	Gage
105	Tooth to tooth composite error		0.40%	3.2	Gage
Minor					
201	Total length		0.65%	3.2	Gage
202	Face width of pinion, max		0.65%	3.2	Gage
203	Length from large end to end of pinion		0.65%	3.2	Gage
204	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235534
4.4.2.16	Gear Assembly				NEXT HIGHER ASSEMBLY 9235532
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Component missing or improperly assembled		0.40%	3.2	Visual-Manual
102	Stake missing or inadequate		0.40%	3.2	Visual-Manual
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235529
4.4.2.17	Gear Sub-Assembly				NEXT HIGHER ASSEMBLY 9235532
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Perpendicularity of gear to shaft		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 6235504
4.4.2.18	Blaster Assembly				NEXT HIGHER ASSEMBLY 9312773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Component missing		0.40%	3.2	Visual
102	Spring in binder post functions improperly		0.40%	3.2	Visual
103	Lever assembled improperly to gear rack		0.40%	3.2	Visual-Manual
104	Lever clip does not restrain handle when handle is in closed position		0.40%	3.2	Visual
105	Retaining ring improperly installed		0.40%	3.2	Visual-Manual
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.19	Barrel, Clutch				9235547
					NEXT HIGHER ASSEMBLY
					9235534
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of large inside diameter with small outside diameter		0.40%	3.2	Gage
102	Large inside diameter		0.40%	3.2	Gage
103	Large outside diameter		0.40%	3.2	Gage
104	Small outside diameter		0.40%	3.2	Gage
Minor					
201	Total length		0.65%	3.2	Gage
202	Depth of cavity		0.65%	3.2	Gage
203	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.20	Gear, Spur				9235546
					NEXT HIGHER ASSEMBLY 9235534
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Inside diameter		0.40%	3.2	Gage
102	Total composite error of gear		0.40%	3.2	Gage
103	Tooth to tooth composite error		0.40%	3.2	Gage
104	Thickness		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.21	Spring, Leaf				9328277
					NEXT HIGHER ASSEMBLY 9312773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Open width		0.40%	3.2	Gage
102.	Material Thickness		0.40%	3.2	Gage
103.	Deflection Test	10(a)	--	3.2	4.5.15
Minor					
201.	Evidence of poor workmanship		1.0%	3.15	Visual

NOTES: (a) Ten (10) samples shall be randomly selected from each heat treat batch composing the lot. The heat treat batch shall be rejected if one (1)or more samples are classed defective.

DRCAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9328271
4.4.2.22	Capacitor, Fixed, Electrolytic				NEXT HIGHER ASSEMBLY 9328276
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101.	Capacitance	200(a)	--	3.2	4.5.11.1
102.	Leakage current	200(b)	--	3.2	4.5.11.2
MINOR					
201.	Evidence of poor workmanship		1.0%	3.15	Visual
Notes	(a) The lot shall be rejected if four (4) or more samples are classed defective.				
	(b) The lot shall be rejected if three (3) or more samples are classed defective.				

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE			SHEET 1 OF 1	DRAWING NUMBER 9328281
4.4.2.23	Capacitor, Fixed, Electrolytic				NEXT HIGHER ASSEMBLY 9328276
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101.	Capacitance	200(a)	----	3.2	4.5.11.1
102.	Leakage current	200(b)	----	3.2	4.5.11.2
MINOR					
201.	Evidence of poor workmanship		1.0%	3.15	Visual
Notes	(a) The lot shall be rejected if four (4) or more samples are classed defective.				
	(b) The lot shall be rejected if three (3) or more samples are classed defective.				

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 0328275
4.4.2.24	Resistor (R1,R2,R7-R9)				NEXT HIGHER ASSEMBLY 0328275
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR 101.	Resistance (Each value)	200(a)	----	3.2	4.5.12
MINOR 201.	Evidence of poor workmanship		1.0%	3.15	Visual

NOTES:
(a) The lot shall be rejected if three (3) or more samples are classed defective.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9328280
4.4.2.25	Lamp, Trigger				NEXT HIGHER ASSEMBLY 9328275
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101.	Aging		100%	3.2	4.5.13.1
102.	Breakdown voltage		100%	3.2	4.5.13.2
103.	Service cycle	5(a)(b)	---	3.2	4.5.13.3
104.	Anode identification improper		0.40%	3.2	Visual
MINOR					
201.	Evidence of poor workmanship		1.0%	3.15	Visual

NOTES:
a. The service life test shall be performed on samples which have undergone the aging cycle.
b. The lot shall be rejected if one (1) or more samples are defective.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235515
4.4.2.26	Magnet, Permanent				NEXT HIGHER ASSEMBLY 9235513
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101.	True position of inner diameter to outside diameter	200(a)	0.40%	3.2	Gage
102.	Flux density		----	3.2	4.5.14
MINOR					
201.	Inside diameter		0.65%	3.2	Gage
202.	Outside diameter		0.65%	3.2	Gage
203.	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES: (a) The lot shall be rejected if three (3) or more samples are classed defective.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9328275
4.4.2.27	Printed Wiring Board Assembly				NEXT HIGHER ASSEMBLY 9312773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101.	Parallelism of flat standoff with center line		0.40%	3.2	Gage
102.	Component missing or improperly located		0.40%	3.2	Visual
103.	Wiring improper		0.40%	3.2	Visual
104.	Soldering improper		0.40%	3.2	Visual
MINOR					
201.	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.28	Internal Assembly				9328276
					NEXT HIGHER ASSEMBLY 9312773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101	Improper solder		0.40%	3.2	Visual
102	Adhesive not uniform		0.40%	3.2	Visual
103	Coating inadequate		0.40%	3.2	Visual
104	Capacitor cavity filled		0.40%	3.2	Visual
105	Capacitor height maximum		0.40%	3.2	Gage
106	Potting, height, maximum		0.40%	3.2	Gage
107	Resistor, R3-R6 resistance	200(a)	------	3.2	4.5.12
MINOR					
201	Evidence of poor workmanship		1.0%	3.15	Visual

NOTES: (a) The lot shall be rejected if three (3) or more samples are classed defective.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9312773
4.4.2.29	M34 Blasting Machine				NEXT HIGHER ASSEMBLY ---------
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101.	Height of blasting machine		0.40%	3.2	Gage
102.	Width of blasting machine		0.40%	3.2	Gage
103.	Thickness of blasting machine		0.40%	3.2	Gage
104.	Weight over max.		0.40%	3.2	Scale
105.	Operating handle missing		0.40%	3.2	Visual
106.	Visual indicator missing		0.40%	3.2	Visual
107.	Binding post(s) loose or missing		0.40%	3.2	Visual-Manual
108.	Waterproof test		100%	3.5	4.5.3.2
109.	Service life cycle		----	3.7	4.4.3.2/4.5.5
110.	Insulation resistance		----	3.10	4.5.8
111.	Output capacity		100%	3.3	4.5.1
112.	Extreme temperature performance		----	3.8	4.4.3.1/4.5.6
113.	Unactivated voltage		100%	3.12	4.5.10
MINOR					
201.	"D" ring missing		0.65%	3.2	Visual
202.	"D" ring not secure in folded position		0.65%	3.2	Visual
203.	Marking missing, misleading or unidentifiable		0.65%	3.2	Visual
204.	Identification marking reflective		0.65%	3.2	Visual
205.	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235541
4.4.2.30	Housing, Electrical				NEXT HIGHER ASSEMBLY 9235509
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101	Diameter of stator assembly hole		0.40%	3.2	Gage
102	True position of stator assembly hole with alternator assembly cavity		0.40%	3.2	Gage
103	Diameter of alternator assembly cavity		0.40%	3.2	Gage
104	True position of bearing plate cavity with center-line of dowel pin holes		0.40%	3.2	Gage
105	Location of dowel pin holes with side and end and true position of dowel pin holes with each other		0.40%	3.2	Gage
106	True position of bearing plate shoulder cavity with bearing plate cavity		0.40%	3.2	Gage
107	True position of alternator assembly cavity with bearing plate cavity		0.40%	3.2	Gage
MINOR					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9235533
4.4.2.31	Housing, Mechanical Drive				NEXT HIGHER ASSEMBLY 9235532
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101	Diameter of gear assembly cavity		0.40%	3.2	Gage
102	Diameter of lower gear assembly bearing cavity		0.40%	3.2	Gage
103	Diameter of outer gear rack assembly cavity		0.40%	3.2	Gage
104	Diameter of inner gear rack assembly cavity		0.40%	3.2	Gage
105	True position of lower gear assembly bearing cavity with gear assembly cavity		0.40%	3.2	Gage
106	True position of outer gear rack assembly cavity with center-line of dowel pin holes		0.40%	3.2	Gage
107	True position of packing groove with outer gear rack assembly cavity		0.40%	3.2	Gage
108	Location of dowel pin holes with side and end and true poistion of dowel pin holes with each other		0.40%	3.2	Gage
109	Depth of smaller gear assembly cavity		0.40%	3.2	Gage
110	Diameter of smaller gear assembly cavity		0.40%	3.2	Gage
111	True position of smaller gear assembly cavity		0.40%	3.2	Gage
112	True position of larger gear assembly cavity		0.40%	3.2	Gage
113	Location of threaded cavity		0.40%	3.2	Gage
114	True position of inner gear rack assembly cavity with outer gear rack assembly cavity		0.40%	3.2	Gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9235533
4.4.2.31	Housing, Mechanical Drive				NEXT HIGHER ASSEMBLY 9235532
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
MINOR					
201	Diameter of packing groove		0.65%	3.2	Gage
202	Width of top segment		0.65%	3.2	Gage
203	Depth of upper gear assembly cavity		0.65%	3.2	Gage
204	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9328278
4.4.2.32	Case, Molded				NEXT HIGHER ASSEMBLY 9312773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101	Diameter of binding post holes		0.40%	3.2	Gage
102	Parallelism of sides of binding post hole cavity with center line		0.40%	3.2	Gage
103	Diameter of spring pin hole		0.40%	3.2	Gage
104	Location of binding post holes		0.40%	3.2	Gage
MINOR					
201	Width of large cavity		0.65%	3.2	Gage
202	Length of large cavity		0.65%	3.2	Gage
203	Marking misleading or unidentifiable		0.65%	3.2	Visual
204	Serrations missing		0.65%	3.2	Visual
205	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

MIL-B-63094B(AR)

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9235508
4.4.2.33	Lever				NEXT HIGHER ASSEMBLY 9235504
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101	Symmetry of gear rack cutout with sides		0.40%	3.2	Gage
102	Symmetry of positioning slot with sides		0.40%	3.2	Gage
MINOR					
201	Width of spring pin holes		0.65%	3.2	Gage
202	Total length		0.65%	3.2	Gage
203	Serrations missing		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.34	Box, Fiberboard Prior to Closing				See 5.1.1
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101.	Number of blasting machines incorrect		0.40%	3.2	Visual
102.	Box damaged		0.40%	3.2	Visual
MINOR					
201.	Packing material missing		0.65%	3.2	Visual
202.	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.35	Box, Fiberboard				See 5.1.1
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR 101.	Box improperly taped		0.40%	3.2	Visual
MINOR 201.	Marking misleading, missing or unidentifiable		0.65%	3.2	Visual
202.	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.36	Sealed Packed Barrier Bag, Prior to Packing in Box				See 5.1.1
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101	Waterproofness of barrier bag destroyed by rupture, puncture or separation of head seal		0.40%	3.2	Visual
102	Evidence of crushed box		0.40%	3.2	Visual
103	All excess air not exhausted from bag prior to sealing		0.40%	3.2	Visual
	NOTE: Package should be opened if there is evidence of crushing				
MINOR					
201	Heat seal of barrier bag located so that one or more subsequent seals cannot be applied		0.65%	3.2	Visual
202	Marking of bag misleading or unidentifiable		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.37	Box, Wood Prior to Closing				See 5.2.1
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101	Fiberboard box missing		0.40%	3.2	Visual
102	Board broken or split		0.40%	3.2	Visual
MINOR					
201	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-B-63094B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 5.2.1
4.4.2.38	Box, Wood				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101	Strapping missing, broken or loose		0.40%	3.2	Visual
102	Magnetic caution label missing (when applicable)		0.40%	3.2	Visual (see 5.3)
MINOR					
201	Marking missing, misleading or unidentifiable		0.65%	3.2	Visual
202	Strapping improperly assembled		0.65%	3.2	Visual
203	Contents move when box is tilted		0.65%	3.2	Manual
204	Evidence of poor workmanship		1.00%	3.15	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

4.4.3 Testing. - Testing is described in the First Article and Quality Conformance Inspection Tables.

4.4.3.1 Extreme temperature performance. - (See 3.8) Major Defect. - Twenty (20) samples shall be randomly selected from each lot and tested in accordance with 4.5.6 for the specified requirements. Ten (10) samples shall be tested for the low temperature requirements and ten (10) samples shall be tested for the high temperature requirements. The lot shall be rejected if two (2) or more samples are classed defective.

4.4.3.2 Service cycle. - Five (5) samples shall be randomly selected from each lot and subjected to the specified requirements in accordance with 4.5.5. After three (3) successive lots without failure, the lot sample shall be reduced to two (2) units. If a lot incurs failures at the reduced inspection level, the contractor shall revert back to the five (5) samples per lot requirement. The lot shall be rejected if one (1) or more samples are classed defective using either sampling plan.

4.4.4 Inspection equipment. - The inspection equipment required to perform the examinations, and tests prescribed herein is described in the Paragraph Reference Inspection Method column in the tables of paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 herein.

4.4.5 Dimensional control of molded parts. - (The requirements of this paragraph apply to those dimensions which are considered "as molded", and which do not undergo subsequent operations). In place of normal sampling and inspections associated with the Classification of Defects, and with the approval of the Contracting Officer, and after a curing time for the parts has been approved (See Note 1) a sample of five (5) parts (as molded) from each cavity shall be inspected dimensionally to qualify a new or reworked cavity for use in production. The molded parts shall carry the individual cavity identification, when more than one cavity is used in production. As a control of each cavity during production the above quantity of parts from each cavity shall be inspected for at least the defects listed in applicable paragraphs so selected. After continuous production of each 5,000 parts or at the end of each week, whichever occurs first.

Of the five (5) samples, one (1) sample shall be the last part produced. If any defective parts are found during qualification of the cavity, the cavity producing the defective part will not be used in production. If any defective parts are found when inspection is performed for the control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for inspection for each separate type of defect according to MIL-STD-105, using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. All cavities removed from production because of some fault, may after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the contracting officer to substantiate the request. Contractor design of gages and test equipment required to perform the inspections listed herein shall be forwarded to Commander, ARRADCOM, Dover, New Jersey, 07801, ATTN: DRDAR-QAA-I for approval prior to manufacture of equipment. The noted subparagraphs identify those items and minimum inspections subject to the requirements of this paragraph.

NOTE 1 - In establishing the curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g. every 30, 60, etc. mins.) until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. The inspection data used in determining the curing time shall be sent to ARRADCOM, Dover, New Jersey, 07801, ATTN: DRDAR-QAA-I. If any new change in material, cycle time, a rework cavity, or a new cavity is used, a new curing time shall be established and approved.

4.5 Test methods and procedures

4.5.1 Output capacity. - The blasting machine shall produce the specified output requirements when it is tested in series with a resistive load of one hundred and fifty plus or minus two (150 + 2) ohms within the second (2nd) activation cycle minimum and the fifth (5th) activation cycle maximum.

Testing shall be performed on an approved Government test fixture that secures the device under test. The test equipment shall be capable of depressing the handle with a ninety plus five (90 + 5) pound force and releasing it as shown in the following paragraphs.

A maximum force of twenty five (25) pounds may be initially applied to the handle prior to exerting the ninety (90) pound force. Complete handle closure should be accomplished within one (1.0) second. Handle release shall be accomplished within seven tenths (0.7) seconds. This concludes one activation cycle.

Successive cycles shall start immediately after the completion of the preceeding cycle. The device under test shall fire within the second (2nd) cycle minimum to the fifth (5th) cycle maximum. The time in between each successive cycle shall not exceed two tenths (0.2) seconds.

Once the device has successfully fired, the sample shall be tested for the unactivated voltage requirement in accordance with 4.5.10. The device under test shall then fire twice more on successive attempts to comply with the output requirements. The device under test shall also comply with the unactivated voltage requirements after each firing.

After three hundred (300) successive samples have complied with the triple firing requirement, the test sample firing requirement shall be reduced to meeting the output capacity one time.

If the device fails to comply with all of the specified requirements it shall be classed defective and removed from the lot.

Data shall be retained on all firings by recording the output trace displayed on a oscilloscope by a photograph for every fiftieth (50th) sample. Other samples not requiring a photograph must have their output trace displayed on a memoscope and the data recorded in accordance with 4.5.16. (Non-destructive test).

4.5.2 Drop test. - The blasting machine shall be dropped a total of three (3) times a vertical distance of five (5) feet onto a solid concrete surface. Each machine shall be impacted; once on the terminals, once on the handle and once on the corner where the handle is pivoted. After drop,

the machine shall show no evidence of damage that would cause non-conformance with the capacity requirements of 3.3. The blasting machine shall then be tested in accordance with the test methods of 4.5.1 for output capacity except that it shall indicate a successful firing three (3) sequential times instead of just once.

The three (3) sequential firings shall be the first three (3) attempts to fire after concluding the drop test. If the device fails to comply with all of the specified requirements, it shall be classed defective (Destructive test).

4.5.3 Waterproofness

4.5.3.1 Waterproofness A. - The sample shall be tested in accordance with the requirements and procedures of Test 108 of MIL-STD-331 and disassembled for internal evidence of water leakage. Any sample failing to comply with all of the specified requirements shall be classed defective. (Destructive test).

4.5.3.2 Waterproofness B. - The blasting machine shall be completely submerged under 6 inches of water heated between 83 degrees C min and 88 degrees C max for a minimum of 5 minutes and maximum of 10 minutes. Any blasting machine emitting bubbles shall be classed defective and removed from the lot. Blasting machines showing no evidence of leakage shall be operationally tested as specified in 4.5.1 for conformance with the requirements of 3.3. (Non-destructive test).

4.5.4 Transportation vibration. - The blasting machine shall be subjected to transportation vibration testing in accordance with Test Method 119, Procedure II of MIL-STD-331. The machine shall then be visually examined for loose components, cracks, broken parts or other evidence of physical damage.

After examination, the blasting machine shall be tested in accordance with the test methods of 4.5.1 for output capacity except that it shall indicate a successful firing three (3) sequential times instead of just once. The three (3) sequential firings shall be the first three (3) attempts to fire after concluding the vibration test. If the sample fails to comply with all of the specified requirements it shall be classed defective (Non-destructive test).

4.5.5 Service life cycle. - The blasting machine shall be tested for the specified amount of functions in accordance with the test method of 4.5.1. An exception to 4.5.1 is that a photograph shall not be required on every function. Instead, photographs shall be required on the first output and every five hundredth (500th) output thereafter. If the sample fails to comply with all of the specified requirements it shall be classed defective (Destructive test).

4.5.6 Extreme temperature performance. - The blasting machine shall be temperature soaked at the specified temperatures for twenty four plus four (24 + 4) hours prior to testing for the required output. At the end of the soak period the unit shall be tested for the specified output in accordance with the test method of 4.5.1. Testing shall be performed at the required temperatures. The blasting machine shall function on the first attempt at the test temperature.

The device under test where applicable for temperature performance other than ambient shall be tested for the output capacity within five (5) minutes after its removal from the temperature chamber.

Any unit failing to comply with all of the specified requirements shall be classed defective (Non-destructive test).

4.5.7 Temperature storage. - For high temperature storage testing the blasting machine shall be stored at seventy degrees centigrade plus five degrees centigrade ($70^{o}C + 5^{o}C$) for a minimum of seventy two (72) hours. Following this conditioning, the machine shall be inspected for physical or mechanical deterioration. The device shall than be temperature soaked at fifty degrees centigrade plus or minus three degrees centigrade ($50^{o}C \pm 3^{o}C$) for a minimum of six (6) hours. While at the required temperature, the device shall be tested as specified in 4.5.1 for the specified output.

For low temperature storage testing, the blasting machine shall be stored at minus fifty five degrees centigrade minus five degrees centigrade ($-55^{o}C - 5^{o}C$) for a minimum of seventy two (72) hours. Following this, the blasting machine shall be temperature soaked for six plus one (6 + 1) hours at minus forty five degrees centigrade minus five degrees centigrade ($-45^{o}C - 5^{o}C$) for a minimum of six (6) hours. While at the required temperature, the device shall be tested as specified in 4.5.1 for the specified output.

The device under test where applicable for temperature performance other than ambient shall be tested for the output capacity within five (5) minutes after its removal from the temperature chamber.

Any device failing to comply with all of the specified requirements shall be classed defective. (Non-destructive test).

4.5.8 Insulation resistance. - The blasting machine shall be tested for the specified requirements using approved test equipment. After passing the insulation resistance test requirements, the machine shall be tested for output capacity in accordance with 4.5.1.

If the sample fails to comply with all the specified requirements, it shall be classed defective (Non-destructive test).

4.5.9 Humidity test. - The blasting machine shall be subjected to 20 hours exposure with relative humidity between 92 and 97 percent and at air temperature from plus 27 degrees C to plus 5 degrees C followed by 4 hours of 100 percent relative humidity with condensation at plus 25 degrees C plus 5 degrees C. At the conclusion of the humidity test the blasting machine shall be inspected for evidence of damage and tested for conformity with the requirements of 3.3.

Any sample failing to comply with all of the specified requirements shall be classed defective (Non-destructive test).

4.5.10 Unactivated voltage. - The device after complete functioning shall be measured using a digital readout voltmeter with a minimum input impedance of ten (10) megohms. Any device measuring an output in excess of the specified requirement shall be classed defective (Non-destructive test).

4.5.11 Capacitor

4.5.11.1 Capacitance. - The capacitor shall be tested for the specified capacitance value using a Government approved test equipment. Any capacitor failing to comply with all of the specified requirements shall be classed defective (Non-destructive test).

4.5.11.2 Leakage current. - The capacitor shall be measured for the specified leakage current using Government approved test equipment. Any sample exceeding the maximum current shall be classed defective. (Non-destructive test).

4.5.12 Resistor (R1-R9) resistance. - The sample shall be measured for the specified resistance using a Government approved digital readout ohmmeter. Any sample failing to comply with all of the requirements shall be classed defective (Non-destructive test).

4.5.13 Lamp, trigger

4.5.13.1 Aging. - The lamp shall be aged to the specified requirements using Government approved aging racks set at the required voltage. All lamps shall be aged prior to undergoing further test.

4.5.13.2 Breakdown voltage. - The lamp shall be tested for the specified breakdown voltage using Government approved test equipment. Breakdown voltage testing shall not occur until after the lamps have been aged in accordance with 4.5.13.1. Any lamp failing to comply with all of the specified requirements shall be classed defective (Non-destructive test).

4.5.13.3 Service cycle. - The lamp, after aging, shall be subjected to five thousand (5000) consecutive operations without failure in accordance with the specified test criteria using Government approved test equipment. Any lamp failing to comply with all of the specified requirements shall be classed defective (Destructive test).

4.5.14 Permanent magnet flux density. - The sample shall be tested for the specified requirements using Government approved test equipment. Any sample failing to comply with all of the specified requirements shall be classed defective (Non-destructive test).

4.5.15 Deflection test. - The sample shall be loaded with the specified force and measured for the specified deflection. The loads shall be removed, and the free lengths measured for the specified dimensions. Any sample failing to comply with all of the specified requirements shall be classed defective (Non-destructive test).

4.5.16 Data requirements. - The contractor shall submit a quality inspection test, demonstration and evaluation report in accordance with Data Item Description DI-R-1724 giving all detailed inspection and test results for 4.5. Data, as accumulated by 4.5 shall be submitted to the technical agency in 6.4.

5. PREPARATION FOR DELIVERY

5.1 Packaging

5.1.1 Level A. - Fifty (50) blasting machines shall be packaged, one per cell, in a fiber box complete with half-slotted partitions assembled to form 25 cells in a 5 by 5 arrangement, 2 layers per box. A filler pad shall be placed on the inside bottom of the box, between layers and on top of the box contents. Additional pads shall be added as necessary on the inside bottom of the box, between layers and on top of the box contents. Additional pads shall be added as necessary to provide a tight package. The box shall conform to the requirements of PPP-B-636 for a Type CF, Class Demestic, Variety SW, Grade 200 box. The partitions and pads shall be constructed of the same test fiberboard as the box. Cell sizes shall be approximately 2 3/4 by 1 1/2 by 5 3/8 inches in depth inside dimensions. Box size shall be approximately 14 3/8 by 8 1/8 by 11 1/8 depth inside dimensions. Filler pads shall be equal to the inside length and width of the box less 1/16 inch. Boxes shall be closed by application of 3 inch wide, PP-T-45 Type II, Class 1 or 2 tape over the full length of the top and bottom center seam of the box with an approximate 3 inch extension onto the end panels. All corners of the box shall be blunted and the box inserted into a barrier bag conforming to MIL-B-117 for a Type I, Style I, Class E bag. Bag size shall be approximately 21 by 25 inches inside dimensions. All excess air shall be exhausted from the bag and the opening closed by means of heatsealing. The closure seam shall meet the heat-seal test contained in MIL-P-116.

5.1.2 Level C. - Blasting machines shall be packaged the same as Level A except the barrier bag shall be omitted.

5.2 Packing

5.2.1 Level A. - Two unit boxes (100 blasting machines) shall be packed in a Grade A wooden box conforming to PP-B-621, for a Class 2, Style 2, 2 1/2 or 4 for a Type 3 load or MIL-B-46506 for a Type I Class 2, Grade A box. The interior surfaces of the box shall be lined with Filler Sheet Form, MIL-F-50449. One or more fillers shall be placed on top of box contents to insure a tight pack. The box size shall be approximately 17 1/8 by 15 1/8 by 11 7/8 inches in depth, inside dimensions. Boxes shall be closed and strapped in accordance with instructions contained in the appendix of the box specificaiton.

5.2.2 Level C. - The unit fiber box, without barrier bag, shall serve as the shipping container.

5.2.3 Air shipment. - When air shipment is specified each box and each pallet load of boxes shall be tested by use of a Gauss meter to insure compliance with the magentic shielding requirements for air shipment, as specified in MIL-S-4473. Boxes or pallet loads failing to meet the air suitability requirements shall be shielded in accordance with the requirement of MIL-S-4473 to meet air shipment requirements.

5.3 Marking. - Each unit box, barrier bag and exterior container shall be marked in accordance with MIL-STD-1169 requirements, except barrier bags shall be printed or stamped In addition each exterior box shall have special magnetic caution lables applied in accordance with paragraphs 5.5.15.8.1 through 5.5.15.8.4 of MIL-STD-129. Labels shall be waterproofed in accordance with MIL-STD-129 requirements.

6. NOTES

6.1 Intended use. - The assembly covered by this specification is intended for use of a generator type blasting machine designed to detonate fifty (50) blasting caps simultaneously.

6.2 Ordering data. - See Section 6.1 and 6.2 of MIL-A-48078.

6.3 Submission of inspection equipment designs for approval (See MIL-A-48078). - Submit equipment designs as required to: Commander, ARRADCOM ATTN: DRDAR-QAA-I, Dover, New Jersey 07801.

6.4 Distribution of ammunition data cards, inspection results and test data. - Distribution of ammunition data cards, inspection and test results shall be submitted to: Commander, ARRADCOM, ATTN: DRDAR-QAA-Q, Dover, New Jersey 07801.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project Number: 1375-A-225

FOLD

POSTAGE AND FEES PAID



OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

Commander
US Army Armament R&D Command
ATTN: DRDAR-QAA
Dover, New Jersey 07801

FOLD

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.

NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-B-63094B BLASTING MACHINE, 50 CAP, M34

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*

TELEPHONE NO.

DATE

DD FORM 1426 1 OCT 76

EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.