MIL-C-63342B(AR)
20 August 1987
SUPERSEDING
MIL-C-63342A (AR)
1 September 1979

MILITARY SPECIFICATION

CHARGE, PROPELLING, 8 INCH, M188A1, LOADING, ASSEMBLING, AND PACKING

This specification is approved for use within the US Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers the manual/semi-automated loading, assembling and packing for one type of propelling charge designated as Charge, Propelling, M188A1 for 8 Inch Howitzer, M110A2.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. The following specifications and standards form a part of this specification to the extent specified herein. Unless otherwise specified, the issues of these documents shall be those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation.

SPECIFICATIONS

MILITARY

MIL-P-223	- Powder, Black
MIL-A-48078	- Ammunition, Standard Quality Assurance Provisions, General Specification For

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, U.S. Army Armament, Munitions and Chemical Command, Attn. AMSMC-QA, Picatinny Arsenal, New Jersey 07806-5000 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A
FSC 1320
DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

STANDARDS

MILITARY

MIL-STD-105	- Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-414	- Sampling Procedures and Tables for Inspection by Variables for Percent Defective
MIL-STD-1235	- Single and Multilevel Continuous Sampling Procedures and Tables for Inspection by Attributes

2.1.2 Other Government documents, drawings and publications. The following other Government documents, drawings and publications form a part of this specification to the extent specified herein. Unless otherwise specified the issues shall be those in effect on the date of the solicitation.

DRAWINGS

US ARMY ARMAMENT RESEARCH DEVELOPMENT AND ENGINEERING CENTER (ARDEC)

9331255	- Packing and Marking for Container, Ammo, Metal PA92 for Charge Propelling 8 Inch, M188A1
11829092	- Charge, Propelling, 8 Inch, M188A1 for 8 Inch Howitzer, SP, M110A2

(Copies of specifications, standards, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

2.1.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, (except for associated detail specifications, specification sheets or MS standards) the text of this specification shall take precedence. Nothing in this specification, however, shall supersede aplicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 Materials. Materials shall be in accordance with applicable drawings and specifications.

3.2 Propelling charge. The propelling charge shall comply with all requirements specified on drawing 11829092 and with all requirements specified in applicable specifications.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.3 Moisture content of black powder. The moisture content of the black powder at the igniter loading station at the time of loading shall not exceed the amount specified in MIL-P-223.

3.4 Weights.

3.4.1 Propellant.

3.4.1.1 Weight tolerance of propellant. The propellant weight shall comply with the weight specified in the loading authorization within the following tolerance:

Increment Number	Tolerance Plus or Minus (+) Ounces
8	0.4
9	0.2

The propellant for Increment 8 may be determined by weighing 50 percent of the loading authorization of Increment 8 twice to a tolerance of 0.2 ounces.

3.4.1.2 Weight and check weight. The propellant shall be weighed and checkweighed 100 percent. The checkweighing shall be accomplished independently of the original weighing using a different scale from that used to make the original weighing and, if performed manually, shall be performed by another operator.

3.4.2 Charge, propelling assembly weight. The weight of the propelling charge prior to packing shall not differ by more than 1.0 ounce from the total of the amount specified in the loading authorization plus actual or average weights of the empty increments, lead sheet, lacing cord, lacing jacket and loaded base igniter and tube assembly. (See 6.8).

3.4.3 Base igniter and tube assembly weight. (See 6.8).

3.4.3.1 Actual weight of tube. The loaded base igniter and tube assembly weight shall not differ by more than 0.25 ounce from the nominal black powder weight plus the actual weight of the tube, actual weight or average weight of the base igniter assembly, and average weight of cap.

3.4.3.2 Average weight of tube. The loaded base igniter and tube assembly weight shall not differ by more than 0.30 ounce from the nominal black powder and average tube weight plus the actual weight or average weight of the base igniter assembly and average weight of the cap.

3.5 Dimensional gages.

3.5.1 Maximum length and diameter. The completed charge shall freely enter the prescribed gage. The gage shall be designed to

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

inspect the maximum diameter and length. If the diameter feature is separate from the length feature, the diameter feature must extend approximately the full length of the charge.

3.5.2 Minimum diameter. The base end of the completed charge shall not freely enter the prescribed gage greater than two inches.

3.6 Proving ground. The muzzle velocity, pressure, and velocity standard deviation shall be as specified in Table I. (See 6.12).

TABLE I. Velocity and pressure

Zone	Proj	Temp	Velocity (feet per second) Minimum	Maximum	Velocity Standard Deviation FPS	Individual* Maximum Pressure PSI
Chg. 8	M106	70°F	2295	2365	6.5	NA
Chg. 9	M106	70°F	2495	2565	6.5	42,100
Chg. 9	M106	145°F	(Differential Pressure)		NA	48,100
Chg. 9	M106	-50°F	(Differential Pressure)		NA	NA

*See 6.14

3.6.1 Differential pressure.

3.6.1.1 Hot firings. No individual differential pressure shall exceed 7000 psi. If the mean plus three (3) times the standard deviation exceeds 7000 psi, the lot will be referred.

3.6.1.2 Cold firings. No individual differential pressure shall exceed 3500 psi. If the mean plus three (3) times the standard deviation exceeds 3500 psi, the lot will be referred (see 6.13).

3.6.2 Safety phase test. (SEMI-AUTOMATED LOADING OPERATION ONLY) (FOR FIRST PRODUCTION LOT ONLY) (see 6.20).

3.7 Complete igniter alignment. An approved method of centering the complete igniter assembly in the Increment 8 assembly will be utilized for all charges.

3.8 Igniter tubes. All tubes shall be free of cracks, dents, creases, tears, flat areas, and softness greater than 0.25 square inch.

3.9 Assembly torque. The packing container test plug shall be assembled to withstand subsequent reapplication of the minimum assembly torque specified on the applicable drawing, without moving.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.10 First article inspection. This specification contains technical provisions for the first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.11 Workmanship. All components shall be free of dirt, grease and other foreign material. There shall be no discoloration or deterioration of cloth and no evidence of rips, tears, or other cloth defects. All work performed shall be performed in a thorough workmanlike manner.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection . Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.1.1 Responsibility for compliance. All items must meet all requirements of sections 3 and 5. The inspection set forth in this specification shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the specification shall not relieve the contractor of any responsibility of assuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling in quality conformance does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to acceptance of defective material.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection
b. Quality Conformance Inspection

4.3 First article inspection.

4.3.1 Submission. The contractor shall submit a first article sample from the initial production lot as designated by the

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

contracting officer for evaluation in accordance with the provisions of 4.3.2. The first article sample shall consist of the following:

Part Description	Drawing	Quantity
Cloth, Laminated, Increment 9	9332451	3
Strap Tying	11829110	3
Bag, Core	11829098	3
Core Bag Assembly	11829097	3
End, Base Igniter, Small	11829106	3
End, Base Igniter, Large	11829107	3
Base Igniter End and Core Bag Assembly	11829099	3
Base Igniter Assembly	11829114	3
Base Igniter and Core Bag Loading Assembly	11829100	3
Cap (if applicable)	11829111	3
Flex 10 (if applicable)	9345159	3
Base Igniter and Tube Assembly	11829102	3
Increment 8 Body	11829096	3
End, Increment 8	11829109	3
End Assembly, Increment 8	11829108	3
Increment 8 Body Assembly	11829093	3
Increment 8 Loading Assembly	11829094	3
Increment 9 Body	11829105	3
End, Increment 9	11829112	3
Increment 9 End Assembly	11829113	3
Increment 9 Assembly	11829103	3
Increment 9 Loading Assembly	11829104	3
Jacket, Lacing	11829095	3
Charge, Propelling, 8 Inch M188A1 for 8 Inch Howitzer, SP, M110A2, in Sealed Containers	9331255 11829092	10 (180)*

* (For semi-automated loading only) - 170, M188A1 Charges shall be sent to a designated Government Proving Ground for Ammunition Safety Phase Test.

4.3.2 Inspections to be performed. The First Article parts submitted in accordance with 4.3.1 will be subjected by the Government to any or all the requirements of the applicable drawings and specifications and to the inspections of Table II. All inspections listed in Table II shall be classified Major unless otherwise specified in referenced paragraphs and specifications.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE II. First article inspection

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63342B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 4		DRAWING NUMBER
	Propelling Charge Components and Assemblies				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Strap, Tying (Dwg. 11829110) Examination for Defects	3		3.2	4.4.2.1
	Bag, Core (Dwg. 11829098) Examination for Defects	3		3.2	4.4.2.2
	Core Bag Assembly (Dwg. 11829097) Examination for Defects	3		3.2	4.4.2.3
	End, Base Igniter small (Dwg. 11829106) Examination for Defects	3		3.2	4.4.2.4
	End, Base Igniter, large (Dwg. 11829107) Examination for Defects	3		3.2	4.4.2.5
	Base, Igniter End and Core Bag Assembly (Dwg. 11829099) Examination for Defects	3		3.2	4.4.2.6
	Base Igniter Assembly (Dwg. 11829114) Examination for Defects	3		3.2	4.4.2.7

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-01-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE II. First article inspection

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE: Propelling Charge Components and Assemblies (Continued)		SHEET 2 OF 4		DRAWING NUMBER / NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Base Igniter and Core Bag Loading Assembly (Dwg. 11829100) Examination for Defects	3		3.2	4.4.2.8
	Cap (if applicable) (Dwg. 11829111) Examination for Defects	3		3.2	4.4.2.9
	Flex 10 (Dwg. 9345159) Examination for Defects 1/	3		3.2	4.4.2.10
	Base Igniter and Tube Assembly (Dwg. 11829102) Examination for Defects	3		3.2	4.4.2.11
	Increment 8 Body (Dwg. 11829096) Examination for Defects	3		3.2	4.4.2.12
	End, Increment 8 (Dwg. 11829109) Examination for Defects	3		3.2	4.4.2.13

NOTES: 1/ If applicable.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE II. First article inspection

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 3 OF 4		DRAWING NUMBER
	Propelling Charge Components and Assemblies (Continued)				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	End Assembly, Increment 8 (Dwg. 11829108) Examination for Defects	3		3.2	4.4.2.14
	Increment 8 Body Assembly (Dwg. 11829093) Examination for Defects	3		3.2	4.4.2.15
	Increment 8 Loading Assembly (Dwg. 11829094) Examination for Defects	3		3.2	4.4.2.16 or 4.4.2.17
	Increment 9 Body (Dwg. 11829105) Examination for Defects	3		3.2	4.4.2.18
	End, Increment 9 (Dwg. 11829112) Examination for Defects	3		3.2	4.4.2.19
	Increment 9 End Assembly (Dwg. 11829113) Examination for Defects	3		3.2	4.4.2.20
	Increment 9 Assembly (Dwg. 11829103) Examination for Defects	3		3.2	4.4.2.21

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE II. First article inspection

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE Propelling Charge Components and Assemblies (Continued)		SHEET 4 OF 4		DRAWING NUMBER NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Increment 9 Loading Assembly (Dwg. 11829104) Examination for Defects	3		3.2	4.4.2.22 or 4.4.2.23
	Jacket, Lacing (Dwg. 11829095) Examination for Defects	3		3.2	4.4.2.24
	Charge, Propelling, 8 Inch, M188A1 for 8 Inch Howitzer, SP, M110A2 in Sealed Containers (Dwg. 11829092 and 9331255) Examination for Defects (except Proving Ground Test)				4.4.2.25/4.4.2.26/ 4.4.2.27/4.4.2.28/ 4.4.2.29/4.4.2.30/ 4.4.2.31
NOTES:					

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of propelling charge assemblies shall contain:

a. Propellant from not more than one lot number from one manufacturer.

b. Black powder from not more than one lot number from one manufacturer.

c. Tubes from not more than one interfix number from one manufacturer.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829110
4.4.2.1	Strap, Tying				NEXT HIGHER ASSEMBLY 11829093
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Length		0.65%	3.2	Scale
202	Width	1/	0.65%	3.2	Scale

NOTES: 1/ If a slitting machine is utilized, in lieu of the specified AQL, during the slitting process each roll will be inspected within the first 10 feet and the last 10 feet, i.e., two measurements per roll.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.2	Bag, Core		11829098
			NEXT HIGHER ASSEMBLY 11829097

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Width of cloth	1/	0.40%	3.2	Scale
102	Cloth improper			3.1	4.5.5
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: 1/ If a slitting machine is utilized, in lieu of the specified AQL, during the slitting process each roll will be inspected within the first 10 feet and the last 10 feet; i.e., two measurements per roll.

Source: https://assist.dla.mil -- Downloaded: 2026-02-25T04:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER 11829097
4.4.2.3	Core Bag Assembly		NEXT HIGHER ASSEMBLY 11829099

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Tape missing, insecure or improper located		100%	3.2	Gage/Manual
102	Cloth improper (tape)			3.1	4.5.5
103	Length, bag core		0.40%	3.2	Scale
104	Seam improper or improperly located		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	End, Base Igniter, Small				11829106
					NEXT HIGHER ASSEMBLY 11829114
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Marking missing, misleading or unidentifiable		0.65%	3.2	Visual
202	Diameter of base igniter end		0.65%	3.2	Gage
203	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-01-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	End, Base Igniter, Large		11829107
			NEXT HIGHER ASSEMBLY 11829099

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Diameter of base igniter end		0.65%	3.2	Gage
202	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.6	Base Igniter End and Core Bag Assembly				11829099
					NEXT HIGHER ASSEMBLY 11829114
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major					
101	Location of core bag assembly		100%	3.2	Gage
102	Distance from end base igniter to first tape		0.40%	3.2	Gage
103	Seam improper		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.7	Base Igniter Assembly		11829114
			NEXT HIGHER ASSEMBLY 11829100

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major					
101	Diameter of seam circle		0.40%	3.2	Scale
102	Quilting missing or improper		0.40%	3.2	Visual/Manual
103	Quilting seam improper length		0.40%	3.2	Scale
Minor					
201	Marking on proper side		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.8	Base Igniter and Core Bag Loading Assembly		11829100
			NEXT HIGHER ASSEMBLY 11829102

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly incorrect or damaged to the extent that black powder can escape (Including any seams or openings incompletely stitched or broken stitching)		100%	3.2	Visual/Manual
Major					
101	Weight of black powder	1/	100%	3.2	4.5.1
102	Moisture content of black powder			3.3	4.5.3
103	Black powder column minimum distance from tape to inner stitching at trimmed end		0.40%	3.2	Visual
104	Tying strap improper, missing or insecure (applicable to semi-automated loading)		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:
1/ See 4.4.3.2

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil - Downloaded: 2026-01-25T04:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER 11829111
4.4.2.9	Cap		NEXT HIGHER ASSEMBLY 11829102

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major	None defined.				
Minor					
201	Length		0.65%	3.2	Scale
202	Thickness		0.65%	3.2	Gage

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9345159
4.4.2.10	Flex 10				NEXT HIGHER ASSEMBLY 11829102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor 201	Maximum diameter		0.65%	3.2	Gage

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil - Downloaded: 2026-02-26T04:13Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829102
4.4.2.11	Base Igniter and Tube Assembly				NEXT HIGHER ASSEMBLY 11829094
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Base igniter and core bag loading assembly damaged or improper		100%	3.2	Visual
Major					
101	Base igniter and core bag loading assembly improperly tied to tube, i.e., tie missing, loose or incorrect (note a) (excluding length of ties after tying)		100%	3.2	Visual
102	Base igniter and tube assembly weight		100%	3.4.3	4.5.9
103	Tube closure missing or insecure		100%	3.2	Visual/Manual
104	Closure overlap (if applicable)		100%	3.2	Gage
Minor					
201	Core bag twisted or folded in tube (to be checked prior to assembly of cap to tube)		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: a. Looseness will be allowed during teardown provided there is evidence the knot was tied.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829096
4.4.2.12	Increment 8, Body				NEXT HIGHER ASSEMBLY 11829093
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major 101	Cloth improper			3.1	4.5.5
Minor 201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil-Downloaded: 2024-10-07T07:06Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829109
4.4.2.13	End, Increment 8				NEXT HIGHER ASSEMBLY 11829108
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Established length		0.65%	3.2	Scale
202	Established width of straight section		0.65%	3.2	Scale

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829108
4.4.2.14	End Assembly, Increment 8				NEXT HIGHER ASSEMBLY 11829093
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major 101	Seam improper		0.40%	3.2	Visual/Manual
Minor 201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA-D(T) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil - Downloaded: 2025-10-07T08:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.15	Increment 8, Body Assembly	1	1	11829093
				NEXT HIGHER ASSEMBLY: 11829094

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major					
101	End assembly improperly assembled to body, increment 8		0.40%	3.2	Visual
102	Any seam improper		0.40%	3.2	Visual/Manual
103	Tying strap improper, missing, or insecure (applicable to manual loading)		0.40%	3.2	Visual/Manual
Minor	None defined.				

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829094
4.4.2.16	Increment 8 Loading Assembly (Manual Loading Operation Only)				NEXT HIGHER ASSEMBLY 11829092
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Base igniter and tube assembly improperly assembled to body assembly		100%	3.2	Visual/Manual
102	Base igniter and tube assembly improper or damaged (including condition of tube immediately prior to insertion into body and end assembly)		100%	3.2/3.8	Visual/Manual
103	Propellant weight			3.4.1	4.5.2
104	Seams improper		100%	3.2	Visual
Minor					
201	Material outside seams after loading		0.65%	3.2	Scale
202	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26 04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.17	Increment 8 Loading Assembly(Semi-Automated Loading Operation Only)				11829094
					NEXT HIGHER ASSEMBLY 11829092
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Clip or clamp removed from closure prior to sewing operation (if applicable)		100%	3.2	Visual
102	Seams improper		100%	3.2	Visual
103	Propellant weight		100%	3.4.1	4.5.2 Semi-Automated
104	Base igniter and tube assembly improperly assembled to body assembly		100%	3.2	Visual/Manual
105	Base igniter and tube assembly improper on damaged (including condition of tube immediately prior to insertion into Increment 8 assembly)		100%	3.2/3.8	Visual/Manual
Minor					
201	Material outside seams after loading		0.65%	3.2	Scale
202	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	Increment 9 Body				11829105
					NEXT HIGHER ASSEMBLY
					11829103
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829112
4.4.2.19	End, Increment 9				NEXT HIGHER ASSEMBLY 11829113
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Cloth improper			3.1	4.5.5
Minor 201	Established Length		0.65%	3.2	Scale
202	Established width of Straight Section		0.65%	3.11	Scale

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829113
4.4.2.20	Increment 9 End Assembly				NEXT HIGHER ASSEMBLY 11829103
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Seam improper		0.40%	3.2	Visual/Manual
Minor 201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829103
4.4.2.21	Increment 9 Assembly				NEXT HIGHER ASSEMBLY 11829104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Increment 9 end assembly improperly assembled to body		0.40%	3.2	Visual
102	Any seam improper		0.40%	3.2	Visual/Manual
103	Liner assembly improper, improperly assembled, or missing		0.40%	3.2	Visual/Scale
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.22	Increment 9 Loading Assembly (Manual Loading Operation Only)				11829104
					NEXT HIGHER ASSEMBLY 11829092
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Propellant weight			3.4.1	4.5.2
102	Seam improper		100%	3.2	Visual
Minor					
201	Material outside seams after loading		0.65%	3.2	Scale
202	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829104
4.4.2.23	Increment 9 Loading Assembly (Semi-Automated Loading Operation Only)				NEXT HIGHER ASSEMBLY 11829092
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Propellant weight		100%	3.4.1	4.5.2 Semi-Automated
102	Seam improper		100%	3.2	Visual
103	Clip or clamp removed from closure prior to sewing operation (if applicable)		100%	3.2	Visual
Minor					
201	Material outside seams after loading		0.65%	3.2	Scale
202	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 11829095
4.4.2.24	Jacket, Lacing				NEXT HIGHER ASSEMBLY 11829092
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
102	Lacing cord missing or improperly assembled (2 locations)		0.40%	3.2	Visual/Manual
103	Lead location (when sewn into jacket)		0.40%	3.2	Visual
Minor					
201	Marking missing, misleading or unidentifiable		0.65%	3.2	Visual
202	Any seam improper or incompletely stitched		0.65%	3.2	Visual/Manual
203	Location of first punched hole		0.65%	3.2	Scale
204	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.25	Charge, Propelling, 8 Inch M188A1 for 8 Inch Howitzer, SP, M110A2 (Manual Loading Operation Only)	1 OF 2	11829092
			NEXT HIGHER ASSEMBLY: --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly damaged or improper to the extent that black powder can escape		100%	3.2	Visual/Manual
2	Black powder missing in basepad		100%	3.2	Manual
	Proving Ground				
3	Pressure (see 6.14)	1/		3.6	4.5.6
Major					
101	Basepad not in true position with respect to outer diameter of charge (to be determined after straps are securely tied and charge is laced)		100%	3.2	Gage
102	Dimensional gage failure		100%	3.5.1	Gage
103	Lacing missing, improper or insecure		100%	3.2	Visual/Manual
104	Igniter protector cap missing or improperly attached		0.40%	3.2	Visual
105	Propelling charge assembly weight		100%	3.4.1	4.5.8
106	Assembly damaged to the extent that propellant can escape (includes any seams or openings incompletely stitched and broken stitches)		100%	3.2	Visual
107	Any component missing, improper, or improperly assembled (including lead sheet when assembled separately)		100%	3.2	Visual

NOTES:
1/ Samples tested for Muzzle Velocity and Muzzle Velocity Standard Deviation and Differential Pressure will be monitored for pressure.

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.25	Charge, Propelling, 8 Inch M188A1 for 8 Inch Howitzer, SP, M110A2 (Manual Loading Operation Only) (Continuation sheet)	2 OF 2	11829092
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
108	Straps loose, broken or insecurely tied		0.40%	3.2	Visual/Manual
109	Condition of igniter tube protruding from Increment 8, prior to assembly of Increment 9		100%	3.8	Visual
110	Dimensional Gage Failure		0.40%	3.5.2	Gage
111	Weight of lead sheet		100%	3.2	Gage
	Proving Ground				
112	Muzzle velocity and muzzle velocity standard deviation (Zone 8)	2/		3.6	4.5.6
113	Muzzle velocity and muzzle velocity standard deviation (Zone 9)	15		3.6	4.5.6
114	Differential pressure	3/		3.6	4.5.6
Minor					
201	Location of lacing jacket		0.65%	3.2	Visual
202	Evidence of poor workmanship (see 6.18)		0.65%	3.11	Visual

NOTES: 2/ Fifteen samples from each lot until three consecutive lots have passed this inspection. Test may be reinstated by Contracting Officer if there is any material or process change.
3/ Twenty samples from each lot for the first three lots and then every fifth lot thereafter.

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.26	Charge, Propelling, 8 Inch M188A1 for 8 Inch Howitzer, SP, M110A2 (Semi-Automated Loading Operation Only)	1 OF 2	11829092
			NEXT HIGHER ASSEMBLY --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly damaged or improper to the extent that black powder can escape		100%	3.2	Visual/Manual
2	Black powder missing in basepad		100%	3.2	Manual
	Proving Ground				
3	Pressure (see 6.14)	1/		3.6	4.5.6
Major					
101	Basepad not in true position with respect to outer diameter of charge (to be determined after straps are securely tied and charge is laced)		100%	3.2	Gage
102	Dimensional gage failure		100%	3.5.1	Gage
103	Lacing missing, improper or insecure		100%	3.2	Visual/Manual
104	Igniter protector cap missing or improperly attached		0.40%	3.2	Visual/Manual
105	Propelling charge assembly weight		100%	3.4.1	4.5.8
106	Assembly damaged to the extent that propellant can escape (includes any seams or openings incompletely stitched and broken stitches)		100%	3.2	Visual
107	Any component missing, improper, or improperly assembled (including lead sheet when assembled separately)		100%	3.2	Visual

NOTES: 1/ Samples tested for Muzzle Velocity and Muzzle Velocity Standard Deviation and Differential Pressure will be monitored for pressure.

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 2 OF 2	DRAWING NUMBER
4.4.2.26	Charge, Propelling, 8 Inch M188A1 for 8 Inch Howitzer, SP, M110A2 (Semi-Automated Loading Operation Only) (Continuation sheet)		11829092
			NEXT HIGHER ASSEMBLY --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
108	Straps loose, broken or insecurely tied		0.40%	3.2	Visual/Manual
109	Condition of igniter tube protruding from Increment 8, prior to assembly of Increment 9		100%	3.8	Visual
110	Dimensional gage failure		0.40%	3.5.2	Gage
111	Weight of lead sheet		100%	3.2	Gage
	Proving Ground				
112	Muzzle velocity and muzzle velocity standard deviation (Zone 8)	2/		3.6	4.5.6
113	Muzzle velocity and muzzle velocity standard deviation (Zone 9)	15		3.6	4.5.6
114	Differential pressure	3/		3.6	4.5.6
Minor					
201	Location of lacing jacket		0.65%	3.2	Visual
202	Evidence of poor workmanship (see 6.18)		0.65%	3.11	Visual

NOTES: 2/ Fifteen samples from each lot until three consecutive lots have passed this inspection. Test may be reinstated by Contracting Officer if there is any material or process change.
3/ Twenty samples from each lot for the first three lots and then every fifth lot thereafter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26 10:47:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331255
4.4.2.27	Charge, Prior to Insertion Into Container				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Charge not tightly wrapped immediately prior to insertion into container (i.e., all charge full diameter points should be in contact with the wrapper)		0.40%	3.2	Visual/Manual
Minor	None defined				

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331255
4.4.2.28	Container, Prior to Insertion of Charge				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Foreign matter or rust in container		0.40%	3.2	Visual
102	Bottom cushion missing		100%	3.2	Visual
Minor					
201	Damaged container (to include dents protruding greater than 1/4 inch into container)		0.65%	3.2	Visual/Gage (see 6.4)

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.29	Container, Prior to Sealing		9331255
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Long filler or wrapper above top of charge (except for one allowable torn filler)		100%	3.2	Visual
102	Charge diametrically loose to the extent that a long filler may be completely inserted		100%	3.2	Manual
103	Any filler (if required) or top cushion missing or improper		100%	3.2	Visual
104	Dimension "X", minimum. (In lieu of measuring Dimension "X", the measurement of Dimension "Y" maximum may be taken)		100%	3.2	Gage
105	Filler inserted in container prior to inserting top cushion		0.40%	3.2	Visual
106	More than five long fillers present		0.40%	3.2	Visual
107	Overlap of one long filler with another at top of charge		0.40%	3.2	Visual
108	Charge cannot be removed by hand	1/		3.2	4.5.10
Minor					
201	None defined				

NOTES: 1/ One sample from each eight (8) hours production.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.30	Container, Sealed				9331255
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Test plug missing		100%	3.2	Visual
102	DOD symbol missing, misleading or unidentifiable (if applicable)		0.40%	3.2	visual
103	Test plug assembly torque		0.40%	3.9	Test (see 6.11)
104	Air pressure test		100%	3.2	4.5.4
Minor					
201	Test plug not greased (to be checked after air pressure test and prior to reassembly)		0.65%	3.2	Visual
202	Metallic seal missing or incorrectly applied		0.65%	3.2	Visual
203	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
204	Cover incompletely engaged		0.65%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63342B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.31	Containerized Charge				9331255
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
NOTE a/	Tear down Inspection	1/		2/	4.5.7 3/

NOTES:

a/ Category is critical or major dependent upon category of the defect inspected.
1/ See 4.4.3.1.
2/ Requirement paragraph is dependent upon inspection performed.
3/ Allowance will be made for stretching of cloth when measuring dimensions that apply prior to loading or assembling. The allowance shall not exceed twice the original tolerance of one-half the minimum dimensions.

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4.3 Testing

4.4.3.1 Teardown inspection

4.4.3.1.1 Initial production lot sampling. (MANUAL LOADING OPERATION ONLY) In addition to the samples of 4.4.3.1.3, three completely assembled charges shall be randomly selected from each days production until three consecutive days production is found acceptable.

4.4.3.1.2 Initial production lot sampling. (SEMI-AUTOMATED LOADING OPERATION ONLY) In addition to the samples of 4.4.3.1.3, ten completely assembled charges shall be randomly selected from each 8 hours of production until three consecutive 8 hours of production are found acceptable. (Three samples in lieu of ten samples after initial prove-out is completed, or if there is a lapse in production in excess of ninety (90) days).

4.4.3.1.3 Lot sampling. One completely assembled charge shall be randomly selected from each eight hour shift for each assembly line. The number of samples per lot shall not exceed twenty. If there is a lapse in production in excess of ninety (90) days, or the previous lot was waived or rejected due to this inspection, sampling will return to initial production lot sampling.

4.4.3.2 Moisture content of black powder. At least one sample of black powder from each eight hours loading of base igniter assemblies will be tested for moisture content.

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the "Paragraph Reference/Inspection Method" column in the tables starting with 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 of this specification.

4.5 Methods of inspection.

4.5.1 Weight of black powder in base igniter and core bag loading assembly. The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. The weight of black powder in the base igniter and core bag will be inspected 100 percent. The weight of black

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

powder in the basepad will be determined by subtracting an average weight of the empty assembly or the actual weight as marked on the individual assembly from the loaded basepad, empty core bag assembly weight. The weight of the black powder in the core bag will be determined by subtracting the average or actual weight of the loaded basepad, empty core bag assembly from the loaded base igniter and core bag assembly weight. Any assembly which fails to comply with the applicable requirement shall be classed defective and removed from the lot. Inspection equipment shall be in accordance with 4.4.4.

4.5.2 Propellant weight (see 3.4). The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. Any increment which fails to comply with the applicable requirement shall be classed defective and removed from the lot. Inspection equipment shall be in accordance with 4.4.4.

4.5.2.1 Method 1. (MANUAL LOADING OPERATION ONLY) The loaded increment will be inspected 100 percent. The weight of the propellent will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.2.2 Method 2. (MANUAL LOADING OPERATION ONLY) The weight of the propellant will be inspected 100 percent prior to loading the increment on a different balance. In addition, the propellant weight of the loaded increment will be inspected using a sampling plan from MIL-STD-105 or MIL-STD-1235 with an AQL of 0.40 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.2.3 Method 3. (SEMI-AUTOMATED LOADING OPERATION ONLY) The loaded increment with mandrel will be inspected 100 percent. The weight of the propellant will be determined by subtracting an average/actual weight of the empty increment bag and the calibrated weights of the mandrel.

4.5.3 Moisture content of black powder. The moisture content of the black powder will be determined in accordance with MIL-P-223. If any sample fails to meet the specified requirement, the eight hours production represented by the sample shall be rejected.

4.5.4 Air pressure test. Each container shall be tested as specified on the appropriate drawing. A pressure drop equivalent to or greater than the applicable requirement shall be cause for rejection and removal from the lot.

Source: https://assist.dla.mil -- Downloaded: 20261O-26T04:26Z
Check the source to verify that this is the currentversion before use.

4.5.5 Cloth. At the time cloth is introduced to the sewing or cutting operation, an identification will be made for each roll to verify that proper material is used. Any cloth failing to be identified as proper material in accordance with applicable drawings and specifications shall be removed from the lot.

4.5.6 Proving ground. This test shall be conducted at a Government Proving Ground in accordance with the applicable acceptance test procedure using M106, HE projectiles inert loaded within 0.1 pound of an as fired weight of 200.0 pounds using Primer, M82 and fired in cannon M201A1 with 50 percent (minimum) remaining life. Firing shall be conducted with a spindle to charge base stand-off of 1 inch (plus or minus 1/4 inch). Prior to firing, all charges shall be temperature conditioned in a large conditioning box with adequate air circulation at the required temperature for a minimum of 24 hours and assurance will be made that, when fired, the charges are at the conditioning temperature. The following tolerances shall apply to all -50°F, 145°F and 70°F conditioning: -50°F from -50°F to -45°F; 145°F from 140°F to 145°F; 70°F from 68°F to 72°F. Copper crusher gages (2) shall be used to measure the maximum chamber pressure of each charge. Velocity coils will be used to measure the muzzle velocity of each charge. Temperature indicator (thermometer) strips shall be placed on the side (lacing jacket) of all charges or on the side of the metal containers, as applicable, conditioned at 145°F as a further assurance of the proper conditioning temperature. If any indicator strip shows the charge has been exposed to a temperature greater than 145°F, that charge will not be fired.

4.5.6.1 Muzzle-velocity and muzzle velocity standard deviation. Determination of acceptance will be in accordance with MIL-STD-414, Section B, Table B3, AQL of 0.65%. All muzzle velocity and muzzle velocity standard deviation samples will be ballistic tested at 70°F. Fifteen (15) charges will be fired for muzzle velocity and muzzle velocity standard deviation. If the sample is determined unacceptable the lot will be rejected. In addition, if the velocity standard deviation of the sample multiplied by the factor 0.76 exceeds the applicable lot requirement, the lot shall be rejected. Fifteen (15) calibration charges will be fired alternately with the test samples and the muzzle velocity and pressure of all the test charges will be corrected to standard conditions.

4.5.6.2 Pressure. If at 70°F any propelling charge individual corrected maximum pressure exceeds the applicable requirement, the lot shall be referred. (See 3.6)

4.5.6.3 Differential pressure. Two pressure-time gages at different locations (one in the spindle and one at the projectile base) will be used to record pressure-time traces. Differential

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

pressure traces will be obtained by subtracting the projectile gage output from the spindle gage output. The maximum differential pressure of any charge will be defined as the maximum amplitude of the first negative wave of the differential pressure trace prior to peak pressure. Any trace which contains no amplitude in the negative direction will be considered to have a maximum differential pressure of zero. Any sample failing to meet the differential pressure requirements shall be cause for the lot to be referred (see 3.6.1). Ignition delay will be recorded on all differential pressure firings. Ten (10) charges will be conditioned to 145°F and ten (10) charges will be conditioned to -50°F for differential pressure firings. Ten (10) calibration charges will be fired intermixed (five (5) at each temperature) with the test samples and the muzzle velocity and pressure of all test charges corrected to standard conditions.

4.5.6.4 Safety phase test. (SEMI-AUTOMATED LOADING OPERATION ONLY) (Part of First Article Inspection) (See Table III and 6.20). (For first production lot only).

4.5.6.4.1 Pretest inspection. (SEMI-AUTOMATED LOADING OPERATION ONLY) Each container shall be serialized and inspected for possible damage. Only the 40 containers used for the Hot Cycle and Cold soak tests shall be disassembled for inspection of the charge assemblies. These charges shall be weighed and the length and diameter measured. The measurements shall be compared to the applicable drawings and all data will be recorded per the container/charge serial number. All charges will be repackaged as near as possible to their original condition.

4.5.6.4.2 Transportation - vibration. (SEMI-AUTOMATED LOADING OPERATION ONLY) Testing shall be performed in accordance with Table III, using guidance given in (Test Operation Procedure) TOP 1-2-601. Unvibrated charges are to be fired, ten (10) at -60°F and ten (10) at 145°F to establish base-line data on muzzle velocity, chamber pressure-versus-time, range or target dispersion, as applicable (see 4.5.6 and TOP 4-2-504). Twenty (20) charges will be vibration tested at 145°F and twenty (20) charges at -60°F. Vibration tests will be conducted in two axis-one with the charge lying on its side and the other in the vertical orientation, with each test period 84 minutes long. Vibration tests of ammunition are most conveniently performed with an up and down motion of the table.

NOTE: Tie down strapping shall not be applied directly to container surface.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE III. Safety phase first article inspection
(AUTOMATED LOADING OPERATION ONLY)

Phase	No. of Rd	Components Proj	Components Fuze	Charge	Prefiring Test (a) Charge	Prefiring Test Temp °F	Temp of Prop (b) °F	Chamber Press PS/100
1	10	M106	M557	M188A1	None	-	-60	Resultant
2	10	M106	M557	M188A1	None	-	+145	Resultant
3	20	M106	M557	M188A1	T-V	+145	+145	Resultant
4	20	M106	M557	M188A1	Hot Cycle	+93 to +155	+145	Resultant
5	20	M106	M557	M188A1	T-V	-60	-60	Resultant
6	20	M106	M557	M188A1	Cold Soak	-60	-60	Resultant
7	35	M106	M557	M188A1	Rough Handling	+145	+145	Resultant
8	35	M106	M557	M188A1	Rough Handling	-60	-60	Resultant
	170							

a. All charges are measured and inspected prior to testing in accordance with MTP 4-2-504.
b. Propelling charge assembly temperature, remaining components fired at ambient temperature.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

The charges should be considered "equipment transported as secured cargo". The cycling test should be 5-200-5 herz, acceleration level of 3.5 g (AX Curve), sweep time of 12 minutes and a sinusoidal cycling for 84 minutes per axis. Next the charges and shipping containers must be inspected for damage. Then repacked and conditioned to the firing temperature of 145°F and -60°F (see 4.5.6). The charges are fired from the same weapon and the same firing data obtained as from the non-vibrated ones.

4.5.6.4.3 Hot cycle. (SEMI-AUTOMATED LOADING OPERATION ONLY) Testing shall be performed in accordance with Table III, using guidance given in TOP 4-2-820. Twenty (20) Propelling Charges will undergo low humidity-high temperature cycle tests. Each propelling charge will be placed in the test chamber and subjected to seven 24 hour cycles (168 hours) as outlined below:

No. of Hours		Temperature at °F (°C)	Relative Humidity, %
6	maintain at	93 ± 3 (34 ± 2)	and 10 to 15
6	increase	93 to 155 (34 to 68)	decrease to under
4	maintain at	155 + 0 - 5 (68 + 0 - 3)	and under 5
8	decrease	155 to 93 (68 to 34)	increase 10 to 15

At the completion of the seven test cycles maintain the propelling charges at 93°F and 15% relative humidity for inspection. Record any evidence of material deterioration or drying out. Next the charges should be repacked and conditioned to the firing temperature of 145°F (see 4.5.6). The charges are then test fired from the same weapon as used in the other tests.

4.5.6.4.4 Cold soak. (SEMI-AUTOMATED LOADING OPERATION ONLY) Testing shall be performed in accordance with Table III using guidance given in TOP 4-2-504, twenty (20) propelling charges must be placed in a conditioning chamber at -60°F for 72 hours. At the completion of the test the charges should be unpacked and inspected for any evidence of material deterioration. Next the charges should be repacked and conditioned to -60°F (see 4.5.6). The charges are next test fired from the same weapon as used in the other tests.

4.5.6.4.5 Sequential rough handling. (SEMI-AUTOMATED LOADING OPERATION ONLY) Testing shall be performed in accordance with Table III and Top 4-2-602. Thirty-five (35) propelling charges must first be conditioned at 145°F and thirty-five (35) propelling charges at -60°F. Sequential testing will consist of the seven foot packaged drop test, loose cargo test and five foot unpackaged drop test. The charges will be conditioned to the firing temperature of 145°F (35 charges) and -60°F (35 charges) (see 4.5.6). The charges are then test fired from the same weapon as used in the other tests.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.6.4.6 Required data. (SEMI-AUTOMATED LOADING OPERATION ONLY) The following data must be recorded for all charges:

a. All the normal round-by-round data required by TOP 4-2-504.
b. Peak chamber pressure.
c. Time-pressure traces.
d. Muzzle velocity.
e. A description of smoke, flash, blast, and any residue deposited in or near the weapon based on visual or actual observations with photographs and measurements of significant excesses in any of these characteristics.
f. High speed photographs of the projectiles in flight near the muzzle.
g. Periodic pullover gage measurements of the tube.
h. A description of any adverse effects of firing (on the weapon).
i. A detailed description of any actual or potential safety problem.
j. A description of each charge after being subjected to the individual environments, with photographs of significant damage or deterioration.
k. Condition of the packaging and the charges after the drop test. Photographs should be taken of damaged components.

4.5.7 Teardown inspection. Each container and propelling charge will be subjected to each of the critical (except critical defect 3, 4.4.2.25 and 4.4.2.26) and 100 percent major (except major defect 101, 4.4.2.8; major defect 102, 4.4.2.11; major defect 103, 4.4.2.16 and 4.4.2.17; major defect 101, 4.4.2.22 and 4.4.2.23; major defects 101, 105 and 111, 4.4.2.25 and 4.4.2.26; major defect 104, 4.4.2.29) inspections defined in 4.4.2 of this specification. Samples may be accumulated or inspected upon selection providing the selection remains random and represents the lot. The inspections will be performed by the contractor and witnessed by the Government. The detection of any one of the above defects shall be cause for rejection of the lot represented by the sample.

4.5.8 Charge, propelling, assembly weight. The average or actual weight of the assembled base igniter and tube assembly, plus average or actual weight of the empty increment assemblies plus the average or actual weights of the lacing cords, lead sheet and jacket together with the nominal propellant weights as specified in the loading authorization shall be subtracted from the assembled charge, propelling assembly weight. If the resulting weight deviation is greater than the requirement, the propelling charge will be classified defective and removed from the lot (see 6.9).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.9 Base igniter and tube assembly weight.

4.5.9.1 Method 1. The actual weight of the tube along with the average weight of the empty base igniter assembly or the actual weight as marked on the individual empty base igniter assembly shall be recorded for each base igniter and tube assembly. These weights along with the nominal weights of black powder and average weight of the tube closure shall be subtracted from the assembled base igniter and tube assembly weight. If the resulting weight deviation is greater than the requirement, the base igniter and tube assembly will be classified defective and removed from the lot (see 6.10.1).

4.5.9.2 Method 2. The average weight of the empty base igniter assembly or the actual weight as marked on the individual empty base igniter assembly shall be recorded for each base igniter and tube assembly. These weights along with the average weight of the tube closure and the nominal weights of the tube and black powder shall be subtracted from the assembled base igniter and tube assembly weight. If the resulting weight deviation is greater than the requirement, the base igniter and the tube assembly will be classified defective and removed from the lot (see 6.10.2).

4.5.10 Charge removal from container. Each sample shall be tested for removal of the propelling charge from the container by hand. The charge may be pulled out by the tying straps or the container may be inverted and the charge either pulled out or slid out. Each charge tested shall be checked for damage to the tying straps (looseness, tears, etc.) and the charge will be repaired (retie and tying straps and relace the charge, if necessary). Each charge tested shall be rewrapped (may use the same wrapper if the wrapper is not badly damaged) and re-packed in accordance with this specification and the applicable drawings. Any charge that cannot be removed from the container using the above method shall be cause for rejection of the production represented by the sample.

4.5.11 Complete igniter alignment. Each complete igniter assembly shall be assembled to the increment assembly utilizing an approved method of assuring alignment between the igniter tube and the outer diameter of the increment assembly. The method to be used during production is to be established by the contractor and approved by the Government (see 6.17).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

5. PACKAGING

5.1 Packing.

5.1.1 Level A. The propelling charges shall be packed, sealed and tested in accordance with the specified requirements of Dwg. 9331255.

5.1.2 Level B. Same as specified in . 5.1.1.

5.1.3 Level C. Same as specified in . 5.1.1.

5.2. Marking

5.2.1 Level A, B, & C. Mark in accordance with Dwg. 9331255.

6. NOTES

6.1 Intended use. The propelling charges covered by this specification are intended for use in M201A1 cannon.

6.2 Ordering data. See MIL-A-48078. In addition, contracts should specify MIL-Q-9858 as the applicable high level contract quality control requirement.

6.3 Submission of designs for approval. See 6.2.3 of MIL-A-48078. Submit equipment designs, as required, to Commander, ARDEC, ATTN: AMSMC-QAR-I(D), Picatinny Arsenal, New Jersey 07806-5000. This address will be specified on the Contract Data Requirements List, DD Form 1423 in the Contract. Unless otherwise specified, data item DI-R-1714 will apply.

6.4 Visual examination qualification. When compliance with the applicable requirement is in doubt as a result of visual examination the characteristic may be measured or gaged to determine acceptability.

6.5 Inspection lot size. It is noted that the size of inspection lots of components, assemblies, or items of delivery may differ from the actual quantities contractually scheduled for delivery. However, in order to facilitate scheduling of tests or deliveries, inspection lots of items of delivery may be equivalent to such contract quantities provided all of the lot formation criteria and sampling provisions of this specification are maintained.

6.6 Proving ground. A copy of all proving ground data should be submitted to Commander, ARDEC, ATTN: AMSMC-QAR-R(D) and SMCAR-AEE-BP, Picatinny Arsenal, N.J. 07806-5000.

6.7 Teardown inspection. A list of all defects found during teardown inspection shall be submitted to Commander, ARDEC, ATTN: AMSMC-QAR-R(D) and SMCAR-AEE-BP, Picatinny Arsenal, New Jersey 07806-5000.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

6.8 Charge, propelling assembly weight and base igniter and tube assembly weight. This requirement applies to the load plant at the time of loading only. Due to subsequent change in weight of the components because of variation in material and moisture content, this test cannot be repeated after initial manufacture to the degree of accuracy required.

6.9 Charge, propelling, assembly weight.

Weights to be determined	Assembly drawing number
Average/Actual Weight of Base Igniter and Tube Assembly	11829102
Average/Actual Weight of Lead Sheet	11829092
Average/Actual Weight of Increment 8 Body Assembly	11829093
Average/Actual Weight of Increment 9 Assembly	11829103
Average Weight of Lacing Cord	11829092
Average Weight of Lacing Jacket	11829095
Propellant Weight	Loading authorization
Component Weight (sum of above weights)	

The propelling charge assembly weight minus the component weight equals the "Weight Deviation".

6.10 Base igniter and tube assembly weight.

6.10.1 Method 1

Weights To be Determined	Assembly Drawing Number
Actual Weight of Tube	11829101
Average/Actual Weight of Base Igniter Assembly	11829114
Average Weight of Tube Closure	11829111/9345159
Nominal Weight of Black Powder	11829100
Component Weight (sum of above weights)	

The base igniter and the tube assembly weight minus the component weight equals the "Weight Deviation".

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

6.10.2 Method 2

Weights To be Determined	Assembly Drawing Number
Nominal Weight of Tube	MIL-I-48252
Average/Actual Weight of Base Igniter Assembly	11829114
Average Weight of Tube Closure	11829111/9345159
Nominal Weight of Black Powder	11829100
Component Weight (sum of above weights)	

The base igniter and tube assembly weights minus the component weight equals the "Weight Deviation".

6.11 Test plug assembly torque. This requirement applies to the load plant at the time of loading only. Due to creep of the mechanical properties of the test plug washer, this test cannot be repeated after initial manufacture.

6.12 Proving ground summary (See 4.5.6).

Test	Zone	Sample Size	Number of Ref Rounds	Velocity	Maximum Individual Pressure	Differential Pressure
70°F	8	15	15	*	INFO	NA
70°F	9	15	15	*	42,000	NA
145°F	9	10	5	INFO	48,000	**
-50°F	9	10	5	INFO	INFO	**

*See 4.5.6.1 and 3.6
**See 4.5.6.3 and 3.6.1

6.13 Differential pressure. If the differential pressure requires referral of the lot, the disposition of the lot shall be referred to AMCCOM, ATTN: AMSMC-QAM(R), Rock Island, Illinois 61299 with an info copy to ARDEC, ATTN: AMSMC-QAR-R(D) and SMCAR-AEE-BP, Picatinny Arsenal, New Jersey 07806-5000.

6.14 Individual maximum pressure. Individual Maximum Pressure specified in 3.6 is based on firing with an M106 Projectile loaded to an as fired weight of 200.0 lbs. Any change in weight or projectile will require an adjustment of this pressure requirement.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

6.15 Muzzle velocity and muzzle velocity standard deviation. This requirement is based on obtaining a nominal velocity of 2510 fps and a standard deviation of 6.0 fps with the M650 HE RA projectile family.

6.16 Data cards. A copy of all data cards should be submitted to Commander, ARDEC, ATTN: AMSMC-QAR-R(D) and SMCAR-AEE-BP, Picatinny Arsenal, New Jersey 07806-5000.

6.17 Method of assuring alignment submission. The method for assuring alignment of the complete igniter assembly shall be submitted to Commander, ARDEC, ATTN: AMSMC-QAR-R(D), Picatinny Arsenal, New Jersey 07806-5000, for approval.

6.18 Workmanship. Rips or tears in the eyelit area of the lacing jacket and stretching of cloth caused by lacing the charge is acceptable provided the lacing cord in the bead is not broken.

6.19 Temperature indicator strips. The highest temperature reading from each indicator strip shall be recorded for informational purposes and reported on the applicable firing record.

6.20 Safety phase test. (SEMI-AUTOMATED LOADING OPERATION ONLY) (See Table III and 4.5.6.4) Failure to pass this test means that the automated LAP line is not qualified.

6.21 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research Development and Engineering Center (ARDEC) may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal drawings. Technical data originally prepared by these activities is now under the cognizance of ARDEC.

6.22 Changes from previous issue. Asterisks are not used in this revision to identify changes with respect to the previous issue due to the extensiveness of the changes.

6.23 Subject term (key word) listing.

Artillery
Base Igniter
Howitzer
Propellant
Propelling Charge

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1320-A914)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-C-63342B	CHARGE, PROPELLING, 8 INCH, M188A1 LOADING, ASSEMBLING, AND PACKING

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ USER
	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

DD FORM 82 MAR 1426 PREVIOUS EDITION IS OBSOLETE.

(TO DETACH THIS FORM, CUT ALONG THIS LINE.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.