MILITARY SPECIFICATION

CHARGE, PROPELLING, 155MM, XM211 LOADING, ASSEMBLING AND PACKING

This specification is approved for use of US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing for one type of propelling charge designated as Charge, Propelling, XM211, for 155mm Howitzer, M198, M109A2/A3.

2. Applicable Documents

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposals form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078	-	Ammunition, Standard Quality Assurance Provisions, General specification for

STANDARDS

MILITARY

MIL-STD-105	-	Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-414	-	Sampling Procedures and Tables for Inspecton by Variables for Percent Defective
MIL-STD-1235	-	Single and Multilevel Continuous Sampling Procedures and Tables for Inspection by Attributes

FSC: 1320

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-04-26T04:26Z
Check the source to verify that this is the current version before use.

DRAWINGS

ARRADCOM

Product and Package Drawings

9331701 - Charge, Propelling, XM211 (Green Bag) for 155mm Howitzer M198, M109A2/A3.

9332424 - Packing and Marking for Container, Ammo, Metal: PA86 for Charge, Propelling 155mm, XM211 (Green Bag) for Howitzer M198, M109A2/A3.

3. Requirement

3.1 Materials - Materials shall be in accordance with applicable drawings and specifications.

3.2 Propelling Charge - The propelling charge shall comply with all requirements specified in applicable drawings and specifications.

3.3 Weights

3.3.1 Weight Tolerance of Propellant - The charge increment weight shall comply with the weight specified in the loading authorization within the following tolerance:

Increment Number	Tolerance Plus or Minus (±) Ounces
3A	0.05
4	0.05
5	0.05
6	0.05

3.3.2 Charge, Propelling Assembly Weight - The charge propelling assembly weight shall not differ by more than 0.5 ounces from the total of the amount specified in the loading authorization plus the actual or average weight of empty increments plus the actual weight of retention device plus average weight of lacing cord and the nominal weights of CBI and potassium nitrate or sulfate (see 6.7).

3.4 Dimensional Gage - The completed propelling charge shall freely enter the prescribed gage. The gage shall be designed to inspect the maximum diameter and length. If the diameter feature is spearate from the length feature, the diameter feature must extend approximately the full length of the charge.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.5 Workmanship - All components shall be free of dirt, grease and other foreign material. There shall be no discoloration or deterioration of cloth and/or no evidece of rips, tears, or other cloth defects. All work performed shall be performed in a thoroughly workmanlike manner

3.6 Proving Ground (see 6.9)- The muzzle velocity, and standard deviation of the velocity shall be as specified in Table I.

TABLE 1

ZONE	TEMPERATURE	VELOCITY (ft per sec) Minimum	Maximum	Vel (fps) Standard Deviation	Individual Max Pressure (psi)
3	70°F	960	1000	4.0	-
6	70°F	1955	2005	6.5	38,000
6	145°F	(Diff Press)		-	40,500
5	145°F	(Diff Press)		-	-

3.7 Assembly Torque - The test plug shall be assembled to withstand subsequent reapplication of the minimum assembly torque specified on the applicable drawing, without moving.

3.8 Retention Device - All retention devices shall be free of cracks, dents, creases, tears and flat areas.

3.9 First Article Inspection - This specification contains technical provisions for First Article Inspection. Requirements for the submission of First Article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions - Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of Inspections - The following types of inspection shall be conducted on this item:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First Article Inspection

4.3.1 Submission - The contractor shall submit a First Article sample as designated by the contracting officer for evaluation in accordance with the provisions of 4.3.2. This sample shall consist of the following:

Description	Drawing	Quantity
Increment Loading Assembly	9331714	5 at each zone
Body and Lead Foil Assembly	9331753	5
Igniter and Flash Reduced Loading Assembly	9331707	5
Base Charge 3 Loading Assy	9331715	5
End, Increment	9331711	5
Flash Reducer End Assy	9331705	5
Cloth, Laminated (lead foil)	9331751	5
Igniter End Assembly	9331702	5
Body Increment	9331712	5
Strap, tying	9331710	5
Base and End Assembly	9331704	5
Charge, Propelling, XM211, (Green Bag) for 155mm How M198, M109A2/A3 (in sealed containers)	9331701	10
Increment Assembly	9331752	5
Base Assembly	9331708	5
Increment Assembly	9331713	5 at each zone

4.3.2 Inspections to be Performed - The First Article parts submitted in accordance with paragraph 4.3.1 will be subjected by the Government to any or all the requirements of the applicable drawings and specifications and to the inspections of Table II. All inspections listed in Table II shall be classified Major unless otherwise specified in referenced paragraphs and specifications.

4.3.3 Rejection - See MIL-A-48078.

4.4 Quality Conformance Inspection

4.4.1 Inspection Lot Formation - Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of propelling charge assemblies shall contain:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

a. Propellant from not more than one lot number from one manufacturer.

b. CBI from not more than one lot number from one manufacturer.

4.4.2. Examination - See MIL-A-48078.

a. Sampling plans - Unless otherwise specified in the Classification of Defects and Test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE II- FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
	Propelling Charge Components and Assemblies				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Body and Lead Foil Assembly (Dwg 9331753)	5		3.2	4.4.2.1
	Cloth, Laminated (Dwg 9331751)	5		3.2	4.4.2.2
	Body Increment (Dwg 9331712)	5		3.2	4.4.2.3
	Increment Loading Assembly (Dwg 9331714)	5		3.2	4.4.2.4
	Increment Assembly (Dwg 9331752)	5		3.2	4.4.2.5
	Increment Assembly (Dwg 9331713)	5		3.2	4.4.2.6
	End Incrment (Dwg 9331711)	5		3.2	4.4.2.7
	Base Charge 3 Loading Assembly (Dwg 9331715)	5		3.2	4.4.2.8
	Strap, Tying (Dwg 9331710)	5		3.2	4.4.2.9
	Base Assembly (Dwg 9331708)	5		3.2	4.4.2.10
	Base and End Assembly (Dwg 9331704)	5		3.2	4.4.2.11
	Flash Reducer End Assembly (Dwg 9331705)	5		3.2	4.4.2.13

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE II- FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
	CONTINUATION SHEET				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Igniter End Assembly (Dwg 9331702)	5		3.2	4.4.2.15
	Igniter and Flash Reducer Loading Assembly (Dwg 9331707)	5		3.2	4.4.2.17
	Charge, Propelling, XM211 (Green Bag) for 155MM, How M198, M109A2/A3 (in sealed container) (Dwg 9331701 and 9331262)	10		3.2	4.4.2.18/4.4.2.19/ 4.4.2.20/4.4.2.21/

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Body and Lead Foil Assembly		9331753
			NEXT HIGHER ASSEMBLY 9331752

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Body and lead foil improperly assembled		0.40%	3.2	visual
Minor 201	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331751
4.4.2.2	Cloth, Laminated				NEXT HIGHER ASSEMBLY 9331753
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Established length		0.40%	3.2	gage
102	Established width		0.40%	3.2	gage
Minor					
201	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALTIY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331712
4.4.2.3	Body Increment				NEXT HIGHER ASSEMBLY 9331713
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any seam incompletely stitched		0.40%	3.2	visual/manual
Minor					
201	Marking improper or missing if applicable		0.65%	3.2	visual
202	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALTIY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331714
4.4.2.4	Increment Loading Assembly				NEXT HIGHER ASSEMBLY 9331701
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Assembly damaged to the extent the propellant can escape including any seam or opening incompletely stitched and broken threads		100%	3.2	visual/manual
102	Weight of propellant		100%	3.3	see 4.5.1.1
Minor					
201	Evidence of poor workmanship (including increment assembly)		0.65%	3.5	visual
202	Marking missing misleading or unidentifiable (includes incorrect increment numbering)		0.40%	3.2	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	Increment Assembly		9331752
			NEXT HIGHER ASSEMBLY 9331714

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any components improperly assembled		0.40%	3.2	visual/manual
102	Any seam incompletely stitched		0.40%	3.2	visual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMACNE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331713
4.4.2.6	Increment Assembly				NEXT HIGHER ASSEMBLY 9331714
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any components improperly stitched		0.40%	3.2	visual
102	Any seam incompletely stitched		0.40%	3.2	visual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331711
4.4.2.7	End Incrment				NEXT HIGHER ASSEMBLY 9331752/9331713
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor 201	Diameter of end		0.65%	3.2	gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET		DRAWING NUMBER
4.4.2.8	Base Charge 3 Loading Assembly		1 OF 1		9331715
					NEXT HIGHER ASSEMBLY 9331714
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly damaged to the extent that CBI can escape		100%	3.2	visual/manual
2	Igniter assembly missing		100%	3.2	visual
Major					
101	Assembly damaged to the extent that propellant and/or potassium nitrate/sulfate can escape (including any seam or opening incompletely stitched or broken threads)		100%	3.2	visual/manual
102	Flash reducer assembly missing		100%	3.2	visual
103	Weight of propellant		100%	3.2	see 4.5.1.2
104	Increment 3A missing		100%	3.2	visual/manual
105	Retention device not properly positioned (including condition of retention device immediately prior to insertion into this assembly)		100%	3.2/3.8	visual/manual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	visual
202	Marking missing, misleading or unidentifiable (3 locations)		0.65%	3.2	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Strap, Tying				9331710
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Length		0.65%	3.2	gage
202	Width		0.65%	3.2	gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALTIY CONFORMACE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331708
4.4.2.10	Base Assembly				NEXT HIGHER ASSEMBLY 9331704
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Tying strap missing, insecure or improperly assembled (4 places)		0.40%	3.2	visual/mamual
Minor 201	Evidence of poor workmanship		0.65%	3.5	visual
202	Marking missing or improper		0.65%	3.2	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMACNE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.11	Base and End Assembly				9331704
					NEXT HIGHER ASSEMBLY
					9331707
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Any component incompletely assembled		0.40%	3.2	visual/manual
Minor 201	Evidence of poor workmanship		0.65%	3.2	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALTIY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331709
4.4.2.12	Base				NEXT HIGHER ASSEMBLY 9331708
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Cloth improper		0.40%	3.2	see 4.5.4
Minor 201	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMACE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 931705
4.4.2.13	Flash Reducer End Assembly				NEXT HIGHER ASSEMBLY 9331704
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper		0.40%	3.2	see 4.5.4
102	Diameter of inner seam		0.40%	3.2	gage
103	Any seam incompletely stitched		0.40%	3.2	visual/manual
Minor					
201	Marking missing, misleading or unidentifiable		0.65%	3.2	visual
202	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALTIY CONFORMACE ISNPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331706
4.4.2.14	End, Flash Reducer				NEXT HIGHER ASSEMBLY 9331705
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	cloth improper		0.40%	3.2	see 4.5.4
102	Diameter of flash reducer end		0.40%	3.2	gage
Minor					
201	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 20260-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.15	Ignition End Assembly				9331702
					NEXT HIGHER ASSEMBLY 9331704
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR /100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper		0.40%	3.2	se 4.5.4
102	Diameter of seam		0.40%	3.2	gage
103	Any seam incompletely stitched		0.40%	3.2	visual/manual
Minor					
201	Marking missing, misleading or unidentifiable		0.65%	3.2	visual
202	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331703
4.4.2.16	End, Igniter				NEXT HIGHER ASSEMBLY 9331702
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Diameter of end		0.65%	3.2	gage
202	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.17	Igniter and Flash Reducer Loading Assy				9331707
					NEXT HIGHER ASSEMBLY 9331715
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical 1	Assembly damaged to the extent that CBI can escape		100%	3.2	visual/manual
Major 101	Assembly damaged to the extent that potassium nitrate/sulfate can escape		100%	3.2	visual/manual
102	Weight of CBI		100%	3.2	4.5.2
103	Weight of potassium nitrate/sulfate		100%	3.2	scale
104	Any seam incompletely stitched		0.40%	3.2	visual
Minor 201	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9331701
4.4.2.18	Charge, Propelling, XM211 (Green Bag) for 155MM, How M198, M109A2/A3				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly damaged or improper to the extent that CBI can escape		100%	3.2	visual/manual
2	Proving Ground Pressure	(a)		3.6	4.5.5
Major					
101	Dimensional gage failure		100%	3.4	gage
102	Lacing missing, improper on insecure		100%	3.2	visual/manual
103	Propelling charge assembly weight		100%	3.3.2	4.5.6
104	Any component improperly assembled or missing		100%	3.2	visual

NOTES:

(a) Pressure sampling will consist of monitoring pressure on differential pressure and muzzle velocity standard deviation samples.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY OCNFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9331701
4.4.2.18	CONTINUATION SHEET				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Proving Ground				
105	Muzzle velocity and muzzle velocity standard deviation (zone 3)	15		3.6	4.5.5
106	Muzzle velocity and muzzle velocity standard deviation (zone 6)	15		3.6	4.5.5
107	Differential Pressure (INFO)				
	a. Zone 5	10			
	b. Zone 6	10		3.6	4.5.5
Minor					
201	Igniter protector cap missing or improperly stitched		0.65%	3.2	visual
202	Thread of excessive length (including loose threads clinging to the charge)		0.65%	3.2	visual
203	Straps loose, broken or insecurely tied		0.65%	3.2	visual/manual
204	Evidence of poor workmanship		0.65%	3.5	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE ISNPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9332424
4.4.2.19	Container, Prior to Insertion of Charge				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Foreign matter or rust in container		100%	3.2	visual
102	Bottom cushion missing		100%	3.2	visual
103	Charge not tightly wrapped immediately prior to insertion into container (i.e., all charge full diameter points shall be in contact with the wrapper)		0.40%	3.2	visual
Minor					
201	Damaged container (to include dents protruding greater than 1/4" into container)		0.65%	3.2	visual gage (see 6.4)

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMACNE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.20	Container, Prior to Sealing				9332424
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Wrapper or long filler above top of charge except for one allowable torn filler (to be inspected with charge in container)		100%	3.2	visual
102	Charge diametrically loose to the extent that a long filler may be inserted		100%	3.2	manual
103	Any component missing or imporper		100%	3.2	visual
104	Dimension "X", minimum (in lieu of missing dimension "X", the measurement of dimension "Y", maximum may be taken)		100%	3.2	gage
105	Filler inserted in container prior to inserting top cushion		0.40%	3.2	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALTIY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9332424
4.4.2.20	CONTINUATION SHEET				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
106	More than five long fillers present		0.40%	3.2	visual
107	Overlap of one long filler with another		0.40%	3.2	visual
108	Charge cannot be removed by hand	(a)		3.2	4.5.7
109	Top cushion incorrect type; i.e. cushion does not have hole		0.40%	3.2	visual
Minor	None defined				

NOTES: (a) One sample from eight (8) hours production

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63346 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.21	Container, Sealed				9332424
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Test plug missing		100%	3.2	visual
102	DOD symbol missing, misleading or unidentifiable (if applicable)		0.40%	3.2	visual
103	Test plug assembly torque		0.40%	3.8	test
104	Air pressure test		100%	3.2	4.5.3
Minor					
201	Test plug not greased (to be checked after air pressure test and prior to reassembly		0.65%	3.2	visual
202	Metallic seal missig or incorrectly applied		0.65%	3.2	visual
203	Marking missing. misleading, or unidentifiable		0.65%	3.2	visual
204	Cover incompletely engaged		0.65%	3.2	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4.3. Inspection Equipment - The inspection equipment required to perform the examinations and tests prescribed herein is described in the "Paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See section 6 of MIL-A-48078 and paragraph 6.3 of this specification.

4.5 Test Methods and Procedures

4.5.1 Propellant Weight (See 3.3) - The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. Any increment which fails to comply with the applicable requirement shall be classed defective and removed from the lot. Inspection equipment shall be in accordance with 4.4.3.

4.5.1.1 Type I Propellant

Method 1 - The loaded increments will be inspected 100 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

Method 2 - The weight of the propellant will be checkweighed 100 percent prior to loading the increment on a different balance. In addition, the propellant weight of the loaded increment will be inspected using a sampling plan from MIL-STD-105 or MIL-STD-1235 with an AQL of 0.40 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.1.2 Type II Propellant

Method 1 - The loaded increment will be inspected 100 percent. The weight of the propellant will be determined by substracting an average/actual weight of the empty increment bag including loaded flash reducer and igniter assemblies, plus retention device and loaded increment 3A from the loaded increment weight.

Method 2 - The weight of the propellant will be checkweighed 100 percent prior to loading the increment on a different balance. In addition, the propellant weight of the loaded increment will be inspected using a sampling plan from MIL-STD-105 or MIL-STD-1235 with an AQL of 0.40 percent. The weight of the propellant will be determined by subtracting an average/actual weight of the empty increment bag including loaded flash reducer and igniter assemblies, plus retention device and loaded increment 3A from the loaded increment weight.

4.5.2 Weight of CBI in Base Igniter Loading Assembly - The inspections below are to be conducted by insepction personnel using equipment designated for inspection purposes and shall be clearly distinguihed from production operations. The weight of the CBI will be inspected 100 percent. Any assembly which fails to comply with the applicable requirement shall be classed defective and removed from the lot.

Method 1 - The loaded assemblies will be inspected 100 percent. The weight of the CBI will be determined by subtracting an average weight of the empty assembly or the actual weight as marked on the individual assembly from the loaded assembly weight.

Method 2 - The weight of the CBI will be checkweighed 100 percent prior to loading the assembly on a different balance and if performed manually, by another operator (no CBI may be added or removed from the container during this operation). In addition, the CBI weight of the loaded assembly will be inspected using a sampling plan from MIL-STD-105 or MIL-STD-1235 with an AQL of 0.40 percent. The weight of the CBI will be determined by subtracting an average weight of the empty assembly or the actual weight as marked on the individual assembly from the loaded assembly weight.

4.5.3 Air Pressure Test - Each container shall be tested as specified on the appropriate drawing. A pressure drop equivalent to or greater than the applicale requirement shall be cause for rejection and removal from the lot.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the currentversion before use.

4.5.4 Cloth - At the time cloth is introduced to the sewing and/or cutting operation, an identification will be made for each roll to verify that proper material is used. Any cloth failing to be identified as proper material in accordance with applicable drawings shall be rejected from the lot.

4.5.5 Proving Ground (see 3.6 and 6.9 - This test shall be conducted at a Government Proving Ground in accordance with the applicable acceptance test procedure using M549, projectiles inert loaded within 0.1. pound of an as fired weight of 96.0 pounds using Primer, M82 and fired in cannon M199 or M185 with 95 percent (minimum) remaining life. Firing shall be conducted with a spindle to charge base stand-off of 1 inch (plus or minus 1/4 inch). Prior to firing, all charges shall be temperature conditioned in a large conditioning box with adequate air circulation at the required temperature for a minimum of 24 hours and assurance will be made that, when fired, the charges are at the conditioning temperature. The following tolerances shall apply to all 145°F and 70°F conditionings: 145°F from 140°F to 145°F; 70°F from 68°F to 72°F. Copper crusher gages (2) shall be used to measure the maximum chamber pressure of each charge. Velocity coils will be used to measure the muzzle velocity of each charge.

4.5.5.1 Muzzle Velocity and Muzzle Velocity Standard Deviation - Determination of acceptance will be in accordance with MIL-STD-414, Section B, Table B3, AQL of 0.65%. All muzzle velocity and muzzle velocity standard deviation samples will be ballistic tested at 70°F. Fifteen (15) charges at zone 6 and fifteen (15) at zone 3 will be fired for muzzle velocity and muzzle velocity standard deviation. If the sample is determined unacceptable, the lot will be rejected. In addition, if the velocity standard deviation of the sample multiplied by the factor 0.76 exceeds the applicable lot requirement, the lot shall be rejected. Calibrtion charges will be fired alternately (fifteen (15) at each zone) with the test samples and the muzzle velocity and pressure of all test charges will be corrected to standard conditions.

4.5.5.2 Differential pressure (Informational) - Two pressure-time gages at different locations (one in the spindle and one at the projectile base) will be used to record pressure-time traces. Differential pressure traces will be obtained by subtracting the projectile gage output from the spindle gage output. The maximum differential pressure of any charge will be defined as the maximum amplitude of the first

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

negative wave of the differential pressure trace prior to peak pressure. Any trace which contains no amplitude in the negative direction will be considered to have a differential pressure of zero. Ignition delay will be recorded on all differential pressure firings. Ten (10) charges at zone 6 and ten (10) charges at zone 5 will be conditioned to 145°F for differential pressure firings. Calibration charges will be fired intermixed (five (5) at each zone) with the test samples and the muzzle velocity and pressure of all test charges shall be corrected to standard conditions.

4.5.5.3 Pressure - If any propelling charge individual corrected maximum pressure exceeds the applicable requirement the lot shall be rejected.

4.5.6 Charge, Propelling, Assembly Weight - The nominal weights of CBI and Potassium Nitrate or Sulfate ,and average weights of increment assembly, plus average weight of base and end assembly, plus actual weight of retention device, plus average weight of lacing cord, together with the nominal propellant weights as specified in the loading authorization shall be subtracted from the assembled charge, propelling, assembly weight. If the resulting weight deviation is greater than the requirement, the propelling charge will be classified defective and removed from the lot (see 6.12).

4.5.7 Charge Removal From Container - Each sample shall be tested for removal of the propelling charge from the container by hand. The charge may be pulled out by the tying straps or the container may be inverted and the charge either pulled out or slid out. Each charge tested shall be checked for damage to the tying straps (looseness, tears, etc.) and the charge will be repaired (retie and tying straps and relace the charge, if necessary). Each chage tested shall be rewrapped (may use the same wrapper if the wrapper is not badly damaged) and re-packed in accordance with this specification and the applicable drawings. Any charge that cannot be removed from the container using the above method shall be cause for rejection of the production represented by the sample.

5. Packaging

5.1 Packing and Marking - The propelling charges shall be packed, sealed, tested, and marked in accordance with the specified requirements of drawing 9332424.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the currentversion before use.

6. NOTES

6.1 Intended Use - The propelling charges covered by this specification are intended for use in the 155mm Howitzer, XM198 and M109A2/A3.

6.2 Ordering Data - MIL-A-48078.

6.3 Submission of Designs for Approval - See 6.2.3 of MIL-A-48078. Submit equipment designs, as required, to Commander, US Army Armament Research and Development Command, Attn; DRDAR-QAR-I, Dover, NJ 07801.

6.4 Visual Examination Qualification - When compliance with the applicable requirement is in doubt as a result of visual examination the characteristic may be measured or gaged to determine acceptability.

6.5 Inspection Lot Size - It is noted that the size of inspection lots of components, assemblies, or items of delivery may differ from the actual quantities contractually scheduled for delivery. However, in order to facilitate scheduling of tests or deliveries, inspection lots of items of delivery may be equivalent to such contract quantities provided all of the lot formation criteria and sampling provisions of this specification are maintained.

6.6 Proving Ground - A copy of all proving ground data should be submitted to Commander, US Army Research and Devleopment Command, Attn; DRDAR-QAR-R and DRDAR-LCA-G, Dover, NJ 07801.

6.7 Charge, Propelling Assembly Weight - This requirement applies to the load plant at the time of loading only. Due to subsequent change in tare weight of the components because of variation in material and moisture content, this test cannot be repeated after initial manufacture to the degree of accuracy required.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

6.8 First Article Inspection Procedure - Sample propelling charges shall be submitted to: Commander, US Army Armament Research and Devleopment Command, ATTN: DRDAR-QAR, Dover, NJ 07801, upon implementation of this military specification for those items procured for the US Army.

6.9 Proving Ground Summary.

Temp	Zone	Sample Size	Number of Ref Rounds	Velocity	Maximum Individual Pressure (psi)	Differential Pressure
70°F	3	15	15	*	-	-
70°F	6	15	15	*	38,000	-
145°F	6	10	5	INFO	40,500	INFO
145°F	5	10	5	INFO	-	INFO

*See 4.5.5.1 and 3.6

6.10 Data Cards A copy of all data cards should be submitted to Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAR-R and DRDAR-LCA-G, Dover, NJ 07801.

6.11 Assembly Torque - The assembly torque of the test plug will apply at time of loading only due to the relaxation of the gasket material.

6.12 Charge, Propelling, Assembly Weight	Assembly Drawing No.
Nominal Weight of CBI	9331707
Nominal Weight of Flash Reducer	9331707
Average Weights of Increment Assembly	9331713
Average Weight of Increment Assembly	9331752
Average Weight of Base and End Assy	9331704
Actual Weight of Retention Device	see MIL-D-63417 (AR)
Average weight of Lacing Cord	9331701
Nominal Propellant Weight	Loading Authorization

Component Weight (sum of above weight)

The propelling charge assembly weight minus the component weight equals the "weight deviation".

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project Number: 1320-A484

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.

NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-C-63346 CHARGE, PROPELLING, 155MM, XM211 LAP

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*	TELEPHONE NO.
	DATE

DD FORM 1 OCT 76 1426 EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

FOLD

DEPARTMENT OF THE ARMY

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY CARD

FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.

POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
US Army Armament R & D Command
ATTN: DRDAR-QAR
Dover, New Jersey 07801

FOLD

Source: https://assist.dla.mil/ -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.