MILITARY SPECIFICATION

CHARGE PROOF, 155MM, PXR-6297 LOADING, ASSEMBLING AND PACKING

This specification is approved for use by US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing for one type of propelling charge designated as Charge, Proof, PXR-6297, for 155MM Cannon, M185 and M199.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposals form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-223	-Powder, Black
MIL-C-43157	-Cloth, Spun Viscose Rayon Resin Impregnated
MIL-A-48078	-Ammunition, Standard Quality Assurance Provisions, General Specification For

DRAWINGS

ARRADCOM

PRODUCT AND PACKAGE DRAWINGS

9331314	-Charge, Proof, 155MM, PXR-6297 for 155MM Cannon M185 and M199

FSC: 1320

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

9331355 -Packing and Marking for Container, Ammo, Metal: PA68 for Charge, Proof, 155MM, PXR-6297 for 155MM Cannon M185 and M199

3. REQUIREMENTS

3.1 Materials. Materials shall be in accordance with applicable drawings and specifications.

3.2 Propelling Charge.The propelling charge shall comply with all requirements specified in applicable drawings and specifications.

3.3 Moisture Content of Black Powder. The moisture content of the black powder at the loading station at the time of loading shall not exceed the amount specified in MIL-P-223.

3.4 Weights

3.4.1 Propellant Weight. The propellant weight shall comply with the weight specified in the loading authorization within plus or minus 0.25 ounce.

3.5 Dimensional Gages

3.5.1 Maximum Length and Diameter. The completed charge shall freely enter the prescribed gage. The gage shall be designed to inspect the maximum diameter and length. If the diameter feature is separate from the length feature, the diameter feature must extend approximately the full length of the charge.

3.6 Workmanship. All components shall be free of dirt, grease and other foreign material. There shall be no discoloration or deterioration of cloth and no evidence of rips, tears, or other cloth defects. All work performed shall be performed in a thorough workmanlike manner.

3.7 Proving Ground. Twenty propelling charges will be fired at 145°F for information.

3.8 Assembly Torque. The test plug shall be assembled to withstand subsequent re-application of the minimum assembly torque specified on the applicable drawing, without moving (See 6.18).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.9 Igniter Tubes. All tubes shall be free of cracks, dents, creases, tears, flat areas and softness greater than 0.25 inch.

3.10 Complete Igniter Alignment. An approved method of centering the complete igniter assembly in the increment assembly will be utilized for all charges.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Quality Conformance Inspection

4.2.1 Inspection Lot Formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of propelling charge assemblies shall contain:

a. Propellant from not more than one lot number from one manufacturer.

b. Black powder from not more than one lot number from one manufacturer.

c. Tubes from not more than one interfix number from one manufacturer.

4.2.2 Examination. See MIL-A-48078.

a. Sampling Plans. Unless otherwise specified in the Classification of Defects and Test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	Body				9331394
					NEXT HIGHER ASSEMBLY 9331391
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				(see 6.4)
Major					
101	Cloth improper			3.1	4.5.5.2
Minor					
201	Width (as established)	Note a	0.65%	3.2	Scale

NOTES: a. If a slitting machine is utilized, in lieu of the specified AQL, during the slitting process each roll will be inspected within the first 10 feet and the last 10 feet; i.e., two measurements per roll.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372

PARAGRAPH	TITLE	SHEET 1 OF 1			DRAWING NUMBER
4.4.2.2	Strap, Tying				9331395
					NEXT HIGHER ASSEMBLY
					9331391
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5.2
Minor					
201	Length		0.65%	3.2	Scale
202	Width	Note a	0.65%	3.2	Scale

NOTES:

a. If a slitting machine is utilized, in lieu of the specified AQL, during the slitting process each roll will be inspected within the first 10 feet and the last 10 feet; i.e., two measurements per roll.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INPSECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Bag, Igniter Core				9331398
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	9331399
					PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Width of cloth	Note a	0.40%	3.2	Scale
102	Cloth improper			3.1	4.5.5.1
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

a. If a slitting machine is utilized, in lieu of the specified AQL, during the slitting process each roll will be inspected within the first 10 feet and the last 10 feet; i.e., two measurements per roll.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Igniter Core Bag Assembly				9331399
					NEXT HIGHER ASSEMBLY 9331393
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None difined				
Major					
101	Tie missing or improperly located		100%	3.2	Gage
102	Location of seams		100%	3.2	Visual
103	Cloth Improper (tape)			3.1	4.5.5.2
Minor					
201	Length of tape after tack		0.65%	3.2	Scale
202	Evidence of poor workmanship		0.65%	3.6	Visual
203	Length of tape before tack		0.65%	3.2	Scale

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	End, Base Igniter		9331396
			NEXT HIGHER ASSEMBLY
			9331392 or 9331393

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5.1
102	Diameter of base igniter end		0.40%	3.2	Gage
Minor					
201	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.6	Base Igniter End and Igniter Core Bag Assembly				9331393
					NEXT HIGHER ASSEMBLY 9331392
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance from end base igniter to first tape		100%	3.2	Gage
102	Location of igniter core bag assembly		100%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.7	Base Igniter Assembly		9331392
			NEXT HIGHER ASSEMBLY 9331400

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of seam circle		0.40%	3.2	Scale
102	Quilting missing or improper (including length)		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.8	Body and Strap Assembly				9331391
					NEXT HIGHER ASSEMBLY
					7331400
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	tying strap missing, incompletely stitched or improperly located		0.40%	3.2	Visual/Scale
Minor	None defined				

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Base Igniter Loading Assembly				9331400
					NEXT HIGHER ASSEMBLY
					9331403
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly incorrect or damaged to the extend that black powder can escape (including any seams or openings incompletely stitched or broken threads)		100%	3.2	Visual/Manual
Major					
101	Weight of black powder		100%	3.2	4.5.1
102	Moisture content of black powder	(a)		3.3	4.5.3
103	Distance from end of igniter core to seam		0.40%	3.2	Scale
104	Any seam incorrect, or incompletely stitched		100%	3.2	visual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

(a) See paragraph 4.4.3.2

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET / OF /		DRAWING NUMBER
4.4.2.10	Cap				9331405
					NEXT HIGHER ASSEMBLY 9331403
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness		0.40%	3.2	Gage
Minor					
201	Length		0.65%	3.2	Scale

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.11	Complete Igniter Assembly		9331403
			NEXT HIGHER ASSEMBLY 9331402

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly incorrect or damaged to the extent thatblack powder can escape (including any seams or openings incompletely stitched or broken stitches)		100%	3.2	Visual
2	Ingiter core twisted or folded in tube (to be checked prior to application of cap)		100%	3.2	Visual
Major					
101	Base igniter loading assembly improperly tied to tube; i.e., tape missing, loose, or incorrect (excluding length of tape after tying)		100%	3.2	Visual/Manual
102	Cap missing or insecure		100%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331383
4.4.2.12	Body				NEXT HIGHER ASSEMBLY 9331388
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5.2
Minor					
201	Length (as established)		0.65%	3.2	Scale
202	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331386
4.4.2.13	Liner Assembly				NEXT HIGHER ASSEMBLY 9331388
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Lead foil not properly matched or not properly assembled to the scrim side of the additive liner		0.40%	3.2	Visual
102	Weight of lead foil prior to laminating to scrim		0.40%	3.2	Balance
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.14	Body and Liner Assembly				9331388
					NEXT HIGHER ASSEMBLY 9331385
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Liner assembly improper, improperly assembled, missing or improperly located		0.40%	3.2	Visual/Scale
102	Minimum distance from seams to edge of cloth		0.40%	3.2	Visual
Minor	None defined				

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.15	End, Increment	1	1	9331390
				NEXT HIGHER ASSEMBLY: 9331389

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5.2
Minor					
201	Established length		0.65%	3.2	Scale
202	Established width of straight section		0.65%	3.2	Scale

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.16	Increment End Assembly				9331389
					NEXT HIGHER ASSEMBLY 9331385
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Seam improper		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.17	Body and End Assembly				933138 5
					NEXT HIGHER ASSEMBLY
					9331 402
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	End assembly improperly assembled to body and liner assembly		0.40%	3.2	Visual
102	Any seam incompletely stitched		0.40%	3.2	Visual/Manual
Minor	None defined				

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	Increment Loading Assembly				9331402
					NEXT HIGHER ASSEMBLY 9331401
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Complete igniter assembly improperly tacked to body and end assembly		100%	3.2	Visual/Manual
102	Complete igniter assembly improper or damaged (including condition of tube immediately prior to insertion into body and end assembly)		100%	3.2/3.9	Visual/Manual
103	Propellant weight			3.4.1	4.5.2
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.19	Charge Propelling Assembly				9331401
					NEXT HIGHER ASSEMBLY 9331314
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Assembly damaged to the extent that propellant can escape (includes any seams or openings incompletely stitched and broken threads)		100%	3.2	Visual
102	Any component missing or improperly assembled		100%	3.2	Visual
103	Strap loose, broken or insecurely tied		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331397
4.4.2.20	Jacket, Lacing				NEXT HIGHER ASSEMBLY 9331314
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5.2
102	Lacing cord missing or improperly assembled (2 locations)		0.40%	3.2	Visual/Manual
Minor					
201	Jacket of excessive length		0.65%	3.2	Scale
202	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.6	Visual
204	Any seam improper or incompletely stitched		0.65%	3.2	Visual/Manual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.21	Charge, Proof, PXR-6297 for 155MM Cannon M199 and M185	1 OF 2	9331314
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly damaged or improper to the extend that black powder can escape Proving Ground		100%	3.2	Visual/Manual
Special					
a.	Pressure	20		3.7	4.5.6
Major					
101	Base pad not in true position with respect to outer diameter of charge (to be determined after straps are securely tied and charge is laced)		100%	3.2	Gage
102	Dimensional gage failure (maximum length and diameter)		100%	3.5.1	Gage
103	Lacing missing, improper or insecure		100%	3.2	Visual/Manual
104	Igniter protector cap missing or improperly assembled		0.40%	3.2	Visual
105	External threads or chains of excessive length (including loose threads) clinging to the outside of bag.		0.40%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-01-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.21	CONTINUATION SHEET				9331314
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual
202	Location of lacing jacket		0.65%	3.2	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.22	Container, Prior to insertion of charge				9331355
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Foreign matter or rust in container		100%	3.2	Visual
102	Bottom cushion missing		100%	3.2	Visual
103	Charge not tightly wrapped immediately prior to insertion into container (i.e., all charge full diameter points shall be in contact with the wrapper).		0.40%	3.2	Visual
Minor					
201	Damaged container (to include dents protruding greater than 1/4" into container)		0.65%	3.2	Visual/Gage (see 6.4)

NOTES:

Document: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.23	Container, Prior to Sealing				9331355
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical MAJOR 101	None defined Wrapper or long filler above top of charge except for one allowable torn filler (to be inspected with charge in container).		100%	3.2	Visual
102	Charge diametrically loose to the extent that a long filler may be inserted		100%	3.2	Manual
103	Any component missing or improper		100%	3.2	Visual
104	Dimension "X", minimum (In lieu of measuring Dimension "X", the measurement of Dimension "Y", maximum may be taken)		100%	3.2	Gage
105	Filler inserted in container prior to inserting top cushion		0.40%	3.2	Visual
106	More than five long fillers present		0.40%	3.2	Visual
107	Overlap of one long filler with another		0.40%	3.2	Visual
108	Charge cannot be removed by hand	(a)		3.2	4.5.11

NOTES:

(a) One sample from eight (8) hours production.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.23	CONTINUATION SHEET				9331355
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
109 Minor	Top cushion incorrect type; i.e., cushion does not have hole None defined		0.40%	3.2	Visual

NOTES:

DRI JA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 W, is Obsolete

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.24	Container, Sealed		9331355
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Test plug missing		100%	3.2	Visual
102	DOD symbol missing, misleading or unidentifiable (if applicable)		0.40%	3.2	Visual
103	Test plug assembly torque		0.40%	3.8	Test
104	Air pressure test		100%	3.2	4.5.4
Minor					
201	Test plug not greased (to be checked after air pressure test and prior to reassembly)		0.65%	3.2	Visual
202	Metallic seal missing or incorrectly applied		0.65%	3.2	Visual
203	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
204	Cover incompletely engaged		0.65%	3.2	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63372(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.25	Containerized Charge				9331355
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Note (a)	Tear down Inspection	(b)		(c), (d)	4.5.7

NOTES:

(a) Category is critical or major dependent upon the category of the defect inspected.
(b) See paragraph 4.4.3.1
(c) Requirement paragraph is dependent upon inspection performed.
(d) Allowance will be made for stretching of cloth and/or relaxation of the charge when verify characteristics that were established prior to loading at loading and assembly. Allowance shall not exceed twice original tolerance or one-half minimum tolerance.

NOTES:

Source: https://assist.dla.mil - Downloaded: 2024-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4.3 Testing

4.3.3.1 Teardown Inspection

4.3.3.1.1 Initial Production Lot Sampling. In addition to the samples of 4.4.3.1.2, three completely assembled charges shall be randomly selected from each days production until three consecutive days production is found acceptable.

4.4.3.1.2 Lot Sampling. Thirty completely assembled charges shall be randomly selected from each lot. If there is a lapse in production in excess of ninety (90) days, or the previous lot was waived or rejected due to this insection, sampling will return to initial production lot sampling.

4.4.3.2 Moisture Content of Black Powder. At least one sample of black powder from each eight hours loading of base igniter assemblies will be tested for moisture content.

4.4.4 Inspection Equipment. The inspection equipment required to perform the examinations and tests prescrib ed herein is described in the "Paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and paragraph 6.3 of this specification.

4.5 Test Methods and Procedures.

4.5.1 Weight of Black Powder in Base Igniter Loadlng Assembly. The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. The weight of the black powder for each compartment will be inspected 100 percent. The weight of the black powder in the basepad will be determined by subtracting an average weight of the empty assembly or the actual weight as marked on the individual assembly from the loaded basepad, empty igniter core bag assembly weight. The weight of the black powder in the igniter core bag will be determined by subtracting the actual weight of the loaded basepad, empty igniter core bag assembly from the loaded base igniter loading assembly weight.

4.5.2 Propellant Weight. (see 3.4) - The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

clearly distinguished from production operations. Any increment which fails to comply with the applicable requirement shall be classed defective and removed from the lot. Inspection equipment shall be in accordance with 4.4.4.

4.5.2.1 Method 1 The loaded increments will be inspected 100 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.2.2 Method 2. The weight of the propellant will be inspected 100 percent prior to loading the increment on a different balance. In addition, the propellant weight of the loaded increment will be inspected using a sampling plan from MIL-STD-1235 with an AQL of 0.40 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.3 Moisture Content of Black Powder. The moisture content of the black powder will be determined in accordance with MIL-P-223. If any sample fails to meet the specified requirement the eight hours production represented by the sample shall be rejected.

4.5.4 Air Pressure Test. Each container shall be tested as specified on the appropriate drawing. A pressure drop equivalent to or greater than the applicable requirement shall be cause for rejection and removal from the lot.

4.5.5 Cloth

4.5.5.1 Cloth, Spun Viscose Rayon Resin Impregnated. Each roll, as a minimum, shall be tested for compliance with the physical characteristics listed in Table I in 3.5 of MIL-C-43157. Testing will be in accordance with 4.3.1 of MIL-C-43157. Any sample which fails to comply with the applicable requirement shall be cause for rejection of the cloth bolt represented by the sample. The method of inspection to be used during production is to be established by the contractor and approved by the government. The method, as a minimum, shall contain positive assurance that the material being utilized has been verified for compliance with the specification requirements as stated above. (See 6.9).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.5.2 Cloth. At the time cloth is introduced to the sewing and/or cutting operation, an identification will be made for each roll to verify that proper material is used. Any cloth failing to be identified as proper material in accordance with applicable drawings and specifications shall be rejected from the lot.

4.5.6 Proving Ground (See 3.7) - This test shall be conducted at a Government Proving Ground in accordance with the applicable acceptance test procedure using M549, RA projectiles inert loaded within 0.1 pound of an as fired weight of 96.0 pounds or M483A1 projectiles (103.0 lbs) using Primer, M82 and fired in cannon M199 or M185 with 95 percent (minimum) remaining life. Firing shall be conducted with a spindle to charge base stand-off of 1 inch (plus or minus 1/4 inch). Prior to firing, all charges shall be temperature conditioned in a large conditioning box with adequate air circulation at the required temperature for a minimum of 24 hours and assurance will be made that, when fired, the charges are at the conditioning temperature. The following tolerances shall apply to all 145°F conditioning: 145°F from 140°F to 145°F. Copper crusher gages (2) shall be used to measure the maximum chamber pressure of each charge. Velocity coils will be used to measure the muzzle velocity of each charge.

4.5.6.1 Pressure. Two pressure-time gages at different locations (one in the spindle and one at the projectile base) will be used to record pressure-time traces. Differential pressure traces will be obtained by subtracting the projectile gage output from the spindle gage output. The maximum differential pressure of any charge will be defined as the maximum amplitude of the first negative wave of the differential pressure trace prior to peak pressure. Any trace which contains no amplitude in the negative direction will be considered to have a differential pressure of zero. Ignition delay will be recorded on all differential pressure firings. Twenty (20) charges will be conditioned to 145°F and ten (10) charges will be fired with the M549A7 (inert loaded) and ten (10) with the M483A1 (inert). Ten (10) calibration charges will be fired intermixed (five (5) with each projectile) with the test samples and the muzzle velocity and pressure of all test charges corrected to standard conditions.

4.5.7 Teardown Inspection. Each container and propelling charge will be subjected to each of the critical (except critical defect 2., paragraph 4.4.2.24) and 100 percent major

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

(except major defect 101, major defect 103, paragraph 4.4.2.21; major defect 104, paragraph 4.4.2.26) inspections defined in 4.4.2 of this specification. Samples may be accumulated or inspected upon selection providing the selection remains random and represents the lot. The inspections will be performed by the contractor and witnessed by the Government. The detection of any one of the above defects shall be cause for rejection of the lot represented by the sample.

4.5.8 Complete Igniter Alignment. Each complete igniter assembly shall be assembled to the increment assembly utilizing an approved method of assuring alignment between the igniter tube and the outer diameter of the increment assembly. The method to be used during production is to be established by the contractor and approved by the Government (see 6.10).

4.5.9 Charge Removal from Container. Each sample shall be tested for removal of the propelling charge from the container by hand. The charge may be pulled out by the tying straps or the container may be inverted and the charge either pulled out or slid out. Each charge tested shall be checked for damage to the tying straps (looseness, tears, etc.) and the charge, will be repaired (retie the tying straps and relace the charge, if necessary). Each charge tested shall be rewrapped (may use the same wrapper if the wrapper is not badly damaged) and re-packed in accordance with this specification and the applicable drawings. Any charge that cannot be removed from the container using the above method shall be cause for rejection of the production represented by the sample.

5. PREPARATION FOR DELIVERY

5.1 Packing and Marking. The propelling charges shall be packed, sealed, tested, and marked in accordance with the specified requirements of drawing 9331355.

6. NOTES

6.1 Intended Use. The proof charges covered by this specification are intended for use with 155MM projectiles, development and acceptance tests, and for M185 and M199 cannon proof tests. This proof charge is for Proving Ground use only, to be fired in a M199 or M185 cannon with all personnel behind a protective barrier. The proof charge is not intended for firing when the charge temperature is less than 140 degrees Fahrenheit or greater than 145 degrees Fahrenheit.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

6.2 Ordering Data. See MIL-A-48078.

6.3 Submission of Designs for Approval. See 6.2.3 of MIL-A-48078. Submit equipment designs, as required, to Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAR-I, Dover, New Jersey 07801.

6.4 Visual Examination Qualification. When compliance with the applicable requirement is in doubt as a result of visual examination the characteristic may be measured or gaged to determine acceptability.

6.5 Inspection Lot Size. It is noted that the size of inspection lots of components, assemblies, or items of delivery may differ from the actual quantities contractually scheduled for delivery. However, in order to facilitate scheduling of tests or deliveries, inspection lots of items of delivery may be equivalent to such contract quantities provided all of the lot formation criteria and sampling provisions of this specification are maintained.

6.6 Proving Ground. A copy of all proving ground data should be submitted to Commander, US Army Research and Development Command, ATTN: DRDAR-QAR-Q and DRDAR-LCA-G, Dover, New Jersey 07801.

6.7 Teardown Inspection. A list of all defects found during teardown inspection shall be submitted to Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAR-Q, Dover, New Jersey 07801.

6.9 Method of Inspection Submission. Methods of inspection for resin impregnated spun viscose rayon cloth shall be submitted to Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAR-Q, Dover, New Jersey 07801 for approval.

6.10 Method of Assuring Alignment Submission. The method for assuring alignment of the complete igniter assembly shall be submitted to Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAR-Q, Dover, New Jersey 07801 for approval.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

6.11 Data Cards. A copy of all data cards should be submitted to Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAR-Q and DRDAR-LCA-G, Dover, New Jersey 07801.

6.12 Assembly Torque. The assembly torque of the test plug will apply at time of loading only due to the relaxation of the gasket material.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project Number: 1320-A503

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.

NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-C-63372 Charge Proof, 155MM, PXR-6297 Loading, assembling and Packing

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*

TELEPHONE NO.

DATE

DD FORM 1 OCT 76 1426

EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.