MIL-F-63090A(AR)
21 April 1981
SUPERSEDING
MIL-F-63090(PA)
13 September 1976

MILITARY SPECIFICATION

FIRING DEVICE, MULTI-PURPOSE, M142 PARTS, ASSEMBLY, AND PACKING

This specification is approved for use by the U.S. Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing for one type of firing device, designated as Firing Device, Multi-Purpose, M142.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids, or request for proposals, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-20444 - Primer, Percussion, M42, Parts For And Loading Assembly And Packing
MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures And Tables For Inspections By Attributes

FSC: 1375

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

DRAWINGS

U.S. ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND (ARRADCOM)

9296865 - Firing Device, Demo Multi-Purpose M142
9311141 - Packing And Marking For Box Ammunition, M19A1, With Firing Device, Demolition, Multi-Purpose, M142
9311138 - Packing And Marking For Box, Wood, Wirebound For Boxes, Ammunition, M19A1

U.S. ARMY MATERIEL DEVELOPMENT AND READINESS COMMAND (DARCOM)

19-48-4116/8S-20PA1002 - Unitization Procedures For Boxed Ammunition And Components On 4-Way Entry Pallets

(Copies of specifications, standards and drawings, required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the Contracting Officer.)

3. REQUIREMENTS

3.1 Material. Materials shall be in accordance with applicable drawings, specifications and standards.

3.2 Components and assemblies. The parts shall comply with all requirements specified on Drawing (dwg) 9296865 as applicable and with all requirements specified in applicable specifications.

3.3 Firing device functioning. The firing device shall not prematurely release the firing pin and shall mechanically initiate the primer providing actuation by pull, tension release, pressure and pressure release as follows.

3.3.1 Pull (trip wire). The firing device shall function the primer when a load of 4.0 pounds minimum (lbs min) to 9.0 lbs maximum (max) is applied to the trip wire in a direction perpendicular to the longitudinal axis of the firing device body (see 4.5.1.1).

3.3.2 Tension release. The firing device shall function the primer when a tension of 3 lbs $\pm$ .25 lbs in the trip wire applied to the tension release attachment is relieved by cutting the trip wire (see 4.5.1.2).

3.3.2.1 The tension of 3 lbs $\pm$ .25 lbs shall place the tension release attachment to the set position where the gooseneck arm (Leg A) is adjacent to the extreme tip of the straight arm (Leg B).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

3.3.3 Pressure. The firing device shall function the primer when a varying load of fifteen (15) lbs. to twenty-five (25) lbs. is applied to the sear platform (see 4.5.1.3).

3.3.4 Pressure release. After a load of 4 lbs. is applied to the sear platform, the device shall function upon the removal of 2.0 ± .1 lbs. (see 4.5.1.4).

3.4 Water immersion. The firing device shall be capable of operation in the pressure and pull modes when submerged in minimum of six (6) inches of water (see 4.5.2).

3.5 Cold temperature functioning. The firing device shall be capable of operation in the pull, pressure and pressure release modes when conditioned at minus 50°F for 16 hours (see 4.5.3).

3.6 Body, coupling web. The web in the body coupling shall not rupture, nor show evidence of leakage when subjected to an air pressure of 5-10 pounds per square inch (psig) for fifteen (15) seconds (sec) min.

3.7 Workmanship. All parts and assemblies shall be fabricated and finished in a thorough workmanlike manner and all manufacturing, processing, and assembly operations shall be correctly performed. They shall be free of burrs, chips, sharp edges, cracks, crazes, unblended radii, porosity, warpage, burn marks, checks, chipped edges, blisters, excess flash, dirt, grease, rust, salt deposits, visible raised cement seams, solder splash, corrosion products, and other defects and foreign matter which would affect their serviceability. The cleaning method used shall not be injurious to any part or assembly nor shall the parts be contaminated by the cleaning agent. All required markings shall be neat, legible and sharply defined.

3.8 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item.

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First article inspection

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer. The first article sample shall consist of twenty-five (25) complete sets of parts and subassemblies (i.e. 25 each of every component and subassembly) 5 plastic parts from each cavity, and 150 complete assemblies with M42 Primer. The first article shall be evaluated in accordance with the provisions of 4.3.2 and 4.3.3.

4.3.2 Inspection to be performed. See MIL-A-48078, and Table I specified herein.

4.3.3 Rejection. (See MIL-A-48078).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

TABLE I. First Article Inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
	Firing Device, Multi-Purpose, M142				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Parts & Sub-Assemblies				
	Dwg 9296865				
	Examination of defects	25(a)		3.2	4.4.2.1 thru 4.4.2.18
	Plastic Parts				
	Dwgs 9296872, 9296876, 9296875, 9296377				
	Examination of defects	5(b)		3.2	4.4.5.1 thru 4.4.5.4
	Firing Device Assemblies				
	Dwg 9296865				
	Testing (Functioning)				
	Group A				
	Pull	25		3.3.1	4.5.1.1
	Tension release	25		3.3.2	4.5.1.2
	Pressure	25		3.3.3	4.5.1.3
	Pressure release	25		3.3.4	4.5.1.3
	Group B (water immersion)				
	Pull	10		3.4	4.5.2
	Pressure	10		3.4	4.5.2
	Group C (cold temp)				
	Pull	10		3.5	4.5.3
	Pressure	10		3.5	4.5.3
	Pressure release	10		3.5	4.5.3

NOTES: (a) 25 each and every component and sub-assembly.
(b) 5 each molded parts from each cavity.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of firing devices shall contain:

a. Parts bearing the same lot interfix number from one manufacturer.

b. Primers from not more than one lot.

4.4.2 Examination. (See MIL-A-48078).

a. Sampling plans. Unless otherwise specified in the classification of defects and test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	Grommet				9296873
					NEXT HIGHER ASSEMBLY
					9296866
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter		0.40%	3.2	Gage
102	Inside diameter		0.40%	3.2	Gage
103	Molding defects		0.40%	3.2	Visual
Minor					
201	Length of flat head		0.65%	3.2	Gage
202	Diameter of groove		0.65%	3.2	Gage
203	Length of beveled head		0.65%	3.2	Gage
204	Overall length		0.65%	3.2	Gage
205	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Packing, Preformed				9296880
					NEXT HIGHER ASSEMBLY
					9296866
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Inside diameter		0.40%	3.2	Gage
102	Incomplete form		0.40%	3.2	Visual
Minor					
201	Outside diameter		0.65%	3.2	Gage
202	Thickness		0.65%	3.2	Gage
203	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9296866 / NEXT HIGHER ASSEMBLY 9296865
4.4.2.3	Coupling Body Assembly				
CATEGORY	**EXAMINATION OR TEST**	**NO. OF SAMPLE UNITS**	**AQL OR 100%**	**REQUIREMENT PARAGRAPH**	**PARAGRAPH REFERENCE /INSPECTION METHOD**
Critical	None defined				
Major					
101	Body coupling web pressure test prior to installing primer		100%	3.6	4.5.5
102	Primer missing or incorrectly installed		0.40%	3.2	Visual
103	Body coupling face or primer not lacquered		0.40%	3.2	Visual
104	Grommet missing		0.40%	3.2	Visual
105	Coupling nut missing		0.40%	3.2	Visual
106	Any packing component missing		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9296878
4.4.2.4	Reel, Cable				NEXT HIGHER ASSEMBLY 9296865
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Outside diameter		0.65%	3.2	Gage
202	Incomplete form		0.65%	3.2	Visual
203	Length of reel		0.65%	3.2	Gage
204	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.5	Cable Reel Assembly				9296867
					NEXT HIGHER ASSEMBLY
					9296865
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Wire missing		0.40%	3.2	Visual
Minor					
201	Coiled wire not secured with lacquer		0.65%	3.2	Visual
202	Loose end of wire not properly secured		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.6	Tension Release Attachment		9296884
			NEXT HIGHER ASSEMBLY
			9296865

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Internal loop width on leg B		0.40%	3.2	Gage
102	Height of straight arm B		0.40%	3.2	Gage
103	Length of section opposite straight arm		0.40%	3.2	Gage
104	Height of step opposite straight arm		0.40%	3.2	Gage
105	Load test of tension release attachment		0.40%	3.2	Gage
Minor					
201	Oxide finish missing		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.7	Switch Assembly				9296868
					NEXT HIGHER ASSEMBLY
					9296865
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Safety pin missing, not opened or improperly assembled		100.0%	3.2	Visual
2	Firing pin released against safety pin with all components (pins) present		100.0%	3.3	Visual
Major					
101	Cord missing from assembly		0.40%	3.2	Visual
102	Square loop or round loop pins missing		0.40%	3.2	Visual
103	Alternative safety pin holes not grease packed		0.40%	3.2	Visual
104	Grease missing or incomplete		0.40%	3.2	Visual
105	Striker assembly missing		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9296871
4.4.2.8	Mounting Hardware				NEXT HIGHER ASSEMBLY 9296865
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any screw or nail missing		0.40%	3.2	Visual
Minor					
201	Nails or screws not properly secured		0.65%	3.2	Visual
202	Tape ends not folded back		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.9	Striker, Firing Device, Demolition	1 OF 1	9296885
			NEXT HIGHER ASSEMBLY: 9296868

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Length of point		0.40%	3.2	Gage
102	Profile of point		0.40%	3.2	Gage
103	True position of four tabs with outside diameter		0.40%	3.2	Gage
104	Outside diameter of striker		0.40%	3.2	Gage
105	Diameter of striker undercut		0.40%	3.2	Gage
106	Length of undercut		0.40%	3.2	Gage
107	Length from undercut to tabs		0.40%	3.2	Gage
Minor					
201	Overall length incorrect		0.65%	3.2	Gage
202	Angle at undercut		0.65%	3.2	Gage
203	Thickness of tabs, 4 places		0.65%	3.2	Gage
204	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.10	Pin, Round Loop Head		9296883
			NEXT HIGHER ASSEMBLY 9296868

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Length to loop		0.65%	3.2	Gage
202	Diameter of wire		0.65%	3.2	Gage
203	Straightness of wire		0.65%	3.2	Gage
204	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.11	Pin, Square Loop Head		9296882
			NEXT HIGHER ASSEMBLY
			9296868

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Overall length		0.65%	3.2	Gage
202	Length to square loop		0.65%	3.2	Gage
203	Length inside loop		0.65%	3.2	Gage
204	Width inside loop		0.65%	3.2	Gage
205	Diameter of wire		0.65%	3.2	Gage
206	Protective finish missing		0.65%	3.2	Visual
207	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.12	Spring, Firing, Device, Demolition				9296881
					NEXT HIGHER ASSEMBLY 9296868
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Solid length, max		0.40%	3.2	Gage
102	Load at compressed length		0.40%	3.2	Gage
Minor					
201	End(s) not closed or not ground		0.65%	3.2	Visual
202	Diameter of coil		0.65%	3.2	Gage
203	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.13	Pin and Cord Assembly				9296869
					NEXT HIGHER ASSEMBLY
					9296868
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Insufficient cord length		0.65%	3.2	Visual
202	Tie incorrect		0.65%	3.2	Visual
203	Cotter pin missing		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.14	Firing Device Demo Multi-Purpose M142, Prior to Closing				9296865
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Any component, any assembly or instruction sheet missing		0.40%	3.2	Visual
Minor 201	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.15	Firing Device Demo Multi-Purpose M142	1 OF 1	9296865
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Closing tape missing or insecure		0.40%	3.2	Visual
102	Tape ends not folded back		0.40%	3.2	Visual
103	Marking missing, incomplete or illegible		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.16	Instruction Sheet				9296874
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any warning statement, phrase or word not printed in red		0.40%	3.2	Visual
102	Any instruction missing, incomplete or illegible		0.40%	3.2	Visual
Minor					
201	Insufficient length of sheet		0.65%	3.2	Visual
202	Insufficient width of sheet		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.17	Container, Bottom				9335591
					NEXT HIGHER ASSEMBLY
					9296865
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter		0.40%	3.2	Gage
102	Width		0.40%	3.2	Gage
103	Container lip not curled		0.40%	3.2	Visual
Minor					
201	Protective finish missing		0.65%	3.2	Visual
202	Height to annular projection		0.65%	3.2	Gage
203	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	Container, Lid				9335590
					NEXT HIGHER ASSEMBLY
					9296865
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Large diameter		0.40%	3.2	Gage
102	Width		0.40%	3.2	Gage
Minor					
201	Protective finish missing		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.19	Liner, For Box, Ammunition, M19A1				9311139
					NEXT HIGHER ASSEMBLY
					9311141
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Length		0.65%	3.2	Scale
202	Inside width		0.65%	3.2	Scale
203	Inside height		0.65%	3.2	Scale
204	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.20	Box, Wood, Wirebound		9311140
			NEXT HIGHER ASSEMBLY 9311141

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	End boards do not project beyond edge of battens or beyond end of boards		0.65%	3.2	Visual
202	Inside length		0.65%	3.2	Gage
203	Inside width		0.65%	3.2	Gage
204	Inside depth		0.65%	3.2	Gage
205	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.21	Packing and Marking For Box, Ammunition, M19A1, Firing Device, Demolition, Multipurpose, M142				9311141
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any packing component missing		0.40%	3.2	Visual
102	Lifting strap missing on middle firing device		0.40%	3.2	Visual
103	Incorrect number of firing devices		0.40%	3.2	Visual
104	Marking missing, incomplete or illegible		0.40%	3.2	Visual
Minor					
201	Box color incorrect		0.65%	3.2	Visual
202	Box not securely closed		0.65%	3.2	Visual/Manual
203	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.22	Packing and Marking For Box, Wood Wirebound For Boxes, Ammunition M19A1 Prior To Closing		9311138
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Number of boxes incorrect		0.40%	3.2	Visual
102	Any packing component missing		0.40%	3.2	Visual
103	Any box inverted		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.23	Packing and Marking For Box, Wood, Wirebound For Boxes, Ammunition M19A1 After Closing				9311138
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Box damaged to the extent that contents are exposed or liable to become exposed		0.40%	3.2	Visual
102	Wire binding missing, broken or loose		0.40%	3.2	Visual
Minor					
201	Wire binding mislocated or improperly engaged		0.65%	3.2	Visual
202	Contents loose		0.65%	3.2	Manual
203	Marking misleading or unidentifiable		0.65%	3.2	Visual
204	Metallic seal missing, unsealed or incorrectly positioned		0.65%	3.2	Visual
205	Cleats or battens split or broken		0.65%	3.2	Visual
206	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.4.3 Testing

4.4.3.1 Functioning. (See 3.3). Critical defect and major defect as denoted below. Beginning with the first lot produced and continuing until three (3) numerically consecutive lots have complied with the applicable requirements specified, one hundred and fifty (150) firing device assemblies with primer shall be selected from each lot for test. For test quantities, modes, requirements and methods see Table II.

TABLE II

MODE OR TEST	SAMPLE SIZE	REQUIREMENT PARAGRAPH	TEST METHOD PARAGRAPH
Group A			
Pull	25	3.3.1	4.5.1.1
Tension release	25	3.3.2	4.5.1.2
Pressure	25	3.3.3	4.5.1.3
Pressure release	25	3.3.4	4.5.1.4
Group B (Water immersion)			
Pull	10	3.4	4.5.2
Pressure	10	3.4	4.5.2
Group C (Cold temp)			
Pull	10	3.5	4.5.3
Pressure	10	3.5	4.5.3
Pressure release	10	3.5	4.5.3

The lot shall be rejected if during test, a critical defect occurs i.e. the firing pin prematurely releases against the safety pin or if four (4) or more firing devices fail to function through the blasting cap (major defect) or if more than two (2) fail to function through the blasting cap in any one (1) firing mode (major defect).

4.4.3.2 Functioning. (See 3.3). Critical defect and major defect as denoted below. After three (3) numerically consecutive lots have complied with the acceptance criteria of 4.4.3.1, sixty (60) firing device assemblies with primer shall be selected from each lot for test. For test quantities, modes, requirements and methods see Table III.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

TABLE III

MODE OR TEST	SAMPLE SIZE	REQUIREMENT PARAGRAPH	TEST METHOD PARAGRAPH
Group A			
Pull	12	3.3.1	4.5.1.1
Tension release	12	3.3.2	4.5.1.2
Pressure	12	3.3.3	4.5.1.3
Pressure release	12	3.3.4	4.5.1.4
Group B (Water immersion)			
Pull	6	3.4	4.5.2
Group C (Cold temp)			
Pressure	6	3.5	4.5.3

The lot shall be rejected if during test, a critical defect occurs i.e. the firing pin prematurely releases against the safety pin, or if three (3) or more firing devices fail to function through the blasting cap (major defect).

4.4.3.3 Check test for possible deterioration of primers. Major Defect. If the total elapsed time between the original acceptance of any primer lot and the assembly of that lot into the coupling body of firing device exceeds two years, or if the primers have been subjected to adverse conditions, however brief, at any time since previous tests, the primer lots shall be subjected to and must satisfactorily pass the check test specifed in MIL-P-20444(PA), the applicable primer specification. The check test shall be performed by the contractor (see 6.5) prior to assembling the primers into the coupling body.

4.4.4 Inspection equipment. The inspection equipment required to perform the inspections and tests prescribed in this specification is identified in the 'Paragraph Reference/Inspection Method' column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078, and 6.3 herein.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.4.5 Dimensional control of molded parts. (The requirements of this paragraph apply to those dimensions which are considered 'as molded', and which do not undergo subsequent operations). In place of normal sampling and inspections associated with the Classification of Defects, and with the approval of the Contracting Officer, and after a curing time for the parts has been approved (see Note 1) a sample of five (5) parts (as molded) from each cavity shall be inspected dimensionally to qualify a new or reworked cavity for use in production. The molded parts shall carry the individual cavity identification, when more than one cavity is used in production. As a control of each cavity during production, the above quantity of parts from each cavity shall be inspected for at least the defects listed in paragraphs 4.4.5.1 through 4.4.5.4 after continuous production of each 5,000 parts or at the end of each week, whichever occurs first. Of the five (5) samples, one (1) sample shall be the last part produced. If any defective parts are found during qualification of the cavity, the cavity producing the defective part will not be used in production. If any defective parts are found when inspection is performed for the control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for inspection for each separate type of defect according to MIL-STD-105, using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. All cavities removed from production because of some fault, may after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the Contracting Officer to substantiate the request. Contractor designs of gages and test equipment required to perform the inspections listed herein shall be forwarded to Commander, ARRADCOM, Dover, New Jersey 07801, ATTN: DRDAR-QAA-I for approval prior to manufacture of equipment. The noted subparagraphs identify those items and minimum inspections subject to the requirements of this paragraph.

NOTE 1: In establishing the curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g. every 30, 60, etc. mins) until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. The inspection data used in determining the curing time shall be sent to ARRADCOM, Dover, New Jersey 07801, ATTN: DRDAR-QAA-M. If any new change in material, cycle time, a reworked cavity, or a new cavity is used, a new curing time shall be established and approved.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.5.1	Nut, Coupling				9296872
					NEXT HIGHER ASSEMBLY 9296866
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Molding defects		0.40%	3.2	Visual
102	Diameter of small hole		0.40%	3.2	Gage
103	True position of small hole with outside diameter		0.40%	3.2	Gage
104	True position of small hole with pitch diameter of thread		0.40%	3.2	Gage
Minor					
201	Outside diameter		0.65%	3.2	Gage
202	Length of nut		0.65%	3.2	Gage
203	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.5.2	Body, Coupling		9296876
			NEXT HIGHER ASSEMBLY 9296866

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Web thickness		0.40%	3.2	Gage
102	Molding defects		0.40%	3.2	Visual
103	Hazard band missing		0.40%	3.2	Visual
104	Diameter of primer hole		0.40%	3.2	Gage
105	Depth of primer hole		0.40%	3.2	Gage
106	Diameter of flash hole		0.40%	3.2	Gage
107	Major diameter of thread at primer end		0.40%	3.2	Gage
108	Pitch diameter of thread at primer end		0.40%	3.2	Gage
109	Major diameter of large thread		0.40%	3.2	Gage
110	Pitch diameter of large thread		0.40%	3.2	Gage
Minor					
201	Length of knurl at primer end		0.65%	3.2	Gage
202	Length of knurl free groove		0.65%	3.2	Gage
203	Overall length of body		0.65%	3.2	Gage
204	Length of thread at primer end		0.65%	3.2	Gage
205	Length of gasket groove at primer end		0.65%	3.2	Gage
206	Length of large thread		0.65%	3.2	Gage
207	Length of gasket groove at large thread end		0.65%	3.2	Gage
208	Thickness thru flash hole		0.65%	3.2	Gage
209	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.5.3	Plate, Sear				9296875
					NEXT HIGHER ASSEMBLY
					9296868
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Parallelism and thickness, max of plate		0.40%	3.2	Gage
102	True position of 3 holes with radius and surface B		0.40%	3.2	Gage
103	Thickness, min.		0.40%	3.2	Gage
104	Length, surface B to end		0.40%	3.2	Gage
105	Angle at trigger end		0.40%	3.2	Gage
106	Radius for firing striker		0.40%	3.2	Gage
Minor					
201	Thickness of pressure tab, 2 places		0.65%	3.2	Gage
202	Width of tab		0.65%	3.2	Gage
203	Radius at surface B		0.65%	3.2	Gage
204	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-63090A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.5.4	Body				9296877
					NEXT HIGHER ASSEMBLY
					9296868
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pitch diameter of thread		0.40%	3.2	Gage
102	True position of rear striker cavity with forward cavity		0.40%	3.2	Gage
103	True position of round loop pin hole		0.40%	3.2	Gage
104	True position of square loop pin hole		0.40%	3.2	Gage
105	True position of slot		0.40%	3.2	Gage
106	Width of slot		0.40%	3.2	Gage
107	Length of slot		0.40%	3.2	Gage
108	Diameter of round loop pin hole		0.40%	3.2	Gage
109	Diameter of square loop pin hole		0.40%	3.2	Gage
110	Diameter of safety pin holes		0.40%	3.2	Gage
111	True position of safety pin hole		0.40%	3.2	Gage
Minor					
201	Overall height		0.65%	3.2	Gage
202	Diameter of screw hcles		0.65%	3.2	Gage
203	Location of wire tie down hole		0.65%	3.2	Gage
204	Total length		0.65%	3.2	Gage
205	Diameter of rear striker cavity		0.65%	3.2	Gage
206	Diameter of forward striker cavity		0.65%	3.2	Gage
207	Evidence of poor workmanship		1.00%	3.7	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.5 Test methods and procedures

4.5.1 Functioning

4.5.1.1 Pull test. Secure switch to a fixed object with nails, screws or wire. Screw coupling base with attached M7 Non-Electric Blasting cap into switch. Attach trip wire to hole in sear plate, remove pin from a safe distance by means of a length of wire or cord. Apply the specified pull force in a direction perpendicular to sear plate, until functioning occurs as indicated by detonation of blasting cap. The force required to function the item shall be observed for compliance with the applicable requirement.

4.5.1.2 Tension release. Secure switch to a fixed object with nails, screws or wire. Screw coupling base with attached M7 Non-Electric Blasting cap into switch. Fit tension release attachment and loop end of trip wire over curved neck. Apply the specified tension to the trip wire and observe compliance with 3.3.2.1. Remove pin with round loop and carefully remove safety pin from a safe distance by means of a length of wire or cord. The trip wire shall be cut and observation made for compliance with the applicable requirement.

4.5.1.3 Pressure (Push). Secure switch to a fixed object with nails, screws or wire. Screw coupling base with attached M7 Non-Electric Blasting cap into switch. Apply a load, not heavy enough to activate the switch, on the sear plate platform. Remove pin with square loop and carefully remove safety pin from a safe distance by means of a length of wire or cord. Apply the specified pressure to the sear plate platform until functioning occurs as indicated by detonation of blasting cap. Note the force required to function item; observe for compliance with the applicable requirement.

4.5.1.4 Pressure release. Secure switch to a fixed object with nails, screws or wire. Screw coupling base with attached M7 Non-Electric Blasting Cap into switch. Place an object so that at least 2.0 lbs. force presses down on sear plate. Remove pin with round loop and carefully remove safety pin from a safe distance by means of a length of wire or cord. Remove object from sear plate and observe for compliance with the applicable requirement.

4.5.2 Water immersion. Secure switch to a fixed object with nails, screws or wire. Screw coupling base with attached M7 Non-Electric Blasting cap into switch. Immerse in water to a covering depth of 6.0 inches. Proceed with pull test, method 4.5.1.1, and pressure push, method 4.5.1.3. Observance shall be made for compliance with the applicable requirement.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

4.5.3 Cold temperature. Condition firing devices, with coupling base with attached M7 Non-Electric Blasting cap screwed in, at minus 50°F for sixteen (16) hours. Remove one at a time and proceed with pull test, method 4.5.1.1, pressure push, method 4.5.1.3 and pressure release, method 4.5.1.4 as quickly as possible. Observation shall be made for compliance with the applicable requirement.

4.5.4 Check test for possible deterioration of primers. Sampling plans and test methods shall be in accordance with Section 6 of MIL-P-20444(PA).

4.5.5 Body coupling web pressure test. The specified pressure shall be applied from the output end toward the primer cavity for the required time. Observation shall be made for compliance with the applicable requirement.

5. PACKAGING

5.1 Preservation and packaging

5.1.1 Level A. Firing devices shall be packaged in accordance with dwgs. 9311139 and 9311141.

5.2 Packing

5.2.1 Level A. Firing devices shall be packed in accordance with dwg. 9311138.

5.3 Marking. Marking shall be in accordance with dwgs. 9311138 and 9311141.

5.4 Unitization

5.4.1 Level A. Unitization of firing devices shall be in accordance with dwg. 19-48-4116/8S-20PA1002 (DARCOM Ammo Center).

6. NOTES

6.1 Intended use. The firing device, multi-purpose, M142, a single firing device capable of being set for pull, tension (pull) release, pressure (push) or pressure release is intended for use in activating demolition blocks and other demolition devices and in booby-trapping.

6.2 Ordering data. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

6.3 Submission of inspection equipment designs for approval. (See MIL-A-48078). Submit designs as required, to Commander, ARRADCOM, ATTN: DRDAR-QAA-I, Dover, New Jersey 07801.

6.4 Distribution of ammunition data cards. Distribution of data cards shall include the following: Commander, ARRADCOM, ATTN: DRDAR-QAA-M, Dover, New Jersey 07801.

6.5 Cost of check test. The Contracting Officer should arrange for the contractor to be reimbursed for the expense incurred in the performance of the check test. The tests shall be conducted at Government expense without cost to the contractor who loaded the primer or to the contractor assembling to primers in the coupling body of the firing device and shall not constitute a basis for rejection against either contractor except where deterioration has occurred as a direct result of carelessness in handling, storage, etc., permitted while the primer lots were under the jurisdiction of either contractor.

6.6 Proving ground test summary.

TEST	PRODUCTION LOTS			REQUIREMENTS
	FIRST ARTICLE	FIRST THREE CONSECUTIVE ACCEPTABLE	REMAINING	
	150	150	60	
Group A				
Pull	25	25	12	3.3.1
Tension Release	25	25	12	3.3.2
Pressure	25	25	12	3.3.3
Pressure Release	25	25	12	3.3.4
Group B (Water immersion)				
Pull	10	10	6	3.4
Pressure	10	10	--	3.4
Group C (Cold temp)				
Pull	10	10	--	3.5
Pressure	10	10	6	3.5
Pressure Release	10	10	--	3.5

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No.: 1375-A-174

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

FOLD

DEPARTMENT OF THE ARMY

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY CARD

FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.

POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
US Army Armament R&D Command
ATTN: DRDAR-QAA
Dover, NJ 07801

FOLD

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.