MILITARY SPECIFICATION

MINE, ANTI-PERSONNEL, M26

PARTS FOR

This specification is approved for use by US Army Armament Research and Development Command, Department of the Army and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification contains requirements not normally covered by the drawings and provides quality assurance provisions for the fabrication of parts, assembly and packing of one type of mine.

2. APPLICABLE DOCUMENTS

2.1 Issues of documents. - The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein:

SPECIFICATIONS

MILITARY

MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes

FSC: 1345

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

DRAWINGS

US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

8822121 - Container, Fiber, Ammunition, M406A2 for Mine, APERS, M26, HE, w/Integral Fuze
8822122 - Box, Packing, Ammunition for Mine, APERS, M26, HE, w/Integral Fuze
8840287 - Metal Parts Assembly, w/Integral Fuze for Mine, APERS, M26

2.2 Other publications. - The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on the date of invitation for bids or request for proposal shall apply.

CODE OF FEDERAL REGULATIONS

TITLE 49 - Transportation, Parts 100-199

(The Code of Federal Regulations is available from the Superintendent of Documents, U.S. Government Printing Office, Washington, D.C. 20402. Orders should specify, "49 CFR 100-199 (latest revision)").

AMERICAN SOCIETY FOR TESTING AND MATERIALS

ASTM B 117-73 - Standard Method of Salt Spray (Fog) Testing
ASTM E 18-67 - Standard Methods of Test for Rockwell Hardness and Rockwell Superficial Hardness of Metallic Materials

(Application for copies should be addressed to: American Society for Testing and Materials, 1916 Race Street, Philadelphia, Pa. 19103)

3. REQUIREMENTS

3.1 Material. - Materials shall be in accordance with the applicable drawings and specifications.

3.2 Parts. - The parts shall comply with all requirements specified on Drawing (Dwg.) 8840287, all associated drawings, and with all requirements specified in applicable specifications.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

3.3 Data requirements. - Generation of data shall be as specified in 6.4.

3.4 First Article Inspection. - This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.5 Workmanship. - All parts and assemblies shall be fabricated and finished in a thorough, workmanlike manner. They shall be free of burrs, chips, sharp edges, cracks, unblended radii, surface defects, dirt, grease, rust, corrosion products, and other foreign matter. The cleaning method used shall not be injurious to any parts, nor shall the parts be contaminated by the cleaning agents. All marking and stamping shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions. - Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of Inspections. - The following types of inspection shall be conducted on this item:

a. First Article Inspection
b. Quality Conformance Inspection

4.3 First Article Inspection.

4.3.1 Submission. - The contractor shall submit a first article as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawings	Quantity
Retainer, Spool	8840292	25
Ring	8840296	25
Pin, Cover Locking	8840297	25
Body	8840299	25
Pin, Firing	8840309	25

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

Ring, Take-up	8840319	25
Ring, Cover	8840320	25
Cover	8840323	25
Retainer Spring Housing	8840300	25
Cover-ring	8840320	25
Barrel	8840317	25
Housing, Spring	8840308	25
Spacer	8840293	25
Latch, Arming	8840325	25
Spring, Firing Pin	8840310	25
Disc	9242434	25
Cam	8840324	25
Handle, Arming Latch	8840350	25
Lever, Trip	8840351	25
Lever, Actuating	8840305	25
Spool Trip Wire	8840349	25
Sleeve	8840302	25
Spool Assembly	8840291	25
Cover and Arming Latch Assembly	8840290	50
Spring Housing Assembly	8840301	50
Firing Pin Assembly	8840306	50
Firing Pin Lever and Housing Assembly	8840303	50
Barrel and Seal Assembly	8840289	50
Trip Wire Assembly	8840352	50
Spring Housing and Body Assembly	8840288	25
Delay Housing and Plug Assembly	8840335	50
Mine Metal Parts Assembly	8840287	50

4.3.2 Inspections to be Performed. - See MIL-A-48078 and Table I herein.

4.3.3 Rejection. - See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE: Mine Metal Parts Assembly and Components		SHEET 1 OF 6		DRAWING NUMBER: See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Retainer spool (Dwg 8840292)				
	Examination for defects	25		3.1	4.4.2.1
	Salt Spray	10		3.1	4.5.4
	Hardness	15		3.1	4.5.5
	Ring (Dwg. 8840296)				
	Salt spray	10		3.1	4.5.4
	Hardness	15		3.1	4.5.5
	Pin, cover locking (dwg. 8840297)				
	Examination for defects	25		3.1	4.4.2.3
	Salt spray	10		3.1	4.5.4
	Body (Dwg. 8840299)				
	Examination for defects	25		3.1	4.4.2.4
	Internal air pressure	25		3.1	4.5.6
	Body porosity	25		3.1	4.5.7
	Pin, firing (Dwg. 8840309)				
	Salt spray	10		3.1	4.5.4

NOTES:

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION
CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 6		DRAWING NUMBER
	Continued				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Ring, take-up (Dwg. 8840319)				
	Examination for defects	25		3.1	4.4.2.6
	Salt spray	10		3.1	4.5.4
	Hardness	15		3.1	4.5.5
	Ring, cover (Dwg. 8840320)				
	Examination for defects	25		3.1	4.4.2.7
	Salt spray	10		3.1	4.5.4
	Cover (Dwg. 8840323)				
	Examination for defects	25		3.1	4.4.2.8
	Salt spray	10		3.1	4.5.4
	Retainer, spring housing (Dwg. 8840300)				
	Examination for defects	25		3.1	4.4.2.9
	Salt spray	10		3.1	4.5.4
	Hardness	15		3.1	4.5.5
	Barrel (Dwg. 8840317)				
	Examination for defects	25		3.1	4.4.2.10
	Housing, spring (Dwg. 8840308)				
	Examination for defects	25		3.1	4.4.2.11

NOTES:

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 3 OF 6		DRAWING NUMBER
	Continued				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Spacer (Dwg. 8840293)				
	Examination for defects	25		3.1	4.4.2.12
	Latch, arming (Dwg 8840325)				
	Examination for defects	25		3.1	4.4.2.13
	Hardness	15		3.1	4.5.5
	Spring, firing pin (Dwg. 8840310)				
	Examination for defects	25		3.1	4.4.2.14
	Hardness	15		3.1	4.5.5
	Disc (Dwg. 9242434)				
	Examination for defects	25		3.1	4.4.2.15
	Salt spray	10		3.1	4.5.4
	Hardness	15		3.1	4.5.5
	Cam (Dwg. 8840324)				
	Examination for defects	25		3.1	4.4.2.16
	Handle, arming latch (Dwg. 8840350)				
	Examination for defects	25		3.1	4.4.2.17
	Lever, trip (Dwg. 8840351)				
	Examination for defects	25		3.1	4.4.2.18
	Load test	25		3.1	4.5.8

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION
CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 4 OF 6		DRAWING NUMBER
	Continued				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Lever, actuating (Dwg. 8840305)				
	Examination for defects	25		3.1	4.4.2.19
	Spool trip wire (Dwg. 8840349)				
	Examination for defects	25		3.1	4.4.2.20
	Sleeve (Dwg. 8840302)				
	Examination for defects	25		3.1	4.4.2.21
	Cover and arming latch assembly (Dwg. 8840290)				
	Examination for defects	50		3.1	4.4.2.22
	Internal air pressure	50		3.1	4.5.9
	Trip lever pull test of cam	50		3.1	4.5.10
	Security of stake of seal retainer	50		3.1	4.5.11
	Security of take-up ring	50		3.1	4.5.12
	Spring housing assembly (Dwg. 8840301)				
	Security of stake of sleeve	50		3.1	4.4.2.23 and 4.5.13
	Firing pin assembly (Dwg. 8840306)				
	Examination of defects	50		3.1	4.4.2.24
	Security of crimp of firing pin	50		3.1	4.5.14

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 5 OF 6		DRAWING NUMBER
	Continued				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Firing pin, lever and housing assembly (Dwg 8840303)				
	Examination for defects	50		3.1	4.4.2.25
	Static load test of actuating lever	50		3.1	4.5.15
	Min deflection at point of release of firing pin	50		3.1	4.5.16
	Security of stake of actuating lever	50		3.1	4.5.17
	Non-tripping test of actuating lever	50		3.1	4.5.18
	Trip wire assemblies (Dwg. 8840352)				
	Security cold test of trip wire tape	50		3.1	4.4.2.26 4.5.19
	Pull test of wire and loop of trip wire	50		3.1	4.4.2.26 4.5.20
	Barrel and seal assembly (Dwg. 8840289)				
	Examination for defects	50		3.1	4.4.2.27
	Spool assembly (Dwg. 8840291)				
	Examination for defects	25		3.1	4.4.2.28
	Spring housing and body assembly (Dwg. 8840288)				
	Examination for defects	25		3.1	4.4.2.29

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 6 OF 6		DRAWING NUMBER
	Continued			See Below
				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Mine metal parts assembly (Dwg. 8840287) Examination for defects	50		3.1	4.4.2.32
	Delay housing and plug assembly (Dwg 8840335) Examination for defects	50		3.1	4.4.2.30
	Cover-ring (Dwg. 8840320) Load test	25		3.1	4.4.2.31 4.5.21

NOTES:

SARPA-QA FORM 2567 FEB 74 4010

10

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.4 Quality Conformance Inspection

4.4.1 Inspection lot formation. - Inspection lots shall comply with the lot formation provisions of MIL-A-48078.

4.4.1.1 Die casting lot. - The die casting lot for:

a. Body (Dwg 8840299)
b. Cover ring (Dwg 8840320)
c. Cover (Dwg 8840323)

shall consist of not less than five thousand (5000) of each part, of uniform quality and conditions, manufactured by the same process from not more than one lot of die casting material. The method of control, formation and identification of each lot shall be documented by the contractor and submitted for approval by the Government. (See 6.5)

4.4.2 Examination. - See MIL-A-48078.

a. Sampling plans. - Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the currentversion before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Retainer, Spool		8840292
			NEXT HIGHER ASSEMBLY 8840286

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Small inside diameter, max	*	0.40%	3.1	Gage
102	Thickness	*	0.40%	3.1	Gage
103	Salt spray test			3.1	4.5.4
104	Hardness			3.1	4.5.5
Minor					
201	Outside diameter, min	*	0.65%	3.1	Gage
202	Large inside diameter, max	*	0.65%	3.1	Gage
203	Color improper	*	0.65%	3.1	Visual

NOTES:

*See 4.5.2

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Ring				8840296
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Salt spray			3.1	4.5.4
102	Hardness			3.1	4.5.5

NOTES:

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Pin, cover locking				8840297
					NEXT HIGHER ASSEMBLY 8840286
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Salt spray			3.1	4.5.4
Minor					
201	Diameter of body		0.65%	3.1	Gage
202	Length of body		0.65%	3.1	Gage
203	Diameter of shank		0.65%	3.1	Gage
204	Total length		0.65%	3.1	Gage
205	Point missing or damaged (bent or mushroomed)		0.65%	3.1	Visual
206	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 3		DRAWING NUMBER
4.4.2.4	Body				8840299
					NEXT HIGHER ASSEMBLY 8840288
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Location of "S" is more than 5° toward the arming position		100%	3.1	Gage
2	Location of "A"		100%	3.1	Gage
3	Location of vent hole		100%	3.1	Gage
4	Thickness of flange, min		100%	3.1	Gage
Major					
101	Diameter of barrel cavity	*	0.40%	3.1	Gage
102	Depth of notch for spring housing assembly	*	0.40%	3.1	Gage
103	Width of notch for spring housing assembly, retaining screw end	*	0.40%	3.1	Gage
104	Diameter of sphere cavity	*	0.40%	3.1	Gage
105	Concentricity of inside diameter for the spring housing with the inside diameter for barrel	*	0.40%	3.1	Gage
106	Location of small notch in flange	*	0.40%	3.1	Gage
107	Internal air pressure test	125	0.40%	3.1	4.5.6
108	Body porosity	125	0.40%	3.1	4.5.7

NOTES:
*See 4.5.1

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE	SHEET 2 OF 3	DRAWING NUMBER
4.4.2.4	Continued		8840299
			NEXT HIGHER ASSEMBLY
			8840288

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
109	O-ring seal diameter		0.40%	3.1	Gage
110	Concentricity of o-ring seal diameter with diameter of sphere cavity including perpendicularity with flange face		0.40%	3.1	Gage
111	Location of cotter pin hole		0.40%	3.1	Gage
112	Depth to seating surface for spring housing assembly		0.40%	3.1	Gage
113	Thickness of flange, max		0.40%	3.1	Gage
114	Scratches, nicks or porosity on large o-ring seal surface		0.40%	3.1	Visual
115	Incomplete fill in any area		0.40%	3.1	Visual
Minor					
201	Location of "S" less than 5 degrees toward arming position	*	0.65%	3.1	Gage
202	Width of ribs	*	0.65%	3.1	Gage
203	Location of body ribs	*	0.65%	3.1	Gage
204	Diameter of body under flange, min	*	0.65%	3.1	Gage

NOTES:
* See 4.5.1

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 3 OF 3	DRAWING NUMBER
4.4.2.4	Continued		8840299
			NEXT HIGHER ASSEMBLY
			8840288

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
205	Inside diameter, bottom	*	0.65%	3.1	Gage
206	Outside diameter, bottom	*	0.65%	3.1	Gage
207	Distance between notches in flange, max	*	0.65%	3.1	Gage
208	Width of small notch in flange, max	*	0.65%	3.1	Gage
209	Width of large notch in flange, max	*	0.65%	3.1	Gage
Minor					
210	Width of cover groove, max		0.65%	3.1	Gage
211	Diameter of cover groove, max		0.65%	3.1	Gage
212	Outside diameter of flange, min		0.65%	3.1	Gage
213	Inside diameter of flange, max		0.65%	3.1	Gage
214	Total height		0.65%	3.1	Gage
215	Diameter of hole for cotter pin		0.65%	3.1	Gage
216	Diameter of hole for stop pin		0.65%	3.1	Gage
217	Diameter of vent hole		0.65%	3.1	Gage
218	Location of stop pin hole		0.65%	3.1	Gage
219	Excess paint in bottom of body (when applicable)		0.65%	3.1	Visual
220	Angle on cover groove missing		0.65%	3.1	Visual
221	Flash on flange end		0.65%	3.1	Visual
222	Exterior protective coating with bare spot		0.65%	3.1	Visual
223	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES: *See 4.5.1

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840309
4.4.2.5	Pin, Firing				NEXT HIGHER ASSEMBLY 8840306
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Salt spray			3.1	4.5.4

NOTES:

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840319
4.4.2.6	Ring, take-up				NEXT HIGHER ASSEMBLY 8840290
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Salt spray			3.1	4.5.4
102	Hardness			3.1	4.5.5
103	Outside diameter, min	*		3.1	Gage
104	Location of guide teeth (6)	*		3.1	Gage
105	Wall thickness	*		3.1	Gage
106	Angle of bend improper	*		3.1	Gage
Minor					
201	Width of guide teeth (6)			3.1	Gage
202	Color improper			3.1	Visual
203	Evidence of poor workmanship			3.5	Visual

NOTES:
*See 4.5.2

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840320
4.4.2.7	Ring, Cover				NEXT HIGHER ASSEMBLY 8840290
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Salt spray			3.1	4.5.4
102	Location of arrow	800	0.015	3.1	Gage
103	Distance from top of sheer lugs to underside of ring, cover lugs, max (6)	800	0.015	3.1	Gage
104	Thickness of sheer lugs, min (2)	*	0.40%	3.1	Gage
105	Distance from top of sheer lugs to underside of ring cover lugs, min (6)	*	0.40%	3.1	Gage
106	Location of cover lug slot on outside diameter	*	0.40%	3.1	Gage
Minor					
201	Evidence of poor workmanship		0.40%	3.5	Visual

NOTES:
*See 4.5.1

SARPA-QA FORM 2567 FEB 74 4810

20

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.8	Cover		8840323
			NEXT HIGHER ASSEMBLY 8840290

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Width of o-ring grooves	*		3.1	Gage
102	Diameter of o-ring grooves	*		3.1	Gage
103	Location of o-ring groove with large outside diameter	*		3.1	Gage
104	Large outside diameter	*		3.1	Gage
105	Concentricity of o-ring grooves with large outside diameter	*		3.1	Gage
106	Location of second o-ring groove from large open end	*		3.1	Gage
107	Location of sphere lug cavities	*		3.1	Gage
108	Location of lug (for cover ring slot)	*		3.1	Gage
109	Diameter of cam o-ring groove, max	*		3.1	Gage
110	Distance from center of part to outer edge of lug cavities	*		3.1	Gage
111	Salt spray			3.1	4.5.4
Minor					
201	Width of large sphere lug cavity	*		3.1	Gage
202	Width of small sphere lug cavity	*		3.1	Gage
203	Depth of sphere lug cavities	*		3.1	Gage
204	Evidence of poor workmanship		0.65%	3.1	Visual

NOTES:
*See 4.5.1

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.9	Retainer, spring housing		8840300
			NEXT HIGHER ASSEMBLY 8840288

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness	*		3.1	Gage
102	Angle of outside diameter	*		3.1	Gage
103	Salt spray			3.1	4.5.4
104	Hardness	5	0-1	3.1	4.5.5
Minor					
201	Outside diameter, min		0.65%	3.1	Gage
202	Inside diameter, max		0.65%	3.1	Gage
203	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES: *See 4.5.2

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.10	Barrel		8840317
			NEXT HIGHER ASSEMBLY 8840289

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of flash hole	*		3.1	Gage
102	Location of flash hole	*		3.1	Gage
103	Location of lugs for spring housing assembly	*		3.1	Gage
104	Location of side wall cutout	*		3.1	Gage
105	Diameter of flange	*		3.1	Gage
106	Concentricity of center hole with outside diameter of body	*		3.1	Gage
107	Diameter of center hole, max	*		3.1	Gage
108	Width of obturator slot, flange end	*		3.1	Gage
109	Location of obturator slot, flange end	*		3.1	Gage
110	Diameter of bottom of cavity, flange end	*		3.1	Gage
111	Diameter top of cavity, flange end	*		3.1	Gage
112	Cold shuts or porosity below or within safety tab		0.40%	3.1	Gage
113	Projections or depressions on lug bearing surface for spring housing		0.40%	3.1	Gage
114	Thickness of bottom of barrel cavity, min		0.40%	3.1	Gage
115	Incomplete fill in any area		0.40%	3.1	Visual

NOTES: *See 4.5.1

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 8840317
4.4.2.10	Continued				NEXT HIGHER ASSEMBLY 8840289
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Total height	*		3.1	Gage
202	Depth of cavity, flange end	*		3.1	Gage
203	Outside diameter, small end	*		3.1	Gage
204	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:
*See 4.5.1

SARPA-QA FORM 2567 FEB 74 4010

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.11	Housing, spring		8840308
			NEXT HIGHER ASSEMBLY 8840304

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Concentricity of diameter of flange with diameter of body	*		3.1	Gage
102	Concentricity of diameter of delay setting post with diameter of body	*		3.1	Gage
103	Diameter of flange	*		3.1	Gage
104	Diameter of setting post	*		3.1	Gage
105	Diameter of hole in primer delay cavity	*		3.1	Gage
106	Diameter of body	*		3.1	Gage
107	Height of setting lug	*		3.1	Gage
108	Width of slot in delay setting post	*		3.1	Gage
109	Depth of slot in delay setting post	*		3.1	Gage
110	Location of setting post hole	*		3.1	Gage
111	Distance between outside of projections on spring housing for positioning in body	*		3.1	Gage
112	Location of projections on spring housing for positioning spring in body	*		3.1	Gage
113	Depth of primer-delay cavity	*		3.1	Gage
114	Weight, max		0.40%	3.1	Balance
115	Incomplete fill in any area		0.40%	3.1	Visual

NOTES:
*See 4.5.1

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 8840308
4.4.2.11	Continued				NEXT HIGHER ASSEMBLY 8840304
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4310

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840293
4.4.2.12	Spacer				NEXT HIGHER ASSEMBLY 8840287
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Length to cover notch, min	*		3.1	Gage
Minor					
201	Lugs for notch cover missing		0.65%	3.1	Visual
202	Lug for barrel notch missing		0.65%	3.1	Visual
203	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:
*See 4.5.2

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.13	Latch, arming		8840325
			NEXT HIGHER ASSEMBLY 8840290

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Height of formed edge, min		100%	3.1	Gage
Major					
101	Hardness			3.1	4.5.5
102	Total width	*		3.1	Gage
103	Distance between latch arms	*		3.1	Gage
104	Width of cam slot	*		3.1	Gage
105	Distance from the cam locking surface to the latch arms, max	*		3.1	Gage
106	Diameter of cotter pin hole	*		3.1	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES: *See 4.5.1

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.14	Spring, firing pin				8840310
					NEXT HIGHER ASSEMBLY
					8840306
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Hardness			3.1	4.5.5
102	Thickness of material, min	*		3.1	Gage
103	Width of lever tab, min	*		3.1	Gage
104	Total width	*		3.1	Gage
105	Location of firing pin hole	*		3.1	Gage
106	Location of screw holes (2)	*		3.1	Gage
107	Width of screw holes, max (2)	*		3.1	Gage
108	Length of screw holes, max (2)	*		3.1	Gage
109	Distance from tab to center of firing pin hole	*		3.1	Gage
110	Tab angle	*		3.1	Gage
Minor					
201	Thickness of material, max		0.65%	3.1	Gage
202	Diameter of firing pin hole		0.65%	3.1	Gage
203	Width of slot		0.65%	3.1	Gage
204	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:
*See 4.5.2

SARPA-QA FORM 2567 FEB 74 4310

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.15	Disc		9242434
			NEXT HIGHER ASSEMBLY 8840289

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Salt spray			3.1	4.5.4
102	Hardness			3.1	4.5.5
103	Location of tab	*		3.1	Gage
104	Location of small hole	*		3.1	Gage
105	Location of large hole	*		3.1	Gage
106	Distance from tab to center of large hole	*		3.1	Gage
107	Flatness of disc	*		3.1	Gage
108	Thickness of disc, min	*		3.1	Gage
Minor					
201	Diameter of small hole	*		3.1	Gage
202	Diameter of large hole	*		3.1	Gage
203	Diameter of body, min	*		3.1	Gage
204	Width of tab	*		3.1	Gage
205	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:
*See 4.5.2

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.16	Cam				8840324
					NEXT HIGHER ASSEMBLY 8840290
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pitch diameter of thread, max		0.40%	3.1	Gage
102	Minor diameter of thread, max		0.40%	3.1	Gage
103	Length of thread, min		0.40%	3.1	Gage
104	Spherical diameter		0.40%	3.1	Gage
Minor					
201	Finish improper		0.65%	3.1	Visual
202	Eivdence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.17	Handle, arming latch		8840350
			NEXT HIGHER ASSEMBLY 8840287

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance from small slot to large slot	*		3.1	Gage
Minor					
201	Width of smaller latch hole	*		3.1	Gage
202	Width of larger latch hole	*		3.1	Gage
203	Length of smaller latch hole	*		3.1	Gage
204	Length of larger latch hole	*		3.1	Gage
205	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES: *See 4.5.2

SARPA-QA FORM 2567 FEB 74 amo

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840351
4.4.2.18	Trip lever				NEXT HIGHER ASSEMBLY 8840291
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Load test	50	0.25%	3.1	4.5.8
102	Pitch diameter of thread		0.40%	3.1	Gage
103	Major diameter of thread		0.40%	3.1	Gage
104	Length of thread		0.40%	3.1	Gage
Minor					
201	Diameter of eye		0.65%	3.1	Gage
202	Length from thread end to center of eye		0.65%	3.1	Gage
203	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4010

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.19	Lever, actuating		8840305
			NEXT HIGHER ASSEMBLY 8840303

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Total length	*		3.1	Gage
102	Distance from center of shaft to firing pin spring surface of lever	*		3.1	Gage
103	Distance from center of shaft to barrel surface of lever	*		3.1	Gage
104	Radius from center of shaft to firing pin spring surface of lever	*		3.1	Gage
105	Perpendicularity of shaft (both ends)	*		3.1	Gage
Minor					
201	Total length of shaft		0.65%	3.1	Gage
202	Diameter of shaft		0.65%	3.1	Gage
203	Dry lubricant missing		0.65%	3.1	Visual
204	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:
*See 4.5.1

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.20	Spool trip wire				8840349
					NEXT HIGHER ASSEMBLY
					8840291
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of slots	*		3.1	Gage
102	Width of slots	*		3.1	Gage
103	Small diameter of trip lever hole, max	*		3.1	Gage
104	Width of wrench slot	*		3.1	Gage
105	Inside diameter, max	*		3.1	Gage
106	Body outside diameter	*		3.1	Gage
107	Length from top to seat	*		3.1	Gage
108	Large diameter of trip lever hole, min to indicated depth	*		3.1	Gage
Minor					
201	Total length		0.65%	3.1	Gage
202	Large outside diameter		0.65%	3.1	Gage
203	Color improper		0.65%	3.1	Visual
204	Crack in arming latch handle slot		0.65%	3.1	Visual
205	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

*See 4.5.3

SARPA-QA FORM 2567 FEB 74 4010

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840302
4.4.2.21	Sleeve				NEXT HIGHER ASSEMBLY 8840301
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Inside diameter		0.40%	3.1	Gage
102	Perpendicularity of end faces with outside diameter		0.40%	3.1	Gage
Minor					
201	Total length		0.65%	3.1	Gage
202	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4010

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.22	Cover and arming latch assembly				8840290
					NEXT HIGHER ASSEMBLY 8840287
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Internal air pressure	125	0.40%	3.1	4.5.9
102	Trip lever pull test of cam	80	0.65%	3.1	4.5.10
103	Security of stake of seal retainer	80	0.65%	3.1	4.5.11
104	Security of take-up ring	80	0.65%	3.1	4.5.12
Minor					
201	Any o-ring missing		0.65%	3.1	Visual
202	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.23	Spring housing assembly				8840301
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Security of stake of sleeve	80	0.65%	3.1	4.5.13

NOTES

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.24	Firing pin assembly		8840306
			NEXT HIGHER ASSEMBLY 8840304

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of firing pin point		0.40%	3.1	Gage
102	Profile of firing pin point		0.40%	3.1	Gage
103	Security of crimp of firing pin	80	0.65%	3.1	4.5.14

NOTES:

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.25	Firing pin lever and housing assembly (in tripped position)		8840303
			NEXT HIGHER ASSEMBLY 8840301

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Non-tripping of actuating lever		100%	3.1	4.5.18
Major					
101	Static load test of actuating lever	80	0.65%	3.1	4.5.15
102	Min deflection at point of release of firing pin	80	0.65%	3.1	4.5.16
103	Security of stake of actuating lever	80	0.65%	3.1	4.5.17
104	Length between firing pin spring and flange with lever tripped, max		0.40%	3.1	Gage
105	Concentricity of firing pin with hole in bottom of primer-delay cavity		0.40%	3.1	Gage
106	Stake of actuating lever in housing missing (2 places)		0.40%	3.1	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840352
4.4.2.26	Trip wire assemblies				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Security cold test of trip wire tape	80	0.65%	3.1	4.5.19
102	Pull test of wire and loop of trip wire	125*	0.40%	3.1	4.5.20

NOTES: *Twenty-four (24) inches long.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.27	Barrel and seal assembly				8840289
					NEXT HIGHER ASSEMBLY 8840287
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Safety tab adjacent to center hole missing		100%	3.1	Visual
2	Seal disc perforated or improperly staked		100%	3.1	Visual
Major					
101	Thickness of seal disc, max		0.40%	3.1	Gage
102	Dry lubricant missing from barrel bottom		0.40%	3.1	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4M6

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840291
4.4.2.28	Spool assembly				NEXT HIGHER ASSEMBLY 8840286
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Number of trip wires incorrect		0.40%	3.1	Visual
102	Color of trip wires incorrect		0.40%	3.1	Visual
103	Hole or cutouts (2) missing from arming latch handle		0.40%	3.1	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840288
4.4.2.29	Spring housing and body assembly				NEXT HIGHER ASSEMBLY 8840287
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Spring housing assembly not free to adjust to alignment		0.40%	3.1	Manual
102	Spring housing turns out of body slot		0.40%	3.1	Manual
103	Actuating lever not in armed (cocked) position		0.40%	3.1	Visual
104	Red seal of primer and delay assembly missing		0.40%	3.1	Visual
105	Staking or crimping of sleeve in housing assembly		0.40%	3.1	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840335
4.4.2.30	Delay housing and plug assembly				NEXT HIGHER ASSEMBLY 8840332
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Flash hole not closed when cut-off plug is at extreme counter - clockwise position when viewed from plug end		100%	3.1	Manual-Visual
Major					
101	Torque of cut-off plug		0.40%	3.1	Test
102	Diameter of delay cavity		0.40%	3.1	Gage
103	Diameter under flange		0.40%	3.1	Gage
104	Concentricity of diameter under flange with third largest outside diameter		0.40%	3.1	Gage
105	Concentricity of smallest outside diameter with third largest outside diameter		0.40%	3.1	Gage
106	Location of flash hole with respect to notch		0.40%	3.1	Gage
107	Diameter of flange		0.40%	3.1	Gage
108	Flash hole not open when cut-off plug is at extreme clockwise position		0.40%	3.1	Manual-Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-M-63126 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8840320
4.4.2.31	Cover, ring				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Load test	125	0.40%	3.1	4.5.21

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.32	Metal parts assembly		8840287
			NEXT HIGHER ASSEMBLY: –

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Tape missing from hole		0.40%	3.1	Visual
102	Arrow on cover ring not opposite letter "S" on body		0.40%	3.1	Visual
103	Arming latch improperly assembled		0.40%	3.1	Visual
Minor					
201	External protective coating with bare spot		0.65%	3.1	Visual
202	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4010

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.33	Fiber container, prior to closing				8822121
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Number of mines incorrect		0.40%	3.1	Visual
102	Mine inverted		0.40%	3.1	Visual
103	Insufficient box fillers		0.40%	3.1	Visual
104	Fiber container damaged		0.40%	3.1	Visual
Minor					
201	Spacer tube on pad missing		0.65%	3.1	Visual
202	Marking of container misleading or unidentifiable		0.65%	3.1	Visual
203	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-M-63126 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.34	Sealed packing box		8822122
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Sealing or strapping insecure		0.40%	3.1	Manual-Visual
102	Box damaged		0.40%	3.1	Visual
103	Marking misleading or unidentifiable		0.40%	3.1	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. - Testing is described in the First Article and Quality Conformance Inspection Tables.

4.4.4 Inspection equipment. - The inspection equipment required to perform the examinations and tests prescribed herein is described in the Paragraph Reference/Inspection Method column in the tables starting with Paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 herein.

4.5 Test methods and procedures.

4.5.1 Dimensional control of cast parts. - In place of the normal sampling associated with the Classification of Defects, and with the approval of the Contracting Officer, a sample of at least three (3) parts (as cast) from each cavity shall be dimensionally inspected to quality a new or reworked cavity for use in production or as a control of the cavity during production. Inspection for control of each cavity during production shall be performed on the above quantities from each cavity after production of 5000 parts. Individual cavity identification must be provided.

If any defective parts are found during qualification of the cavity, the cavity producing the defective part shall not be used in production. If any defective parts are found when inspection is performed for control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for corrective action.

All cavities formerly removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test specified above. The contractor may request a change of inspection frequency providing he presents objective evidence to substantiate the request to the Contracting Officer.

4.5.2 Dimensional control of stamped parts. - In place of the normal sampling associated with the Classification of Defects, and with the approval of the Contracting Officer, a sample of at least ten (10) parts shall be dimensionally inspected to qualify the tool used in the stamping process for use in production. In addition, a random sample of five (5) parts shall be selected from the last portion of each hour's

Source: https://assist.dla.mil -- Downloaded: 202640-26T04:25Z
Check the source to verify that this is the current version before use.

production for dimensional inspection as a control of the tool during production.

If any defective parts are found during qualification of the tool, the tool producing the defective part shall not be used in production.

If any defective parts are found when inspection is performed for control of the tool, the tool producing the defective part shall be removed from production. Further, that portion of production since the last tool control check shall be returned to the contractor for corrective action.

All tools removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the Contracting Officer to substantiate the request.

4.5.3 Dimensional control of molded or plastic parts. - In place of the normal sampling and inspections associated with the Classification of Defects, and after a curing time for the parts has been approved (See Note 1), a sample ofthree (3) parts (as molded) from each cavity shall be fully inspected dimensionally to qualify a new or reworked cavity for use in production. The molded parts shall carry the individual cavity identification. As a control of each cavity during production, the above quantity of parts from each cavity shall be inspected for at least the defects listed in paragraphs 4.4.2.1 through 4.4.2.34 after continuous production of each 5,000 parts or at the end of each week, whichever occurs first. Of the three (3) samples, one (1) sample shall be the last part produced. If any defective parts are found during qualification of the cavity, the cavity producing the defective part will not be used in production. If any defective parts are found when inspection is performed for the control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for inspection for each separate type of defect according to MIL-STD-105, using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. All cavities removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the Contracting Officer to substantiate the request. Contractor designs of

Source: https://assist.dla.mil -- Downloaded: 202640-26T04:25Z
Check the source to verify that this is the currenversion before use.

gages and test equipment required to perform the inspections listed herein shall be forwarded to Commander, ARRADCOM, Dover, New Jersey 07801, ATTN: DRDAR-QAA-I for approval prior to manufacture of equipment. The noted sub-paragraphs identify those items and minimum inspections subject to the requirements of this paragraph.

NOTE 1: In establishing a curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g. every 30, 60 etc. mins) until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. The inspection data used in determining the curing time shall be sent to ARRADCOM, Dover, New Jersey 07801 ATTN: DRDAR-QAA-Q. If there is a change in material, or in the cycle time, or if a cavity is reworked, or a new cavity is used, a new curing time shall be established and approved.

4.5.4 Salt spray.

4.5.4.1 Batch-type process. - When the parts are produced in a batch-type process, ten (10) of each part shall be selected from each batch and subjected to the salt spray test. If any part fails to comply with the specified requirement, the batch represented by the failing part shall be rejected. The test shall be performed in accordance with ASTM-B-117-73. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.5.4.2 Continuous-type process. - When the parts are produced in a continuous-type process, five (5) parts shall be selected from each four (4) hours production and subjected to the salt spray test specified in ASTM-B-117-73. If any part fails to comply with the applicable requirement, the quantity represented by the sample shall be rejected. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.5.4.3 Lot plan. - Ten (10) parts shall be selected from each lot and subjected to the salt spray test specified in ASTM-B-117-73. If any part fails to comply with the applicable requirement, the lot shall be rejected. This test is a destructive test. Parts so tested shall not be returned to the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.5.5 Hardness. - Five (5) parts shall be selected from each heat-treatment batch (see Note 1) and subjected to the test specified in ASTM-E-18-67. If any part fails to comply with the applicable requirement, the batch represented by the sample shall be rejected.

NOTE 1: A heat-treatment batch shall be defined as parts that have been heat treated at the same time in the same furnace and quench batch for each of all phases of the entire heat-treatment process.

4.5.6 Internal air pressure of body. - The body shall be placed in an approved fixture and the required pressure specified on the applicable drawing shall be applied. This test is a non-destructive test. Parts so tested may be returned to the lot.

4.5.7 Body porosity. - Each body selected for this determination shall be sectioned longitudinally in four (4) places, 90 degrees apart. Only the cross sectioned area of each segment shall be examined for voids or pits that exceed drawing requirements.

4.5.8 Load test of trip lever. - The trip lever shall be placed in an approved fixture and the load specified on the applicable drawing shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.5.9 Internal air pressure of cover and arming latch assembly. - The cover and arming latch assembly shall be placed in an approved fixture and the required pressure specified on the applicable drawing shall be applied. This test is a non-destructive test. Parts so tested may be returned to the lot.

4.5.10 Trip lever pull test of cam on cover and arming latch assembly. - The cover and arming latch assembly shall be placed in an approved fixture and the load specified on the applicable drawing shall be applied. This test is a non-destructive test. Parts so tested may be returned to the lot.

4.5.11 Security of stake of seal retainer on cover and arming latch assembly. - The cover and arming latch assembly shall be placed in an approved fixture and the load specified on the applicable drawing shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.5.12 Security of take-up ring on cover. - The cover with staked take-up ring shall be placed in an approved fixture and the load specified on the applicable drawing shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.5.13 Security of stake of sleeve on spring housing assembly. - The spring housing assembly with sleeve and steel pin assembled shall be placed in an approved fixture and the force specified on the applicable drawing shall be applied parallel to the longitudinal centerline. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.5.14 Security of crimp of firing pin on firing pin assembly. - The firing pin assembly shall be placed in an approved fixture and the force specified on the applicable drawing shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.5.15 Static load test of actuating lever on firing pin, lever and housing assembly. - The firing pin, lever and housing assembly shall be placed in an approved fixture and the static load specified on the applicable drawing shall be applied. This test is a non-destructive test. Parts so tested may be returned to the lot.

4.5.16 Min. deflection at point of release of firing pin on firing pin, lever and housing assembly. - The firing pin, lever and housing assembly shall be placed in an approved fixture and observation shall be made for the amount of deflection specified on the applicable drawing. This test is a non-destructive test. Parts so tested may be returned to the lot.

4.5.17 Security of stake of actuating lever on firing pin, lever and housing assembly. - The firing pin, lever and housing assembly shall be placed in an approved fixture and the force specified on the applicable drawing shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.5.18 Non-tripping test of actuating lever and firing pin, lever and housing assembly. - The firing pin, lever and housing assembly shall be placed in an approved fixture and

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the currentversion before use.

observation shall be made for the amount of travel of lever specified on the applicable drawing. This test is a non-destructive test. Parts so tested may be returned to the lot.

Actuating levers that trip the firing pin prior to attaining the max. dimension specified on the applicable drawing shall be classed defective.

4.5.19 Security cold test of trip wire tape on trip wire assembly. - The trip wire assembly shall be placed in an approved chamber and the temperature of the chamber shall be lowered to that specified on the applicable drawing. This test is a non-destructive test. Trip wires without visible signs of tape looseness may be returned to the lot.

4.5.20 Pull test of wire and loop of trip wire. - The trip wire assembly shall be placed in an approved fixture and the load specified on the applicable drawing shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

4.5.21 Load test of cover ring. - The cover ring shall be placed in an approved fixture and the load specified on the applicable drawing shall be applied. This test is a destructive test. Parts so tested shall not be returned to the lot.

5. PACKAGING.

5.1 Preservation and packaging.

5.1.1 Level C. - The mines shall be preserved and packaged in accordance with Dwg 8822121.

5.2 Packing.

5.2.1 Level C. - The mines, preserved and packaged as specified in 5.1.1, shall be packed in accordance with Dwg. 8822122.

5.3 Marking. - Marking of the cartons shall be in accordance with Army Regulation AR 380-55, Dwg. 8822121, 8822122 and Code of Federal Regulation, Title 49, Parts 100-199.

5.4 Shipping. - When components from more than one lot are shipped as a carload, each lot shall be kept separate, and the division between lots clearly indicated to prevent mixing of the lots in transit.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

6. NOTES

6.1 Intended use. - The components covered by this specification are intended for use on Mine, Anti-Personnel, M26.

6.2 Ordering data. - See MIL-A-48078.

6.3 Submission of inspection equipment designs for approval. - See MIL-A-48078. Submit equipment designs as required to Commander, ATTN: DRDAR-QA-I, ARRADCOM, Dover, NJ 07801.

6.4 Data requirements. - Deliverable data required by this specification is cited on the 1423 form specified in the contract.

(Copies of data item descriptions required by the contractor in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

6.5 Documentation submitted for approval. - Documentation concerning the formation of die casting lots shall be submitted for approval to: Commander, ARRADCOM, ATTN: DRDAR-QAA-A.

Custodian:
Army-AR

Preparing activity:
Army-AR

Project Number: 1345-A-184

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

OMB Approval
No. 22-R255

INSTRUCTIONS: The purpose of this form is to solicit beneficial comments which will help achieve procurement of suitable products at reasonable cost and minimum delay, or will otherwise enhance use of the document. DoD contractors, government activities, or manufacturers/ vendors who are prospective suppliers of the product are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity.

DOCUMENT IDENTIFIER AND TITLE

NAME OF ORGANIZATION AND ADDRESS

CONTRACT NUMBER

MATERIAL PROCURED UNDER A

☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?
   A. GIVE PARAGRAPH NUMBER AND WORDING.

   B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY DOCUMENT REQUIREMENT CONSIDERED TOO RIGID

3. IS THE DOCUMENT RESTRICTIVE?

   ☐ YES ☐ NO *(If "Yes", in what way?)*

4. REMARKS

SUBMITTED BY *(Printed or typed name and address - Optional)*

TELEPHONE NO.

DATE

DD FORM 1 JAN 72 1426 REPLACES EDITION OF 1 JAN 68 WHICH MAY BE USED

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

FOLD

POSTAGE AND FEES PAID
DEPARTMENT OF THE ARMY
DOD – 314

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

Commander
US Army Armament R&D Command
ATTN: DRDAR-QAA
Dover, NJ 07801

FOLD

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.