MIL-P-63066
1 June 1976

MILITARY SPECIFICATION

PROJECTILE, 155MM, SPECIAL TEST, FOR M692 AND M731

LOADING, ASSEMBLING AND PACKING OF

This specification is approved for use by Picatinny Arsenal, Department of the Army, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing of the Special Test Projectile, 155MM, for the M692 and M731 Projectiles and the assembly of the munition contained therein.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078	- Ammunition, Standard Quality Assurance Provisions, General Specification For

STANDARDS

MILITARY

MIL-STD-105	- Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-286	- Propellants, Solid: Sampling, Examination and Testing
MIL-STD-453	- Inspection, Radiographic

FSC: 1320

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

DRAWINGS

PICATINNY ARSENAL

8837839	- Pallet for Projectile, 155MM, HE, M470 or M483
9298319	- Special Test Projectile for M692/M731 155MM (U)
9298399	- Special Test Mine
9298714	- Self Destruct Time Requirements

2.2 Other Publications - The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on the date of invitation for bids or request for proposal shall apply.

CODE OF FEDERAL REGULATIONS

Title 49	- Transportation, Parts 100-199

(The Code of Federal Regulations is available from the Superintendent of Documents, US Government Printing Office, Washington, D.C. 20402. Orders should specify "49 CFR 100-199 (latest revision)").

3. REQUIREMENTS

3.1 Material - Materials shall be in accordance with the applicable drawings and specifications.

3.2 Components and Assemblies -

3.2.1 Projectile - The Projectile Assembly and Components shall comply with all requirements specified on Drawing (Dwg.) 9298319, all associated drawings and with all requirements specified in applicable specifications.

3.2.2 Munition - The munition and components shall comply with all requirements specified on Dwg. 9298399, all associated drawings and with all requirements specified in applicable specifications.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

3.3 Ballistic Functioning -

3.3.1 Projectile - There shall be no premature burst (See 6.5.1) or evidence thereof, and there shall be no separation of metal parts either in the bore of the weapon or in flight, prior to initiation of the nose fuze in any of the ballistic functioning tests.

3.3.2 Projectile Functioning - The projectile shall function satisfactorily (See 6.5.2)

3.3.3 Munition Functioning - The munition shall meet the followin requirements after being ejected into a prepared impact area from a projectile fired in accordance with 4.5.7.

3.3.3.1 Time-out Functioning - The munitions from an M731 projectile shall have functioned the detonator within the time specified on Dwg. 928714 for a type 1 housing, and the munitions from an M692 projectile shall have functioned the detonator within the time specified on Dwg. 9298714 for a type 2 housing.

3.3.3.2 Functioning after Maximum Time - The munitions from an M731 projectile shall not be capable of functioning after the maximum time specified on Dwg. 9298714 for a type 1 housing, and the munitions from an M692 projectile shall not be capable of functioning after the maximum time specified on Dwg. 9298714 for a type 2 housing.

3.4 Radiographic Examination of Projectile - The projectile shall have each layer of munitions properly positioned with respect to the keyway and shall have the column segments (in layers 1 through 4) aligned to form a straight column when the projectile is radiographically examined. Radiographs shall be taken in accordance with MIL-STD-453 and shall be of a quality which will permit evaluation as determined by the responsible Government Technical Agency.

3.5 Documentation of Plan for Safety in Handling of Munitions - Prior to loading, the contractor shall document a detailed plan of the procedures to be employed during handling of the munition. This documentation shall describe, as a minimum, the procedures to be employed to assure that:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

(1) The shorting bar is not deformed or broken;
(2) The battery is not activated;
(3) The two munition models remain segregated at all times;
(4) The exterior model markings on each projectile are consistent with the munitions it contains;
(5) The temperature of the housing, timing and fuzing, or the munition does not exceed 165°F at any time during processing or storage.
(6) Special test munitions remain segregated from HE munitions.

The plan shall be submitted to the address specified in 6.7 for approval. Approval shall be received prior to any loading. Any changes to the approved plan shall be submitted for approval prior to implementation.

3.6 Compressive Strength of Molding Compound - The molding compound for assembling the plug to the housing shall comply with MIL-M-48245. The resin/hardener weight ratio shall be 2.0/1.0 ± 5% (1.8/1 to 2.2/1) and the ultimate compressive strength shall be 29,000 to 38,200 psi.

3.7 Temperature Control during Molding and Cure of Munition - The munition shall not be subjected to temperatures exceeding 165°F at any time.

3.8 Workmanship - All parts and assemblies shall be fabricated, loaded and assembled in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, grease, rust and other foreign matter that may impair proper functioning. The cleaning method used shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agents. All required marking and stamping shall be neat and sharply defined.

3.9 First Article Inspection - This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions - Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.2 Classification of Inspections - The following type of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First Article Inspection -

4.3.1 Submission - The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawing		Quantity
Special Test Mine	9298399		10
Test bars			2
Charge Assembly			20
Projectile (prior to assembly of charge and sleeve assembly)	9298319 Note 2	See Note 1 Note 3	1

Note 1: The Projectile shall contain 27 special test mines in all layers except 4 and 8.

Note 2: The Projectile shall be used for all the examinations and tests specified in Table 1.

Note 3: The Contracting Officer shall designate the projectile model required.

4.3.2 Inspections to be Performed - See MIL-A-48078 and Table 1 herein.

4.3.3 Rejection - See MIL-A-48078. The first article sample shall be rejected if any projectile fails to comply with any of the examinations or tests specified in this specification or any of the requirements of the applicable drawing.

In addition, the first article sample shall be rejected if the ballistic test results reveal any one of the following defects:

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the currentversion before use.

a. Any premature burst occurs (See 6.5.1)
b. Any separation of metal parts occurs prior to initiation of the nose fuze.
c. Any detonation of the projectile cargo occurs prior to initiation of the nose fuze.
d. Any projectile fails to function satisfactorily (See 6.5.2)
e. Any shorting bar is not completely removed or any battery ball is not depressed to activate the battery.
f. Any munition functions (or is capable of functioning) after the maximum time has elapsed (Hazardous dud)
g. A total of two or more munitions do not function (and are not capable of functioning) after the maximum time has elapsed - (Non hazardous dud)

Source: https://assist.dla.mil -- Downloaded: 202640-26T04:25Z
Check the source to verify that this is the currentversion before use.

TABLE 1 - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63066

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
	Projectile and Components				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Special Test Mine (Dwg. 9298399)				
	Examination for Defects	10		3.2	4.4.2.6
	Compressive Strength of Test bars			3.6	4.5.1
	Charge Assembly (Dwg. 9298363)				
	Examination for Defects	20		3.2	4.4.2.19
	Leakage Test	20		3.2	4.5.4
	Projectile, (prior to assembly of charge and sleeve assembly) (Dwg. 9298319)				
	Examination for Defects	3		3.2	4.4.2.16
	Radiographic Examination	3		3.4	4.5.5
	Projectile, (prior to assembly of grommet) (Dwg. 9298319)				
	Examination for Defects	3		3.2	4.4.2.22
	Projectile (Dwg. 9298319)				
	Ballistic Functioning Test	1		3.3	4.5.7

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.4 Quality Conformance Inspection -

4.4.1 Inspection Lot Formation - Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of projectiles shall contain:

a. Projectile metal parts assemblies of one lot interfix number from one manufacturer.
b. Hardware components of one lot interfix number from one manufacturer.
c. Housing, Timing and Fuzing of one lot serial number from one manufacturer and of one designated type.
d. Charge assembly propellant from one lot only.
e. Projectiles of one model only.

4.4.2 Examination - See MIL-A-48078.

a. Sampling Plans - Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Kill Mechanism Assembly, Inert		9298442
			NEXT HIGHER ASSEMBLY 9298449

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Minor					
201	Outside diameter, max.		0.65%	3.2	Gage
202	Total height, max.		0.65%	3.2	Gage
203	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298449
4.4.2.2	Kill Mechanism and Overlay Assembly (Inert)				NEXT HIGHER ASSEMBLY 9298399
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical 1	Presence of any explosive component		100%	3.2	Visual
Major 101	Diameter, max (at equator)		0.40%	3.2	Gage
Minor 201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.3	Housing, Timing and Fuzing (Prior to assembly of inert kill mechanism and overlay assembly)		9298450
			NEXT HIGHER ASSEMBLY 9298399

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Special					
a.	Barrier assembly not present or not properly positioned in S&A		100%	3.2	X-Ray
Major					
101	Shorting bar broken or damaged		100%	3.2	Visual
102	Battery ball depressed below normal position		100%	3.2	Gage
103	Foreign material in kill mechanism cavity		0.40%	3.2	Visual
104	Largest diameter in kill mechanism cavity not prepared for bonding		0.40%	3.2	Visual
105	Sensor plug(s) missing or damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298401
4.4.2.4	Plug, Housing				NEXT HIGHER ASSEMBLY 9298399
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Applicable surfaces not prepared for bonding		0.40%	3.2	Visual
102	Any projection on concave surface		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

SARPA-QA FORM 2567 FEB 74 4810

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298399
4.4.2.5	Special Test Mine (prior to assembly of plug)				NEXT HIGHER ASSEMBLY 9298399
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Presence of HE Kill Mechanism and Overlay Assembly		100%	3.2	Visual
Major					
101	Housing not marked to indicate inert kill mechanism and overlay assembly		100%	3.2	Visual
102	Distance from arc face to top of kill mechanism and overlay assembly, minimum		0.40%	3.2	Gage
103	Kill mechanism and overlay assembly incorrectly positioned, or loose in housing		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9298399
4.4.2.6	Special Test Mine				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Shorting bar broken or damaged		100%	3.2	Visual
102	Battery ball below minimum		0.40%	3.2	Gage
103	Shorting bar height below minimum		0.40%	3.2	Gage
104	Total height		0.40%	3.2	Gage
105	Arc face radius		0.40%	3.2	Gage
106	Distance from arc face to apex gaging radius		0.40%	3.2	Gage
107	Perpendicularity of arc face to triangular face		0.40%	3.2	Gage
108	Any sensor deployed		0.40%	3.2	Gage
109	Voids in plug bond area		0.40%	3.2	Gage
110	Surface Finish on Arc Face		0.40%	3.2	Finish Blocks
111	Any sensor restricted (caps not removed)		0.40%	3.2	Visual
112	Temperature control during cure			3.7	4.5.2
113	Resin/Hardener Weight Ratio of molding compound			3.6	4.5.1
114	Compressive strength of molding compound			3.6	4.5.1
115	Molding compound shelf life expired			3.1	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9298399
4.4.2.6	Special Test Mine				NEXT HIGHER ASSEMBLY 9298319
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Test pads exposed		0.65%	3.2	Visual
202	Marking missing, incorrect or unidentifiable		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.7	Projectile metal parts assembly (prior to insertion of battery activation assembly)		9298350
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Depth of cavity, min.		100%	3.2	Gage
102	Rust or foreign matter on interior wall, threads, or face at base end		0.40%	3.2	Visual
103	Base or ogive thread damaged		0.40%	3.2	Visual
104	Lubricant coating missing, incomplete, damaged, or peeling		0.40%	3.2	Visual
105	Lubricant coating present on threads		0.40%	3.2	Visual
106	Rotating band damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298890
4.4.2.8	Battery activation assembly				NEXT HIGHER ASSEMBLY 9298319
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance from top of piston to forward face of pusher plate, max.		100%	3.2	Gage
102	Distance from top of piston to second shoulder on battery rod, max.		100%	3.2	Gage
103	O-ring missing, damaged, or not lubricated		0.40%	3.2	Visual
104	Battery rod bent or without cutouts		0.40%	3.2	Visual
Minor					
201	Adhesive missing from threads (prior to assembly)		0.65%	3.2	Visual
202	Excessive adhesive around threaded joints		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298399
4.4.2.9	Special Test Mine (immediately prior to assembly into stack-up)				NEXT HIGHER ASSEMBLY 9298319
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Type 2 munition being assembled into stack-up for M731 projectile		100%	3.2/3.6	Visual
Major					
101	Shorting bar missing, broken, or damaged		100%	3.2	Visual
102	Any sensor deployed		100%	3.2	Visual
103	Type 1 munition being assembled into stack-up for M692 projectile		100%	3.2/3.6	Gage
104	Battery ball or shorting bar below min height		100%	3.2	Gage
105	Any sensor plug not removed		0.40%	3.2	Visual
106	Munition damaged		0.40%	3.2	Visual
107	Paint missing (if applicable)		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.10	Munition Stack-up (layers 1 to 8 prior to assembly into projectile)		9298319
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical 1	Presence of any HE munition		100%	3.2/3.5	Visual
Major 101	Any munition improperly positioned, (i.e., #7 sensor not facing base end of stack-up)		100%	3.2	Visual
102	Segment column height to munition column height incorrect		100%	3.2	Certification
103	Sizing ring for radial compressive load incorrect for projectile diameter		100%	3.2	Visual
104	Disc pad missing from pusher plate		100%	3.2	Visual
105	Any plate pad missing		100%	3.2	Visual
106	Any munition missing or damaged		100%	3.2	Visual
107	Any layer not properly aligned with keyway		100%	3.2	Certification
108	Any layer not radially sized or failing to comply with the specified force		100%	3.2	Certification
109	Layer 2,3,4,6,7, or 8 not containing all dummy units		100%	3.2	Visual
110	Layer 1 or 5 not containing all special test mines		100%	3.2	Visual
Minor 201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.11	Projectile(during and after assembly of munitions and prior to assembly of base plug)		9298319
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Exterior markings indicate M731 projectile, but munitions are for M692 projectile		100%	3.2/3.6	Visual
102	Exterior markings indicate M692 projectile, but munitions are for M731 projectile		100%	3.2/3.6	Visual
103	Base pad missing		100%	3.2	Visual
104	Base clearance inadequate		100%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298335
4.4.2.12	Base Plug (prior to assembly to body)				NEXT HIGHER ASSEMBLY 9298319
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Seal ring missing		0.40%	3.2	Visual
Minor					
201	Sealant not applied to threads		0.65%	3.2	Visual
202	Threads damaged		0.65%	3.2	Visual
203	Nicks on shoulder adjacent to threads		0.65%	3.2	Visual
204	Seal ring not lubricated		0.65%	3.2	Visual
205	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.13	Projectile (after assembly of base and prior to assembly of ogive)				9298319
					NEXT HIGHER ASSEMBLY
					9298319
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Base turns when specified disassembly torque is applied		100%	3.2	Gage
102	Excessive gap between body and base		100%	3.2	Gage
Minor					
201	Sealant on exterior surface		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the currenversion before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.14	Shim, Ogive (prior to assembly to projectile)	1 OF 1	9298339
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Thickness incorrect for required preload		100%	3.2	Gage
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298324
4.4.2.15	Ogive (prior to assembly to projectile)				NEXT HIGHER ASSEMBLY 9298319
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Seal ring missing		0.40%	3.2	Visual
Minor					
201	Compound not applied to external threads		0.65%	3.2	Visual
202	External threads damaged		0.65%	3.2	Visual
203	Nicks on shoulder adjacent to external threads		0.65%	3.2	Visual
204	Seal ring not lubricated		0.65%	3.2	Visual
205	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.16	Projectile (immediately after assembly of ogive and prior to assembly of charge and sleeve assembly)		9298319
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Gap between body and ogive beyond specified limits		100%	3.2	Gage
102	Concentricity of ogive to bourrelets (2 places)		100%	3.2	Gage
103	Radiographic Examination (Column segments not axially aligned)		100%	3.4	4.5.5
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298370
4.4.2.17	Spotting Charge Assembly				NEXT HIGHER ASSEMBLY 9298360
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cup not completely filled (settling permitted)		0.40%	3.2	Visual
102	Tape missing or loose		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298360
4.4.2.18	Charge and Sleeve Assembly (prior to insertion of charge assembly)				NEXT HIGHER ASSEMBLY 9298319
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Spotting charge assembly not secure (when applicable)		0.40%	3.2	Visual/Manual
102	Closure cup missing (when applicable)		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.19	Charge Assembly (prior to insertion into charge and sleeve assembly)		9298363
			NEXT HIGHER ASSEMBLY 9298360

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Weight of propellant incorrect		0.40%	3.2	Balance
102	Bag waterproofness destroyed (separation of heat seal, bag punctured etc)		0.40%	3.2	Visual
103	Leakage test	32-0-1		3.2	4.5.4
104	Moisture and Volatiles content of propellant			3.2	4.5.3
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

SARPA-QA FORM 2567 FEB 74 4810

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.20	Charge and Sleeve Assembly (prior to insertion into projectile)		9298360
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Staking of charge cover missing or inadequate (4)		0.40%	3.2	Visual
102	Cover damaged (dented, punctured etc)		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.21	Projectile (after assembly of charge and sleeve assembly and prior to assembly of lifting plug)	1 OF 1	9298319
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Weight		100%	3.2	4.5.6
102	Retaining ring missing or improperly assembled		0.40%	3.2	Visual
103	Foreign matter in fuze cavity		0.40%	3.2	Visual
104	Lifting plug gasket missing		0.40%	3.2	Visual
105	Lifting plug threads not greased		0.40%	3.2	Visual
106	Threads damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.22	Projectile (prior to assembly of grommet)	1 OF 1	9298319
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Lifting plug turns when disassembly torque is applied		0.40%	3.2	Test
102	Diameter of bourrelet, max (applicable after retouching paint)		0.40%	3.2	Gage
103	Rotating band damaged		0.40%	3.2	Visual
104	Obturator missing or damaged		0.40%	3.2	Visual
105	Stamped letter "A" missing from ogive (indicating air pressure test failure)		0.40%	3.2	Visual
106	Ballistic functioning test (High Zone)	1 Rd		3.3	4.5.7
Minor					
201	Protective coating with a total of bare areas in excess of 1/4 square inch		0.65%	3.2	Visual
202	Marking missing or unidentifiable		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.23	Pallet (loaded)		8837839
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Projectile lifting plug missing or damaged, or wrong type (not fusible)		0.40%	3.2	Visual
102	Projectile grommet assembly missing, damaged, or improperly assembled		0.40%	3.2	Visual
103	Board broken or split		0.40%	3.2	Visual
Minor					
201	Strap width incorrect		0.65%	3.2	Visual
202	Strapping improperly assembled		0.65%	3.2	Visual
203	Marking missing, incorrect or unidentifiable		0.65%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63066 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.24	Wood box (prior to closing) (Applicable when projectiles are not shipped on pallets)				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Provisional pack warning sheet missing		100%	3.2	Visual
102	Projectile not secured		100%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63066 (PA)

PARAGRAPH	TITLE			SHEET 1 OF 1	DRAWING NUMBER
4.4.2.25	Wood Box (after closing and sealing) (applicable when projectiles are not shipped on pallets)				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Provisional pack warning missing		100%	3.2	Visual
102	Exterior markings missing, incorrect or unidentifiable		100%	3.2	Visual
103	Cover not secured		100%	3.2	Visual
Minor					
201	Box damaged		100%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.4.3 Testing - Testing is described in the First Article and Quality Conformance Inspection Tables.

4.4.4 Inspection Equipment - The inspection equipment required to perform the examinations and tests prescribed herein is described in the "Paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1. The contractor shall submit inspection equipment designs for approval in accordance with the terms of the contract. See Section 6 of MIL-A-48078.

4.5 Test Methods and Procedures -

4.5.1 Quality Controls for each Molding Compound Batch for Assembling Plugs to Housings -

4.5.1.1 Molding Compound Batch Definition - A batch of molding compound is herein defined as that quantity of compound mixed at one time using base resin and hardener from one lot interfix number from one manufacturer and used to assemble plugs to housings in one unchanged process. When a continuous type mixing process is used, a batch is defined as that quantity of molding compound mixed and dispensed in one continuous unchanged process during a four (4) hour period or portion thereof using base resin and hardener from one lot interfix number from one manufacturer.

4.5.1.2 Resin/Hardener Weight Ratio Control -

a. Hand mixing: For each batch of molding compound mixed at one time, the hardener and resin shall be weighed separately to verify that the ratio is between 1.8/1 and 2.2/1 before use.

b. Automatic Mixer Method: At the beginning of production and once each four (4) hours during production, two test shots shall be drawn with the mixer set to expel the hardener and resin separately. The hardener and resin shall be weighed to verify that the ratio is between 1.8/1 and 2.2/1. If the shots fail to meet the requirement, all wedges filled since the last acceptable test shall be rejected. Further, the mixer shall be corrected and shall pass the above test before being returned to use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.5.1.3 Cure Control - Two test bars (1/2 inch x 1/2 inch x 1.6 inches) from each batch of molding compound shall be molded at the same time the batch is used to assemble plugs to housings. Test bar molding shall be by best commercial practice, including vibration and evacuation if necessary. The mix weight ratio limits shall be 2/1 + 5% (1.8/1 to 2.2/1). The test bars shall be processed with the items assembled from the batch of molding compound which the bars represent., i.e. the bars shall be cured in the same ovens and subjected to the same temperatures for the same time periods as the items they represent. After completion of the cure, the bar shall be tested for ultimate compressive strength as specified in ASTM D-695 except that the test bar dimension shall be 0.5 inches by 0.5 inches by 1.6 inches. The ends shall be flat and parallel to within .001 inch and shall be perpendicular to the long axis of the test bar. Speed of testing shall be as specified in the ASTM. If the results of this test are outside the limits specified in 3.6, the munitions represented by the bar shall be rejected.

4.5.2 Temperature Control during Molding/Cure Operations - Whenever the housing or mine is subjected to heating in ovens, temperature records shall be maintained and reviewed to assure that the minimum temperature has been reached and that the maximum temperature has not been exceeded. If any units have been subjected to temperatures beyond the maximum limit at any time, regardless of duration, they shall be rejected. Temperature measuring instruments shall be approved and calibrated in accordance with 4.4.4.

In addition, if units are stored where temperatures may exceed the limit specified in 3.7, temperature monitoring equipment shall be provided and constant records maintained of the temperature to assure that the temperature limit is not exceeded.

4.5.3 Moisture and Total Volatiles Content of Charge Assembly Propellant - The contractor shall provide adequate controls to insure compliance with the applicable requirement. The moisture and total volatiles content of each lot of propellant shall be determined at the loading station at the time of loading the charge assemblies. This determination shall be

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the currentversion before use.

made at least once for eight (8) hours of production. Sampling and testing of the propellant shall be in accordance with MIL-STD-286, Method 101.1.2. If the moisture and total volatiles content fails to comply with the requirement specified on the applicable drawing and loading of the charge assemblies has not begun, the propellant lot shall be rejected until corrective action has been taken as verified by repeating the moisture and total volatiles content determination. If loading has begun, charge assemblies loaded with the nonconforming propellant shall be rejected.

4.5.4 Leakage Test of Charge Assembly - The specified quantity of charge assemblies shall be subjected to the pressure specified on the applicable drawing using equipment as specified in 4.4.4. A water immersion test shall be used. Any assembly which emits bubbles shall be rejected. Charge assemblies so tested shall not be returned to any lot. (Destructive test)

4.5.5 Radiographic Examination of Projectile - Prior to assembly of the base plug, the location of the keyway shall be marked on the exterior of each projectile. The projectiles shall be radiographed after assembly of the ogive and prior to assembly of the charge and sleeve assembly. In all exposures, the radiographic beam shall be focused along the center axis of the projectile and parallel to the face of the shelf plate. One radiograph shall be taken 10° clockwise from the keyway position, such that the column segments are in line with the source. A second radiograph shall be taken at a location with the projectile rotated 45° clockwise from the view of the first radiograph. The radiograph shall, as a minimum, show the entire cargo pack including the base and forward plate. If necessary, more than one radiograph in a view shall be taken as required to avoid detrimental parallax effects. The radiographs shall be examined for any of the conditions specified in 3.4. All projectiles failing to conform to the requirements shall be suitably identified and removed from the lot. Projectiles and radiographs shall be identified to permit future reference. The radiograph for the ballistic sample shall be furnished with the projectile to the Government inspector.

NOTE: Radiographic equipment, operations and procedures shall be qualified in accordance with MIL-STD-453. In addition, the

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

photographic density of the film used shall be of quality which will produce a sharp definition of internal structure.

4.5.6 Projectile Weight Determination - The projectile, without lifting plug, gasket and grommet assembly, shall be weighed using equipment of suitable range and accuracy. The weight shall be marked in the specified location on the projectile and this marking shall be verified as being the same as the weight indicated by the equipment.

4.5.7 Ballistic Functioning -

4.5.7.1 Testing - This test shall be conducted at a Government proving ground in accordance with approved Acceptance Test Procedures. The round shall be fitted with a fuze which is standard for the projectile. The projectile fuze setting and the quadrant elevation of the weapon shall be adjusted to achieve a burst height between fifteen hundred (1500) and twenty-five hundred (2500) feet over a prepared impact area. A photograph shall be taken of the fuze setting for each round immediately prior to firing and each photograph shall be marked for future identification with the round. The sample projectile(s) shall be tested at high zone (zone 8) in the M109A1 weapon using equipment, methods and procedures in accordance with the acceptance test procedures referenced above. Suitable equipment for safely monitoring cargo performance must be provided at the impact area. The M109A1 weapon shall be used unless otherwise specified by the procuring agency. Observation shall be made for failure to comply with the requirements of 3.3.

After ejection and impact, a record shall be made of the number of sensors deployed from each munition and approximate length of each tripline. Then one-third of the items shall be tested in the breakwire mode, one-third shall be tested in the anti-disturbance (AD) mode, and one-third shall be tested in the self-destruct mode. Any unit which fails to deploy any sensors shall be tested in the self destruct mode.

Those units to be tested in the breakwire mode shall be tested by restricting movement of the item and attaching a force gage to a tripline and exerting an axial pull force to function the item. A record shall be made of the force required to function the breakwire. Units which fail to function on first attempt shall be tested in the AD mode.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

Those units to be tested in the anti-disturbance mode shall be tested by rolling the item from one face to another. Units which fail to function on the first attempt shall be tested in the breakwire mode. The breakwire mode and anti-disturbance mode tests are for informational purposes.

Recording equipment may be used to determine the time of functioning of items tested in the self-destruct time. After the maximum time-out time has elapsed plus one hour, the impact area shall be searched for non-functioning munitions. Any munition which has not functioned shall be treated as a hazardous dud until it can be determined that the item is not capable of functioning. This shall be determined as follows using suitable protection and safety precautions for personnel handling the munitions:

a. Perform visual observation to assure the battery ball is depressed, the shorting bar is sheared and to determine if there is any evidence that the detonator has functioned.

b. If it cannot be determined whether or not the detonator has functioned, attempts shall be made to function the item by tipping about an edge, pulling all deployed triplines, and then dropping from a height of five (5) feet minimum onto a firm surface a minimum of five (5) times.

If the detonator functions at any time, the item shall be classed as a hazardous dud.

c. If the item has not functioned after the above external inputs have been applied, it shall be placed in an approved explosive handling box and removed from the impact area.

d. After a minimum sterilization period from time of impact, the item shall be remotely removed from the box and examined. If there is any evidence that the detonator has functioned, the item shall be classed as a hazardous dud. If the item has not functioned, it shall be examined to determine if the battery ball has been depressed. Normally, the ball is depressed approximately flush with the apex radius. If the ball is depressed and there is not evidence of functioning, the item shall be dropped as specified in b. If the item still has not functioned, it shall be classed as a non-hazardous dud.

If it can be determined that the battery has not been activiated, the item shall be classed as a hazardous dud unless it can also be determined that the S&A has not armed, i.e., at least one barrier assembly is in-line between the detonator and lead cup assembly. This may be determined by x-raying such that face 1 is closest to the film. (Face 1 is the triangular face with four sensors).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

4.5.7.2 Records of Ballistic Tests - A record shall be made for each round fired and shall include an accounting for the defects listed in 4.2.3 or below as applicable. In addition, the record shall include nose fuze duds or malfunctions, expulsion height, actual munition functioning times including early functions, sensor deployment of each munition, antidisturbance and breakwire functioning performance units which fail to function on first attempt, etc, and any other pertinent data. A copy of the ballistic test results for each projectile lot shall be forwarded to the address specified in 6.6. The lot shall be rejected if any one of the following occurs:

a. Any premature burst occurs (See 6.5.1)
b. Any separation of metal parts occurs prior to initiation of the nose fuze.
c. Any detonation of the projectile cargo occurs prior to initiation of the nose fuze.
d. The projectile fails to function satisfactorily (See 6.5.2).
e. Any shorting bar is not completely removed or any battery ball is not completely depressed.
f. Any munition functions (or is capable of functioning) after the maximum time has elapsed (Hazardous Dud).
g. Two or more munitions do not function (and are not capable of functioning) after the maximum time has elapsed. (non-hazardous dud).

4.5.7.3 Nose Fuze Malfunctions - Nose fuze malfunctions shall not be considered as cause for rejection. When a nose fuze malfunction occurs, the proving ground shall notify the technical agency and request a determination as to the need for a replacement projectile.

4.5.8 Process Control - At random intervals, the Government inspector shall monitor the contractor's assembly operations to assure compliance with the requirements specified on the applicable drawings and in approved loading and assembling procedures. As a minimum, the following shall be monitored:

a. Application of pads to munitions.
b. Equalization of column segment heights by selective assembly or use of column shims.
c. Radial compression of layers prior to assembly into stack-up.
d. Loading size ring diameter for projectile I.D.

Source: https://assist.dla.mil -- Downloaded: 202640-26T04:25Z
Check the source to verify that this is the current version before use.

e. Determination of ogive shim thickness including application of specified load.

f. Torquing of ogive.

g. Axial alignment of column segment wedges in layers 1 through 4.

5. PREPARATION FOR DELIVERY

5.1 Packing (Level A) - The projectiles shall be packed in accordance with Dwg. F-8837839.

5.2 Marking - Marking shall be in accordance with Dwg. F-8837839 and Code of Federal Regulations, Title 49, Parts 100-199.

5.3 Shipping - When projectiles from more than one lot are shipped at one time, each lot shall be kept separate and the division between lots clearly indicated to prevent mixing of the lots in transit.

6. NOTES

6.1 Intended Use - This specification is intended for use in loading assembling and packing the special test projectile M692/M731, 155MM and the munition contained therein.

6.2 Ordering Data - See MIL-A-48078.

6.3 Submission of Designs for Approval - See MIL-A-48078. Submit equipment designs as required to Commander, Picatinny Arsenal, Attn: SARPA-QA-T, Dover, New Jersey 07801

6.4 Submission of Results of Contractor-conducted Examinations and Tests - Data shall be submitted in accordance with data item DI-R-1721 on the DD Form 1423 for the contract.

6.5 Projectile Functioning -

6.5.1 Premature Burst - A premature burst is considered to have occurred if the projectile functions in the weapon or the time of flight is less than 1.9 seconds.

6.5.2 Functioning - Satisfactory functioning of the projectile is defined as successful delivery of the cargo to the target area with all projectile hardware remaining intact until initiation of the nose fuze at a pre-determined time after firing, and also includes removal of all shorting bars, depression of all battery balls, and expulsion of the entire cargo.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:25Z
Check the source to verify that this is the currentversion before use.

6.6 Submission of Test Data - In addition to the normal distribution of records, when the projectiles are procured by the US Army Armament Command, one (1) copy of all ballistic data and ammunition data cards shall be forwarded to: Commander, Picatinny Arsenal, Attn: SARPA-QA-S, Dover, New Jersey 07801.

6.7 Submission of Plans for Approval - The plans required in Section 3 shall be submitted to the following address for approval: Commander, Picatinny Arsenal, Attn: SARPA-QA-A-S, Dover, New Jersey 07801.

6.8 Safety Precautions for Molding Compound and Bedding Compound - When handling, mixing or curing the molding or bedding compound or its constituents suitable precautions must be taken as some of the constituents and compounds are toxic and/or exude toxic fumes when mixed or heated. Use adequate ventilation. Avoid contact with skin, eyes and clothing and prolonged or repeated breathing of fumes.

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number: 1320-A334

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

OMB Approval
No. 22-R255

INSTRUCTIONS: The purpose of this form is to solicit beneficial comments which will help achieve procurement of suitable products at reasonable cost and minimum delay, or will otherwise enhance use of the document. DoD contractors, government activities, or manufacturers/ vendors who are prospective suppliers of the product are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity.

DOCUMENT IDENTIFIER AND TITLE

NAME OF ORGANIZATION AND ADDRESS

CONTRACT NUMBER

MATERIAL PROCURED UNDER A

☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?

A. GIVE PARAGRAPH NUMBER AND WORDING.

B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY DOCUMENT REQUIREMENT CONSIDERED TOO RIGID

3. IS THE DOCUMENT RESTRICTIVE?

☐ YES ☐ NO *(If "Yes", in what way?)*

4. REMARKS

SUBMITTED BY *(Printed or typed name and address - Optional)*

TELEPHONE NO.

DATE

DD FORM 1 JAN 72 1426

REPLACES EDITION OF 1 JAN 66 WHICH MAY BE USED

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:25Z
Check the source to verify that this is the current version before use.