MILITARY SPECIFICATION

SAFETY AND ARMING ASSEMBLIES FOR MINES: XM74 AND XM75

This specification is approved for use by the U.S. Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification contains requirements not normally covered by the drawings and provides quality assurance provisions for the fabrication of parts, assembly, loading and packing for two types of S&A assemblies for Mines: XM74 and XM75.

2. APPLICABLE DOCUMENTS

2.1 Issues of documents. The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein:

SPECIFICATIONS

FEDERAL

QQ-A-225/6	-	Aluminum Alloy Bar Rod, and Wire; Rolled Drawn or Cold Finished, 2024
QQ-P-416	-	Plating, Cadmium (Electrodeposited)
QQ-S-571	-	Solder; Tin Alloy, Tin-Lead Alloy; and Lead Alloy
QQ-S-365	-	Silver Plating, Electrodeposited: General Requirements For.

MILITARY

MIL-C-5541	-	Chemical Conversion Coatings on Aluminum and Aluminun Alloys

FSC: 1345

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

MIL-T-10727	-	Tin Plating, Electrodeposited or Hot Dipped, For Ferrous and Non-Ferrous Metals.
MIL-T-12879	-	Treatments, Chemical, Prepaint and Corrosion Inhibitive, for Zinc Surfaces
MIL-A-48078	-	Ammunition, Standard Quality Assurance Provisions, General Specification for
MIL-D-48120	-	Detonator, Electric, M-100; Parts For, And Loading, Assembling and Packing
MIL-C-50697	-	Cord, Detonating
MIL-D-63197	-	Detonator, Delay Electric: PA-506; Parts For, And Loading, Assembling And Packing
MIL-L-63246	-	Leads, Explosive, PA 509, PA 512, PA 513, PA 514, PA 516 and PA 517; Parts for, and Loading, Assembling and Packing

STANDARDS

MILITARY

MIL-STD-105	-	Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-202	-	Test Methods for Electronic and Electrical Component Parts
MIL-STD-331	-	Fuze and Fuze Components, Environmental and Performance Tests for
MIL-STD-454	-	Standard General Requirements for Electronic Equipment

DRAWINGS

U.S. ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

9292700	-	Safety and Arming Assembly
9328756	-	Safety and Arming Assembly
9329608	-	Packing & Marking for Box, Fiberboard for S&A Assembly for Mines

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

2.2 Other publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on the date of invitation for bids or request for proposal shall apply.

CODE OF FEDERAL REGULATIONS

TITLE 49 - Transportation, Parts 100-199

(The Code of Federal Regulations is available from the Superintendent of Documents, U.S. Government Printing Office, Washington, D.C. 20402. Orders should specify, "49 CFR 100-199 (latest revision)").

AMERICAN SOCIETY FOR TESTING AND MATERIALS

ASTM A 108 -	Standard Specification for Steel Bars, Carbon, ColdFinished, Standard Quality
ASTM B 117 -	Standard Method of Salt Spray (Fog) Testing
ASTM E 18 -	Standard Test Methods for Rockwell Hardness and Rockwell Superficial Hardness of Metallic Materials

(Application for copies should be addressed to: American Society for Testing and Materials, 1916 Race Street, Philadelphia, Pa. 19103).

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer).

3. REQUIREMENTS

3.1 Material. Materials shall be in accordance with the applicable drawings and specifications and standards.

3.2 Parts and assemblies. The parts and assemblies shall comply with all requirements specified on Drawings (Dwgs.) 9292700 and 9328756, as applicable, all associated drawings and with all requirements specified in applicable specifications and standards.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.3 Mild Detonating Fuse (MDF) assembly explosive output test. The MDF assembly shall be tested for explosive output in accordance with Test 303 of MIL-STD-331 except as follows: Output from the end face of a single HMX loaded cup shall produce a 0.013 inch minimum (min) dent in an aluminum witness plate when tested as specified in 4.5.8.1.

3.4 Environmental and safety tests.

3.4.1 Jolt. The Safety and Arming (S&A) assembly shall comply with the requirements of MIL-STD-331, Test No. 101.2, Procedure II.

3.4.2 Jumble. The S&A assembly shall comply with the requirements of MIL-STD-331, Test No. 102.1.

3.4.3 Transportation. Vibration. The S&A assembly shall comply with the requirements of MIL-STD-331, Test No. 119, Procedure 2.

3.5 Arming of the S&A assembly. The S&A assembly shall arm when subjected to the following sequence:

a. The S&A assembly shall commit-to-arm when tested as specified in 4.5.17.1.

b. Following step “a”, the micropiston actuator, on activation, shall enable spring loaded slider and its explosive trains to the in-line/armed position as per 4.5.17.2.

3.6 In-line explosive functioning. The armed S&A assembly shall demonstrate high order functioning through the MDF assembly and main charge lead explosive trains, as applicable.

3.6.1 MDF train functioning (Dwg. 9328756). Upon initiation of the M100 detonator, the MDF train explosive elements shall function high order and cause the specified min. dent in the aluminum witness plate, at the temperature indicated when tested in accordance to 4.5.18 and 4.5.18.1.

Temperature	Depth of Dent
-35° - 5°F	.013 inch min
+70° ± 10°F	.013 inch min
+145° ± 5°F	.013 inch min

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.6.2 Main charge lead train functioning - Dwg. 9328756: Delay Detonator, PA-506. - Dwg. 9292700: Microdetonator M100. Upon initiation of the appropriate detonator for the particular S&A listed above, the main charge lead train explosive elements shall function high order and cause the specified min. dents in a steel confining ring (witness block) at the temperature indicated. The test shall be performed as specified in 4.5.18.1-/4.5.18.2. In the case of Delay Det PA 506, the output from the main leads shall occur between 20 milliseconds (ins) and 50 ms after initiation of the delay detonator (applies to Dwg. 93287516 only).

Temperature	Depth of Dent
-35° -5°F	.005 inch min
+70° ± 10°F	.005 inch min
+145° ± 5°F	.005 inch min

3.7 Verification of safe condition of S&A assemblies. Prior to packaging, positive verification of the presence and safe position of the following safety features shall be made for each assembly (See 4.5.19).

a. Safe position of both spring loaded centrifugal locks.

b. Safe position of slider release pin and shear pin.

c. Safe position of spring loaded slider assembly: distance of slider assembly from end of S&A, maximum (max.).

3.8 Detonator and micropiston actuator short circuit. The resistance of the short circuit across the detonator(s)/-micropiston actuator shall be less than 0.015 ohm.

3.9 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.10 Workmanship. All parts and assemblies shall be fabricated, loaded and assembled in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, grease, rust, and other foreign matter. The cleaning method used shall not be injurious to any parts, nor shall the parts be

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

contaminated by the cleaning agents. Soldering shall be neat and have a shiny appearance. Exterior surface coatings shall be continuous, except for a few light scratches not exposing base material. All required marking and stamping shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection.

b. Quality Conformance Inspection.

4.3 First article inspection.

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawings	Quantity
Lower Housing Assembly	9329813	15
Actuator, Microminiature Piston	9328715	15
MDF Assembly	9328723-1	15
MDF Assembly	9328723-2	15
Slider Assembly	9329822-1	15
Slider Assembly	9329822-2	15
MDF, PBXN-5, Lead Sheathed	9328726	30
Upper Housing Assembly	9329810	15
Flexible Cable Assembly	9328757	15
Flexible Cable Assembly	9329825	15
S&A Assembly	9328756	44
S&A Assembly	9292700	44

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

In addition, the other parts and assemblies of Table I shall be submitted in sample quantities of ten (10).

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I herein.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 7		DRAWING NUMBER
	S&A Assembly and Components				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Shield (Dwg. 9329831)				
	Examination for defects	10	-	3.2	4.4.2.1
	Spring, Centrifugal Lock (Dwg. 9329820)				
	Examination for defects	10	-	3.2	4.4.2.2
	Clip, Shorting (Dwg. 9329815)				
	Examination for defects	10	-	3.2	4.4.2.3
	Plate, Lock (Dwg. 9328745)				
	Examination for defects	10	-	3.2	4.4.2.4
	Salt Spray	5	-	3.2	4.5.4
	Body, Slider (Dwg. 9329823)				
	Examination for defects	10	-	3.2	4.4.2.5
	Spring, Slider (Dwg. 9328717)				
	Examination for defects	10	-	3.2	4.4.2.6
	Lock, Centrifugal (Dwg. 9329821)				
	Examination for defects	10	-	3.2	4.4.2.7
	Clip, Ground (Dwg. 9329827)				
	Examination for defects	10	-	3.2	4.4.2.8
	Salt Spray	5	-	3.2	4.5.4

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 2 OF 7		DRAWING NUMBER
	S&A Assembly and Components				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Interrupter (Dwg. 9329812)				
	Examination for defects	10	-	3.2	4.4.2.9
	Salt Spray	5	-	3.2	4.5.4
	Pin, Shear, Slider Release (Dwg. 9329816)				
	Examination for defects	10	-	3.2	4.4.2.10
	Salt Spray	5	-	3.2	4.5.4
	Cable Flexible (Dwg. 9329826)				
	Examination for defects	10	-	3.2	4.4.2.11
	Salt Spray	5	-	3.2	4.5.4
	Shield, Blast (Dwg. 9329833)				
	Examination for defects	10	-	3.2	4.4.2.12
	Blast Shield Assembly (Dwg. 9329832)				
	Examination for defects	10	-	3.2	4.4.2.13
	Housing, Upper (Dwg. 9329811)				
	Examination for defects	10	-	3.2	4.4.2.14
	Salt Spray	5	-	3.2	4.5.4
	Housing, Lower (Dwg. 9329817)				
	Examination for defects	10	-	3.2	4.4.2.15
	Salt Spray	5	-	3.2	4.5.4

NOTES:

Source: http://assist.daps.dla.mil - Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 3 OF 7		DRAWING NUMBER
	S&A Assembly and Components				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Actuator, Microminiature Piston (Dwg. 9328715)				
	Examination for defects	16	-	3.2	4.4.2.16
	Resistance test	16	-	3.2	4.5.6.1
	Functioning test	16	-	3.2	4.5.6.3
	Solderability test	5	-	3.2	4.5.6.2
	Disc, Spacer (Dwg. 9328720)				
	Examination for defects	10	-	3.2	4.4.2.17
	MDF Assembly (Dwg. 9328723-1)				
	Examination for defects	16	-	3.2	4.4.2.18
	Output test	16	-	3.3	4.5.8.1
	Pull test	16	-	3.2	4.5.8.2
	MDF Assembly (Dwg. 9328723-2)				
	Examination for defects	16	-	3.2	4.4.2.18
	Output test	16	-	3.3	4.5.8.1
	Pull test	16	-	3.2	4.5.8.2
	Slider Assembly (Dwg. 9329822-1)				
	Examination for defects	15	-	3.2	4.4.2.19
	Separation test	15	-	3.2	4.5.9
	Slider Assembly (Dwg. 9329822-2)				
	Examination for defects	15	-	3.2	4.4.2.19
	Separation test	15	-	3.2	4.5.9

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE: S&A Assembly and Components		SHEET 4 OF 7		DRAWING NUMBER: See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	MDF, PMXN-5 Lead Sheated (Dwg. 9328726)	a			
	Examination for defects		-	3.2	4.4.2.20
	Flexibility test		-	3.2	4.5.10
	Detonation velocity test		-	3.2	4.5.12
	Cup, Centrifugal Lock (Dwg. 9329819)				
	Examination for defects	10	-	3.2	4.4.2.21
	Cup, Slider (Dwg. 9329824)				
	Examination for defects	10	-	3.2	4.4.2.22
	Upper Housing Assembly (Dwg. 9329810)				
	Examination for defects	15	-	3.2	4.4.2.23
	Lower Housing Assembly (Dwg. 9329813)				
	Examination for defects	15	-	3.2	4.4.2.24
	Load test	15	-	3.2	4.5.13
	Flexible Cable Assembly (Dwg. 9328757)				
	Examination for defects	15	-	3.2	4.4.2.25
	Flexible Cable Assembly (Dwg. 9329825)				
	Examination for defects	15	-	3.2	4.4.2.26
	Pin, Slider Release (Dwg. 9329814)				
	Examination for defects	10	-	3.2	4.4.2.27

NOTES:

a. Sampling and rejection shall be in accordance with MIL-C-50697. 10 samples of 2 feet lengths.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET 5 OF 7	DRAWING NUMBER
	S&A Assembly and Components		See Below
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Retainer, Interrupter (Dwg. 9328747)				
	Examination for defects	10	-	3.2	4.4.2.28
	Salt Spray	5	-	3.2	4.5.4
	MDF Spacer (Dwg. 9328746)				
	Examination for defects	10	-	3.2	4.4.2.30
	Spacer, Detonator (Dwg. 9329828)				
	Examination for defects	10	-	3.2	4.4.2.31
	Terminal (Dwg. 9329829)				
	Examination for defects	10	-	3.2	4.4.2.32
	Salt Spray	5	-	3.2	4.5.4
	Spacer, Actuator (Dwg. 9329830)				
	Examination for defects	10	-	3.2	4.4.2.33
	Ferrule (Dwg. 9328724)				
	Examination for defects	10	-	3.2	4.4.2.34
	Cup, End Cap (Dwg. 9328725)				
	Examination for defects	10	-	3.2	4.4.2.35
	Insulator (Dwg. 9328728)	10			
	Examination for defects		-	3.2	4.4.2.36

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202640-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE 1 - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 6 OF 7		DRAWING NUMBER
	S&A Assembly and Components				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	S&A Assy (Dwg. 9292700)	10			
	Prior to installing lock plate, blast shield assy, actuator spacer, flexible cable assy and shield				
	Non-arm spin test		-	3.2	4.5.7.2
	Arming spin test		-	3.2	4.5.7.1
	S&A Assy (Dwg. 9292756)	10	-		
	Prior to installing lock plate, blast shield assy, actuator spacer, flexible cable assy, MFD assemblies and shield				
	Non-arm spin test		-	3.2	4.5.7.2
	Arming spin test		-	3.2	4.5.7.1
	S&A Assy (Dwg. 9292700)	44	-		
	Jolt test	6	-	3.4.1	4.5.15.1
	Jumble test	6	-	3.4.2	4.5.15.2
	Examination for defects	32	-	3.2	4.4.2.43
	Continuity resistance test	32	-	3.2	4.5.14
	--- S&A Assy Functioning Test ---	32			
	Transportation vibration		-	3.4.3	4.5.15.3
	Safe condition examination		-	3.7	4.5.19
	Continuity resistance		-	3.2	4.5.14
	Temperature conditioning	*	-	3.6.2	4.5.16
	Initial arming (commit to arm)		-	3.5	4.5.17.1
	Final arming (micropiston actuator function)		-	3.5	4.5.17.2

NOTES: * Test sample of 32: 16 shall be conditioned @ minus 35° -5°F and 16 @ 145° +5°F before arming and functioning. The sample shall be functioned with random orientation of lock plates.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET 7 OF 7	DRAWING NUMBER
	S&A Assembly and Components		See Below
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Continuity resistance test		-	3.2	4.5.14
	Main charge lead function (4 places)		-	3.6.2	4.5.18.2
	S&A Assy (Dwg. 9328756)	44	-		
	Jolt test	6	-	3.4.1	4.5.15.1
	Jumble test	6	-	3.4.2	4.5.15.2
	Examination for defects	32	-	3.2	4.4.2.44
	Continuity resistance test	32	-	3.2	4.5.14
	--- S&A Assy Functioning Test ---	32			
	Transportation vibration	.	-	3.4.3	4.5.15.3
	Safe condition examination		-	3.7	4.5.19
	Continuity resistance		-	3.2	4.5.14
	Temperature conditioning	*	-	3.6.1	4.5.16
	Initial arming (Commit to arm)		-	3.5	4.5.17.1
	Final arming (micropiston actuator function)		-	3.5	4.5.17.2
	Continuity resistance test		-	3.2	4.5.14
	MDF Train function		-	3.6.1	4.5.18.1
	Delay Det. -- Time delay		-	3.6.2	4.5.18.1
	Main charge lead function (4 places)		-	3.6.2	4.5.18.2

NOTES: * Test sample of 32: 16 shall be conditioned @ minus 35° -5°F and 16 @ 145° +5°F before arming and functioning. Half the sample shall be functioned with lock plate facing up, and half with lock plate facing down.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. - Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, each inspection lot of S&A assemblies shall contain the following:

a. Detonators, micropiston actuators, MDF assemblies and lead assemblies, each item from the same lot interfix number from one manufacturer.

b. Explosive composition "PBXN-5" of one lot interfix number from one manufacturer.

c. Explosive composition HMX of one lot interfix number from one manufacturer.

d. Metal parts of one lot interfix number from one manufacturer.

4.4.2 Examination.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Forms, sampling plans for major and minor defects shall be in accordance with MIL-STD-105.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AF)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9329831
4.4.2.1	Shield				NEXT HIGHER ASSEMBLY 9328756 or 9292700
CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Outside diameter, max.		0.40%	3.2	Gage
102.	Total length		0.40%	3.2	Gage
103.	Diameter of main lead blast hole, 4 places		0.40%	3.2	Gage
104.	True position of diameter of main lead blast hole with datums A and B, 4 places		0.40%	3.2	Gage
105.	True Position of tang width datum A		0.40%	3.2	Gage
106.	Width of tang		0.40%	3.2	Gage
107.	True position of diameter of release pin hole with datums A and B		0.40%	3.2	Gage
108.	Diameter of release pin inspection hole		0.40%	3.2	Gage
109.	Thickness of shield		0.40%	3.2	Gage
110.	Inside diameter, min.,		0.40%	3.2	Gage
111.	Length to tang		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Gage
202.	Length of tang		0.65%	3.2	Gage
203.	Length to release pin inspection hole		0.65%	3.2	Gage
204.	Length to main lead blast hole, 4 places		0.65%	3.2	Gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Spring, Centrifugal Lock				9329820
					NEXT HIGHER ASSEMBLY
					9328756/9292700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Outside diameter		0.40%	3.2	Gage
102.	Wire diameter		0.40%	3.2	Gage
103.	Solid height, max.		0.40%	3.2	Gage
104.	Load at .256 inch		0.40%	3.2	Gage
105.	Load at .150 inch		0.40%	3.2	Gage
106.	Free length		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual
202.	Squareness of ends		0.65%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Clip, Shorting				9329815
					NEXT HIGHER ASSEMBLY 9328713
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Inside diameter		0.40%	3.2	Gage
102.	Total length		0.40%	3.2	Gage
103.	Protrusion of tabs		0.40%	3.2	Gage
104.	Material thickness		0.40%	3.2	Gage
105.	Gap between ends (in restrained condition)		0.40%	3.2	Gage
106.	Hardness test	(a)		3.2	ASTM-E-18
107.	Sliver plating missing or improper	(b)		3.2	Visual, QQ-S-365
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES: * See 4.5.2, Dimensional control of stamped parts.
(a) Sample size per MIL-STD-105, Inspection Level S-3, Accept 0, Reject 1
(b) Sampling and rejection shall be in accordance with QQ-S-365.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE			SHEET 1 OF 1	DRAWING NUMBER
4.4.2.4	Plate, Lock				9328745
					NEXT HIGHER ASSEMBLY
					9292700/9328756
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Outside diameter		0.40%	3.2	Gage
102.	Thickness of projections		0.40%	3.2	Gage
103.	Thickness of plate		0.40%	3.2	Gage
104.	Inside angle-detail A		0.40%	3.2	Gage
105.	Corner edge radius, max., detail A		0.40%	3.2	Gage
106.	Outside flat, min., detail A		0.40%	3.2	Gage
107.	Salt Spray Test	(a)		3.2	4.5.4
108.	Hardness test	(b)		3.2	ASTM-E-18
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES: * See 4.5.2, Dimensional control of stamped parts.
(a) Sampling and rejection shall be in accordance with QQ-P-416.
(b) MIL-STD-105, Inspection Level S-3, Accept 0, Reject 1.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil - Downloaded: 2025-08-26T06:46Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.5	Body, Slider				9329823
					NEXT HIGHER ASSEMBLY 9329822
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE INSPECTION METHOD
Critical	None defined				
Major					
101.	Largest outside diameter		0.40%	3.2	Gage
102.	Overall length		0.40%	3.2	Gage
103.	Length from basic taper diameter to smallest outside diameter		0.40%	3.2	Gage
104.	Smallest outside diameter		0.40%	3.2	Gage
105.	Length of smallest outside diameter		0.40%	3.2	Gage
106.	True position of smallest outside diameter		0.40%	3.2	Gage
107.	Inside diameter		0.40%	3.2	Gage
108.	True position of inside diameter		0.40%	3.2	Gage
109.	Width of slot, 4 places		0.40%	3.2	Gage
110.	Depth of slot, 4 places		0.40%	3.2	Gage
111.	True position of slot, 4 places		0.40%	3.2	Gage
112.	Diameter of largest thru hole		0.40%	3.2	Gage
113.	True position of largest thru hole		0.40%	3.2	Gage
114.	Diameter of smallest hole		0.40%	3.2	Gage
115.	Depth of smallest hole		0.40%	3.2	Gage
116.	True position of smallest hole		0.40%	3.2	Gage
117.	Second largest outside diameter		0.40%	3.2	Gage
118.	Length of second largest outside diameter		0.40%	3.2	Gage
119.	True position of second largest outside diameter		0.40%	3.2	Gage
120.	Crimp groove missing		0.40%	3.2	Gage
121.	Length to largest thru hole		0.40%	3.2	Gage
122.	Length from largest thru hole		0.40%	3.2	Gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.5 cont'd	Body, Slider				9329823
					NEXT HIGHER ASSEMBLY 9329822
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor 201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 71 which is Obsolete.

Downloaded from http://assist.daps.dla.mil - Document: MIL-S-63302A(AR)
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.6	Spring, Slider	1 OF 1	9328717
			NEXT HIGHER ASSEMBLY: 9328756/9292700

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Outside diameter		0.40%	3.2	Gage
102.	Minimum load, at .445 in., before and after compression for 24 hours	(a)		3.2	Test Set Up
103.	Solid Height, Max.		0.40%	3.2	Gage
104.	Diameter of wire		0.40%	3.2	Gage
105.	Free length		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual
202.	Ends not square		0.65%	3.2	Gage

NOTES: (a) Sample size per MIL-STD-105, Inspection Level S-3, Accept 0, Reject 1, acceptable parts may be returned to the lot.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.7	Lock, Centrifugal				9329821
					NEXT HIGHER ASSEMBLY
					9328756/9292700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Flange missing or damaged		100%	3.2	Visual
Major					
101.	Largest outside diameter		0.40%	3.2	Gage
102.	Diameter of flange		0.40%	3.2	Gage
103.	True position of flange with Datum -A-		0.40%	3.2	Gage
104.	Length from undercut to outside end of flange		0.40%	3.2	Gage
105.	Chamfer incorrect, 2 places		0.40%	3.2	Gage
106.	Length of largest outside diameter - including chamfer's		0.40%	3.2	Gage
107.	Length of flange undercut diameter		0.40%	3.2	Gage
108.	Width of outside radial groove		0.40%	3.2	Gage
109.	Depth of outside radial groove		0.40%	3.2	Gage
110.	Length to outside radial groove from undercut (#115)		0.40%	3.2	Gage
111.	Largest inside diameter		0.40%	3.2	Gage
112.	Depth of largest inside diameter		0.40%	3.2	Gage
113.	True position of largest inside diameter with datum -A-		0.40%	3.2	Gage
114.	Surface finish of large O.D.		0.40%	3.2	Visual
115.	Depth of undercut - next to flange		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual
202.	Depth of smallest inside diameter		0.65%	3.2	Gage
203.	Flange corner not broken, 2 places		0.65%	3.2	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74, which is Obsolete

Source: https://assist.dla.mil - Downloaded: 2020-05-26T08:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.8	Clip, Ground		9329827
			NEXT HIGHER ASSEMBLY 9328757/9329825

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Inside diameter of loops		0.40%	3.2	Gage
102.	Largest length of plate		0.40%	3.2	Gage
103.	Diameter of largest hole		0.40%	3.2	Gage
104.	Diameter of smallest hole		0.40%	3.2	Gage
105.	Length to notch in plate		0.40%	3.2	Gage
106.	Length of notch in plate		0.40%	3.2	Gage
107.	Length of loops		0.40%	3.2	Gage
108.	Largest height to loop		0.40%	3.2	Gage
109.	Smallest height to loop		0.40%	3.2	Gage
110.	Material thickness		0.40%	3.2	Gage
111.	True position of loops		0.40%	3.2	Gage
112.	Hardness test	(a)		3.2	ASTM-E-18
113.	Salt Spray Test	(b)		3.2	4.5.4
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES: * See 4.5.2.

(a) Sample size per MIL-STD-105, Inspection Level S-3, Accept 0, Reject 1.

(b) Sampling and rejection shall be in accordance with MIL-T-10727.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Interrupter				9329812
					NEXT HIGHER ASSEMBLY 9329810
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Flatness		0.40%	3.2	Gage
102.	Diameter		0.40%	3.2	Gage
103.	Thickness		0.40%	3.2	Gage
104.	Chamfer or radius missing, 2 places		0.40%	3.2	Visual/Gage
105.	Salt Spray Test	(a)		3.2	4.5.4
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:
* See 4.5.2.
(a) Sampling and rejection shall be in accordance with QQ-P-416.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.10	Pin, Shear, Slider Release				9329816
					NEXT HIGHER ASSEMBLY 9329813
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Diameter		0.40%	3.2	Gage
102.	Length		0.40%	3.2	Gage
103.	Salt Spray Test	(a)		3.2	4.5.4
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES: (a) Sampling and rejection shall be in accordance with MIL-C-5541.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202640-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1)	Cable, Flexible				9329826
					NEXT HIGHER ASSEMBLY
					9328757/9329825
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Diameter of smallest holes (A)		0.40%	3.2	Gage
102.	Diameter of second smallest hole (B)		0.40%	3.2	Gage
103.	Diameter of third smallest holes (C)		0.40%	3.2	Gage
104.	Location of smallest holes (A)		0.40%	3.2	Gage
105.	Location of second smallest hole (B)		0.40%	3.2	Gage
106.	Location of third smallest holes (C)		0.40%	3.2	Gage
107.	Soldering poor or incorrect		0.40%	3.2	Visual
108.	Terminal pads and exposed conductor without solder		0.40%	3.2	Visual
109.	Insulation resistance test		0.40%	3.2	4.5.5
110.	Conductor width, min.		0.40%	3.2	Gage/Pattern
111.	Conductor spacing, min.		0.40%	3.2	Gage/Pattern
112.	Diameter of largest hole (D)		0.40%	3.2	Gage
113.	Location of largest hole (D)		0.40%	3.2	Gage
114.	Bonding of layers, improper		0.40%	3.2	Visual vs Sample
115.	Broken or improper conductor pattern		0.40%	3.2	Visual/Pattern
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual
202.	Marking missing, improper or illegible		0.65%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.12	Shield, Blast				9329833
					NEXT HIGHER ASSEMBLY 9329832
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Total length		0.40%	3.2	Gage
102.	Length to tab		0.40%	3.2	Gage
103.	Length of tab		0.40%	3.2	Gage
104.	Length of step		0.40%	3.2	Gage
105.	Largest radius		0.40%	3.2	Gage
106.	Location of largest radius		0.40%	3.2	Gage
107.	Largest angle		0.40%	3.2	Gage
108.	Depth of smallest hole		0.40%	3.2	Gage
109.	Diameter of largest holes		0.40%	3.2	Gage
110.	Depth of largest holes		0.40%	3.2	Gage
111.	Height to end of tab from Datum -A- and -B-		0.40%	3.2	Gage
112.	Length to largest holes		0.40%	3.2	Gage
113.	Diameter of smallest hole		0.40%	3.2	Gage
114.	True position of smallest hole with largest holes		0.40%	3.2	Gage
115.	Height to flat in largest holes		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 or 1		DRAWING NUMBER
4.4.2.13	Blast Shield Assembly				9329832
					NEXT HIGHER ASSEMBLY
					9328756/9292700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Insulator projects in excess of dwg. requirement, 2 places		0.40%	3.2	Gage
102.	Insulator loose or missing		0.40%	3.2	Visual/Manual
Minor	None defined				

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74, Which is Obsolete
Source: https://assist.dla.mil - Downloaded: 2026-01-28 04:04:52
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 3		DRAWING NUMBER
4.4.2.14	Housing, Upper				9329811
					NEXT HIGHER ASSEMBLY
					9329810
CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Height to datum -A- diameter		0.40%	3.2	Gage
102.	Height to datum -B- diameter		0.40%	3.2	Gage
103.	Depth of cutout for lock plate (sec. H-H)		0.40%	3.2	Gage
104.	Depth of recess for interrupter retainer		0.40%	3.2	Gage
105.	Width of recess for interrupter retainer		0.40%	3.2	Gage
106.	True position, of width of recess for interrupter retainer		0.40%	3.2	Gage
107.	Length of recess for interrupter retainer		0.40%	3.2	Gage
108.	True position, length of recess for interrupter retainer		0.40%	3.2	Gage
109.	Largest height of flats at small end		0.40%	3.2	Gage
110.	Largest outside radius (Sht 1)		0.40%	3.2	Gage
111.	True position of largest outside radius		0.40%	3.2	Gage
112.	Second largest outside radius		0.40%	3.2	Gage
113.	True position of second largest outside radius		0.40%	3.2	Gage
114.	Depth of smallest slider cavity radius (Sec. A-A, Sht. 1)		0.40%	3.2	Gage
115.	Depth of centrifugal lock cavitites (Sec. A-A, Sht. 1), 2 places		0.40%	3.2	Gage
116.	Width of centrifugal lock cavities, 2 places		0.40%	3.2	Gage
117.	True position of width of centrifugal lock		0.40%	3.2	Gage
118.	Distance from centerline to inner end of centrifugal lock cavities, 2 places		0.40%	3.2	Gage
119.	Length of cutout for lock plate (Sec. H-H, Sht 2)		0.40%	3.2	Gage

NOTES:

* See 4.5.1 for inspection of cast features.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 2 OF 3		DRAWING NUMBER
4.4.2.14 cont'd	Housing, Upper				9329811
					NEXT HIGHER ASSEMBLY 9329810
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
120.	Width of cutout for lock plate		0.40%	3.2	Gage
121.	True position of cutout for lock plate		0.40%	3.2	Gage
122.	Radius of largest slider cavity (Det. J, Sht 2)		0.40%	3.2	Gage
123.	True position of radius of largest slider cavity		0.40%	3.2	Gage
124.	Depth of largest slider cavity		0.40%	3.2	Gage
125.	Total length		0.40%	3.2	Gage
126.	Wall thickness and end of slider cavity		0.40%	3.2	Gage
127.	Length to largest slider cavity, (Sec. H-H)		0.40%	3.2	Gage
128.	Radius of smallest slider cavity, (Sec. A-A, Sht. 1)		0.40%	3.2	Gage
129.	True position of radius of smallest slider cavity (Sec. A-A, Sht. 1)		0.40%	3.2	Gage
130.	Depth of relief in smallest slider cavity (Sec. H-H, Sht. 2)		0.40%	3.2	Gage
131.	Radius of relief in smallest slider cavity (Sec. H-H-, Sht. 2)		0.40%	3.2	Gage
132.	True position of radius of relief in smallest slider cavity (Sec. H-H-, Sht. 2)		0.40%	3.2	Gage
133.	Diameter of main explosive lead cavity (Sec. E-E, Sht. 3) 2 places		0.40%	3.2	Gage
134.	True position of main explosive lead cavity (Sec E-E, Sht. 3) 2 places		0.40%	3.2	Gage
135.	Diameter of main explosive lead thru hole (Sec E-E, Sht. 3) 2 places		0.40%	3.2	Gage
136.	True position of main explosive lead thru hole (Sec E-E, Sht. 3) 2 places		0.40%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 3 OF 3		DRAWING NUMBER
4.4.2.14 cont'd	Housing, Upper				9329811
					NEXT HIGHER ASSEMBLY 9329810
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
137.	Distance from bottom of main explosive lead cavity to centerline of part (Sec E-E, Sht. 3) 2 places		0.40%	3.2	Gage
138.	Diameter of MDF lead cavity (Det. L, Sht. 3) 2 places		0.40%	3.2	Gage
139.	True position of MDF lead cavity (Det. L, Sht 3) 2 places		0.40%	3.2	Gage
140.	Diameter of MDF lead cavity flash hole (Det. L, Sht. 3) 2 places		0.40%	3.2	Gage
141.	True position of MDF lead cavity flash hole (Det. L, Sht. 3) 2 places		0.40%	3.2	Gage
142.	Burrs in cavities		0.40%	3.2	Gage
143.	Smallest hole diameter (Det. N-N, Sht. 2)		0.40%	3.2	Gage
144.	True position of smallest hole diameter (Det. N-N, Sht. 2)		0.40%	3.2	Gage
145.	Salt Spray Test	(a)		3.2	4.5.4
Minor 201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

(a) Sampling and rejection shall be in accordance with MIL-T-12879

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 3		DRAWING NUMBER
4.4.2.15	Housing, Lower				9329817
					NEXT HIGHER ASSEMBLY
					9329813
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Total length		0.40%	3.2	Gage
102.	Depth of largest slider cavity (Sec. F-F, Sht 3)		0.40%	3.2	Gage
103.	Height to flat of second largest outside diameter		0.40%	3.2	Gage
104.	Depth of datum -A- diameter (Sec. G-G, Sht. 5)		0.40%	3.2	Gage
105.	Depth of datum -B- diameter (Sec. G-G, Sht. 2)		0.40%	3.2	Gage
106.	Width of slider cavity (Sec. F-F, Sht. 3)		0.40%	3.2	Gage
107.	True position, of width of largest of slider cavity (Sec. F-F, Sht. 3)		0.40%	3.2	Gage
108.	Height of lock plate cavity (Det. H, Sht. 2)		0.40%	3.2	Gage
109.	Width of centrifugal lock cavity (Det. A, Sht. 1), 2 places		0.40%	3.2	Gage
110.	True position of width of centrifugal lock cavity, 2 places		0.40%	3.2	Gage
111.	Length to slider guide pin slot		0.40%	3.2	Gage
112.	Largest outside radius		0.40%	3.2	Gage
113.	True position of largest outside radius		0.40%	3.2	Gage
114.	Depth of centrifugal lock cavity (Sec. D-D, Sht. 3)		0.40%	3.2	Gage
115.	Second largest outside radius		0.40%	3.2	Gage
116.	True position of second largest outside radius		0.40%	3.2	Gage
117.	Wall thickness at end of slider cavity		0.40%	3.2	Gage
118.	Length to slider cavity (Sec. L-L, Sht. 4)		0.40%	3.2	Gage
119.	Distance from part centerline to centrifugal lock cavity, (Det. A, Sht. 1), 2 places		0.40%	3.2	Gage

NOTES:

* See 4.5.1 for inspection of cast features.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 2 OF 3		DRAWING NUMBER
4.4.2.15 cont'd	Housing, Lower				9329817
					NEXT HIGHER ASSEMBLY
					9329813
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
120.	Length of centrifugal lock cavity (Sec. D-D, Sht. 3), 2 places		0.40%	3.2	Gage
121.	Diameter of piston actuator hole		0.40%	3.2	Gage
122.	True position of diameter of piston actuator hole		0.40%	3.2	Gage
123.	Diameter of terminal hole (Det. T-T, Sht 2)		0.40%	3.2	Gage
124.	True position of diameter of terminal hole		0.40%	3.2	Gage
125.	Diameter of slider release pin shear pin hole (Det T-T-, Sht 2)		0.40%	3.2	Gage
126.	True position of diameter of slider release pin shear pin hole (Det. T-T, Sht. 2)		0.40%	3.2	Gage
127.	Diameter of main explosive lead cavity, 2 places		0.40%	3.2	Gage
128.	True position of diameter of main explosive lead cavity, 2 places		0.40%	3.2	Gage
129.	Distance from centerline of part to bottom of main explosive lead cavity, 2 places		0.40%	3.2	Gage
130.	Diameter of main explosive lead flash hole		0.40%	3.2	Gage
131.	True position of diameter of main explosive lead flash hole		0.40%	3.2	Gage
132.	Diameter of slider release pin hole		0.40%	3.2	Gage
133.	True position of diameter of slider release pin hole		0.40%	3.2	Gage
134.	Diameter of electric detonator cavity, 2 places		0.40%	3.2	Gage
135.	True position of diameter of electrical detonator cavity, 2 places		0.40%	3.2	Gage
136.	Largest depth to electric detonator cavity (Det M, Sht. 4)		0.40%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 3 OF 3		DRAWING NUMBER
4.4.2.15 cont'd	Housing, Lower				9329817
					NEXT HIGHER ASSEMBLY 9329813
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
137.	Smallest depth to electric detonator cavity (Det M, Sht. 4)		0.40%	3.2	Gage
138.	Diameter of electric detonator flash hole		0.40%	3.2	Gage
139.	Diameter of shorting clip hole (Sec. R-R, Sht 3)		0.40%	3.2	Gage
140.	True position of diameter of shorting clip hole (Sec. R-R, Sht. 3)		0.40%	3.2	Gage
141.	Diameter of spring pin hole (Sec S-S, Sht 3)		0.40%	3.2	Gage
142.	True position of diameter of spring pin hole (Sec. S-S, Sht. 3)		0.40%	3.2	Gage
143.	Depth of slider guide pin slot (Sec. F-F, Sht 3)		0.40%	3.2	Gage
144.	Length to end of slider guide pin slot		0.40%	3.2	Gage
145.	Depth of smallest slider cavity radius (Sec. D-D, Sht. 3)		0.40%	3.2	Gage
146.	Width of smallest slider cavity radius (Sec. D-D, Sht. 3)		0.40%	3.2	Gage
147.	True position of width of smallest slider cavity radius (Sec. D-D, Sht. 3)		0.40%	3.2	Gage
148.	Burrs in cavities		0.40%	3.2	Visual
149.	Salt Spray Test	(a)		3.2	4.5.4
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

(a) Sampling and rejection shall be in accordance with MIL-T-12879.

Source: https://assist.dla.mil -- Downloaded: 2024-10-28T04:28Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.16	Actuator, Microminiature Piston				9328715
					NEXT HIGHER ASSEMBLY
					9328757/9329825
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Largest diameter		0.40%	3.2	Gage
102.	Length of housing		0.40%	3.2	Gage
	Piston Actuator Function Test at minus 60° and +160°F				
103.	No fire test	(a)	0.40%	3.2	4.5.6.3
104.	All fire test	(a)	0.40%	3.2	4.5.6.3
105.	Output test	(a)	0.40%	3.2	4.5.6.3
106.	Resistance test	(a),(b)	100%	3.2	4.5.6.1
107.	Piston Travel, min	(a)	0.40%	3.2	Gage
108.	Solderability test	(c)		3.2	4.5.6.2
109.	Lead diameter		0.40%	3.2	Gage
110.	Nickel plating missing		0.40%	3.2	Visual
Minor					
201.	Evidence of poor workmanship		0.65%	3.2	Visual

NOTES: (a) Sample size per MIL-STD-105, Inspection Level I. Half the sample shall be tested at low temperature and half at high temperature. (b) Remainder of the lot shall be tested at ambient. (c) Sample size per MIL-STD-105, Inspection Level S-3, Accept 0, Reject 1.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.17	Disc, Spacer				9328720
					NEXT HIGHER ASSEMBLY 9329822
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201.	Thickness		0.65%	3.2	Gage
202.	Outside diameter		0.65%	3.2	Gage
203.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.18	MDF Assembly		9328723-1/-2
			NEXT HIGHER ASSEMBLY 9328756

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Total length (-1 Assy/-2 Assy)		0.40%	3.2	Gage
102.	Diameter of end cup, max, 2 places		0.40%	3.2	Gage
103.	Crimp missing or imcomplete		0.40%	3.2	Visual
104.	Sealant missing or incorrect		0.40%	3.2	Visual
105.	Lead sheath smear across core, 2 places*		0.40%	3.2	Visual
106.	Length of roll crimp cup, min, 2 places		0.40%	3.2	Gage
107.	Pull Test, 2 places - Note 8	(a)	0.40%	3.2	4.5.8.2
108.	Spacing of MDF with Ferrule, Max., 2 places, Note 5		0.40%	3.2	Gage, *
109.	Spacing present between MDF and HMS, 2 places		100%	3.2	4.5.11.2
110.	Output test @ -60°F and @ 160°F	(a)	0.40%	3.2	4.5.8.1
111.	Ferrule loose after swaging, Note 9		0.40%	3.2	Manual/Visual
Minor					
201.	Evidence of poor workmanship		0.65%	3.2	Visual

NOTES:
(a) Sample size per MIL-STD-105, Inspection Level I.
* Prior to assembly of end caps.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.19	Slider Assembly				9329822-1, -2
					NEXT HIGHER ASSEMBLY
					9328756 or 9292700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	True position of tabs seperation to datum A & B		100%	3.2	Gage
Major					
101.	Total length of large O.D. and groove pin protrusion		0.40%	3.2	Gage
102.	PA 513, explosive lead inverted 1/		0.40%	3.2	Gage
103.	Slider disc missing or incorrect 1/		0.40%	3.2	Gage
104.	PA 513 lead loose or improperly staked 1/		0.40%	3.2	Visual
105.	PA 516 explosive lead inverted or above flush in slider body (-2 assy only)		0.40%	3.2	Gage
106.	PA 516 lead loose or improperly staked		0.40%	3.2	Visual
107.	True position of groove pin to datum A & B		0.40%	3.2	Gage
108.	Groove pin loose or improperly staked		0.40%	3.2	Gage
109.	Large outside diameter, max.		0.40%	3.2	Gage
110.	Largest length		0.40%	3.2	Gage
111.	O.D. of groove pin		0.40%	3.2	Gage
112.	Separation test of slider cup	2/	0-1	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.2	Visual

NOTES:
1/ Prior to assembling slider body.
2/ Sample size per MIL-STD-105, Inspection Level S-4.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.20	MDF, PBXN-5 Lead Sheathed				9328726
					NEXT HIGHER ASSEMBLY 9328723
CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Outside diameter		0.40%	3.2	Gage
102.	Flexibility test	(a)	0.40%	3.2	4.5.10
103.	Inclusions, voids or impurities	(a)	0.40%	3.2	4.5.11.1
104.	Detonation velocity test	(a)	0.40%	3.2	4.5.12
Minor					
201.	Evidence of poor workmanship		0.65%	3.2	Visual

NOTES:
(a) Sampling and rejection shall be in accordance with MIL-C-50697.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.21	Cup, Centrifugal Lock		9329819
			NEXT HIGHER ASSEMBLY
			9328756/9292700

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Inside diameter		0.40%	3.2	Gage
102.	Hole diameter		0.40%	3.2	Gage
103.	Outside diameter		0.40%	3.2	Gage
104.	Bottom thickness		0.40%	3.2	Gage
105.	Length		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.2	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.22	Cup, Slider				9329824
					NEXT HIGHER ASSEMBLY 9329822
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Tab misoriented, missing or damaged, 2 places		100%	3.2	Visual
Major					
101.	Largest outside diameter		0.40%	3.2	Gage
102.	Smallest inside diameter		0.40%	3.2	Gage
103.	True position of smallest inside diameter with datum A		0.40%	3.2	Gage
104.	Smallest outside diameter, max.		0.40%	3.2	Gage
105.	Largest inside diameter, min.		0.40%	3.2	Gage
106.	True position of largest hole with datum A and B		0.40%	3.2	Gage
107.	True position of smallest hole with datums A and B, 4 places		0.40%	3.2	Gage
108.	True position tab separation with datum A		0.40%	3.2	Gage
109.	True position tab width with datum A		0.40%	3.2	Gage
110.	Length to largest hole from forward end		0.40%	3.2	Gage
111.	Length to smallest hole, 4 places		0.40%	3.2	Gage
112.	Width of tab, 2 places		0.40%	3.2	Gage
113.	Height between tabs, 2 places		0.40%	3.2	Gage
114.	Largest length		0.40%	3.2	Gage
115.	Length to center of largest radius		0.40%	3.2	Gage
116.	Largest radius		0.40%	3.2	Gage
117.	Length of tab, 2 places		0.40%	3.2	Gage
118.	Diameter of largest hole		0.40%	3.2	Gage
119.	Diameter of smallest hole, 4 places		0.40%	3.2	Gage
120.	Thickness through forward end of cup, max.		0.40%	3.2	Gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.22 cont'd	Cup, Slider				9329824
					NEXT HIGHER ASSEMBLY 9329822
CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
121.	Location of clearnace "C" hole		0.40%	3.2	Gage
122.	Depth of "C" hole		0.40%	3.2	Gage
123.	Offset of "C" hole		0.40%	3.2	Gage
124.	"C" hole radius		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.23	Upper Housing Assembly				9329810
					NEXT HIGHER ASSEMBLY
					9328756/9292700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Explosive lead, PA 517, 2 places		0.40%	3.2	Visual
102.	Improper staking of PA 517, 2 places		0.40%	3.2	Visual
103.	Improper staking of interrupter retainer		0.40%	3.2	Visual
104.	Interrupter binds *		100%	3.2	Visual/Manual
105.	Protrusions or burrs in slider channel		0.40%	3.2	Visual/Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.2	Visual

NOTES:

* Interrupter must have full freedom of movement -- Any hesitation must reject part.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.24	Lower Housing Assembly				9329813
					NEXT HIGHER ASSEMBLY 9328756/9292700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Protrusions or burrs in slider channel		0.40%	3.2	Visual/Gage
102.	Cover of explosive lead, PA 517, inverted, 2 places		0.40%	3.2	Visual
103.	Improper staking of PA 517 lead, 2 places		0.40%	3.2	Visual
104.	Improper assembly of shorting clip		0.40%	3.2	Visual
105.	Improper staking of shear pin		100%	3.2	Visual
106	Improper assy or missing spring pin		0.40%	3.2	Visual
107.	Load test of shear pin through slider release pin	(a)		3.2	4.5.13
Minor					
201.	Evidence of poor workmanship		0.65%	3.2	Visual

NOTES:
(a) Sample size per MIL-STD-105, Inspection Level I. Accept 0, Reject 1. Any failure shall require that all previous assemblies be subjected to this test.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 which is obsolete.
Document Provided by IHS Not for Resale, No reproduction or networking permitted without license from IHS
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.25	Flexible Cable Assembly				9328757
					NEXT HIGHER ASSEMBLY 9328756
CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Height of Actuator, max		0.40%	3.2	Gage
102.	Height of Actuator soldered terminal, max		0.40%	3.2	Gage
103.	Height of Delay Detonator, max		0.40%	3.2	Gage
104.	Height of M100 Detonator, max		0.40%	3.2	Gage
105.	Height of Detonator soldered terminal, max 2 places		0.40%	3.2	Gage
106.	Height of Terminal, max		0.40%	3.2	Gage
107.	Height of Terminal soldered end, max		0.40%	3.2	Gage
108.	Soldering poor or improper		0.40%	3.2	Visual, MIL-STD-454
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202640-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.26	Flexible Cable Assembly				9329825
					NEXT HIGHER ASSEMBLY 9292700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Height of Actuator, max		0.40%	3.2	Gage
102.	Height of Actuator soldered terminal, max		0.40%	3.2	Gage
103.	Height of Delay Detonator, max		0.40%	3.2	Gage
104.	Height of M100 Detonator, max		0.40%	3.2	Gage
105.	Height of Detonator soldered terminal, max		0.40%	3.2	Gage
106.	Height of Terminal, max		0.40%	3.2	Gage
107.	Height of Terminal soldered end, max		0.40%	3.2	Gage
108.	Soldering poor or incorrect		0.40%	3.2	Visual, MIL-STD-454
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

REMARKS

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.27	Pin, Slider Release				9329814
					NEXT HIGHER ASSEMBLY
					9329813
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Outside diameter		0.40%	3.2	Gage
102.	Finish of O.D.		0.40%	3.2	Gage
103.	Overall length		0.40%	3.2	Gage
104.	Hole diameter (shear pin)		0.40%	3.2	Gage
105.	True position of hole with datum A and B		0.40%	3.2	Gage
106.	Inside diameter		0.40%	3.2	Gage
107.	True position of inside diameter with datum A		0.40%	3.2	Gage
108.	Chamfer, 2 places		0.40%	3.2	Visual
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202640-26T04:26Z
Check the source to verify that this is the currentversion before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.28	Retainer, Interrupter		9328747
			NEXT HIGHER ASSEMBLY 9329810

CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Total length		0.40%	3.2	Gage
102.	Largest width		0.40%	3.2	Gage
103.	Largest thickness		0.40%	3.2	Gage
104.	Smallest inside length		0.40%	3.2	Gage
105.	Depth to inside shoulder		0.40%	3.2	Gage
106.	Smallest inside width		0.40%	3.2	Gage
107.	True position of smallest inside length		0.40%	3.2	Gage
108.	True position of smallest inside width		0.40%	3.2	Gage
109.	Largest inside length		0.40%	3.2	Gage
110.	Largest inside width		0.40%	3.2	Gage
111.	True position of largest inside length		0.40%	3.2	Gage
112.	True position of largest inside width		0.40%	3.2	Gage
113.	Largest radius		0.40%	3.2	Gage
114.	True position of largest radius		0.40%	3.2	Gage
115.	Thickness to largest radius		0.40%	3.2	Gage
116.	Fillet radius max around inside shoulder		0.40%	3.2	Gage
117.	Salt Spray Test	(a)		3.2	4.5.4
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

* See 4.5.1

(a) Sampling and rejection shall be in accordance with MIL-T-12879.

Source: https://assist.dla.mil - Downloaded: 2022-01-26 10:50:22
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.29	Packing and marking for fiberboard/wood box, for S&A Assembly for Mines				9329607, 9329608
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	S&A, Cable, and MDF are improperly secured on support by blister		0.40%	3.2	Visual
102.	Dessicant missing or mislocated		0.40%	3.2	Visual
103.	Filler missing or incorrect in corrugated box		0.40%	3.2	Visual
104.	Skin packing about package not sealed properly		0.40%	3.2	Visual
105.	Cushioning missing between sealed fiberboard box and wooden box		0.40%	3.2	Visual
106.	Nails/screws securing wooden box missing or incorrect		0.40%	3.2	Visual
107.	Fiberboard box improperly sealed		0.40%	3.2	Visual
Minor					
201.	Identification missing, mislocated, illegible or incorrect		0.65%	3.2	Visual
202.	Strapping over cover missing or insecure		0.65%	3.2	Visual
203.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.30	MDF Spacer				9328746
					NEXT HIGHER ASSEMBLY 9328756
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Thickness		0.40%	3.2	Gage
102.	Profile of side		0.40%	3.2	Gage
103.	Profile of end		0.40%	3.2	Gage
104.	Angle of recess		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES: * See 4.5.3, Dimensional control of molded parts.

Document provided by HIS Licensee: Boeing Co. -- Boeing Internal No reproduction or networking permitted unless authorized per IHS Agreement Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.31	Spacer, Detonator				9329828
					NEXT HIGHER ASSEMBLY 9329825
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Outside diameter		0.40%	3.2	Gage
Minor					
201.	Inside diameter		0.65%	3.2	Gage
202.	Length		0.65%	3.2	Gage
203.	Evidence of poor workmanship		0.65%	3.10	Visual
204.	True position of inside diameter		0.65%	3.2	Gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.32	Terminal				9329829
					NEXT HIGHER ASSEMBLY
					9328757/9329825
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE INSPECTION METHOD
Critical	None defined				
Major					
101.	Largest diameter		0.40%	3.2	Gage
102.	Smallest diameter		0.40%	3.2	Gage
103.	True position of smallest diameter		0.40%	3.2	Gage
104.	True position of second smallest diameter		0.40%	3.2	Gage
105.	Second smallest diameter		0.40%	3.2	Gage
106.	Knurl diameter		0.40%	3.2	Gage
107.	Length of second smallest diameter		0.40%	3.2	Gage
108.	Salt Spray Test	(a)	-	3.2	4.5.4
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

(a) Sampling and rejection shall be in accordance with MIL-T-10727.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.33	Spacer, Actuator				9329830
					NEXT HIGHER ASSEMBLY
					9328756/9292700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Total length		0.40%	3.2	Gage
102.	End profile of part including largest radius		0.40%	3.2	Gage
103.	Height		0.40%	3.2	Gage
104.	Location of cavity		0.40%	3.2	Gage
105.	Depth of cavity		0.40%	3.2	Gage
106.	Cross section of tapered hole	10	0-1	3.2	Comparator/Gage
107.	Tonque radius		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

* See 4.5.3.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.34	Ferrule				9328724
					NEXT HIGHER ASSEMBLY 9328723
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Inside diameter		0.40%	3.2	Gage
102.	True position of ID to OD		0.40%	3.2	Gage
103.	Outside diameter		0.40%	3.2	Gage
104.	Length		0.40%	3.2	Gage
105.	C'sink or break of edge of ID, 2 places		0.40%	3.2	Visual
106.	Chamfer, 2 places		0.40%	3.2	Visual
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which Is Obsolete

Source: http://assist.dla.mil - Downloaded: 2026-03-26T04:06Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.35	Cup, End Cap (MDF)				9328725
					NEXT HIGHER ASSEMBLY 9328723
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Length		0.40%	3.2	Gage
102.	Outside diameter		0.40%	3.2	Gage
103.	Inside diameter		0.40%	3.2	Gage
104.	Thickness through bottom		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES: * See 4.5.2

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.36	Insulator				9328728
					NEXT HIGHER ASSEMBLY 9329832
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE INSPECTION METHOD
Critical	None defined	*			
Major					
101.	Outside diameter		0.40%	3.2	Gage
102.	Height to flat		0.40%	3.2	Gage
103.	Thickness		0.40%	3.2	Gage
104.	Depth of cavity		0.40%	3.2	Gage
105.	Wall thickness of cavity		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

* See 4.5.2

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete
Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.37	Safe & Arming Assembly (Mine, AP, XM74) (Prior to Assembling Upper and Lower Housing Assemblies)				9292700
					NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Centrifugal lock spring missing, 2 places		100%	3.2	Manual
2.	Centrifugal lock binding or sticking, 2 places		100%	3.2	Visual/Manual
3.	Slider cup tab missing, deformed or misoriented with centrifugal lock, 2 places		100%	3.2	Visual
4.	Centrifugal lock end flange missing or deformed, 2 places		100%	3.2	Visual
5.	Slider release pin shear pin missing		100%	3.2	Visual
6.	Slider improperly positioned		100%	3.2	Visual/Gage
Major					
101.	Slider spring missing		0.40%	3.2	Visual
102.	Slider binding or sticking		0.40%	3.2	Manual/Visual
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.38	Safe & Arm Assembly (Mine, AT/AV, XM74) (Prior to Assembling Upper and Lower Housing Assemblies)				9328756
					NEXT HIGHER ASSEMBLY ---
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Centrifugal lock spring missing, 2 places		100%	3.2	Visual
2.	Centrifugal lock binding or sticking, 2 places		100%	3.2	Visual/Manual
3.	Slider cup tab missing, deformed or misoriented with centrifugal lock, 2 places		100%	3.2	Visual
4.	Centrifugal lock end flange missing or deformed, 2 places		100%	3.2	Visual
5.	Slider release pin shear pin missing		100%	3.2	Visual
6.	Slider improperly positioned		100%	3.2	Visual/Gage
Major					
101.	Slider spring missing		0.40%	3.2	Visual
102.	Slider binding or sticking		0.40%	3.2	Manual/Visual
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-03-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.39	S&A Assembly (Prior to installing lock plate, blast shield assy, actuator spacer, flexible cable assy and shield)	1 OF 1	9292700
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Non-arming spin test --		100%	3.2	3.5.7.2
Major					
101.	Arming spin test --		100%	3.2	4.5.7.1
Minor	None defined				

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202640-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.40	S&A Assembly (Prior to installing lock plate, blast shield assy, actuator spacer, flexible cable assy and MDF assemblies and shield)				9328756
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Non-arming spin test --		100%	3.2	3.5.7.2
Major					
101.	Arming spin test --		100%	3.2	4.5.7.1
Minor	None defined				

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.41	S&A Assembly (Prior to installing the shield)				9292700
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101.	Lock plate, adhesive disc, blast shield assy, and flexible cable assy missing or incorrectly installed		100%	3.2	Visual
Minor 201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.42	S&A Assembly (Prior to installing the shield)				9328756
					NEXT HIGHER ASSEMBLY ---
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	Non defined				
Major					
101.	MDF assembly incorrectly installed, cut and/or damaged, 2 places		0.40%	3.2	Visual
102.	MDF assembly not staked or loose after staking, 2 places		0.40%	3.2	Visual
103.	Lock plate, adhesive disc, blast shield assy, actuator spacer, MDF spacer and flexible cable assy missing or incorrectly installed		100%	3.2	Visual
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 which is obsolete

Source (http://assist.dla.mil) Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.43	S&A Assembly				9292700
					NEXT HIGHER ASSEMBLY ---
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Eyelet ground open circuit, detonator or micro-piston actuator not commonly shorted to S&A body	(a)	100%	3.2	4.5.14
2.	Length to slider assy, max.		100%	3.2,3.7	Gage, 4.5.19
3.	Slider release pin and shear pin improperly assembled		100%	3.2,3.7	Visual, 4.5.19
Major					
101.	Longest length, max.		0.40%	3.2	Gage
102.	Shield above flush (Note 4)		0.40%	3.2	Gage
103.	Shield staking missing or incorrect (Note 4)		0.40%	3.2	Manual/Visual
104.	Outside diameter of shield, max.		0.40%	3.2	Gage
105.	Gap between housing assemblies (Note 4)	(b)	0.40%	3.2	Gage/Visual
106.	Lock plate and adhesive disc missing or incorrect		100%	3.2	Visual
107.	Identification missing or incorrect (Note 2)		0.40%	3.2	Visual
108.	Main explosive leads obstructed		0.40%	3.2	Visual
109.	Electrical Continuity and Impedance Test (Note 5)				
	a. M100 Detonator		100%	3.2	4.5.14
	b. Micro Piston Actuator		100%	3.2	4.5.14
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:
(a) After installation of eyelet.
(b) Visible contact of bodies, two places minimum at each end.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.44	S&A Assembly				9328756
					NEXT HIGHER ASSEMBLY ---
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Eyelet ground open circuit, detonator or micro piston actuator not commonly shorted to S&A body	(a)	100%	3.2	4.5.14
2.	Length to slider assy, max.		100%	3.2,3.7	Gage, 4.5.19
3.	Slider release pin and shear pin improperly assembled		100%	3.2,3.7	Visual, 4.5.19
Major					
101.	Longest length, max.		0.40%	3.2	Gage
102.	Shield above flush (Note 5)		0.40%	3.2	Gage
103.	Shield staking missing or incorrect (Note 5)		0.40%	3.2	Manual/Visual
104.	Outside diameter of shield, max.		0.40%	3.2	Gage
105.	Gap between housing assemblies (Note 5)	(b)	0.40%	3.2	Gage/Visual
106.	Lock plate and adhesive disc missing or incorrect		100%	3.2	Visual
107.	Identification missing or incorrect (Note 2)		0.40%	3.2	Visual
108.	Main explosive leads obstructed		0.40%	3.2	Visual
109.	MDF damaged, 2 places		100%	3.2	Visual
110.	Electrical Continuity and Impedance Test (Note 6)				
	a. Parallel detonators		100%	3.2	4.5.14
	b. Micro Piston Actuator		100%	3.2	4.5.14
Minor					
201.	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

(a) After installation of eyelet.
(b) Visible contact of bodies, two places minimum at each end.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.45	S&A Assembly		9292700
			NEXT HIGHER ASSEMBLY
			--

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	LAT of S&A ASSEMBLIES	*	See Below		
	Transportation vibration		-	3.4.3	4.5.15.3
	Safe condition examination		-	3.4.3,3.7	4.5.19
	Continuity - resistance checks		-	3.8	4.5.14
	IN-LINE EXPLOSIVE FUNCTIONING				
	Temperature conditioning		-	3.6	4.5.16
	Initial arming (commit to arm)		-	3.5a	4.5.17.1
	Final arming		-	3.5b	4.5.7.2
	Main charge train functioning		-	3.6.2	4.5.18.2

INSPECTION LOT SIZE	* SAMPLE SIZE	-35°-5°F	70°±5°F	145°+5°F	ACCEPT - REJECT SAFE CONDITION	CONTINUITY RESISTANCE	DUD OR DEFECTIVE DENT MAIN CHG.
1201-3200	50	10	30	10	0-1	0-1	0-1
3201-10,000	80	20	40	20	0-1	0-1	1-2
10,000-35,000	125	20	85	20	0-1	1-2	1-2

NOTES:

1. Sample units shall have passed Quality Conformance Inspection 4.4.2.43.
2. Orientation of lock plate shall be random.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63302(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.46	S&A Assembly		9328756
			NEXT HIGHER ASSEMBLY ----

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	LAT of S&A ASSEMBLIES	*	See Below		
	TRANSPORTATION VIBRATION				
	Safe condition examination		-	3.4.3	4.5.15.3
	Continuity - resistance		-	3.4.3,3.7	4.5.19
			-	3.8	4.5.14
	IN-LINE EXPLOSIVE FUNCTIONING				
	Temperature conditioning		-	3.6	4.5.16
	Initial arming (commit-to-arm)		-	3.5a	4.5.17.1
	Final arming		-	3.5b	4.5.17.2
	MDF train functioning		-	3.6.1	4.5.18.1
	Delay detonator, delay time		-	3.6.2	4.5.18.1
	Main charge train functioning		-	3.6.2	4.5.18.2

INSPECTION LOT SIZE	* SAMPLE SIZE	-35°-5°F	70°±5°F	145°+5°	ACCEPT - REJECT SAFE CONDITION	CONT. RESIS	DELAY TIME	DUD OR DEFECTIVE DENT MDF	MAIN CHARGE
1201-3200	50	10	30	10	0-1	0-1	0-1	0-1	0-1
3201-10,000	80	20	40	20	0-1	0-1	0-1	1-2	1-2
10,000-35,000	125	20	85	20	0-1	1-2	1-2	1-2	1-2

NOTES: 1. Sample units shall have passed Quality Conformance Inspection 4.4.2.44.
2. 50% of the sample shall be functioned with the lock plate facing up; and remaining units with lock plate facing down.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26 10:4:262
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First Article and Quality Conformance Inspection Tables.

4.4.3.1 Check test for deterioration of detonators/explosive leads (listed below). If the total time between original acceptance of any lot and the assembly of that lot into the S&A exceeds two years, or if the detonators or explosive leads have been subjected to adverse conditions, however brief, at any time since previous tests, the detonator or explosive lead lot shall be subjected to and must satisfactorily pass the check test for deterioration specified in Military Specifications listed below immediately before they are assembled into the S&A. This test shall be performed by the contractor, on detonators or explosive leads selected by the Government inspector, at the facility assembling the detonators or explosive leads into the S&A. The test shall be conducted at Government expense without cost to the contractor who assembled the detonators/explosive leads or the contractor assembling the detonators/explosive leads into the S&A and shall not constitute a basis for rejection against either contractor except where deterioration has occurred as a direct result of carelessness in handling, storage, etc., permitted while the detonator or explosive lead lot was under the responsibility of either contractor. The Contracting Officer shall arrange to have the contractor reimbursed for the expense incurred in the performance of check tests. In the check test for deterioration of the M100 Detonator, the lead cup functioning requirement of MIL-D-48120 shall be omitted.

MIL-D-48120	-	Detonator, Electric, M100, Parts For, And Loading, Assembling And Packing.
MIL-D-63197	-	Detonator, Delay Electric, PA 506; Parts For, And Loading, Assembling And Packing.
MIL-L-63246	-	Lead, Explosive: PA-509, PA-512, PA-513, PA-514, PA-516, PA-517; Parts For, And Loading, Assembling And Packing.

4.4.4 Inspection equipment. The inspection equipment required to peform the examinations and tests prescribed herein is described in the Paragraph Reference/Inspection Method column in the forms starting with Paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.4 herein.

Source: https://assist.dla.mil/ Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5 Test methods and procedures.

4.5.1 Dimensional control of cast parts. In place of the normal sampling and inspections associated with the Classification of Defects, and with the approval of the Contracting Officer, a sample of at least three (3) parts (as cast) from each cavity shall be fully inspected dimensionally to qualify a new or reworked cavity for use in production or as a control of the cavity during production (See Note 1). Inspection for control of each cavity during production shall be performed on the above quantities from each cavity after production of 5,000 parts or at the end of each week, whichever comes first. Individual cavity identification must be provided.

If any defective parts are found during qualification of the cavity, the cavity producing the defective part(s) shall not be used in production. If any defective parts are found when inspection is performed for control of the cavity, the cavity producing the defective part(s) shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for corrective action.

All cavities formerly removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test specified above. The contractor may request a change of inspection frequency providing he presents objective evidence to substantiate the request to the Contracting Officer.

NOTE 1: Those features of a part which are subsequently machined or otherwise worked upon to meet its drawing requirements shall be inspected in accordance with the classificationof defects. A list of these features shall be supplied with the first article sample.

4.5.2 Dimensional control of stamped parts. In place of the normal sampling and inspection associated with the Classification of Defects, and with the approval of the Contracting Officer a sample of at least ten (10) parts shall be dimensionally inspected to qualify the tool used in the stamping process for use in production (See Note 1). In addition, a random sample of five (5) parts shall be selected from the last portion of each hour's production for dimensional inspection as a control of the tool during production.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

If any defective parts are found during qualification of the tool, the tool producing the defective part(s) shall not be used in production.

If any defective parts are found when inspection is performed for control of the tool, the tool producing the defective part(s) shall be removed from production. Further, that portion of production since the last tool control check shall be returned to the contractor for corrective action.

All tools removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the Contracting Officer to substantiate the request.

NOTE 1: Those features of a part which are subsequently machined or otherwise worked upon to meet its drawing requirements shall be inspected in accordance with the classificationof defects. A list of these features shall be supplied with the first article sample.

4.5.3 Dimensional control of molded or plastic parts. In place of normal sampling and inspections associated with the Classification of Defects, and after a curing time for the parts has been approved (See Note 1) and with the approval of the Contracting officer a sample of three (3) parts (as molded) from each cavity shall be fully inspected dimensionally to qualify a new or reworked cavity for use in production (See Note 2). The molded parts shall carry the individual cavity identification. As a control of each cavity during production, the above quantity of parts from each cavity shall be inspected for at least the defects listed in pertinent paragraphs of 4.4.2. after continuous production of each 5,000 parts or at the end of each week, whichever occurs first. of the three (3) samples, one (1) sample shall be the last part produced. If any defective parts are found during qualification of the cavity, the cavity producing the defective part(s) will not be used in production. If any defective parts are found when inspection is performed for the control of the cavity, the cavity producing the defective part(s) shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for inspection for each separate type of defect according to MIL-STD-105, using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

All cavities removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test specified above. The contractor may request a change of inspection frequency providing he presents objective evidence to the contracting officer to substantiate the request. Contractor design of gages and test equipment required to perform the inspections listed herein shall be forwarded to Commander, ARRADCOM, Dover, New Jersey 07801, ATTN: DRDAR-QAA-I for approval prior to manufacture of equipment.

NOTE 1: Prior to the start of normal production, the contractor shall obtain approval from the procuring activity for the process specification of molded or plastic parts submitted with the first article in establishing a curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g. every 30, 60, etc. reins.) until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability *is* attained. The inspection data used in determining the curing time shall be sent to ARRADCOM, Dover, New Jersey 07801, ATTN: DRDAR-QAA-M/SA . If there is a change in material, or in the cycle time, or if a cavity is reworked, or a new cavity is used, a new curing time shall be established and approved.

NOTE 2: Those features of a part which are subsequently machined or otherwise worked upon to meet its drawing requirements shall be inspected in accordance with the classification of defects. A list of these features shall be submitted with the first article sample.

4.5.4 Salt spray test. The applicable parts shall be tested in accordance with ASTM-B-117 using a 5% salt solution and with the requirements specified on the applicable drawings and specifications. The rejection criteria shall be as specified in the applicable specifications. Assemblies subjected to this test shall not be returned to the lot.

4.5.5 Insulation Resistance Test of flexible cable. Dwg. 9329826. The flexible cable shall be assembled to an approved fixture and subjected to the insulation resistance test specified on the applicable drawing. Observation shall be made for compliance with requirements of the drawing. (Non-destructive test)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.6 Functioning test of microminiature piston acutator. Dwg. 9328715.

4.5.6.1 Resistance test. The piston actuator shall be assembled to an approved test fixture and subjected to the resistance test specified on applicable drawing. A milliohmmeter with a test current of one milliamp or less shall be used. Observation shall be made for compliance with the requirements of the drawing. (Non-destructive test)

4.5.6.2 Solderability test. This test shall be performed in accordance with METHOD 208 of MIL-STD-202. Observation shall be made for compliance with the requriements of the drawing. (Non-destructive test)

4.5.6.3 No fire, all fire and output tests. Immediately following the resistance test of 4.5.6.1, the selected sample of piston actuators shall be temperature conditioned, half at minus 60° - 5°F and half at 160° + 5°F for two (2) hours min. and then shall be subjected to the no fire, all fire and output tests specified on applicable drawing. Observation shall be made for compliance with the requirements of the drawing. (Destructive test)

4.5.7 Spin tests.

4.5.7.1 Arming spin test of centrifugal locks. - Dwg's 9292700/9328756. The S&A assembly shall be placed in an approved fixture and spin machine and subjected to the arming speed specified on the applicable drawing. While at this RPM, observation shall be made for compliance with the arming requirements of the drawing. With rotation stopped, observation shall be made that both centrifugal locks have returned to their safe position. Any assembly failing this test shall be classed defective and removed from the lot. (Non-destructive test)

4.5.7.2 Non-arming spin test of centrifugal locks. - Dwg's 9292700/9328756. Following 4.5.7.1, the same S&A assemblies shall be subjected to the non-arming speed specified on the applicable drawing. While at this RPM, observation shall be made for compliance with the non-arming requirement of the drawing. With rotation stopped, verification shall be made that both locks are in the safe position. Any assembly failing this test shall be classed defective and removed from the lot. (Non-destructive test)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.8 MDF assembly tests - Dwg. 9328723.

4.5.8.1 Output test of MDF assembly. The samples selected shall be temperature conditioned, half at minus 60° -5°F and half at 160° +5°F for two (2) hours min. The assembly shall be subjected to the output test as specified in 3.3 within five minutes after removal from the conditioning chamber. Observation shall be made for compliance with requirements of 3.3. Witness plate, 5/8 X 1 1/4 X 1 1/4 inches, shall be 2024-T351 aluminum alloy bar (rolled drawn or cold finished) Federal Specification QQ-A-225/6 having a Brinell Hardness of 120-130, HB 10/500/30. No confinement of MDF Assembly shall be used. (Destructive test.)

4.5.8.2 Pull test of MDF assembly. The assembly shall be placed in an approved fixture and the pull load applied as specified on the applicable drawing. Observations shall be made for compliance with the requirements of the drawing. Assemblies subjected to this test shall not be returned to the lot. (Destructive test)

4.5.9 Separation test of slider assembly - Dwg. 9329822-1,-2. The slider assembly shall be placed in an approved fixture and the separation load applied as specified on the applicable drawing. Observations shall be made for compliance with the requirements of the drawing. Assemblies subjected to this test shall not be returned to the lot. (Destructive test)

4.5.10 Flexibility test of MDF, PBXN-5, lead sheathed - Dwg. 9328726. This test shall be performed in accordance with MIL-C-50697. Observation shall be made for compliance with the requirements of the Drawing-Note 3. Samples subjected to this test shall not be returned to the lot but shall be used in 4.5.12.

4.5.11 Neutron radiographic examination.

4.5.11.1 MDF, PBXN-5 lead sheathed. Dwg. 9328726. The MDF cord shall be subjected to neutron radiographic examination. Observation shall be made for the requirements of the drawing - Notes 4 and 5. (Non-destructive inspection)

4.5.11.2 MDF assembly. Dwg. 9328723. The MDF assembly shall be subjected to neutron radiographic examination. Observation shall be made for compliance with the requirements of the drawing. (Non-destructive inspection)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.12 Detonation velocity of MDF, PBXN-5 lead sheathed - Dwg. 9328726. Following examination of 4.5.11.1 the sample from 4.5.10 shall be subjected to a detonation velocity test in accordance with the procedure specified on the applicable drawing. Observation shall be made for compliance with the requirements of the drawing - Note 3. (Destructive test)

4.5.13 Load test of lower housing assembly - Dwg. 9329813. The assembly shall be placed in an approved fixture and the static load applied as specified on the applicable drawing. Observation shall be made for compliance with the requirements of the drawing. Assemblies subjected to this test shall not be returned to the lot.

4.5.14 Continuity resistance test of flexible cable assembly after assembly to S&A's. - Dwg's 9328756/9292700. Following assembly to appropriate S&A and the drilling of a hole for the subsequent insertion of an eyelet, the flexible cable assembly shall be subjected to the resistance test specified on the applicable S&A drawing. Readout meter shall be a milliohmmeter or equivalent with a test current of one milliamps or less. Observation shall be made for compliance with the requirements of the applicable S&A drawing. After resistance measurements, the electro explosive device(s) shall have their input leads positively shorted. (Non-destructive test)

4.5.15 Environmental and safety tests of S&A assembly - Dwg’s. 9328756/9292700.

4.5.15.1 Jolt. After verification of the safe condition of 4.5.19, the test sample of S&A assemblies shall be assembled to fixtures and shall be tested in accordance with MIL-STD-331, Test No. 101.2, Procedure II. Observation shall be made for compliance with the requirement of 3.4.1. (Destructive test)

4.5.15.2 Jumble. After verification of the safe condition of 4.5.19, the test sample of S&A assemblies shall be tested in accordance with MIL-STD-331, Test No. 102.1. Observation shall be made for compliance with the requirements specified in 3.4.2. (Destructive test)

4.5.15.3 Transportation vibration - Dwg's 9328756/9292700. After verification of the safe condition of 4.5.19, the S&A assemblies shall be assembled to fixtures and subjected to Test 119, procedure 2 of MIL-STD-331. Observation shall be made for compliance with the applicable requirements specified in 3.4.3.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.16 Temperature conditioning. After verification of the safe condition of 4.5.19, the test items from 4.5.15.3 shall be subjected to continuity resistance measurement of the circuits containing detonator(s), micropiston actuator and common ground as per 4.5.14. The test items shall then be temperature conditioned at the prescribed temperature for two (2) hours min. (See 3.6).

4.5.17 Arming of S&A assemblies. Arming will consist of the following:

a. Initial arming will consist of displacing & locking the two centrifugal locks.

b. Final arming will consist of firing micropiston actuator and displacing slider release pin.

4.5.17.1 Initial arming of S&A assembly. The S&A test samples form 4.5.16 shall be placed in an approved fixture and spin machine and subjected to a spin of 3160 + 290 RPM above its center line, as noted on the applicable drawing. While at this RPM, the lock plate shall be impacted with required minimum force to lock both centrifugal locks at the armed position.

4.5.17.2 Final arming of the S&A assemblies. The sample S&A assemblies form 4.5.17.1 shall be prepared for remote final arming (See c, f) and functioning (See a, b, c, d, f):

a. An aluminum witness plate shall be secured at the end face of MDF cap preselected for functioning. (Dwg. 9328756 only)

b. A confining steel cylinder shall be placed around the S&A shield to provide a witness surface for each of the four (4) main explosive leads. The cylinder shall be secured to preclude unwanted displacement.

c. The S&l+ assembly shall be wired for remote initiation of the micropiston actuator and detonator(s).

d. Temperature conditioning of the sample S&A assemblies shall be continuous until five (5) minutes before functioning.

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T04:26Z
Check the source to verify that this is the current version before use.

e. Prior to functioning of the explosive(s) , the integrity of the detonator(s) circuits shall be verified (See 4.5.14).

f. Final arming shall be obtained by remotely subjecting the micropiston actuator to the energy from a one hundred (100) microfarad capacitor charged to 1.6 volts max.

4.5.18 In-line explosive functioning. Dwg(s) 9292700/ 9328756.

4.5.18.1 MDF and main charge lead explosive train functioning. - Dwg 9328756. The S&A assemblies previously armed and fitted with witness plates and confining ring witness blocks, see 4.5.17.2, shall be functioned by subjecting the parallel M100 and PA 506 delay detonators to the energy from a 100 microfarad capacitor charged to 1.6 volts max. Observation shall be made for compliance with requirements of 3.6.1 and 3.6.2. The 20 ms to 50 ms delay time of the delay detonator PA 506 shall be recorded. Material for the 1/2 in X3/4 in X1/8 in. thick aluminum witness plate shall be as specified in 4.5.1.

4.5.18.2 Main charge lead explosive train functioning. - Dwg. 9292700. The S&A Assemblies previously armed and fitted with steel confining ring witness blocks shall be functioned by subjecting the M100 detonator to the energy from a 100 microfarad capacitor charged to 1.6 volts max. Observation shall be made for compliance with 3.6.2. A holding fixture or weight shall be used to contain movement of witness block during functioning. Material for the 1 3/16 in I.D. X 1 1/2 in long X 3 in O.D. confining ring shall be cold drawn or cold rolled steel, per ASTM-A-108, C1018 or C1020, hardness Rockwell B70-95.

4.5.19 Verification of safe condition of S&A assemblies prior to shipment - Dwg's. 9292700/9328756. Inspection shall be made for the requirements of 3.7 using depth and/or flush pin gages with visual examination through inspection ports. S&A assemblies will be 100% visually inspected to verify safe position of slider, maximum distance of slider from end of S&A and/or probed for presence and proper position of slider release pin and shear pin. Prior to assembling lock plate, verification shall be made for presence and safe position of centrifugal locks and the presence and proper orientation of slider two lock tabs. Any S&A failing to conform with the applicable requirement shall be classed defective and removed from the lot. (Non-destructive test.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

5.0 PREPARATION FOR DELIVERY

5.1 Preservation, packaging and marking. Packaging shall be in accordance with drawing 9329608. Extra care shall be taken in the handling and nesting of flexible cable and MDF(s) of the S&A assemblies.

5.2 Packing and marking. Packing and Marking shall be in accordance with Dwg. 9329607.

5.3 Shipping. When components from more than one lot are shipped as a carload, each lot shall be kept separate, and the division between lots clearly indicated to prevent mixing of the lots in transit.

6. NOTES

6.1 Intended use. The components covered by this specification are intended for use in Mines, Antipersonnel: HE, XM74 and Antitank: HE, XM75.

6.2 All requirements of this specification apply equally to S&A assemblies of Dwg. 9292700 and 9328756 except as otherwise noted.

6.3 Ordering data. See MIL-A-48078

6.4 Submission of inspection equipment designs for approval. See MIL-A-48078. Submit equipment designs as required to Commander, ARRADCOM, ATTN: DRDAR-QAA-1, Dover, NJ 07801. Request letter of submittal state contractor, contract number, specification number, item nomenclature and classification of defects or test paragraph.

6.5 Submission of test data. In addition to the normal distribution of records,one (1) copy of all ballistic data and ammunition data cards shall be forwarded to Commander, ARRADCOM, ATTN: DRDAR-QAA-M,Dover, NJ 07801.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

6.6 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research and Development Command (ARRADCOM) may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities is now under the cognizance of ARRADCOM.

Custodian:
Army-AR

Preparing Activity
Army-AR

Project Number: 1345-A217

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.
NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-S-63302 Safety and Arming Assemblies for Mines: XM74 and XM75

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*

TELEPHONE NO.

DATE

DD FORM 1426 1 OCT 76 EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED

Source: https://assist.dla.mil -- Downloaded: 2026-01-26T04:26Z
Check the source to verify that this is the current version before use.