MILITARY SPECIFICATION

# SAFETY AND ARMING ASSEMBLIES FOR MINES: BLU-91/B AND BLU-92/B

This specification is approved for use by all Departments and Agencies of the Department of Defense.

## 1. SCOPE

1.1 This specification contains requirements not normally covered by the drawings and provides quality assurance provisions for the fabrication of parts, assembly, loading and packing for two types of S&A assemblies for Mines: BLU-91/B and BLU-92/B used in CBU-78/B and CBU-89/B Dispenser.

## 2. APPLICABLE DOCUMENTS

2.1 Issues of documents. The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein:

SPECIFICATIONS

FEDERAL

| | | |
|---|---|---|
| QQ-A-225/6 | - | Alluminum Alloy Bar Rod, and Wire; Rolled Drawn or Cold Finished, 2024 |
| QQ-P-416 | - | Plating, Cadmium (Electrodeposited) |
| QQ-S-571 | - | Solder; Tin Alloy, Tin-Lead Alloy; and Lead Alloy |
| QQ-S-465 | - | Silver Plating, Electrodeposited; General Requirements For |

MILITARY

| | | |
|---|---|---|
| MIL-C-5541 | - | Chemical Conversion Coatings on Aluminum and Aluminum Alloys |
| MIL-T-10727 | - | Tin plating, Electrodeposited or Hot Dipped, For Ferrous and Non-Ferrous Metals |
| MIL-T-12879 | - | Treatments, Chemical, Prepaint and Corrosion Inhibitive, for Zinc Surfaces |

FSC: 1345

**Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.**

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

MIL-S-45743 - Soldering, Manual Type, High Reliability, Electrical and Electronic Equipment
MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For
MIL-D-48120 - Detonator, Electric, M-100; Parts For, and Loading, Assembling and Packing
MIL-C-50697 - Cord, Detonating
MIL-D-63197 - Detonator, Delay Electric: PA506; Parts For, and Loading, Assembling and Packing
MIL-L-63246 - Leads, Explosive, PA509, PA512, PA513, PA514, PA516, PA517 and PA521; Parts For, and Loading, Assembling and Packing

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables For Inspection By Attributes
MIL-STD-202 - Test Methods For Electronic and Electrical Component Parts
MIL-STD-331 - Fuze and Fuze Components, Environmental and Performance Tests For

DRAWINGS

U.S. ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

9328743 - Safe and Arm Assembly
9328692 - Safe and Arm Assembly
9329608 - Packing and Marking For Box, Fiberboard For S&A Assembly For Mines
9329607 - Packing and Marking For Box, Wood For S&A Assembly For Mines

2.2 Other publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on the date of invitation for bids or request for proposal shall apply.

CODE OF FEDERAL REGULATIONS

TITLE 49 - Transportation, Parts 100-199

(The Code of Federal Regulations is available from the Superintendent of Documents, U.S. Government Printing Office, Washington, D.C., 20402. Orders should specify, “49 CFR 100-199 (latest revision)”).



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

AMERICAN SOCIETY FOR TESTING AND MATERIALS

ASTM A 108 - Standard Specification for Steel Bars, Carbon, Cold-Finished, Standard Quality

ASTM B 117 - Standard Method of Salt Spray (Fog) Testing

ASTM F 18 - Standard Test Methods For Rockwell Hardness and Rockwell Superficial Hardness of Metallic Materials

(Application for copies should be addressed to: American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA., 19103).

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the Contracting Officer).

3. REQUIREMENTS

3.1 Material. Materials shall be in accordance with the applicable drawings, specifications and standards.

3.2 Parts and assemblies. The parts and assemblies shall comply with all requirements specified on Drawings (Dwgs.) 9328743 and 9328692, as applicable, all associated drawings and with all requirements specified in applicable specifications and standards.

3.3 Mild Detonating Fuse (MDF) assembly explosive output test. The MDF assembly shall be tested for explosive output in accordance with Test 303 of MIL-STD-331 except as follows: PBXN-5 output from the side of a single loaded cup shall produce 0.010 inch minimum (min) dent in an aluminum witness plate When tested as specified in 4.5.4.1.

3.4 Environmental and safety tests

3.4.1 Jolt. The Safety and Arming (S&A) assembly shall comply with the requirements of MIL-STD-331, Test No. 101, Procedure II.

3.4.2 Jumble. The S&A assembly shall comply with the requirements of MIL-STD-331, Test No. 102.

3.4.3 Transportation Vibration. The S&A assembly shall comply with the requirements of MIL-STD-331, Test No. 119, Procedure 2.

3.5 Arming of the S&A assembly. The S&A assembly shall arm when subjected to the following sequence:

a. The S&A assembly shall commit-to-arm when tested as specified in 4.5.13.1.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

b. Following step "a", the micropiston actuator, on activation, shall enable spring loaded slider and its explosive trains to move to the in-line/armed position as per 4.5.13.2.

3.6 In-line explosive functioning. The armed S&A assembly shall demonstrate high order functioning through the MDF assembly and/or main charge lead explosive trains, as applicable.

3.6.1 MDF train functioning. Upon initiation of the M100 detonator, the MDF train explosive elements shall function high order and cause the specified min. dent in the aluminum witness plate, at the temperature indicated when tested in accordance to 4.5.14 and 4.5.14.1

| Temperature | Depth of Dent |
|---|---|
| -40° - 5°F | .010 inch min |
| +70° + 10°F | .010 inch min |
| +140° + 5°F | .010 inch min |

3.6.2 Main charge lead train functioning - Dwg. 9328692: Delay Detonator, PA506. - Dwg. 9328743: Microdetonator M100. Upon initiation of the appropriate detonator for the particular S&A listed above, the main charge lead train explosive elements shall function high order and cause the specified min. dents in a steel confining ring (witness block) at the temperature indicated. The test shall be performed as specified in 4.5.14.2.

| Temperature | Depth of Dent |
|---|---|
| -40° - 5°F | .005 inch min |
| +70° + 10°F | .005 inch min |
| +140° + 5°F | .005 inch min |

3.7 Verification of safe condition of S&A assemblies. Prior to packaging, positive verification of the presence and safe position of the following features shall be made for each assembly (See 4.5.15).

a. Interlock pin

b. Borerider ball lock

c. Borerider

d. Slider release and shear pin

e. Slider assembly

3.8 Detonator and micropiston actuator short circuit. The resistance of the short circuit across the detonator(s)/micropiston actuator shall be less than 0.015 ohm.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.9 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.10 Workmanship. All parts and assemblies shall be fabricated, loaded and assembled in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, grease, rust, and other foreign matter. The cleaning method used shall not be injurious to any parts, nor shall the. parts be contaminated by the cleaning agents. Soldering shall be neat and have a shiny appearance. Exterior surface coatings shall be continuous, except for a few light scratches not exposing base material. All required marking and stamping shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First article inspection

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2. The first article sample shall consist of the parts and assemblies of Table I in the sample quantities indicated.

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I herein.

4.3.3 Rejection. See MIL-A-48078.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I. FIRST ARTICLE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 7 | DRAWING NUMBER |
|---|---|---|---|
| | S&A Assembly and Components | | See Below |
| | | | NEXT HIGHER ASSEMBLY |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| | Borerider Assembly (Dwg. 9328700) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.1 |
| | Borerider (Dwg. 9328701) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.2 |
| | Spring, Borerider (Dwg. 9328751) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.3 |
| | Interlock Assembly (Dwg. 9328740) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.4 |
| | Pin, Interlock (Dwg. 9328711) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.5 |
| | Spring, Interlock (Dwg. 9328712) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.6 |
| | Cup, Interlock (Dwg. 9328709) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.7 |
| | Slider Assembly (Dwg. 9328718-1) | | | | |
| | Examination for defects | 15 | - | 3.2 | 4.4.2.8 |
| | Separation test | 15 | - | 3.2 | 4.5.5 |
| | Slider Assembly (Dwg. 9328718-2) | | | | |
| | Examination for defects | 15 | - | 3.2 | 4.4.2.8 |
| | Separation test | 15 | - | 3.2 | 4.5.5 |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I. FIRST ARTICLE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 2 OF 7 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| | S&A Assembly and Components | | | | See Below |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| | Cup Slider (Dwg. 9328721)<br>Examination for defects | 10 | - | 3.2 | 4.4.2.9 |
| | Body Slider (Dwg. 9328719)<br>Examination for defects | 10 | - | 3.2 | 4.4.2.10 |
| | Disc Spacer (Dwg. 9328720)<br>Examination for defects | 10 | - | 3.2 | 4.4.2.11 |
| | Blast Shield Assembly (Dwg. 9328710)<br>Examination for defects | 10 | - | 3.2 | 4.4.2.12 |
| | Shield Blast (Dwg. 9328727)<br>Examination for defects | 10 | - | 3.2 | 4.4.2.13 |
| | Insulator (Dwg. 9328728)<br>Examination for defects | 10 | - | 3.2 | 4.4.2.14 |
| | Flexible Cable Assembly (Dwg. 9328713)<br>Examination for defects | 10 | - | 3.2 | 4.4.2.15 |
| | Flexible Cable Assembly (Dwg. 9328742)<br>Examination for defects | 10 | - | 3.2 | 4.4.2.16 |
| | Cable, Flexible (Dwg. 9328714)<br>Examination for defects | 10 | - | 3.2 | 4.4.2.17 |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I. FIRST ARTICLE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 3 OF 7 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| | S&A Assembly and Components | | | | See Below |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| | Clip, Ground (Dwg. 9328716) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.18 |
| | Salt spray | 5 | - | 3.2 | 4.5.1 |
| | Actuator, Microminature Piston (Dwg. 9328715) | | | | |
| | Examination for defects | 16 | - | 3.2 | 4.4.2.19 |
| | Resistance test | 16 | - | 3.2 | 4.5.3.1 |
| | Functioning test | 16 | - | 3.2 | 4.5.3.3 |
| | Solderability test | 5 | - | 3.2 | 4.5.3.2 |
| | MDF Assembly (Dwg. 9328750-1) | | | | |
| | Examination for defects | 16 | - | 3.2 | 4.4.2.20 |
| | Output test | 16 | - | 3.3 | 4.5.4.1 |
| | Pull test | 16 | - | 3.2 | 4.5.4.2 |
| | MDF Assembly (Dwg. 9328750-2) | | | | |
| | Examination for defects | 16 | - | 3.2 | 4.4.2.20 |
| | Output test | 16 | - | 3.2 | 4.5.4.1 |
| | Pull test | 16 | - | 3.2 | 4.5.4.2 |
| | Ferrule (Dwg. 9328724) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.21 |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I. FIRST ARTICLE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 4 OF 7 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| | S&A Assembly and Components | | | | See Below |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| | Cup, End Cap (Dwg. 9328725) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.22 |
| | MDF PBXN-5 Lead Sheathed (Dwg. 9328726) | | | | |
| | Examination for defects | (a) | - | 3.2 | 4.4.2.23 |
| | Flexibility test | | - | 3.2 | 4.5.6 |
| | Detonation velocity test | | - | 3.2 | 4.5.8 |
| | Lower Housing Assembly (Dwg. 9328693) | | | | |
| | Examination for defects | 15 | - | 3.2 | 4.4.2.24 |
| | Housing, Lower (Dwg. 9328694) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.25 |
| | Salt spray | 5 | - | 3.2 | 4.5.1 |
| | Upper Housing Assembly (Dwg. 9328703) | | | | |
| | Examination for defects | 15 | - | 3.2 | 4.4.2.26 |
| | Housing, Upper (Dwg. 9328704) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.27 |
| | Salt spray | 5 | - | 3.2 | 4.5.1 |
| | Retainer Interrupter (Dwg. 9328705) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.28 |
| | Salt spray | 5 | - | 3.2 | 4.5.1 |
| | Interrupter (Dwg. 9329812) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.29 |
| | Salt spray | 5 | - | 3.2 | 4.5.1 |

NOTES: (a) Sampling and rejection shall be in accordance with MIL-C-50697. 10 samples of 2 feet lengths.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I. FIRST ARTICLE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 5 OF 7 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| | S&A Assembly and Components | | | | See Below |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| | Pin, Slider Release (Dwg. 9328707) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.30 |
| | Pin, Shear Slider Release (Dwg. 9328708) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.31 |
| | Salt spray | 5 | - | 3.2 | 4.5.1 |
| | Pin, Shear Borerider (Dwg. 9328695) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.32 |
| | Salt spray | 5 | - | 3.2 | 4.5.1 |
| | Sleeve (Dwg. 9328699) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.33 |
| | Spring, Slider (Dwg. 9328717) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.34 |
| | Cup, Centrifugal Lock (Dwg. 9329819) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.35 |
| | MDF Spacer (Dwg. 9328731) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.36 |
| | Spacer, Actuator (Dwg. 9328729) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.37 |
| | Shield (Dwg. 9328730) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.38 |

NOTES:



Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I. FIRST ARTICLE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 6 OF 7 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| | S&A Assembly and Components | | | | See Below |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| | Lock Plate (Dwg. 9328733) | | | | |
| | Examination for defects | 10 | - | 3.2 | 4.4.2.39 |
| | Salt spray | 5 | - | 3.2 | 4.5.1 |
| | S&A Assembly (Dwg. 9328692) | 30 | | | |
| | Jolt test | 6 | | 3.4.1 | 4.5.11.1 |
| | Jumble test | 6 | | 3.4.2 | 4.5.11.2 |
| | Examination for defects | 18 | | 3.2 | 4.4.2.45(a) |
| | Continuity resistance test | 18 | | 3.2 | 4.5.10 |
| | ---S&A Assy Functioning Test--- | 18 | | | |
| | Transportation vibration | | | 3.4.3 | 4.5.11.3 |
| | Safe condition examination | | | 3.7 | 4.5.15 |
| | Continuity resistance | | | 3.2 | 4.5.10 |
| | Temperature conditioning | (b) | | 3.6 | 4.5.12 |
| | Initial arming | | | 3.5 | 4.5.13.1 |
| | Final arming | | | 3.5 | 4.5.13.2 |
| | Continuity resistance test | | | 3.2 | 4.5.10 |
| | Main charge lead function (4 places) | | | 3.6.2 | 4.5.14.2 |
| | MDF charge function | | | 3.6.1 | 4.5.14.1 |

NOTES: (a) The contractor shall provide certification that the examinations of 4.4.2.41 and 4.4.2.43 been performed.
(b) Test sample 18: 6 shall be conditioned at $-40^{0}F$ $-5^{o}F$, 6 at $70^{o}F \pm 10^{o}F$ and 6 at $145^{o}F$ $+5^{o}F$ before arming and functioning. 3 assy from each temperature group shall be tested borerider down.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I. FIRST ARTICLE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 7 OF 7 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| | S&A Assembly and Components | | | | See Below |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| | S&A Assembly (Dwg. 9328743) | 30 | | | |
| | Jolt test | 6 | | 3.4.1 | 4.5.11.1 |
| | Jumble test | 6 | | 3.4.2 | 4.5.11.2 |
| | Examination for defects | 18 | | 3.2 | 4.4.2.46(a) |
| | Continuity resistance test | 18 | | 3.2 | 4.5.10 |
| | ---S&A Assy Functioning Test--- | 18 | | | |
| | Transportation vibration | | | 3.4.3 | 4.5.11.3 |
| | Safe condition examination | | | 3.7 | 4.5.15 |
| | Continuity resistance | | | 3.2 | 4.5.10 |
| | Temperature conditioning | (b) | | 3.6 | 4.5.12 |
| | Initial arming | | | 3.5 | 4.5.13.1 |
| | Final arming | | | 3.5 | 4.5.13.2 |
| | Continuity resistance test | | | 3.2 | 4.5.10 |
| | Main charge lead function (4 places) | | | 3.6.2 | 4.5.14.2 |

NOTES: (a) The contractor shall provide certification that the examinations of 4.4.2.42 and 4.4.2.44 been performed.
(b) Test sample 18: 6 shall be conditioned at $-40^{0}$F $-5^{o}$F, 6 at $70^{o}$F $\pm$ $10^{o}$F and 6 at $145^{o}$F $+5^{o}$F before arming and functioning.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, each inspection lot of S&A assemblies shall contain the following:

a. Detonators, micropiston actuators, MDF assemblies and lead assemblies, each item from the same lot inter fix number from one manufacturer.

b. Explosive composition "PBXN-5" of one lot interfix number from one manufacturer.

c. Metal parts of one lot interfix number from one manufacturer.

4.4.2 Examination.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Forms, sampling plans for major and minor defects shall be in accordance with MIL-STD-105.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.1 | Borerider Assembly | | | | 9328700 |
| | | | | | NEXT HIGHER ASSEMBLY 9329693 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | O-ring damaged or not lubricated | | 0.40% | 3.2 | Visual |
| 102 | Components missing or incorrect | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 2 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.2 | Borerider | | | | 9328701 |
| | | | | | NEXT HIGHER ASSEMBLY 9328700 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Overall length | | 0.40% | 3.2 | Gage |
| 102 | Distance from tip of tine to retaining ring groove | | 0.40% | 3.2 | Gage |
| 103 | Shear pin hole diameter | | 0.40% | 3.2 | Gage |
| 104 | Shear pin hole depth | | 0.40% | 3.2 | Gage |
| 105 | Retaining ring groove diameter | | 0.40% | 3.2 | Gage |
| 106 | Distance from fork to retaining ring groove | | 0.40% | 3.2 | Gage |
| 107 | Distance between tines | | 0.40% | 3.2 | Gage |
| 108 | True position of retaining ring groove to datum A diameter | | 0.40% | 3.2 | Gage |
| 109 | Location of shear pin hole | | 0.40% | 3.2 | Gage |
| 110 | True position of outside fork diameter to datum A diameter | | 0.40% | 3.2 | Gage |
| 111 | Thickness of tines | | 0.40% | 3.2 | Gage |
| 112 | Diameter of datum A | | 0.40% | 3.2 | Gage |
| 113 | Width of datum B | | 0.40% | 3.2 | Gage |
| 114 | Fork outside diameter | | 0.40% | 3.2 | Gage |
| 115 | True position of distance between tines to datum A diameter | | 0.40% | 3.2 | Gage |
| 116 | Porosity in O-ring groove | | 0.40% | 3.2 | Visual |
| 117 | True position of thickness of tines to datum A diameter | | 0.40% | 3.2 | Gage |
| 118 | Distance from inside fork to retaining ring groove | | 0.40% | 3.2 | Gage |
| 119 | Diameter of O-ring groove | | 0.40% | 3.2 | Gage |

NOTES:





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 2 OF 2 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.2 | Borerider | | | | 9328701 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328700 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| 120 | Sleeve shaft diameter | | 0.40% | 3.2 | Gage |
| 121 | Sleeve shaft diameter true position with datum A diameter | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 71 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.3 | Spring, Borerider | | | | 9328751 |
| | | | | | NEXT HIGHER ASSEMBLY 9328700 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Outside diameter | | 0.40% | 3.2 | Gage |
| 102 | Wire diameter | | 0.40% | 3.2 | Gage |
| 103 | Diameter of end coils | | 0.40% | 3.2 | Gage |
| 104 | Load at .55 in. | | 0.40% | 3.2 | Gage |
| 105 | Free length | | 0.40% | 3.2 | Gage |
| 106 | Number of active coils | | 0.40% | 3.2 | Visual/Manual |
| Minor | | | | | |
| 201 | Ends not square | | 0.65% | 3.10 | Gage |
| 202 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:



Source: https://assistdla.mil -- Downloaded: 2020-10-20T04:20Z
Check the source to verify that this is the current version before use.

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.4 | Interlock, Assembly | | | | 9328740 |
| | | | | | NEXT HIGHER ASSEMBLY 9328692/9328743 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | | | | | |
| 1 | Interlock pin binds or fails to return to the required position when depressed | | 100% | 3.2 | Gage/Visual/Manual |
| Major | | | | | |
| 101 | Crimping incorrect | | 0.40% | 3.2 | Gage |
| 102 | Outside diameter, max | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.2 | Visual |

NOTES:



DRDAR QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.5 | Pin, Interlock<br>. | 1 OF 1 | 9328711<br>NEXT HIGHER ASSEMBLY<br>9328740 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | | | | | |
| 1 | Flange missing or damaged | | 100% | 3.2 | Visual |
| Major | | | | | |
| 101 | Outside diameter (body) | | 0.40% | 3.2 | Gage |
| 102 | Diameter of flange | | 0.40% | 3.2 | Gage |
| 103 | True position of flange with Datum A diameter | | 0.40% | 3.2 | Gage |
| 104 | Distance from body to end of flange | | 0.40% | 3.2 | Gage |
| 105 | Length of body | | 0.40% | 3.2 | Gage |
| 106 | Distance from body to flange | | 0.40% | 3.2 | Gage |
| 107 | Diameter of radial groove | | 0.40% | 3.2 | Gage |
| 108 | Diameter of flat bottomed well | | 0.40% | 3.2 | Gage |
| 109 | Depth of flat bottomed well | | 0.40% | 3.2 | Gage |
| 110 | True position of flat bottomed well with datum A | | 0.40% | 3.2 | Gage |
| 111 | Surface finish of body | | 0.40% | 3.2 | Gage |
| 112 | Depth of groove | | 0.40% | 3.2 | Gage |
| 113 | Distance from end of body to start of undercut for borerider tine | | 0.40% | 3.2 | Gage |
| 114 | Distance from end of body to end of undercut for borerider tine | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | Flange corner not broken, 2 places | | 0.65% | 3.2 | Visual |
| 203 | Chamfers incorrect | | 0.65% | 3.2 | Gage |

NOTES:





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.6 | Spring, Interlock | | | | 9328712 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328740 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Outside diameter | | 0.40% | 3.2 | Gage |
| 102 | Wire diameter | | 0.40% | 3.2 | Gage |
| 103 | Solid height, max. | | 0.40% | 3.2 | Gage |
| 104 | Load at .070 in. | | 0.40% | 3.2 | Gage |
| 105 | Free length | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | Squareness of ends | | 0.65% | 3.2 | Gage |

NOTES:

DRDAR QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.7 | Cup, Interlock | | | | 9328709 |
| | | | | | NEXT HIGHER ASSEMBLY 9328740 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Length to tab | | 0.40% | 3.2 | Gage |
| 102 | Diameter of borerider tine holes | | 0.40% | 3.2 | Gage |
| 103 | Inside diameter | | 0.40% | 3.2 | Gage |
| 104 | Width of tabs | | 0.40% | 3.2 | Gage |
| 105 | Location of tabs to datum A | | 0.40% | 3.2 | Gage |
| 106 | Location of tine holes with datums A and B | | 0.40% | 3.2 | Gage |
| 107 | Length to center of tine holes | | 0.40% | 3.2 | Gage |
| 108 | Outside diameter | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Length | | 0.65% | 3.2 | Gage |
| 202 | Diameter of hole in bottom of cup, min. | | 0.65% | 3.2 | Gage |
| 203 | Evidence of poor workmanship | | 0.65% | 3.2 | Visual |

NOTES:





Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.8 | Slider Assembly | | | | 9328718-1, -2 |
| | | | | | NEXT HIGHER ASSEMBLY 9328692/9328743 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | | | | | |
| 1 | True position of tabs to datum A | | 100% | 3.2 | Gage |
| Major | | | | | |
| 101 | Length | | 0.40% | 3.2 | Gage |
| 102 | PA513, explosive lead inverted 1/ | | 0.40% | 3.2 | Gage |
| 103 | Spacer disc missing or incorrect 1/ | | 0.40% | 3.2 | Gage |
| 104 | PA513 lead loose | | 0.40% | 3.2 | Visual |
| 105 | PA521 explosive lead inverted or above flush in slider body (-1 assy only) | | 0.40% | 3.2 | Gage |
| 106 | PA521 lead loose or improperly staked | | 0.40% | 3.2 | Visual |
| 107 | Separation test of slider cup | 2/ | 0-1 | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.2 | Visual |

NOTES: 1/ Prior to assembling slider body.
2/ Sample size per MIL-STD-105, Inspection Level S-4.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 2 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.9 | Cup, Slider | | | | 9328721 |
| | | | | | NEXT HIGHER ASSEMBLY 9328718 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | | | | | |
| 1 | Tab mislocated, missing or damaged, 2 places | | 100% | 3.2 | Gage/Visual |
| Major | | | | | |
| 101 | Largest outside diameter | | 0.40% | 3.2 | Gage |
| 102 | Smallest inside diameter | | 0.40% | 3.2 | Gage |
| 103 | True position of smallest inside diameter with datum A | | 0.40% | 3.2 | Gage |
| 104 | Smallest outside diameter | | 0.40% | 3.2 | Gage |
| 105 | True position of lead input hole with datum A and B | | 0.40% | 3.2 | Gage |
| 106 | True position of lead output holes with datums A and B, 4 places | | 0.40% | 3.2 | Gage |
| 107 | Width of tabs | | 0.40% | 3.2 | Gage |
| 108 | Distance between tabs | | 0.40% | 3.2 | Gage |
| 109 | Length from end to tabs | | 0.40% | 3.2 | Gage |
| 110 | Length of tab, 2 places | | 0.40% | 3.2 | Gage |
| 111 | Diameter of lead input hole | | 0.40% | 3.2 | Gage |
| 112 | Diameter of lead output hole, 4 places | | 0.40% | 3.2 | Gage |
| 113 | Wall thickness | | 0.40% | 3.2 | Gage |
| 114 | Depth of notch | | 0.40% | 3.2 | Gage |
| 115 | Centerline off set of notch | | 0.40% | 3.2 | Visual |
| 116 | Location of notch with datums A and B | | 0.40% | 3.2 | Gage |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 2 OF 2 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.9 | Cup, Slider | | | | 9328721 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328718 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| 118 | Length of radius between large and small outside diameters | | 0.40% | 3.2 | Gage |
| 119 | Distance from cup at tab end to center of radius between outside diameters | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 2 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.10 | Body, Slider | | | | 9328719 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328718 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Diameter/width of "D" section | | 0.40% | 3.2 | Gage |
| 102 | Length from end to boss | | 0.40% | 3.2 | Gage |
| 103 | Length from basic taper diameter to boss | | 0.40% | 3.2 | Gage |
| 104 | Inside diameter of tines | | 0.40% | 3.2 | Gage |
| 105 | True position of tine ID with datum C | | 0.40% | 3.2 | Gage |
| 106 | Width of slot, 4 places | | 0.40% | 3.2 | Gage |
| 107 | Depth of slot, 4 places | | 0.40% | 3.2 | Gage |
| 108 | True position of slot, with datums A and B, 4 places | | 0.40% | 3.2 | Gage |
| 109 | Diameter of PA521 lead cavity | | 0.40% | 3.2 | Gage |
| 110 | True position of lead cavity with datums A and B | | 0.40% | 3.2 | Gage |
| 111 | Width of rails, 2 places | | 0.40% | 3.2 | Gage |
| 112 | Height of rails, 2 places | | 0.40% | 3.2 | Gage |
| 113 | Distance of center of tine OD to base of rails | | 0.40% | 3.2 | Gage |
| 114 | Tine outside diameter | | 0.40% | 3.2 | Gage |
| 115 | Length of "D" section | | 0.40% | 3.2 | Gage |
| 116 | True position of tine outside diameter to datum A | | 0.40% | 3.2 | Gage |
| 117 | Thickness of shoulder at bottom of lead cavity | | 0.40% | 3.2 | Gage |

NOTES:





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 2 OF 2 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.10 | Body, Slider | | 9328719 |
| | | | NEXT HIGHER ASSEMBLY 9328718 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| 118 | Inside diameter of shoulder at bottom of lead cavity | | 0.40% | 3.2 | Gage |
| 119 | Distance from base of boss to notch | | 0.40% | 3.2 | Gage |
| 120 | Centerline offset of notch | | 0.40% | 3.2 | Gage |
| 121 | Depth of crimp groove | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | Length of boss | | 0.65% | 3.2 | Gage |
| 203 | Diameter of boss | | 0.65% | 3.2 | Gage |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET | OF | DRAWING NUMBER |
|---|---|---|---|---|
| 4.4.2.11 | Disc, Spacer | 1 | 1 | 9328720 |
| | | | | NEXT HIGHER ASSEMBLY: 9328718 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | | | | |
| Major | None defined | | | | |
| Minor | | | | | |
| 201 | Thickness | | 0.65% | 3.2 | Gage |
| 202 | Diameter | | 0.65% | 3.2 | Gage |
| 203 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.?.12 | Blast Shield Assembly | | | | 9328710 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328692/9328743 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Insulator projects in excess of dwg. requirement, 2 places | | 0.40% | 3.2 | Gage |
| 102 | Insulator loose or missing | | 0.40% | 3.2 | Visual/manual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRD:?-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.13 | Shield, Blast | | 9328727 |
| | | | NEXT HIGHER ASSEMBLY 9328710 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Total length | | 0.40% | 3.2 | Gage |
| 102 | Length to notch | | 0.40% | 3.2 | Gage |
| 103 | Length of tab | | 0.40% | 3.2 | Gage |
| 104 | Length of notch | | 0.40% | 3.2 | Gage |
| 105 | Chamfer on tab incorrect | | 0.40% | 3.2 | Gage |
| 106 | Location of flat bottomed holes | | 0.40% | 3.2 | Gage |
| 107 | Bend angle | | 0.40% | 3.2 | Gage |
| 108 | Diameter of thru hole | | 0.40% | 3.2 | Gage |
| 109 | Diameter of flat bottomed holes | | 0.40% | 3.2 | Gage |
| 110 | Thickness, from bottom of flat bottomed holes | | 0.40% | 3.2 | Gage |
| 111 | Distance from edge to center of flat bottomed hole, 2 places | | 0.40% | 3.2 | Gage |
| 112 | Width of notch | | 0.40% | 3.2 | Gage |
| 113 | True position of thru hole with datum A | | 0.40% | 3.2 | Gage |
| 114 | Thickness | | 0.40% | 3.2 | Gage |
| 115 | Width, including tab (see A-A) | | 0.40% | 3.2 | Gage |
| 116 | Width, not including end of tab (see A-A) | | 0.40% | 3.2 | Gage |
| 117 | Chamfer on edge opposite tab end incorrect | | 0.40% | 3.2 | Gage |
| 118 | Distance from edge to bend line | | 0.40% | 3.2 | gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.14 | Insulator | | | | 9328728 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328710 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Outside diameter | | 0.40% | 3.2 | Gage |
| 102 | Height to flat | | 0.40% | 3.2 | Gage |
| 103 | Thickness | | 0.40% | 3.2 | Gage |
| 104 | Depth of cavity | | 0.40% | 3.2 | Gage |
| 105 | Wall thickness of cavity | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.15 | Flexible Cable Assembly | | | | 9328713 |
| | | | | | NEXT HIGHER ASSEMBLY 9328692 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Height of actuator, max | | 0.40% | 3.2 | Gage |
| 102 | Height of actuator soldered terminal, max | | 0.40% | 3.2 | Gage |
| 103 | Height of delay detonator, max | | 0.40% | 3.2 | Gage |
| 104 | Height of M100 detonator, max | | 0.40% | 3.2 | Gage |
| 105 | Height of detonator soldered terminal, max, 2 places | | 0.40% | 3.2 | Gage |
| 106 | Soldering poor or improper | | 0.40% | 3.2 | Visual, MIL-S-45743 |
| 107 | Ground clip missing or improper | | 0.40% | 3.2 | Gage |
| 108 | Improper component or components assembled in wrong position | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.16 | Flexible Cable Assembly | | 9328742 |
| | | | NEXT HIGHER ASSEMBLY 9328743 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Height of actuator, max | | 0.40% | 3.2 | Gage |
| 102 | Height of actuator soldered terminal, max | | 0.40% | 3.2 | Gage |
| 103 | Height of M100 detonator, max | | 0.40% | 3.2 | Gage |
| 104 | Height of detonator soldered terminal, max | | 0.40% | 3.2 | Gage |
| 105 | Soldering poor or improper | | 0.40% | 3.2 | Visual, MIL-S-45743 |
| 106 | Ground clip missing or improper | | 0.40% | 3.2 | Gage |
| 107 | Improper component or components assembled in wrong position | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.17 | Cable, Flexible | | 9328714 |
| | | | NEXT HIGHER ASSEMBLY |
| | | | 9328713/9328742 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Diameter of (A) size holes | | 0.40% | 3.2 | Gage |
| 102 | Diameter of (B) size holes | | 0.40% | 3.2 | Gage |
| 103 | Diameter of (C) size holes | | 0.40% | 3.2 | Gage |
| 104 | Location of (A) size holes | | 0.40% | 3.2 | Gage |
| 105 | Location of (B) size holes | | 0.40% | 3.2 | Gage |
| 106 | Location of (C) size holes | | 0.40% | 3.2 | Gage |
| 107 | Soldering poor or incorrect | | 0.40% | 3.2 | Visual |
| 108 | Insulation resistance test | | 0.40% | 3.2 | 4.5.2 |
| 109 | Conductor width, min. | | 0.40% | 3.2 | Gage/Pattern |
| 110 | Conductor spacing, min. | | 0.40% | 3.2 | Gage/Pattern |
| 111 | Diameter of (D) size hole | | 0.40% | 3.2 | Gage |
| 112 | Location of (D) size hole | | 0.40% | 3.2 | Gage |
| 113 | Bonding of layers, improper | | 0.40% | 3.2 | Visual vs Sample |
| 114 | Broken or improper conductor pattern | | 0.40% | 3.2 | Visual/Pattern |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | Marking missing, improper or illegible | | 0.65% | 3.2 | Visual |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.18 | Clip, Ground | | 9328716 |
| | | | NEXT HIGHER ASSEMBLY |
| | | | 9328713/9328742 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Inside diameter of detonator loops, 2 places | | 0.40% | 3.2 | Gage |
| 102 | Inside diameter of MPA loop | | 0.40% | 3.2 | Gage |
| 103 | Distance between detonator loops | | 0.40% | 3.2 | Gage |
| 104 | Distance from center of delay det loop to center of MPA loop | | 0.40% | 3.2 | Gage |
| 105 | Distance from center of det loop to center of MPA loop | | 0.40% | 3.2 | Gage |
| 106 | Height from plate to top of delay det loop | | 0.40% | 3.2 | Gage |
| 107 | Height from plate to top of MPA loop | | 0.40% | 3.2 | Gage |
| 108 | Height from plate to top of det loop | | 0.40% | 3.2 | Gage |
| 109 | Distance from center line of det loops to tab cutout | | 0.40% | 3.2 | Gage |
| 110 | Width of tab | | 0.40% | 3.2 | Gage |
| 111 | Height of tab | | 0.40% | 3.2 | Gage |
| 112 | Width of plate | | 0.40% | 3.2 | Gage |
| 113 | Length of plate | | 0.40% | 3.2 | Gage |
| 114 | Thickness of material | | 0.40% | 3.2 | Gage |
| 115 | Hardness test | (a) | | 3.2 | ASTM E-18 |
| 116 | Salt spray test | (b) | | 3.2 | 4.5.1 |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES: (a) Sample size per MIL-STD-105, Level S-3, Accept D, Reject 1.
(b) Sampling and rejection shall be in accordance with MIL-T-10727.





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.19 | Actuator, Microminiature Piston | | | | 9328715 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328742/9328713 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Largest diameter | | 0.40% | 3.2 | Gage |
| 102 | Length of housing | | 0.40% | 3.2 | Gage |
| | Piston actuator function test at -60° and +160°F | | | | |
| 103 | No fire test | (a) | 0.40% | 3.2 | 4.5.6.3 |
| 104 | All fire test | (a) | 0.40% | 3.2 | 4.5.6.3 |
| 105 | Output test | (a) | 0.40% | 3.2 | 4.5.6.3 |
| 106 | Resistance test | (a),(b) | 100% | 3.2 | 4.5.6.1 |
| 107 | Piston travel, min | (a) | 0.40% | 3.2 | Gage |
| 108 | Solderability test | (c) | | 3.2 | 4.5.6.2 |
| 109 | Lead diameter | | 0.40% | 3.2 | Gage |
| 110 | Nickel plating missing | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.2 | Visual |

NOTES: (a) Sample size per MIL-STD-105, Inspection Level I. Half the sample shall be tested at low temperature and half at high temperature. (b) Remainder of the lot shall be tested at ambient. (c) Sample size per MIL-STD-105, Inspection Level S-3, Accept 0, Reject 1.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.20 | MDF Assembly | | 9328750-1/2 |
| | | | NEXT HIGHER ASSEMBLY 9328692 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Total length (-1 Assy/-2 Assy) | | 0.40% | 3.2 | Gage |
| 102 | Diameter of end cup, max, 2 places | | 0.40% | 3.2 | Gage |
| 103 | Crimp missing or incomplete | | 0.40% | 3.2 | Visual |
| 104 | Sealant missing or incorrect | | 0.40% | 3.2 | Visual |
| 105 | Lead sheath smear across core, 2 places* | | 0.40% | 3.2 | Visual |
| 106 | Length of roll crimp cup, min, 2 places | | 0.40% | 3.2 | Gage |
| 107 | Pull test, 2 places - Note 8 | (a) | 0.40% | 3.2 | 4.5.8.2 |
| 108 | Spacing of MDF with Ferrule, max, 2 places, Note 5 | | 0.40% | 3.2 | Gage, * |
| 109 | Output test @ -60°F and @ 160°F | (a) | 0.40% | 3.2 | 4.5.4.1 |
| 110 | Ferrule loose after swaging, Note 9 | | 0.40% | 3.2 | Manual/Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.2 | Visual |

NOTES: (a) Sample size per MIL-STD-105, Inspection Level I.
* Prior to assembly of end caps.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.22 | Cup, End Cap (MDF) | | | | 9328725 |
| | | | | | NEXT HIGHER ASSEMBLY 9328750 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Length | | 0.40% | 3.2 | Gage |
| 102 | Outside diameter | | 0.40% | 3.2 | Gage |
| 103 | Inside diameter | | 0.40% | 3.2 | Gage |
| 104 | Thickness through bottom | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.21 | Ferrule | | | | 9328724 |
| | | | | | NEXT HIGHER ASSEMBLY 9328750 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Inside diameter | | 0.40% | 3.2 | Gage |
| 102 | True position of ID to OD | | 0.40% | 3.2 | Gage |
| 103 | Outside diameter | | 0.40% | 3.2 | Gage |
| 104 | Length | | 0.40% | 3.2 | Gage |
| 105 | C'sink or break of edge of ID, 2 places | | 0.40% | 3.2 | Visual |
| 106 | Chamfer, 2 places | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER 9328726 |
|---|---|---|---|---|---|
| 4.4.2.23 | MDF, PBXN-5 Lead Sheathed | | | | NEXT HIGHER ASSEMBLY 9328750 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Outside diameter | | 0.40% | 3.2 | Gage |
| 102 | Flexibility test | (a) | 0.40% | 3.2 | 4.5.10 |
| 103 | Inclusions, voids or impurities | (a) | 0.40% | 3.2 | 4.5.7.1 |
| 104 | Detonation velocity test | (a) | 0.40% | 3.2 | 4.5.8 |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.2 | Visual |

NOTES: (a) Sampling and rejection shall be in accordance with MIL-C-50697.



Source: https://assist.dla.mil -- Downloaded: 2026-01-28T01:28Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.24 | Lower Housing Assembly | | | | 9328693 |
| | | | | | NEXT HIGHER ASSEMBLY 9328693/9328743 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Explosive lead, PA517, inverted, 2 places | | 0.40% | 3.2 | Visual |
| 102 | Improper staking of PA517 lead, 2 places | | 0.40% | 3.2 | Visual |
| 103 | Borerider Assy missing or improper | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.2 | Visual |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 4 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.25 | Housing, Lower | | 9328694 |
| | | | NEXT HIGHER ASSEMBLY 9328693 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | * | | | |
| Major | | | | | |
| 101 | Total length | | 0.40% | 3.2 | Gage |
| 102 | Depth of slider cavity (Sec. G-G, Sht 4) | | 0.40% | 3.2 | Gage |
| 103 | Height to "D" flat of second largest outside diameter | | 0.40% | 3.2 | Gage |
| 104 | Depth of datum -A- diameter (Sec H-H, Sht 4) | | 0.40% | 3.2 | Gage |
| 105 | Depth of datum -B- diameter (Sec U-U, Sht 4) | | 0.40% | 3.2 | Gage |
| 106 | Width of datum -C-, slider cavity (Sec E-E, Sht. 4) | | 0.40% | 3.2 | Gage |
| 107 | Location of datum -C- (Sec E-E, Sht. 4) | | 0.40% | 3.2 | Gage |
| 108 | Diameter of lock plate cavity (Sht. 3) | | 0.40% | 3.2 | Gage |
| 109 | Width of datum -D-, interlock cavity (Det. A, Sht. 1), 2 places | | 0.40% | 3.2 | Gage |
| 110 | True position of datum -D-, 2 places | | 0.40% | 3.2 | Gage |
| 111 | Distance from centerline of datum -A- to end of rectangular section of slider cavity | | 0.40% | 3.2 | Gage |
| 112 | Largest outside radius | | 0.40% | 3.2 | Gage |
| 113 | True position of largest outside radius | | 0.40% | 3.2 | Gage |
| 114 | Depth of interlock cavity (Sec D-D, Sht. 4) | | 0.40% | 3.2 | Gage |
| 115 | Second largest outside radius | | 0.40% | 3.2 | Gage |
| 116 | True position of second largest outside radius | | 0.40% | 3.2 | Gage |
| 117 | Length of interlock cavity (Sec D-D, Sht. 4), 2 places | | 0.40% | 3.2 | Gage |
| 118 | Diameter of datum -L-, piston acctuator hole (Det N, Sht. 3) | | 0.40% | 3.2 | Gage |

NOTES: * See 4.5.1 for inspection of cast features.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 2 OF 4 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.25 | Housing, Lower | | 9328694 |
| | | | NEXT HIGHER ASSEMBLY 9328693 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| 119 | True position of datum -L- | | 0.40% | 3.2 | Gage |
| 120 | Diameter of slider release MPA pin hole (Det N, Sht 3) | | 0.40% | 3.2 | Gage |
| 121 | True position of diameter of slider release pin shear pin hole (Det. N, Sht 3) | | 0.40% | 3.2 | Gage |
| 122 | Diameter of datum -H-, main explosive lead cavity, 2 places | | 0.40% | 3.2 | Gage |
| 123 | True position of datum -H-, 2 places | | 0.40% | 3.2 | Gage |
| 124 | Distance from datum -C- to bottom of main explosive lead cavity, 2 places | | 0.40% | 3.2 | Gage |
| 125 | Diameter of main explosive lead flash hole | | 0.40% | 3.2 | Gage |
| 126 | Diameter of datum -G-, electric detonator cavity | | 0.40% | 3.2 | Gage |
| 127 | True position of datum -G- | | 0.40% | 3.2 | Gage |
| 128 | Diameter of ground clip relief hole | | 0.40% | 3.2 | Gage |
| 129 | True position of ground clip relief hole | | 0.40% | 3.2 | Gage |
| 130 | Depth of ground clip relief well, 2 places | | 0.40% | 3.2 | Gage |
| 131 | Thickness of shoulder formed by detonator flash hole | | 0.40% | 3.2 | Gage |
| 132 | Diameter of datum -F-, electric detonator cavity | | 0.40% | 3.2 | Gage |
| 133 | True position of datum -F- | | 0.40% | 3.2 | Gage |
| 134 | Depth of smallest slider cavity radius (Sht. 3) | | 0.40% | 3.2 | Gage |
| 135 | Width of smallest slider cavity radius (Sht. 3) | | 0.40% | 3.2 | Gage |
| 136 | True position of width of smallest slider cavity (Sht. 3) | | 0.40% | 3.2 | Gage |
| 137 | Burrs in cavities | | 0.40% | 3.2 | Visual |
| 138 | Salt spray test | (a) | | 3.2 | 4.5.4 |
| 139 | Diameter of borerider shear pin hole | | 0.40% | 3.2 | Gage |
| 140 | True position of borerider shear pin hole | | 0.40% | 3.2 | Gage |

NOTES:



Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS



| PARAGRAPH | TITLE | | SHEET 3 OF 4 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.25 | Housing, Lower | | | | 9328694 |
| | | | | | NEXT HIGHER ASSEMBLY 9328693 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| 141 | Distance from end of part to bottom of lock plate cavity (Sec K-K, Sht 5) | | 0.40% | 3.2 | Gage |
| 142 | Width of borerider ball lock slot (Sec K-K, Sht. 5) | | 0.40% | 3.2 | Gage |
| 143 | Depth of borerider ball lock slot | | 0.40% | 3.2 | Gage |
| 144 | True position of borerider ball lock slot | | 0.40% | 3.2 | Gage |
| 145 | Depth of well forming datum -A- | | 0.40% | 3.2 | Gage |
| 146 | Depth of well forming datum -B- | | 0.40% | 3.2 | Gage |
| 147 | Width of well forming datum -B- | | 0.40% | 3.2 | Gage |
| 148 | Width of borerider assembly spring cavity (Sec G-G, Sht 4) | | 0.40% | 3.2 | Gage |
| 149 | Depth of borerider assembly spring cavity | | 0.40% | 3.2 | Gage |
| 150 | True position of borerider assembly spring cavity | | 0.40% | 3.2 | Gage |
| 151 | Width of borerider assembly tine slot (Sec F-F, Sht 4) | | 0.40% | 3.2 | Gage |
| 152 | Depth of borerider assembly tine slot | | 0.40% | 3.2 | Gage |
| 153 | True position of borerider assembly tine slot | | 0.40% | 3.2 | Gage |
| 154 | Thickness of housing at flat for MPA cavity (Sec F-F, Sht 4) | | 0.40% | 3.2 | Gage |
| 155 | Width of slots in slider cavity, 2 places (Sec G-G, Sht 4) | | 0.40% | 3.2 | Gage |
| 156 | Depth of slots in slider cavity, 2 places | | 0.40% | 3.2 | Gage |
| 157 | Distance from centerline to edge of interlock pin cavity, 2 places (Sec D-D, Sht 4) | | 0.40% | 3.2 | Gage |
| 158 | Diameter of MPA cavity (Sht 3) | | 0.40% | 3.2 | Gage |
| 159 | Depth of MPA cavity | | 0.40% | 3.2 | Gage |
| 160 | True positionof MPA cavity | | 0.40% | 3.2 | Gage |
| 161 | Width of housing (Sht 3) | | 0.40% | 3.2 | Gage |

NOTES: (a) Sampling and rejection shall be in accordance with MIL-T-12879.





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 4 OF 4 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.25 | Housing, Lower | | | | 9328694 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328693 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| 162 | Width of housing at reduced section, 2 places | | 0.40% | 3.2 | Gage |
| 163 | Length of housing between reduces section | | 0.40% | 3.2 | Gage |
| 164 | Depth of lock plate cavity | | 0.40% | 3.2 | Gage |
| 165 | Width of slider release pin cavity (Sht 1) | | 0.40% | 3.2 | Gage |
| 166 | Distance of slider release pin cavity from end of part | | 0.40% | 3.2 | Gage |
| 167 | Distance of slider release pin to center line of datum -C- (Sht 1) | | 0.40% | 3.2 | Gage |
| 168 | Depth of slider release pin cavity (Sht 1) | | 0.40% | 3.2 | Gage |
| 169 | Radius of housing on end with flat, 2 places (Sht 1) | | 0.40% | 3.2 | Gage |
| 170 | True position of radius on end with flat, 2 places (Sht 1) | | 0.40% | 3.2 | Gage |
| 171 | Diameter of borerider sleeve notch (Sht 1) | | 0.40% | 3.2 | Gage |
| 172 | True position of borerider sleeve notch (Sht 1) | | 0.40% | 3.2 | Gage |
| 173 | Depth of borerider sleeve notch (Sht 1) | | 0.40% | 3.2 | Gage |
| 174 | Thickness of borerider sleeve notch (Sht 1) | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | Interlock assembly notch incorrect | | 0.65% | 3.2 | Gage |
| 203 | Wall thickness at end of slider cavity | | 0.65% | 3.2 | Gage |
| 204 | Slider assembly inspection notch incorrect | | 0.65% | 3.2 | Gage |
| 205 | Blast shield flat missing or incorrect (Det L, Sht 3) | | 0.65% | 3.2 | Gage |
| 206 | Diameter of detonator flash hole, 2 places | | 0.65% | 3.2 | Gage |
| 207 | Interlock assembly inspection notch missing or incorrect | | 0.65% | 3.2 | Gage |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.26 | Upper Housing Assembly | | | | 9328703 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328692/9328743 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Explosive lead missing, PA517, 2 places | | 0.40% | 3.2 | Visual |
| 102 | Improper staking of PA517, 2 places | | 0.40% | 3.2 | Visual |
| 103 | Improper staking of interrupter retainer | | 0.40% | 3.2 | Visual |
| 104 | Interrupter binds* | | 100% | 3.2 | Visual/Manual |
| 105 | Protrusions or burrs in slider channel | | 0.40% | 3.2 | Visual |
| 106 | Improper staking of shear pin | | 0.40% | 3.2 | Visual/Manual |
| 107 | Shear pin, static load | | 0.40% | 3.2 | Test/4.5.9 |
| Minor | | | | | |
| 201 | Evidence of poor workmanhip | | 0.65% | 3.2 | Visual |

NOTES: * Interrupter must have full freedom of movement -- Any hesitation will reject part.





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 5 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.27 | Housing, Upper | | | | 9328704 |
| | | | | | NEXT HIGHER ASSEMBLY 9328703 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Total length | | 0.40% | 3.2 | Gage |
| 102 | Depth of slider cavity (Sec. F-F, Sht 3), 2 places | | 0.40% | 3.2 | Gage |
| 103 | Height to "D" flat of second largest outside diameter | | 0.40% | 3.2 | Gage |
| 104 | Height of datum -A- (Sht 4) | | 0.40% | 3.2 | Gage |
| 105 | Height of datum -B- (Sht 4) | | 0.40% | 3.2 | Gage |
| 106 | Diameter of datum -C-, 2 places (Sht. 2) | | 0.40% | 3.2 | Gage |
| 107 | True position of datum -C- 2 places, (Sht. 2) | | 0.40% | 3.2 | Gage |
| 108 | Width of lock plate cavity | | 0.40% | 3.2 | Gage |
| 109 | Width of interlock cavity, 2 places (Sht 3) | | 0.40% | 3.2 | Gage |
| 110 | True position of interlock cavity, 2 places | | 0.40% | 3.2 | Gage |
| 111 | Distance from end of slider cavity major section to end of part (Sec F-F, Sht 3) | | 0.40% | 3.2 | Gage |
| 112 | Largest outside radius | | 0.40% | 3.2 | Gage |
| 113 | True position of largest outside radius | | 0.40% | 3.2 | Gage |
| 114 | Depth of interlock pin cavity (Sec T-T, Sht. 3) | | 0.40% | 3.2 | Gage |
| 115 | Second largest outside radius, 4 places | | 0.40% | 3.2 | Gage |
| 116 | True position of second largest outside radius, 4 places | | 0.40% | 3.2 | Gage |
| 117 | Length of centerline to end of interlock pin cavity | | 0.40% | 3.2 | Gage |
| 118 | Length from centerline to start of interlock pin cavity | | 0.40% | 3.2 | Gage |
| 119 | Width of slider release pin cavity (Sht 5) | | 0.40% | 3.2 | Gage |
| 120 | True position of slider release pin cavity width | | 0.40% | 3.2 | Gage |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 2 OF 5 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.27 | Housing, Upper | | | | 9328704 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328703 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| 121 | Length of slider release pin cavity | | 0.40% | 3.2 | Gage |
| 122 | True position of slider release pin cavity length | | 0.40% | 3.2 | Gage |
| 123 | Diameter of datum -D-, main explosive lead cavity, 2 places (Sht 4) | | 0.40% | 3.2 | Gage |
| 124 | True position of datum -D-, 2 places | | 0.40% | 3.2 | Gage |
| 125 | Distance from centerline to bottom of main explosive lead cavity, 2 places | | 0.40% | 3.2 | Gage |
| 126 | Diameter of main explosive lead flash hole, 2 places | | 0.40% | 3.2 | Gage |
| 127 | Diameter of MDF end cap counter bore, 2 places (Sht 2) | | 0.40% | 3.2 | Gage |
| 128 | Thickness of barrier between MDF assembly holes | | 0.40% | 3.2 | Gage |
| 129 | Width of MDF channels, 2 places | | 0.40% | 3.2 | Gage |
| 130 | True position of MDF channels, 2 places | | 0.40% | 3.2 | Gage |
| 131 | Diameter of ball lock inspection hole (Sht 2) | | 0.40% | 3.2 | Gage |
| 132 | True position of ball lock inspection hole (Sht 2) | | 0.40% | 3.2 | Gage |
| 133 | Width of slider release pin shear pin cavity (Sht 5) | | 0.40% | 3.2 | Gage |
| 134 | True position of slider release pin shear pin cavity (Sht 5) | | 0.40% | 3.2 | Gage |
| 135 | Depth of slider release pin shear pin cavity (Sec N-N, Sht 5) | | 0.40% | 3.2 | Gage |
| 136 | Depth of shear pin staking well (Sec N-N, Sht 5) | | 0.40% | 3.2 | Gage |
| 137 | Height of slider release pin cavity boss (Sec N-N, Sht 5) | | 0.40% | 3.2 | Gage |

NOTES:





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 3 OF 5 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.27 | Housing, Upper | | | | 9328704 |
| | | | | | NEXT HIGHER ASSEMBLY 9328703 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| 138 | Depth of slider cavity at smallest radius (Sec T-T, Sht. 6) | | 0.40% | 3.2 | Gage |
| 139 | Smallest slider cavity radius | | 0.40% | 3.2 | Gage |
| 140 | True position of slider cavity at smallest radius section | | 0.40% | 3.2 | Gage |
| 141 | Burrs in cavities | | 0.40% | 3.2 | Visual |
| 142 | Salt spray test | (a) | | 3.2 | 4.5.4 |
| 143 | Largest slider cavity radius, 2 places (Sec S-3, Sht 6) | | 0.40% | 3.2 | Gage |
| 144 | True position of slider cavity largest radius section | | 0.40% | 3.2 | Gage |
| 145 | Distance from end of part to bottom of lock plate cavity (Sec F-F) | | 0.40% | 3.2 | Gage |
| 146 | Width of borerider ball lock slot (Sec H-H) | | 0.40% | 3.2 | Gage |
| 147 | Depth of borerider ball lock slot (Sec S-S) | | 0.40% | 3.2 | Gage |
| 148 | True position of borerider ball lock slot (Sec H-H) | | 0.40% | 3.2 | Gage |
| 149 | Distance from centerline of slider cavity to center of slider release pin cavity semicircular section 1 | | 0.40% | 3.2 | Gage |
| 150 | Width of slider release pin cavity boss | | 0.40% | 3.2 | Gage |
| 151 | Thickness of slider release pin stop (Sec S-S) | | 0.40% | 3.2 | Gage |
| 152 | Width of borerider assembly spring cavity (Sec L-L) | | 0.40% | 3.2 | Gage |
| 153 | Depth of borerider assembly spring cavity (Sec L-L) | | 0.40% | 3.2 | Gage |
| 154 | True position of borerider assembly spring cavity (Sec L-L) | | 0.40% | 3.2 | Gage |

NOTES: (a) Sampling and rejection shall be in accordance with MIL-T-12879.



Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS



| PARAGRAPH | TITLE | SHEET 4 OF 5 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.27 | Housing, Upper | | 9328704 |
| | | | NEXT HIGHER ASSEMBLY 9328703 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| 155 | Width of borerider assembly tine slot (Sec S-S) | | 0.40% | 3.2 | Gage |
| 156 | Depth of borerider assembly tine slot (Sec S-S) | | 0.40% | 3.2 | Gage |
| 157 | True position of borerider assembly tine slot (Sec S-S) | | 0.40% | 3.2 | Gage |
| 158 | Thickness of housing at flat for MDF assembly wells and MDF channel excluding datums A & B and slider release pin boss (Sec F-F) | | 0.40% | 3.2 | Gage |
| 159 | Depth to bottom of interrupter retainer well (Sec F-F) | | 0.40% | 3.2 | Gage |
| 160 | Depth of interrupter well (Sec F-F) | | 0.40% | 3.2 | Gage |
| 161 | Thickness of shoulder formed by MDF assembly blast hole (Sec F-F) 2 places | | 0.40% | 3.2 | Gage |
| 162 | Length of interrupter cavity | | 0.40% | 3.2 | Gage |
| 163 | True position of interrupter cavity | | 0.40% | 3.2 | Gage |
| 164 | Width of interrupter cavity | | 0.40% | 3.2 | Gage |
| 165 | True position of interrupter cavity width | | 0.40% | 3.2 | Gage |
| 166 | Width of housing | | 0.40% | 3.2 | Gage |
| 167 | Length from end of housing to end of reduced section (D section measured on radial portion) | | 0.40% | 3.2 | Gage |
| 168 | Length from end of housing to start of reduced section | | 0.40% | 3.2 | Gage |
| 169 | Length from centerline datum -A- to end of housing | | 0.40% | 3.2 | Gage |
| 170 | Width of slider cavity (Sec S-S) | | 0.40% | 3.2 | Gage |
| 171 | True position of slider cavity (Sec S-S) | | 0.40% | 3.2 | Gage |
| 172 | Width of interrupter retainer cavity | | 0.40% | 3.2 | Gage |
| 173 | True position of interrupter retainer cavity width | | 0.40% | 3.2 | Gage |

NOTES:





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 5 OF 5 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.27 | Housing, Upper | | | | 9328704 |
| | | | | | NEXT HIGHER ASSEMBLY 9328703 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| 174 | Length of interrupter retainer cavity | | 0.40% | 3.2 | Gage |
| 175 | True position of interrupter retainer cavity length | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | Wall thickness at end of slider cavity | | 0.65% | 3.2 | Gage |
| 203 | Distance between shield staking notch oversize | | 0.65% | 3.2 | Gage |
| 204 | Length of posts containing datums A & B oversize | | 0.65% | 3.2 | Gage |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.28 | Retainer, Interrupter | | 9328705 |
| | | | NEXT HIGHER ASSEMBLY 9328703 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | * | | | |
| Major | | | | | |
| 101 | Total length | | 0.40% | 3.2 | Gage |
| 102 | Width | | 0.40% | 3.2 | Gage |
| 103 | Thickness | | 0.40% | 3.2 | Gage |
| 104 | Length of through slot | | 0.40% | 3.2 | Gage |
| 105 | Depth to inside shoulder | | 0.40% | 3.2 | Gage |
| 106 | Width of through slot | | 0.40% | 3.2 | Gage |
| 107 | True position of through slot length | | 0.40% | 3.2 | Gage |
| 108 | True posotion of through slot width | | 0.40% | 3.2 | Gage |
| 109 | Length of interrupter cavity | | 0.40% | 3.2 | Gage |
| 110 | Width of interrupter cavity | | 0.40% | 3.2 | Gage |
| 111 | True position of interrupter cavity length | | 0.40% | 3.2 | Gage |
| 112 | True position of interrupter cavity width | | 0.40% | 3.2 | Gage |
| 113 | Width of arc running full length | | 0.40% | 3.2 | Gage |
| 114 | True position of arc running full length | | 0.40% | 3.2 | Gage |
| 115 | Thickness of thinnest section | | 0.40% | 3.2 | Gage |
| 116 | Fillet radius max around inside shoulder | | 0.40% | 3.2 | Gage |
| 117 | Salt Spray Test | (a) | | 3.2 | 4.5.1 |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES: * See 4.5.1
(a) Sampling and rejection shall be in accordance with MIL-T-12879.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.2° | Interrupter | | | | 9329812 |
| | | | | | NEXT HIGHER ASSEMBLY 9328703 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | * | | | |
| Major | | | | | |
| 101 | Diameter | | 0.40% | 3.2 | Gage |
| 102 | Thickness | | 0.40% | 3.2 | Gage |
| 103 | Chamfer or radius missing, 2 places | | 0.40% | 3.2 | Visual |
| 104 | Salt Spray Test | (a) | | 3.2 | 4.5.1 |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES: * See 4.5.2

(a) Sampling and rejection shall be in accordance with QQ-P-416.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2016-10-28T04:28Z
Check the source to verify that this is the current version before use.

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.30 | Pin, Slider Release | | | | 9328707 |
| | | | | | NEXT HIGHER ASSEMBLY 9328703 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Height | | 0.40% | 3.2 | Gage |
| 102 | Width | | 0.40% | 3.2 | Gage |
| 103 | Overall length | | 0.40% | 3.2 | Gage |
| 104 | Hole diameter (shear pin) | | 0.40% | 3.2 | Gage |
| 105 | True position of hole with datum A and B | | 0.40% | 3.2 | Gage |
| 106 | Salt Spray Test | (a) | | 3.2 | 4.5.1 |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | True position of thru hole with datum A | | 0.65% | 3.2 | Gage |

NOTES: (a) Sampling and rejection shall be in accordance with MIL-T-12897.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.31 | Pin, Shear, Slider Release | | 9328708 |
| | | | NEXT HIGHER ASSEMBLY 9328703 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Diameter | | 0.40% | 3.2 | Gage |
| 102 | Length | | 0.40% | 3.2 | Gage |
| 103 | Salt Spray Test | (a) | | 3.2 | 4.5.1 |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES: (a) Sampling and rejection shall be in accordance with MIL-C-5541.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

## CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.32 | Pin, Shear Borerider | | | | 9328695 |
| | | | | | NEXT HIGHER ASSEMBLY 9328693 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Diameter | | 0.40% | 3.2 | Gage |
| 102 | Length | | 0.40% | 3.2 | Gage |
| 103 | Salt Spray Test | (a) | | 3.2 | 4.5.1 |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES: (a) Sampling and rejection shall be in accordance with MIL-T-10727.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.33 | Sleeve | 1 OF 1 | 9328699 |
| | | | NEXT HIGHER ASSEMBLY: 9328693 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Outside diameter (mounting flange) | | 0.40% | 3.2 | Gage |
| 102 | Diameter of datum B | | 0.40% | 3.2 | Gage |
| 103 | Diameter of datum C (mounting flange groove) | | 0.40% | 3.2 | Gage |
| 104 | Length of datum C | | 0.40% | 3.2 | Gage |
| 105 | Length from mounting flange to end of sleeve | | 0.40% | 3.2 | Gage |
| 106 | Width of "O" ring groove | | 0.40% | 3.2 | Gage |
| 107 | Depth of "O" ring groove | | 0.40% | 3.2 | Gage |
| 108 | Diameter of datum A | | 0.40% | 3.2 | Gage |
| 109 | True position of datum B to datum A | | 0.40% | 3.2 | Gage |
| 110 | Datum A surface finish | | 0.40% | 3.2 | Gage |
| 111 | "O" ring groove surface finish | | 0.40% | 3.2 | Gage |
| 112 | True position of datum C to datum A | | 0.40% | 3.2 | Gage |
| 113 | Runout of mounting flange base to datum A | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | Chamfer missing, 2 places | | 0.65% | 3.10 | Visual |
| 203 | Thickness of mounting flange | | 0.65% | 3.10 | Gage |
| 204 | Diameter of clearance groove | | 0.65% | 3.10 | Gage |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2025-10-26T10:42:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.34 | Spring, Slider | | | | 9328717 |
| | | | | | NEXT HIGHER ASSEMBLY 9328692/9328743 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Outside diameter | | 0.40% | 3.2 | Gage |
| 102 | Minimum load, at .445 in., before and after compression for 24 hours | (a) | | 3.2 | Test Set Up |
| 103 | Solid height, max. | | 0.40% | 3.2 | Gage |
| 104 | Diameter of wire | | 0.40% | 3.2 | Gage |
| 105 | Free length | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | Ends not square | | 0.65% | 3.2 | Gage |

NOTES: (a) Sample size per MIL-STD-105, Inspection Level S-3, Accept 0, Reject 1, acceptable parts may be returned to the lot.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.35 | Cup, Centrifugal Lock | | 9328819 |
| | | | NEXT HIGHER ASSEMBLY: 9328692/9328743 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Inside diameter | | 0.40% | 3.2 | Gage |
| 102 | Hole diameter | | 0.40% | 3.2 | Gage |
| 103 | Outside diameter | | 0.40% | 3.2 | Gage |
| 104 | Bottom thickness | | 0.40% | 3.2 | Gage |
| 105 | Length | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.36 | MDF Spacer | | | | 9328731 |
| | | | | | NEXT HIGHER ASSEMBLY 9328692 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Thickness | | 0.40% | 3.2 | Gage |
| 102 | Profile of side | | 0.40% | 3.2 | Gage |
| 103 | Profile of end | | 0.40% | 3.2 | Gage |
| 104 | Angle of recess | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.37 | Spacer, Actuator | | | | 9328729 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328692/9328743 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Total length of datum A | | 0.40% | 3.2 | Gage |
| 102 | Profile of part | | 0.40% | 3.2 | Gage |
| 103 | Width | | 0.40% | 3.2 | Gage |
| 104 | Location of cavity | | 0.40% | 3.2 | Gage |
| 105 | Depth of cavity (Sec A-A) | | 0.40% | 3.2 | Gage |
| 106 | Diameter of cavity (Sec A-A) | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |
| 202 | Chamfer missing | | 0.65% | 3.10 | Visual |
| 203 | Taper of hole incorrect | | 0.65% | 3.2 | Gage |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.38 | Shield | | | | 9328730 |
| | | | | | NEXT HIGHER ASSEMBLY 9328692/9328743 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Outside diameter, max. | | 0.40% | 3.2 | Gage |
| 102 | Total length | | 0.40% | 3.2 | Gage |
| 103 | Diameter of main lead blast hole, 4 places | | 0.40% | 3.2 | Gage |
| 104 | True position of diameter of main lead blast hole with datums A and B, 4 places | | 0.40% | 3.2 | Gage |
| 105 | True position of tang width datum A | | 0.40% | 3.2 | Gage |
| 106 | Width of tang | | 0.40% | 3.2 | Gage |
| 107 | True position of inspection holes with datums A and B, 2 places | | 0.40% | 3.2 | Gage |
| 108 | Diameter of inspection holes, 2 places | | 0.40% | 3.2 | Gage |
| 109 | Thickness of shield | | 0.40% | 3.2 | Gage |
| 110 | Length to tang | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Gage |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.39 | Plate, Lock | | | | 9328733 |
| | | | | | NEXT HIGHER ASSEMBLY |
| | | | | | 9328743/9328692 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Outside diameter | | 0.40% | 3.2 | Gage |
| 102 | Height of plate | | 0.40% | 3.2 | Gage |
| 103 | Material thickness | | 0.40% | 3.2 | Gage |
| 104 | Inside angle-detail A | | 0.40% | 3.2 | Gage |
| 105 | Corner edge radius, max., detail A | | 0.40% | 3.2 | Gage |
| 106 | Outside flat, min., detail A | | 0.40% | 3.2 | Gage |
| 107 | Salt Spray Test | (a) | | 3.2 | 4.5.1 |
| 108 | Hardness test | (b) | | 3.2 | ASTM-E-18 |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES: (a) Sampling andd rejection shall be in accordance with QQ-P-416.
(b) MIL-STD-105, Inspection Level S-3, Accept 0, Reject 1.





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.40 | Packing and Marking for Fiberboard/Wood Box, for S&A Assembly for Mines | | | | 9329607/9329608 |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | S&A, Cable, and MDF are improperly secured on support by blister | | 0.40% | 3.2 | Visual |
| 102 | Desiccant missing or mislocated | | 0.40% | 3.2 | Visual |
| 103 | Filler missing or incorrect in corrugated box | | 0.40% | 3.2 | Visual |
| 104 | Skin packing about package not sealed properly | | 0.40% | 3.2 | Visual |
| 105 | Cushioning missing between sealed fiberboard box and wooden box | | 0.40% | 3.2 | Visual |
| 106 | Nails/screws securing wooden box missing or incorrect | | 0.40% | 3.2 | Visual |
| 107 | Fiberboard box improperly sealed | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Identification missing, mislocated, illegible or incorrect | | 0.65% | 3.2 | Visual |
| 202 | Strapping over cover missing or insecure | | 0.65% | 3.2 | Visual |
| 203 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.41 | Safe & Arm Assembly (Prior to Assembling Borerider Shear Pin and Lock Plate) | 1 OF 1 | 9328692/9328743 |
| | | | NEXT HIGHER ASSEMBLY |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | | | | | |
| 1 | Interlock assy missing | | 100% | 3.2 | Visual |
| 2 | Interlock pin sticking or binding | | 100% | 3.2 | Manual |
| 3 | Slider assembly, missing, tabs missing, deformed or misoriented with interlock | | 100% | 3.2 | Visual/Manual |
| 4 | Slider release pin shear pin missing | | 100% | 3.2 | Gage |
| 5 | Slider assembly improperly positioned | | 100% | 3.2 | Gage |
| Major | | | | | |
| 101 | Slider assy, spring missing, binding or sticking | | 0.40% | 3.2 | Visual/Manual |
| 102 | Borerider assy, binding, sticking or missing | | 0.40% | 3.2 | Visual/Manual |
| 103 | Centrifugal lock cup missing | | 0.40% | 3.2 | Visual |
| 104 | Improper slider assembly | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:



Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.42 | Safe & Arm Assembly (Prior to Assembling Shield and Lock Plate) | | | | 9328743 |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | | | | | |
| 1 | Ball lock missing | | 100% | 3.2 | Gage |
| Major | | | | | |
| 101 | Improper flexible cable assembly | | 0.40% | 3.2 | Visual |
| 102 | Flexible cable assembly improperly installed | | 0.40% | 3.2 | Visual |
| 103 | Borerider assembly shear pin missing | | 100% | 3.2 | Visual |
| 104 | Actuator spacer missing | | 100% | 3.2 | Visual |
| 105 | Blast shield assembly missing | | 100% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.43 | Safe & Arm Assembly (Prior to Assembling Shield and Lock Plate) | | | | 9328692 |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined | | | | |
| Major | | | | | |
| 101 | Improper flexible cable assembly | | 0.40% | 3.2 | Visual |
| 102 | Flexible cable assembly improperly installed | | 0.40% | 3.2 | Visual |
| 103 | Borerider assembly shear pin missing | | 0.40% | 3.2 | Visual/Manual |
| 104 | Actuator spacer missing | | 0.40% | 3.2 | Visual |
| 105 | MDF assemblies improperly installed or missing | | 0.40% | 3.2 | Visual |
| 106 | Blast shield assembly missing | | 100% | 3.2 | Visual |
| 107 | MDF spacer missing or improperly installed | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.44 | Safe & Arm Assembly | | 9328743 |
| | | | NEXT HIGHER ASSEMBLY |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | | | | | |
| 1 | Eyelet ground open circuit, detonator or micropiston actuator not commonly shorted | (a) | 100% | 3.2 | 4.5.10 |
| 2 | Length to slider assy, max | | 100% | 3.2 | Gage/4.5.15 |
| 3 | Slider release pin and shear pin missing or improperly assembled | | 100% | 3.2 | Gage/4.5.15 |
| 4 | Borerider ball lock missing | | 100% | 3.2 | Gage/4.5.15 |
| 5 | Lock plate spacer, lock plate and adhesive disc missing or incorrect | | 100% | 3.2 | Visual |
| Major | | | | | |
| 101 | Length, max | | 0.40% | 3.2 | Gage |
| 102 | Shield above flush | | 0.40% | 3.2 | Gage |
| 103 | Shield staking missing or incorrect | | 0.40% | 3.2 | Visual |
| 104 | Outside diameter, max | | 100% | 3.2 | Gage |
| 105 | Gap between housing assembly | | 0.40% | 3.2 | Visual |
| 106 | Identification missing or incorrect | | 0.40% | 3.2 | Visual |
| 107 | Main explosive leads obstructed | | 0.40% | 3.2 | Visual |
| 108 | Electrical Continuity and Impedance Test | | | | |
| | a. M100 Detonator | | 100% | 3.2 | |
| | b. Micro Piston Actuator | | 100% | 3.2 | |
| 109 | Length to borerider | | 100% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES: (a) After installation of eyelet.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER |
|---|---|---|---|---|---|
| 4.4.2.45 | Safe & Arm Assembly | | | | 9328692 |
| | | | | | NEXT HIGHER ASSEMBLY |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | | | | | |
| 1 | Eyelet ground open circuit, detonators or micropiston actuator not commonly shorted | (a) | 100% | 3.2 | 4.5.10 |
| 2 | Length to slider assy, max | | 100% | 3.2 | Gage/4.5.15 |
| 3 | Slider release pin and shear pin missing or improperly assembled | | 100% | 3.2 | Gage/4.5.15 |
| 4 | Borerider ball lock missing | | 100% | 3.2 | Gage/4.5.15 |
| 5 | Lock plate spacer, lock plate and adhesive disc missing or incorrect | | 100% | 3.2 | Visual |
| Major | | | | | |
| 101 | Length, max | | 0.40% | 3.2 | Gage |
| 102 | Shield above flush | | 0.40% | 3.2 | Gage |
| 103 | Shield staking missing or incorrect | | 0.40% | 3.2 | Visual |
| 104 | Outside diameter, max | | 100% | 3.2 | Gage |
| 105 | Gap between housing assembly | | 0.40% | 3.2 | Visual |
| 106 | Identification missing or incorrect | | 0.40% | 3.2 | Visual |
| 107 | Main explosive leads obstructed | | 0.40% | 3.2 | Visual |
| 108 | Electrical Continuity and Impedance Test | | | | |
| | a. Parallel detonators | | 100% | 3.2 | |
| | b. Micro Piston Actuator | | 100% | 3.2 | |
| 109 | Length to borerider | | 100% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Evidence of poor workmanship | | 0.65% | 3.10 | Visual |

NOTES: (a) After installation of eyelet.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil - Downloaded: 2026Z0-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.46 | Safe & Arm Assembly | | 9328743 |
| | | | NEXT HIGHER ASSEMBLY |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| | LAT OF S&A ASSEMBLIES | * | See Below | | |
| | Transportation vibration | | - | 3.4.3 | 4.5.15.3 |
| | Safe condition examination | | - | 3.7 | 4.5.15 |
| | Continuity-resistance checks | | - | 3.8 | 4.5.10 |
| | IN-LINE FUNCTIONING | | | | |
| | Temperature conditioning | | - | 3.6 | 4.5.12 |
| | Arming | | - | 3.5 | 4.5.17 |
| | Main charge functioning | | - | 3.6 | 4.5.14 |

| INSPECTION LOT SIZE | SAMPLE SIZE | -40°-5°F | +70°+5°F | 145°+5°F | SAFE CONDITION | ACCEPT-REJECT CONTINUITY RESISTANCE | DUD OR DEFECTIVE DENT MAIN CHG |
|---|---|---|---|---|---|---|---|
| 1201-3200 | 54 | 18 | 18 | 18 | 0-1 | 0-1 | 0-1 |
| 3201-10000 | 84 | 28 | 28 | 28 | 0-1 | 0-1 | 1-2 |
| 10000-35000 | 126 | 42 | 42 | 42 | 0-1 | 1-2 | 1-2 |

NOTES: 1. Sample units shall have passed Quality Conformance Inspection 4.4.2.44.
2. Orientation of borerider not required.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

# CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63326(AR)

| PARAGRAPH | TITLE | SHEET 1 OF 1 | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.47 | Safe & Arm Assembly | | 9328692 |
| | | | NEXT HIGHER ASSEMBLY |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| | | | See | | |
| | LAT OF S&A ASSEMBLY | * | Below | | |
| | Transportation vibration | | - | 3.4.3 | 4.5.15.3 |
| | Safe condition examination | | - | 3.7 | 4.5.15 |
| | Continuity-resistance checks | | - | 3.8 | 4.5.10 |
| | IN-LINE FUNCTIONING | | | | |
| | Temperature conditioning | | - | 3.6 | 4.5.12 |
| | Arming | | - | 3.5 | 4.5.13 |
| | MDF functioning | | - | 3.5 | 4.5.14 |
| | Delay detonator, delay time | | - | 3.5 | 4.5.14 |
| | Main charge functioning | | - | 3.6 | 4.5.14 |

| | | | | | ACCEPT-REJECT | | | | |
|---|---|---|---|---|---|---|---|---|---|
| INSPECTION LOT SIZE | SAMPLE SIZE | -40°-5°F | +70°+5°F | 145°+5°F | SAFE CONDITION | CONT. RESIS | DELAY TIME | MDF | DUD OR DEF DENT MAIN CHG |
| 1201-3200 | 54 | 18 | 18 | 18 | 0-1 | 0-1 | 0-1 | 0-1 | 0-1 |
| 3201-10000 | 84 | 28 | 28 | 28 | 0-1 | 0-1 | 0-1 | 1-2 | 1-2 |
| 10000-35000 | 126 | 42 | 42 | 42 | 0-1 | 1-2 | 1-2 | 1-2 | 1-2 |

NOTES:
1. Sample units shall have passed Quality Conformance Inspection 4.4.2.45.
2. 50% of sample shall be functioned with the borerider up; and the remaining units with borerider down.



Source: https://assist.dla.mil -- Downloaded: 2020-04-20T04:20Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First Article and Quality Conformance Inspection Forms.

4.4.3.1 Check test for deterioration of detonators/explosive leads (listed below). If the total time between original acceptance of any lot and the assembly of that lot into the S&A exceeds two years, or if the detonators or explosive leads have been subjected to adverse conditions, however brief, at any time since previous tests, the detonator or explosive lead lot shall be subjected to and must satisfactorily pass the check test for deterioration specified in Military Specifications listed below immediately before they are assembled into the S&A. This test shall be performed by the contractor, on detonators or explosive leads selected by the Government inspector, at the facility assembling the detonators or explosive leads into the S&A. The test shall be conducted at Government expense without cost to the contractor who assembled the detonators/explosive leads or the contractor assembling the detonators/explosive leads into the S&A and shall not constitute a basis for rejection against either contractor except where deterioration has occurred as a direct result of carelessness in handling, storage, etc., permitted while the detonator or explosive lead lot was under the responsibility of either contractor. The Contracting Officer shall arrange to have the contractor reimbursed for the expense incurred in the performance of check tests. In the check test for deterioration of the M100 Detonator, the lead cup functioning requirement of MIL-D-48120 shall be omitted.

| | |
|---|---|
| MIL-D-48120 - | Detonator, Electric, M100, Parts For, And Loading, Assembling And Packing. |
| MIL-D-63197 - | Detonator, Delay Electric, PA506; Parts For, And Loading, Assembling And Packing. |
| MIL-L-63246 - | Lead, Explosive: PA509, PA512, PA513, PA514, PA516, PA517, PA521; parts For, And Loading, Assembling And Packing. |

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the Paragraph Reference/Inspection Method column in the forms starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.4 herein.

4.5 Test methods and procedures.

PRECAUTION - This specification covers sampling and testing of explosive materials which are potentially hazardous to personnel. Accordingly, it is emphasized that all applicable safety rules, regulations and procedures must be followed in handling and processing these materials.

4.5.1 Salt spray test. The applicable parts shall be tested in accordance with ASTM-B-117 using a 5% salt solution and with the requirements specified on the applicable drawings and. specifications. The rejection criteria shall be as specified in the applicable specifications. Assemblies subjected to this test shall not be returned to the lot.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.2 Insulation resistance test of flexible cable. Dwg. 9328714. The flexible cable shall be assembled to an approved fixture and subjected to the insulation resistance test specified on the applicable drawing. Observation shall be made for compliance with requirements of the drawing. (Non-destructive test).

4.5.3 Functioning test of maicrominiature piston actuator. Dwg. 9328715.

4.5.3.1 Resistance test. The piston actuator shall be assembled to an approved test fixture and subjected to the resistance test specified on applicable drawing. A milliohmmeter with a test current of one milliamp or less shall be used. Observation shall be made for compliance with the requirements of the drawing. (Non-destructive test).

4.5.3.2 Solderability test. This test shall be performed in accordance with Method 208 of MIL-STD-202. Observation shall be made for compliance with the requirements of the drawing. (Non-destructive test).

4.5.3.3 No fire, all fire and output tests. Immediately following the resistance test of 4.5.3.1, the selected sample of piston actuators shall be temperature conditioned, half at minus 60° - 5°F and half at 160° + 5°F for two (2) hours min. and then shall be subjected to the no fire, all fire and output test specified on applicable drawing. Observation shall be made for compliance with the requirements of the drawing. (Destructive test).

4.5.4 MDF assembly tests. Dwg. 9328750.

4.5.4.1 Output test of MDF assembly. The samples selected shall be temperature conditioned, half at minus 60° - 5°F and half at 160° + 5°F for two (2) hours min. The assembly shall be subjected to the output test as specified in 3.3 within five minutes after removal from the conditioning chamber. Observation shall be made for compliance with the requirements of 3.3.

The witness plate, of 2024-T351 aluminum alloy bar (rolled draw or cold finished) Federal Specification QQ-A-225/6 having a Brinell Hardness of 120-130, HB 10/500/30, shall be 5/8 X 1 1/4 X 1 1/4 inches or other approved size. No confinement of MDF assembly shall be used. (Destructive test).

4.5.4.2 Pull test of MDF assembly. The assembly shall be placed in an approved fixture and the pull load applied as specified on the applicable drawing. Observations shall be made for compliance with the requirements of the drawing. Assemblies subjected to this test shall not be returned to the lot. (Destructive test).

4.5.5 Separation test of slider assembly. The slider assembly shall be placed in an approved fixture and the separation load applied as specified on the applicable drawing. Observations shall be made for compliance with the requirements of the drawing. Assemblies subjected to this test shall not be returned to the lot. (Destructive test).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.6 Flexibility test of MDF, PBXN-5, lead sheathed. This test shall be performed in accordance with MIL-C-50697. Observation shall be made for compliance with the requirements of the drawing. Sample subjected to this test shall not be returned to the lot but shall be used in 4.5.8.

4.5.7 Neutron radiographic examination.

4.5.7.1 MDF, PBXN-5 lead sheathed. The MDF cord shall be subjected to neutron radiographic examination. Observation shall be made for the requirements of the drawing. (Non-destructive test).

4.5.8 Detonation velocity of MDF, PBXN-5 lead sheathed. Following examination of 4.5.7.1 the sample from 4.5.6 shall be subjected to a detonation velocity test in accordance with the procedure specified on the applicable drawing. Observation shall be made for compliance with the requirements of the drawing. (Destructive test).

4.5.9 Load test of upper housing assembly. The assembly shall be placed in an approved fixture and the static load applied as specified on the applicable drawing. Observation shall be made for compliance with the requirements of the drawing. Assemblies subjected to this test shall not be returned to the lot. (Non-destructive test).

4.5.10 Continuity resistance test of flexible cable assembly after assembly to S&A's. Following assembly to appropriate S&A and the drilling of a hole for the subsequent insertion of an eyelet, the flexible cable assembly shall be subjected to the resistance test specified on the applicable S&A drawing. Readout meter shall be a milliohmmeter or equivalent with a test current of one milliamps or less. Observation shall be made for compliance with the requirements of the applicable S&A drawing. After resistance measurements, the electro explosive device(s) shall have their input leads positively shorted. (Non-destructive test).

4.5.11 Environmental and safety tests of S&A assembly.

4.5.11.1 Jolt. After verification of the safe condition of 4.5.15, the test sample of S&A assemblies shall be assembled to fixtures and shall be tested in accordance with MIL-STD-331, Test No. 101, Procedure 11. Observation shall be made for compliance with the requirement of 3.4.1. (Destructive test).

4.5.11.2 Jumble. After verification of the safe condition of 4.5.15, the test sample of S&A assemblies shall be tested in accordance with MIL-STD-331, Test No. 102. Observation shall be made for compliance with the requirements specified in 3.4.2. (Destructive test).

4.5.11.3 Transportation vibration. After verification of the safe condition of 4.5.15, the S&A assemblies shall be assembled to fixtures and subjected to Test No. 119, Procedure 2 of MIL-STD-331. Observation shall be made for compliance with the applicable requirements specified in 3.4.3.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.12 Temperature conditioning. After verification of the safe condition of 4.5.15, the test items from 4.5.11.3 shall be subjected to continuity resistance measurement of the circuits containing detonator(s), micropiston actuator and common ground as per 4.5.10. The test items shall then be temperature conditioned at the prescribed temperature for two (2) hours min. (See 3.6).

4.5.13 Arming of S&A assemblies. The arming and functioning (see 4.5.14) of the S&A assemblies shall be performed in an remotely operated, approved fixture within two (2) minutes after removal from temperature conditioning and consist of the following:

a. Initial arming will consist of locking the interlock pin, and releasing the borerider.

b. Final arming shall consist of firing the micropiston actuator and displacing the slider release pin.

4.5.13.1 Initial arming of S&A assembly. Initial arming of the S&A test samples from 4.5.12 shall be accomplished by depressing the borerider with sufficient force to shear the borerider shear pin, and while in this position the EMP shall be functioned impacting the lock plate with sufficient force to lock the interlock pin into position. The borerider shall then be released.

4.5.13.2 Final arming of the S&A assemblies. The micropiston actuator circuit integrity of the sample S&A assemblies from 4.5.13.1 shall be verified (see 4.5.10) prior to functioning. Final arming shall be accomplished by subjecting the micropiston actuator to the energy from a 82 microfarad capacitor charged to 5.0 + 0.1 volts.

4.5.14 In-line explosive functioning. The witness plates required for this test should be installed prior to starting the arming sequence.

4.5.14.1 MDF explosive train functioning. The previously armed S&A assemblies shall have the integrity of the detonator(s) circuits verified (see 4.5.10) prior to functioning. The detonators shall then be subjected to the energy from a 82 microfarad capacitor charged to 5.0 ± 0.1 volts. Observation shall be made for compliance with the requirements of 3.6.1 and 3.6.2.

A witness plate 1 in X 1 in X 5/8 in thick minimum, as specified in 4.5.4.1 shall be used for this test.

4.5,14.2 Main charge lead explosive train functioning. The previously armed S&A assemblies shall have the integrity of the detonator(s) circuits verified (see 4.5.10) prior to functioning. The detonators shall then be subjected to the energy from a 82 microfarad capacitor charged to 5.0 ± 0.1 volts. Observation shall be made for compliance with the requirements with 3.6.2. A holding fixture or weight shall be used to contain movement of witness block during functioning. The witness ring shall be 1 3/16 in I.D. X 1 1/2 in long X 3 in O.D., cold drawn or cold rolled steel, per ASTM-A-108, C1018 or C1020, Rockwell B70-95 hardness".


Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.15 Verification of safe condition of S&A prior to shipment. The S&A's shall be 100% inspected for compliance with the requirements of 3.7 using depth and/or flush pin gages through inspection ports. Any S&A failing to conform with the applicable requirement shall be classed defective and removed from the lot. (Non-destructive test).

4.5.16 Dimensional control of cast parts. In place of the normal sampling and inspections associated with the Classification of Defects, and with the approval of the Contracting Officer, a sample of at least three (3) parts (as cast) from each cavity shall be fully inspected dimensionally to qualify a new or reworked cavity for use in production (see Note 1). Inspection for control of each cavity during production shall be performed on the above quantities from each cavity after production of 5,000 parts or at the end of each week, whichever comes first. Individual cavity identification must be provided.

If any defective parts are found during qualification of the cavity, the cavity producing the defective part(s) shall not be used in production. If any defective parts are found when inspection is performed for control of the cavity, the cavity producing the defective part(s) shall be removed from production. Further, that portion of production since the last control check shall be considered defective and shall not be used without verifying that the parts meet the drawing by inspection for compliance in accordance with the Classification of Defects.

If any defective parts are found during qualification of the tool, the tool producing the defective part(s) shall not be used in production.

If any defective parts are found when inspection is performed for control of the tool, the tool producing the defective part(s) shall be removed from production. Further, that portion of production since the last control check shall be considered defective and shall not be used without verifying that the parts meet the drawing by inspections for compliance in accordance with the Classification of Defects.

All tools removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the Contracting Officer to substantiate the request.

NOTE 1: Those features of a part which are subsequently machined or otherwise worked upon to meet its drawing requirements shall be inspected in accordance with the Classification of Defects. A list of these features shall be supplied with the first article sample.

4.5.18 Dimensional control of molded or plastic parts. In place of normal sampling and inspections associated with the Classification of Defects, and after a curing time for the parts has been approved (See Note 1) and with the approval of the Contracting Officer a sample of three (3) parts (as molded) from each cavity shall be fully inspected dimensionally to qualify a

Source: https://assist.dla.mil – Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

new or reworked cavity for use in production (See Note 2). The molded parts shall carry the individual cavity identification. As a control of each cavity during production, the above quantity of parts from each cavity shall be inspected for at least the defects listed in pertinent paragraphs of 4.4.2 after continuous production of each 5,000 parts or at the end of each week, whichever occurs first. Of the three (3) samples, one (1) sample shall be the last part produced. If any defective parts are found during qualification of the cavity, the cavity producing the defective part(s) will not be used in production. If any defective parts are found when inspection is performed for the control of the cavity, the cavity producing the defective part(s) shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for inspection for each separate type of defect according to MIL-STD-105, using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect.

All cavities removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test specified above. The contractor may request a change of inspection frequency providing he presents objective evidence to the Contracting Officer to substantiate the request. Contractor design of gages and test equipment required to perform the inspections listed herein shall be forwarded to Commander, ARRADCOM, Dover, New Jersey 07801, ATTN: DRDAR-QAT-I for approval prior to manufacture of equipment.

NOTE 1: Prior to the start of normal production, the contractor shall obtain approval from the procuring activity for the process specification of molded or plastic parts submitted with the first article in establishing a curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g. every 30, 60, etc. mins.) until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. The inspection data used in determining the curing time shall be sent to ARRADCOM, Dover, New Jersey 07801, ATTN: DRDAR-QAT-M. If there is a change in material, or in the cycle time, or if a cavity is reworked, or a new cavity is used, a new curing time shall be established and approved.

NOTE 2: Those features of a part which are subsequently machined or otherwise worked upon to meet its drawing requirements shall be inspected in accordance with the Classification of Defects. A list of these features shall be submitted with the first article sample.

## 5. PREPARATION FOR DELIVERY

5.1 Preservation, packaging and marking. packaging shall be in accordance with drawing 9329608. Extra care shall be taken in the handling and nesting of flexible cable and MDF(s) of the S&A assemblies.

5.2 Packing and marking. Packing and marking shall be in accordance with Dwg. 9329607.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

5.3 Shipping. When components from more than one lot are shipped as a carload, each lot shall be kept separate, and the division between lots clearly indicated to prevent mixing of the lots in transit.

6. NOTES

6.1 Intended use. The components covered by this specification are intended for use in Mines: Antipersonnel BLU-92/B, and Antitank BLU-91/B used in CBU-78/B and CBU-89/B Dispenser.

6.2 All requirements of this specification apply equally to S&A assemblies of Dwg. 9328692 and 9328743 except as otherwise noted.

6.3 Ordering data. See MIL-A-48078.

6.4 Submission of inspection equipment designs for approval. See MIL-A-48078. Submit equipment designs as required to Commander, ARRADCOM, ATTN: : DRDAR-QAT-I, Dover, New Jersey 07801. Request letter of submittal state contractor, contract number, specification number, item nomenclature and Classification of Defects or test paragraph.

6.5 Submission of test data. In addition to the normal distribution of records, one (1) copy of all performance data and ammunition data cards shall be forwarded to Commander, ARRADCOM, ATTN: DRDAR-QAT-M, Dover, NJ 07801.

6.6 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research and Development Command (ARRADCOM) may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities is now under the cognizance of ARRADCOM.

Custodian:
Army-AR

Preparing Activity
Army-AR

Project Number: 1345-A165

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

FOLD

DEPARTMENT OF THE ARMY

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

**BUSINESS REPLY CARD**

FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.

POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
US ARMY ARMAMENT RESEARCH & DEVELOPMENT COMMAND
ATTN: DRDAR-QAF
DOVER, NJ 07801

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

## STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.

NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-S-63326 SAFETY AND ARMING ASSEMBLIES FOR MINES: BLU-91/B and BLU-92/B

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*

TELEPHONE NO.

DATE

DD FORM 1426 1 OCT 76

EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.