MILITARY SPECIFICATION

FLAGSTAFFS AND INSIGNIA, FLAGSTAFF HEADS, GENERAL SPECIFICATION FOR

This interim amendment was issued for use by the Defense Personnel Support Center in conjunction with MIL-F-0040048B, dated 3 June 1977.

Page 3

Add "Type XII - Flagstaff Band".

Page 7

Add "B-7-26 - Flagstaff Band".

Page 8

Paragraph 3.3.2, 2nd sentence - Delete in its entirety.

Page 10

Add the following paragraph:

"3.3.12 Sterling silver.- The sterling silver shall be not less than 92.5% pure silver."

Page 11

Paragraph 3.4.2.1, line 3 - Before "chrome" insert "mirror-like polished".

Add the following paragraph in its proper sequence:

"3.4.2.1.1 Assembly.- Metal components (coupling and upper and butt ferrules) shall be assembled to the wooden sections of the staff in accordance with drawing B-7-10 and the requirements specified herein. Brass spacers shall be placed in a 1/4 inch diameter hole drilled through the tenon in the location specified on the applicable drawing. Locktite Adhesive 324 and Locktite Activator 707 or equal shall be applied to the flagstaff tenon (milled end) and the inside of the metal components respectively and the metal components mounted with the countersunk hole in the side walls in line with the brass spacer in the staff. The brass screw threads shall then be coated with a one step Locktite Adhesive or equal and tightened into the brass spacer."

Paragraph 3.4.2.2, line 2 - Before "chrome" insert "mirror-like polished".

Paragraph 3.4.3, line 3 - Delete "be chrome plated" and substitute "have a mirror-like polished chrome plated finish".

/FSC 8345/

Source: https://assist.dla.mil -- Downloaded: 20261O-21T19:05Z
Check the source to verify that this is the current version before use.

Page 12

Add the following paragraph in its proper sequence:

"3.4.4.1.2 Assembly.- Metal components (ferrule and base) shall be assembled to the wooden sections of the staff in accordance with drawing B-7-12 and the requirements specified herein. Brass spacers shall be placed in a 1/4 inch diameter hole drilled through the tenon in the location specified on the applicable drawing. Locktite Adhesive 324 and Locktite Activator 707 or equal shall be applied to the flagstaff tenon (milled end) and the inside of the metal components respectively and the metal components mounted with the countersunk holes in the side walls in line with the brass spacer in the staff. The brass screw shall then be coated with a one step Locktite Adhesive or equal and tightened into the brass spacer."

Page 13

Paragraph 3.4.5.2, 3rd sentence - Delete and substitute "When a flagstaff head is procured as a separate item, three oval Phillips head machine screws shall be furnished with the flagstaff head. The screw shall be No. 10-24 NC 2A, 1/2 inch long."

Page 15

Paragraph 3.4.8.1, line 2 - Delete "8-7-14" and substitute "B-7-14".

Add the following paragraph:

"3.4.9 Flagstaff band.- Flagstaff band shall be fabricated from sterling silver specified in 3.3.12 and shall be in accordance with drawing B-7-26. The face side of the band (surface to be engraved) shall have a mirror-like polished finish. The reverse face shall be bright. After finishing the complete band shall be coated with lacquer specified in 3.3.11. After lacquering, the face side shall be completely covered with a piece of adhesive paper or tape to protect the finish for engraving. Each band shall be furnished with two cadium plated oval head wood screws. The screws shall be 1/4 inch long and 3/32 inch in diameter."

Paragraph 3.5 - After first sentence add "All unplated metal components as well as those having a plated finish shall be mirror-like polished."

Page 20

Paragraph 4.3.1.2 - Add the following:

"Sterling silver	Material Identification	3.3.12"

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:05Z
Check the source to verify that this is the current version before use.

Paragraph 4.3.2 - Add the following:

"Finishing, lacquering, and application of adhesive paper or tape.....3.4.9
Insertion of brass spacers in tenon. .....3.4.2.1.1 and 3.4.4.1.2
Application of Locktite.....3.4.2.1.1 and 3.4.4.1.2"

Page 23

Paragraph 4.3.3, line 3 - After "one" insert "assembled".

Page 26

Under "Quality of wood", 4th and 6th defects, change classification from "Minor" to "Major".

Page 29

Under "Construction and workmanship" after last defect add "(Flagstaff loose within coupling when shaken after assembly)".

Pages 33 & 34

Paragraph 4.4.2 - Delete in its entirety.

Page 37

Add the following paragraph:

"5.1.1.7 Type XII (Flagstaff band).- Each flagstaff band together with the two mounting screws attached to the reverse face of the band by adhesive paper or tape be wrapped in three thicknesses of anti-tarnish tissue paper or placed in a fitting polyethylene bag and heat sealed. Prior to heat sealing, excess air shall be expelled. One hundred flagstaff bands shall then be packaged in a snug fitting paperboard box conforming to type IV of PPP-B-676. Closure shall be in accordance with the appendix of the box specification.

Page 39

Paragraph 6.3 - Delete second sentence in its entirety.

Page 40

Add the following paragraph:

"6.5 Flagstaff band.- The flagstaff bands covered by this specification are used as awards for company size Army units which are entitled to campaign participation credits which are not applicable to the battalion or regiments of which they are attached. The band shall be mounted on the flagstaff in accordance with AR 840-10 and AR 672-5-1."

Project No. 8345-A145

Preparing Activity:
TIOH, USA

Source: https://assist.dla.mil -- Downloaded: 202610-21T19:05Z
Check the source to verify that this is the current version before use.