MIL-F-60044A (AR)
Amendment 2
25 MAY 1979
SUPERSEDING
Amendment 1
27 Dec 1978

MILITARY SPECIFICATION

Fuze, Base Detonating, M62A2

Loading, Assembling and Packing

This amendment forms a part of Military Specification MIL-F-60044A (MU) dated 9 October 1978.

Page 1

Paragraph 2. - Specifications

Military - Add the following:

"MIL-C-45467 (AR) - Cartridge 165MM, HEP, M123A1 Loading, Assembling and Packing."

Page 3

Paragraph 3.9, Delete in its entirety and substitute:

"3.9 Static Functioning: The fuze shall function high order as evidenced by a minimum depth depression of 0.115 inches in a steel plate when tested as specified in 4.3.7."

Add the following:

"3.9.1 First Article Inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract."

Page 4

Add the following:

"4.1.2 First Article Inspection".

"4.1.2.1 Submission. The contractor shall submit a first article sample as designated by the contracting officer for evaluation in accordance with provisions of paragraphs 4.2 and 4.3".

FSC: 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:06Z
Check the source to verify that this is the current version before use.

"4.1.2.2 The First Article sample shall consist of twenty-five (25) each of all partial assemblies and twenty-five (25) assembled fuzes which shall be inspected in accordance with the applicable provision as specified in 4.2.2."

"4.1.2.3 The First Article sample shall consist of one hundred ninety-five (195) assembled fuzes for use in performing the following tests.

a. Twenty-five fuzes shall be tested ballistically against armor plate as specified in MIL-C-45467.

b. Twelve (12) fuzes shall be subjected to the jolt and jumble test specified in 4.3.3.

c. Eight (8) fuzes shall be subjected to the transportation vibration test as specified in 4.3.4.

d. One hundred twenty-five (125) fuzes shall be tested for functioning in accordance with 4.3.5.

e. Twenty-five (25) fuzes shall be tested for static functioning as specified in 4.3.7."

Page 6

Paragraph 4.2.2.4

"Major:

101. Delete the word "Concentricity" and substitute the words "True Position".

Page 7

Paragraph 4.2.2.5, Delete all Majors in their entirety and substitute:

"Major

101	Fuze not packed with Booster down	Visual	05009
102	Sealing Strip incomplete or badly wrinkled	Visual	05010
103	Bag torn or damaged	Visual	05011
104	Failure of Heat Seal Test	Manual/ Visual	05012"

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:06Z
Check the source to verify that this is the current version before use.

Page 8

Paragraph 4.2.3.4.1 - Delete in its entirety.

Paragraph 4.2.3.4.2 - Delete in its entirety and substitute:

"A sample of 50 fuze assemblies shall be selected from each production lot for this test in accordance with paragraph 4.3.5. If there are any premature bursts or if 3 or more assemblies fail to function high order the lot shall be rejected."

Page 9

Paragraph 4.2.3.7, Delete the first sentence and substitute the following:

"A sample of fifteen (15) fuzes shall be randomly selected from each lot for this test subsequent to completion of the slider non-arming test. The test shall be performed as specified in 4.3.7, using test equipment specified in 4.2.4."

Page 11

Paragraph 4.3.7, Delete in its entirety and substitute the following:

"4.3.7 Static functioning - The slider shall be armed by inserting a plug into the slider cavity in the fuze body and reassembling the slider, slider spring and retaining screw. The firing pin assembly shall be removed and replaced by a firing pin guide plug. A hole shall be drilled through the fuze head in line with the hole in the firing pin guide plug and detonator holder to receive the firing pin. The modified fuze assembly shall be mounted in a suitable fixture with the booster end down. The firing pin, which has been equipped with a rubber o-ring to prevent inserting it too far into the head assembly shall be placed booster end down upon a steel plate (approximately 14" x 18" x 2" in accordance with ASTM 836, Rockwell B60-80. The operator then returns to the test building and removes safety pin from the test arm, pulls the cord connecting the test arm which then falls and depresses the firing pin into the detonator. If the fuze fails to function all personnel will wait behind the barricade for a period of 30 minutes minimum prior to returning to the test sample. The fuze shall then be destroyed in place (in accordance with local safety regulations) by means of a demolition charge, taking extreme care when placing the charge, not to disturb the fuze in any way. Any fuze which fails to function high order shall be cause for rejection.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project Number: 1390-A228

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:06Z
Check the source to verify that this is the current version before use.