MILITARY SPECIFICATION

FUZE, ROCKET, PIBD, M438 SUB-ASSEMBLY WITH DETONATER

This Amendment forms a part of Military Specification MIL-F-48057B, dated 17 February 1981, and is approved for use by the US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 8

4.3.1: Delete "11706267" and substitute "8883713" in two places.
Delete "11008392" and substitute "8883718" in two places.
Delete "11001692" and substitute "8883710" in two places.
Delete "11008394" and substitute "9260774 .
Delete "11830063" and substitute "9260774 .
Delete "11001687" and substitute "8883703" in two places.
Delete "11008395" and substitute "9260804" in two places.
Delete "11001689" and substitute "8883700" in two places.
Delete item Outer Plate Assembly in its entirety.
Delete "11706262" and substitute "9260776" in two places.

PAGE 14

TABLE 1: Delete "Dwg. 11001692" and substitute "Dwg. 8883710".
Delete "Dwg. 11001687" and substitute "Dwg. 8883703".
Delete "Dwg. 11001689" and substitute "Dwg. 8883700".
Delete "Dwg. 11008394" or 11830063" and substitute "Dwg. 9260774".

PAGE 15

TABLE 1: Delete "Dwg. 11008395" and substitute "Dwg. 9260804".

PAGE 16

TABLE 1: Delete examination and test for Outer Plate Assembly (Dwg. 11008400) in its entirety.

Delete "Dwg. 11706262" and substitute "Dwg. 9260776".

FSC 1340

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

In No. of Sample Units, delete "80: and substitute "120" in five places; delete "40" and substitute "60(a)" in two places.

In Arm Time (27 g's) Test, delete "4.5.11.3" and substitute "4.5.11.4".

In Arm Time (40 g's) Test, delete "4.5.11.4" and substitute "4.5.11.5".

Add Note: "a: 20 at 70°F ± 5°F; 20 at -40°F ± 5°F; 20 at 160°F ± 5°F."

PAGE 18

TABLE 1: Delete "Dwg. 11706267" and substitute "Dwg. 8883713".
Delete "Dwg. 11008392" and substitute "Dwg. 8883718".

PAGE 27

4.4.2.8: Delete "11706267" and substitute "8883713" in two places.
Delete "11008394" and substitute "9260774".
Delete "11830063" and substitute "9260774".

PAGE 36

4.4.2.17 Delete "11001692" and substitute "8883710" in two places.
Delete "11008394" and substitute "9260774".
Delete "11830063" and substitute "9260774".

PAGE 37

4.4.2.18 Delete "11001687" and substitute "8883703: in two places.
Delete "11008394" and substitute "9260774".
Delete "11830063" and substitute "9260774".

PAGE 38

4.4.2.19 Delete "11001689" and substitute "8883700" in two places.
Delete "11008394" and substitute "9260774".
Delete "11830063" and substitute "9260774".

PAGE 39

4.4.2.20 Delete "11706262" and substitute "9260776" in two places.
Delete "11008394" and substitute "9260774".
Delete "11830063" and substitute "9260774".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

PAGE 41

4.4.2.22 Delete "11008394" and substitute "9260774".
Delete "11830063" and substitute "9260774".

PAGE 42

4.4.2.23 Delete "11008395" and substitute "9260804" in two places.
Delete "11008394" and substitute "9260774".
Delete "11830063" and substitute "9260774".

PAGE 43

4.4.2.24 Delete in its entirety.

PAGE 44

4.4.2.25: In Major 110, add "(a,b)" next to "Arm Time Test"; delete "4.5.11.4" and substitute "4.5.11.5"

In Major 111, delete "4.5.11.3" and substitute "4.5.11.4".

Add Notes: "a: In addition to testing at ambient, a sample of 100 S&A's shall be tested at -40°F and another sample of 100 S&A's shall be tested at +160°F." and "b: Temperature conditioning shall be 4 hours minimum, and each S&A shall be tested within 3 minutes of removal from extreme temperatures. Be advised that removing the S&A from the cold temperature environment prior to performing the centrifigue test may cause frost to form on the metal parts. This may have an effect on the test results due to attenuation of the acoustic signal of the arming mechanism, thus making it difficult to distinguish the arm signal from background noise. The contractor shall take appropriate action to allevaiate this potential problem. One effective method has been to seal each S&A in a plastic bag prior to temperature conditioning. Bagged S&A's are then subjected to the centrifuge test. Another method has been to house the centrifuge inside the temperature conditioning chamber. S&A's are then tested inside the temperature conditioning chamber".

PAGE 50

4.4.2.31 Delete "11008392" and substitute "8883718" in two places.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

PAGE 56

4.5.11.1 Delete last two sentences and substitute: "This test equipment, if housed within a temperature conditioning chamber, shall be capable of operation between -40°F and +160°F with a tolerance of ±5°F. The acceleration tolerance shall be ±.10g. Time measuring equipment shall be accurate within ±0.01 second.".

PAGE 57

4.5.11.5 Delete last sentence and substitute: "Any S&A that fails to meet the requirement when tested at ambient temperature shall be classed defective and isolated to preclude its inclusion with acceptable material. Each lot of S&A's shall be rejected if one or more S&A's fail to meet the requirement when tested at -40°F and +160°F.".

Custodian:
Army-AR

Preparing activity:
Army AR

Project No. 1340-A622

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.