MIL-P-48043A (AR)
AMENDMENT 2
5 March 1986
SUPERSEDING
AMENDMENT 1
7 January 1985

MILITARY SPECIFICATION

PROJECTILE, 155MM, ILLUMINATING
M485A2, METAL PARTS ASSEMBLY

This Amendment forms a part of Military Specification MIL-P-48043A (AR), dated 26 October 1983, and is approved for use within the U.S. Army Armament Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

3.2 At the end of second sentence add the following: "unless followed by a stress relief".

PAGE 7

4.3.1 Last paragraph: In the third sentence delete "or extrude" and add "or centrifugally cast".

PAGE 8

TABLE I, Base Plug: Add as follows:

"Macro Etch	2	3.1	4.5.1.3"

TABLE I, Body Assembly: Add as follows:

"Rotating Band bandseat clearance	2	3.5.4	4.5.2
Sidewall contact	2	3.5.3	4.5.2.3
Mechanical properties of rotating band	2	3.5.5	4.5.2.4"

PAGE 11

4.4.2.1, Major: Delete 102 in its entirety.

AMSC N/A
FSC 1320
DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

PAGE 12

4.4.2.2 Major, 105: Under column "Examination" delete and replace with "Runout of underside of flange with press fit diameter".

4.4.2.2 Major: Add 108 as follows:

"108 Macro Etch * 3.1 4.4.3.1.3/4.5.1.3".

PAGE 14

4.4.2.3, Major: Add 125 as follows:

"125 Runout of rear face with bourrelet diameter 0.40% 3.1 Gage".

Also in Category column, below "125" add "126".

PAGE 15

4.4.2.3, Minor, 208: Delete "Gage" and substitute "Visual".

PAGE 17

4.4.2.5 Delete "4.4.2.5" in its entirety, and substitute new para "4.4.2.5" included.

Para 4.4.2.5 Minor Category:

* Minor 203: Delete the word "rar" and replace with the word "rear"

PAGE 19

4.4.2.7, After "Critical" add the following:

"Special, a. - Cover support missing (8 places).... 100% ... 3.1 ... Visual".

Change Dwg "7549275" to Dwg "8837839"

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

PAGE 19

4.4.2.8 Add new CD "4.4.2.8", (see page 5.) (included)

* Para 4.4.2.8 Minor Category: Add the following inspections:

"Minor 205 paint overspray on rotating band exceeding allowable limit 0.65% 3.1 Gage. Minor 206 paint overspray on Press fit diameter exceeding allowable limit 0.65% 3.1 gage".

4.4.3.1.3 Add new paragraph as follows:

"4.4.3.1.3 Macro Etch (base plug). Sample test quantities of base plugs shall be subject to a Macro Etch Test to comply with the cross forging requirement in accordance with 4.5.1.3."

PAGE 23

4.5.1.3 Add new paragraph as follows:

"4.5.1.3 Macro Etch (base plug). One base plug from each standard heat treatment lot and one from each miscellaneous heat treatment lot shall be subjected to a Macro Etch Test (chemical analysis). The base plug shall be sectional through its diameter and one of the sectioned surfaces prepared by grinding the surface to a flat. This part shall then be immersed in a macro etch solution of 50 percent hydrochloric acid and 50 percent water and heated to a temperature of 180°F, minimum. The base part shall remain in the macro etch solution until flow lines become clearly visible. The part shall then be rinsed with water, dried and visually examined for compliance with dwg 9214146.

PAGE 27

5.2.1.1 Delete Dwg "7549275" to "8837839".

PAGE 28

5.3 Delete Dwg "7549275" to "8837839".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9362659
4.4.2.5	Body Assembly (after banding)				NEXT HIGHER ASSEMBLY 9214142
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Magnetic particle stamp missing (indicating failure to pass test)		100%	3.1	Visual
Major					
101	Runout of rotating band with bourrelet and internal base diameter		0.40%	3.1	Gage
102	Diameter of rotating band		0.40%	3.1	Gage
103	Diameter between rotating bands		0.40%	3.1	Gage
104	Length from rear face to rear shoulder of rotating band		0.40%	3.1	Gage
105	Rotating band bandseat clearance		*	3.5.4	4.4.3.2/4.5.2
106	Sidewall contact		*	3.5.3	4.4.3.2.3/4.5.2.3
107	Mechanical properties of rotating band		*	3.5.5	4.4.3.2.4/4.5.2.4
Minor					
201	Width of rotating band		0.65%	3.1	Gage
202	Depth of undercut front and rear of rotating band (if applicable)		0.65%	3.1	Gage
203	Width of undercut front and rear of rotating band (if applicable)		0.65%	3.1	Gage
204	Radii or chamfer missing or incorrect		0.65%	3.1	Visual
205	Width of groove in rotating band		0.65%	3.1	Visual
206	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: *Sampling size as specified in applicable test method paragraph.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-48043A (AR)
AMENDMENT 2

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.8	Body Assembly (after painting)		1 1		9362659
					NEXT HIGHER ASSEMBLY
					9214142
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of bourrelet, max.		100%	3.1	Gage
102	Salt spray		*	3.1	4.5.3
Minor					
201	Protective coating inadequate or damaged		0.65%	3.1	Visual
202	Paint on threads		0.65%	3.11	Visual
203	Paint on base fit area		0.65%	3.11	Visual
204	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:
*Sampling size as specified in applicable test method paragraph.

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this documents based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1320-A874)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.