MILITARY SPECIFICATION

CANISTER SMOKE, ASSEMBLY
PARTS FOR ASSEMBLING AND PACKING

This specification is approved for use by US Army Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This military specification covers parts for assembling and packing of Canister Smoke, Assembly.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078	-Ammunition, Standard Quality Assurance Provisions, General Specification for
MIL-I-45607	-Inspection Equipment, Supply and Maintenance of

STANDARDS

MILITARY

MIL-STD-414	-Sampling Procedures and Tables for Inspection by Variables for Percent Defective
MIL-STD-1218	-ACS Chemicals

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

FSC: 1320

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

DRAWINGS (see 6.7)

US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND (ARRADCOM)

9333792	-Canister Smoke, Assembly
9344016	-Packaging and Shipping for Canister Smoke, Assembly

(Copies of specifications, standards, drawings and publications, required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer).

2.2 Publications. The following document forms a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on date of invitation for bids or request for proposal shall apply.

AMERICAN SOCIETY FOR TESTING AND MATERIALS PUBLICATION

ASTM Designation E300	-Recommended Practice for Sampling Industrial Chemicals
ASTM Designation D2905	-Statement on Number of Specimens Required to Determine the Average Quality of a Textile

(Application for copies of ASTM Standards should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103).

(Technical society and technical association specifications and standards are generally available for reference from libraries. They are also distributed among technical groups and using Federal agencies).

3. REQUIREMENTS

3.1 Material. Materials, parts and assemblies shall comply with the requirements specified on the applicable drawings and specifications.

3.2 Canister Smoke, Assembly. The assembly and components shall comply with all requirements specified on Drawing (Dwg.) 9333792 and with all requirements specified in applicable specifications.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

3.3 First Article Inspection. This specification contains technical provisions for first article inspection. Requirements for submission of first article samples by the contractor shall be as specified in the contract.

3.4 Workmanship. All parts shall be fabricated and finished in a thorough, workmanlike manner. They shall be clean and free of burrs, sharp edges, unblended radii, cracks, surface defects, chips, dirt, grease, dust and other foreign matter. The cleaning method used shall not be injurious to any part nor shall the parts be contaminated by the cleaning agent. The finished mix shall be uniform and free from lumps or the tendency to form lumps.

3.5 Moisture content. The moisture content of the smoke mix, in the sealed container, shall be 0.2% maximum.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection
b. Quality Conformance Inspection

4.3 First article inspection.

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawing	Quantity
Canister Smoke, Assembly	9333792	20
Cup, Closing	9341640	5
Body	8838201	5

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:27Z
Check the source to verify that this is the current version before use.

Part Description	Drawing	Quantity
Disc, Closing	8838202	5
Pad	9342877	5

All assemblies and components shall have been manufactured using the same production processes, procedures and equipment which will be used in fulfilling the contract. All parts and materials, including packaging and packing, shall be obtained from the same source of supply as will be used in regular production. Prior to submission, the contractor shall inspect the sample to the degree necessary to assure that it conforms to the requirements of the contract and submit a record of this inspection with the sample including statements of findings for materials, processes and tests. A sample containing known defects will not be submitted unless specifically authorized, by the Contracting Officer. A first article sample, or portion thereof, as directed by the Contracting Officer, shall also be submitted whenever there is a lapse in production for a period in excess of 90 days or whenever a change occurs in manufacturing process, material used, drawing or specification such as to significantly affect product uniformity as determined by the Government.

4.3.2 Inspections to be performed. The First Article parts submitted in accordance with paragraph 4.3.1 will be subjected by the Government to any or all the requirements of the applicable drawings and specifications and to the inspections of Table I. All inspections listed in Table I shall be classified Major unless otherwise specified in referenced paragraphs and specifications.

4.3.2.1 Smoke mix. Five (5) of the assemblies shall be opened and the mix in each tested for composition and moisture content.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63418 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
	Canister Smoke, Assembly and Components				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Canister Smoke, Assembly (Dwg. 9333792) Examination for Defects	20		3.2	4.4.2
	Components Examination for Defects	5		3.2	4.4.2

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test tables, sampling plans for Major and Minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63418 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	Disc, Closing				8838202
					NEXT HIGHER ASSEMBLY 9333792
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None Defined.				
MAJOR					
101	Thickness		0.40%	3.2	Gage
MINOR					
201	Diameter		0.65%	3.2	Gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63418 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.2	Pad		9342877
			NEXT HIGHER ASSEMBLY 9333792

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None Defined.				
MAJOR	None Defined.				
MINOR					
201	Diameter		0.65%	3.2	Gage
202	Thickness		0.65%	3.2	Gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63418 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.3	Cup, Closing		9341640
			NEXT HIGHER ASSEMBLY 9333792

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None Defined.				
MAJOR					
101	Inside diameter, max.		0.40%	3.2	Gage
MINOR					
201	Thickness through sidewall, min.		0.65%	3.2	Gage
202	Thickness through base, min.		0.65%	3.2	Gage
203	Height, min.		0.65%	3.2	Gage
204	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63418 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.4	Body		8838201
			NEXT HIGHER ASSEMBLY 9333792

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None Defined.				
MAJOR					
101	Thickness through base, min.		0.40%	3.2	Gage
102	Inside diameter, max.		0.40%	3.2	Gage
103	Outside diameter, min.		0.40%	3.2	Gage
104	Depth, min.		0.40%	3.2	Gage
MINOR					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63418 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	Canister Smoke, Assembly		9333792
			NEXT HIGHER ASSEMBLY 9331795

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None Defined.				
MAJOR					
101	Mix composition incorrect		4.4.3.1	3.2	4.5.1
102	Moisture content over max.		4.4.3.2	3.5	4.5.2
103	Container height at crimp		0.40%	3.2	Gage
104	Any component missing or incorrectly assembled		0.40%	3.2	Visual
105	Weight of change in body		0.40%	3.2	Balance
MINOR					
201	Evidence of excessive adhesive		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.4	Visual
203	Marking missing, misleading or unidentifiable		0.65%	3.2	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63418 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.6	Packing		9344016
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None Defined.				
MAJOR	None Defined.				
MINOR					
201	Any spacer missing, prior to sealing box		0.65%	3.2	Visual
202	Incorrect number of units in box, prior to sealing		0.65%	3.2	Visual
203	Box improperly sealed		0.65%	3.2	Visual
204	Box improperly marked		0.65%	3.2	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

4.4.3 Testing.

PRECAUTION WARNING

This specification covers sampling and testing of toxic or hazardous materials. Accordingly, it is emphasized that all applicable safety rules, regulations and procedures must be followed in handling and processing these materials.

4.4.3.1 Composition.

4.4.3.1.1 Batch inspection. Each batch (see 6.8) of smoke mix shall be inspected for composition, if process inspection is not opted. Acceptance for this test shall be in accordance with MIL-STD-414, Table B-3, Inspection Level I, AQL 1.0%, with the inspection lot equal to each batch of mix. Lot size shall be the number of containers, ± 10%, to be filled from the batch. The samples shall be drawn from filled bodies. Total percent defective shall be calculated for each constituent. If any of the constituents fail to meet the acceptability criterion, the batch shall be rejected.

4.4.3.1.2 Process inspection.

4.4.3.1.2.1 Process qualification. The initial batches (see 6.8) of smoke mix from each blender to be used in production shall be tested for composition. Acceptance for this test shall be in accordance with MIL-STD-414, Table B-3, Inspection Level I, AQL 1.0%, with the inspection lot equal to each batch of mix. Lot size shall be the number of containers, ± 10%, to be filled from the batch. The samples shall be drawn from filled bodies. Total percent defective shall be calculated for each constituent. If any of the constituents fail to meet the acceptability criterion, the batch shall be rejected. The process shall be considered qualified when five consecutive batches have been accepted from each blender to be used in production.

4.4.3.1.2.2 Process control. At the option of the contractor, process control may be substituted for batch inspection after qualification per 4.4.3.1.2.1. Process control shall be as follows:

a. During process qualification, record the blender speed and blending time for each batch.

b. Prepare control limits for blending speed and time based on recorded data from the five (5) qualifying batches (see 6.10).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

c. Weigh and check weigh each constituent.

d. Control blending speed and time within the established limits.

If blending speed or time is outside the control limits, sample inspection for composition of that batch shall be conducted per 4.4.3.1.1. If blending speed or time must be adjusted to fall outside the control limits, re-qualification shall be conducted per 4.4.3.1.2.1. Re-qualification shall also be required, if in the opinion of the Government, maintenance or repair to the blender or dispensing mechanism effects process control parameters.

4.4.3.1.2.3 Verification. When process control is in effect, a verification inspection shall be conducted on one batch from each seven (7) batches from each blender. Sample batch inspection shall be per 4.4.3.1.1. If a sample batch is rejected, re-qualification of the process per 4.4.3.1.2.1 shall be required before process control is resumed.

4.4.3.2 Moisture content. Each shift's production shall be tested for moisture content. Acceptance for this test shall be in accordance with MIL-STD-414, Table B-3, Inspection Level I, AQL 1.0%, with the inspection lot equal to each shift's loading. Lot size shall be the number of containers, ± 10%, to be filled and sealed during one production shift. The samples shall be drawn from filled containers prior to sealing. If percent defective calculated fails to meet the acceptability criterion, the shift's production shall be rejected.

4.4.4 Inspection equipment. Commercially available inspection equipment should be used in the performance of all tests specified in 4.4. The contractor shall have the required equipment available, follow proper calibration methods and perform the testing in accordance with accepted operating procedures. Government approval of all inspection equipment is required prior to its use for acceptable purposes. See Section 6 of MIL-A-48078 and paragraph 6.3 herein.

4.5 Test methods and procedures (see 6.9). The following tests shall be performed using prescribed analytical procedures for replicate determinations given in standard analytical text books. ASTM Method D2905 may also be used to determine the number of replicates required. Unless otherwise specified herein, all chemicals and reagents used in test methods shall be ACS grade in accordance with MIL-STD-1218 or reagent grade.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

4.5.1 Composition.

4.5.1.1 Potassium nitrate. Into a tared 150 millilitre (ml) beaker accurately weigh to the nearest 0.0001 gram (g) approximately 3g of smoke composition. Add 40 ml of distilled water and continuously swirl the contents of the beaker for 5 minutes. Allow the solid material to settle to the bottom of the beaker. Fit a Fisher Filtrator or equal with a clean glass medium porosity filtering crucible and a 250 ml beaker to receive the filtrate. Adjust the filtrator vacuum so the filtrate does not splash out of the receiver flask and decant the supernatant liquid from the 150 ml beaker through the crucible and into the 250 ml receiver beaker. Wash the solid to the bottom of the flask with a stream of distilled water (10 ml or less) and again swirl the contents of the 150 ml beaker for two minutes. Allow the residue to settle to the bottom of the beaker and decant the liquid through the filtering crucible into the 250 ml beaker. Wash the residue using this procedure two more times, transferring the solid residue to the filtering crucible on the final wash (quantitative transfer not necessary). Rinse the crucible and crucible holder with a small amount of distilled water catching the rinse water in the 250 ml beaker. Transfer the filtrate and washings to a 100 ml volumetric flask, dilute to the mark with distilled water and mix thoroughly. Fill a 1.0 centimeter (cm) path length silica spectra photometric cell with the solution from the volumetric flask and fill the matching cell with distilled water. Using the distilled water as the blank, measure the absorbance of the solution at 301 nanometer (nm) using a Beckman Model DU Spectrophotometer or equal.

Prepare standards for the potassium nitrate determination as follows: Weigh the approximate amounts given in Table 1, to the nearest 0.0001g in a clear, dry, tared 150 ml beaker.

TABLE 1

Potassium Nitrate Standardization Solutions

Standard No.	Potassium Nitrate, g	Potassium perchlorate, g
1	0.570 - 0.585	0.600
2	0.600	0.600
3	0.615 - 0.630	0.600

Add 40 ml of distilled water to each standard and follow the same procedure given for the analysis of the sample.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

Calculate the percent potassium nitrate using the following equations:

Standardization Values:

$$b = \frac{(\Sigma A)(\Sigma c^2) - (\Sigma Ac)(\Sigma c)}{N(\Sigma c^2) - (\Sigma c)^2}$$

and

$$m = \frac{(\Sigma A - Nb)}{(\Sigma c)}$$

where A = Absorbance of the standard solutions.
b = The A intercept.
c = The concentration of potassium nitrate in g/100 ml.
m = The slope of the absorbance vs. concentration data.
and N = The number of standard samples tested.

Percent Potassium Nitrate:

$$\text{Potassium nitrate, \%} = \frac{100\left(\frac{A-b}{m}\right)}{W - WM}$$

where A = The absorbance obtained for the sample.
b & m = The values obtained from the standardization calculation above.
W = The sample weight in g.
and M = The percent moisture obtained in 4.5.2 expressed as a decimal.

4.5.1.2 Determination of potassium perchlorate. Into a tared 30 ml medium porosity glass filtering crucible weigh to the nearest 0.0001g an approximately 1.3g sample of smoke compositon. Pl~ce a clean, dry glass stirring rod in the crucible and weigh the crucible, sample and stirring rod to the nearest 0.0001g. Place the crucible and contents in a crucible holder attached to a suction flask and add a 15 ml portion of distilled water. Allow the water to remain in contact with the sample for 5 minutes, stirring immediately after the water addition, after 2-3 minutes and just prior to turning on the vacuum to draw the water through the crucible. Use the glass stirring rod for the stirring operations, being careful to avoid

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

grinding the metal particles against the sides or bottom of the crucible. Repeat the extraction procedure four more times with 15 ml portions of distilled water allowing the water to remain in contact with the sample for three minutes in each case. Stir the mixture immediately after water addition, after 1.5 minutes and prior to applying vacuum. Rinse the crucible side and contents with a stream of distilled water and aspirate. Wash the contents of the crucible with about 5 ml of 95% ethanal and aspirate. Wash the crucible contents with about 5 ml of ether and aspirate until the ether odor is no longer noticeable. Dry the crucible stirring rod, and contents, for a half hour at 100 degrees Celcius (^{o}C) $\pm$ 2°C. Coal in a desiccator and weigh to the nearest 0.0001g. Reserve the crucible stirring rod and residue for the determination of zinc and aluminum. Calculate the percent potassium perchlorate as follows:

$$\% \text{ Potassium Perchlorate} = \frac{(A - B)\ 100}{W - WM} - C$$

where

A = The weight of the sample, crucible and glass rod prior to water extraction in g.

B = The weight of the residue, crucible and glass rod after water extraction in g.

W = The weight of the sample in g.

M = The percent moisture as determined in 4.5.2 expressed as a decimal.

C = The percent potassium nitrate as determined in 4.4.1.1.

4.5.1.3 Determination of zinc and aluminum. Place the crucible containing the zinc and aluminum residue reserved from the potassium perchlorate determination in a crucible holder attached to a suction flask. Add 20 ml of 5% nitric acid (5 ml concentrated nitric acid added to 95 ml distilled water), which has been cooled to 2°C +1°C, to the crucible and stir. Allow the acid to remain in contact with the residue for five minutes, stirring after 2-3 minutes. Apply vacuum to remove the acid from the crucible. Add a second 20 ml portion of cold (2°C + 1°C) 5% nitric acid and repeat the extraction procedure. Perform four additional extractions using room temperature 10% nitric acid (10ml nitric acid and 90 ml distilled water) stirring and aspirating each in the same

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

manner as was done with the 5% nitric acid extractions. Wash the residue with several small portions of distilled water to remove any excess acid and aspirate. Discard the acid washings from the suction flask. Replace the crucible in the suction flask and wash the residue with 5 ml of 95% ethanol and aspirate. Wash the residue with 5 ml of ether and aspirate until the odor of ether is no longer noticeable. Dry the crucible contents and stirring rod in an oven at 100°C ± 2°C for a half hour, cool in a deseccator and weigh to the nearest 0.0001g.

Calculate the percent zinc and aluminum as follows:

$$\% \text{ zinc} = \frac{100\ (B - D)}{W - WM}$$

and

$$\% \text{ aluminum} = \frac{100\ (D - E)}{W - WM}$$

where

B = The weight of the residue, crucible and glass rod after water extraction in g (see 4.5.1.2).

D = The weight of the crucible residue and glss rod after the nitric acid extraction in g.

W = The weight of the sample in g.

M = The percent moisture as determined in 4.5.2.

E = The tare weight of the crucible plus the stirring rod in g.

4.5.2 Moisture content. Transfer an accurately weighed portion of approximately 5g of the sample to a tared weighing bottle. Dry the bottle and contents at 100°C + 5°C for 2 hours minimum, cool in a desiccator and weigh. Calculate the loss in weight as percent moisture.

5. PREPARATION FOR DELIVERY

5.1 Packing. Canisters shall be packed in accordance with Dwg. 9344016.

5.2 Marking. Marking shsall be in accordance with Dwg. 9333792.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

6. NOTES

6.1 Intended use. The smoke canister covered by this specification is intended for use in spotting of artillery practice projectiles.

6.2 Ordering data. See MIL-A-48078.

6.3 Submission of inspection procedures and/or equipment designs for approval - See MIL-A-48078. Submit equipment designs as required to: Commander, ARRADCOM, ATTN: DRDAR-QAR-I, Dover, New Jersey 07801.

6.4 Inspection lot size. It is noted that the size of inspection lots of components, assemblies or items of delivery may differ from the actual quantities contractually scheduled for delivery. However, in order to facilitate scheduling of tests or deliveries, inspection lots of items of delivery may be equivalent to such contract quantities provided all of the lot formation criteria and sampling provisions of this specification are maintained.

6.5 Visual examination qualification. When compliance with the acceptable requirement is in doubt as a result of visual examination, the characteristics may be measured or gaged to determine acceptability.

6.6 Submission of ammunition data cards. In addition to the normal distribution of records for items procured by the Department of the Army, two copies of all ammunition data cards shall be forwarded to: Commander, ARRADCOM, ATTN: DRDAR-QAR-Q and DRDAR-LCU-CP, Dover, New Jersey 07801.

6.7 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research and Development Command (ARRADCOM) may also include drawings prepared by and identified as Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal, or Picatinny Arsenal drawings. Technical data originally prepared by these activities is now under the cognizance of ARRADCOM.

6.8 Batch. A batch is defined as a quantity of ingredients blended in a single container at one time.

6.9 Equivalent test methods. Prior approval of the Contracting Officer is required for use of equivalent test methods. A description of the proposed method should be submitted through the Contracting Officer to: Commander, ARRADCOM, ATTN: DRDAR-QAR-Q, Dover, New Jersey 07801.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

This description should include, but not be limited to the procedures used, the accuracy and precision of the method, test data to demonstrate the accuracy and precision and drawings of any special equipment required.

6.10 Computing process control limits. The control limits shall be: $\bar{X} \pm 1.342\,\sigma$.

where: $\bar{X}$ = average blending time or speed for 5 consecutive acceptable batches.

σ = standard deviation of 5 times or speeds calculated as: $\sigma = \sqrt{\frac{\sum X^2 - (\sum X)^2}{5}}$

with X being the individual batch blending time or speed.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No.: 1320-A564

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.

NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-C-63418 Canister Smoke, Assembly Parts For Assembling & Packing

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*

TELEPHONE NO.

DATE

DD FORM 1 OCT 76 1426

EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.