INCH-POUND

MIL-H-64033A(AR)
22 May 1989
SUPERSEDING
MIL-H-64033 (AR)
20 October 1986

MILITARY SPECIFICATION

HOUSING, MOLDED, FOR ANTI-PERSONNEL MINE M131 SYSTEM

This specification is approved for use within the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification contains requirements not normally covered by drawings and provides quality assurance provisions for the fabrication of parts, assemblies and packing of the metal and plastic parts for the antipersonnel mine for the M131 System.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications, standards and handbooks. The following specifications standards and handbooks form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents are those listed in the issue of the Department of Defense Index of Specifications and Standards (DoDISS) and supplement thereto, cited in the solicitation.

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, U.S. Army Armament, Munitions and Chemical Command, Attn AMSMC-QA, Picatinny Arsenal, New Jersey 07806-5000 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSMC N/A FSC 1345

DISTRIBUTION STATEMENT D. Distribution authorized to the Department of Defense and DoD Contractors only. This Technical Data Package contains sensitive technology on a new weapons system. This determination was made on 10 July 1987. Other requests for this document will be referred to: Commander, ARDEC, AITN: SMACAR-FSM, Picatinny Arsenal, NJ 07806-5000.
DESTRUCTION NOTICE. For classified documents, follow the procedures in DoD 5200.22-M, Industrial Security Manual, Section II-19 or DoD 5200.1-R, Information Security Program Regulation, Chapter IX. For unclassified, limited documents, destroy by any method that will prevent disclosure of contents or reconstruction of the document.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

SPECIFICATIONS

MILITARY

MIL-I-23053 - Insulation Sleeving, Heat Shrinkable.
MIL-S-45743 - Soldering, Manual Type. High Reliability, Electrical and Electronic For.
MIL-A-48078 - Ammunition Standard Quality Assurance. Provisions, General Specification For.
MIL-P-50884 - Printed Wiring, Flexible General Specification For.

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.

(Unless otherwise indicated, copies of federal and military specifications, standards, and handbooks are available from the Naval Publications and Forms Center, (ATTN: NPODS), 5801 Tabor Avenue, Philadelphia, PA 19120-5099.)

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this document to the extent specified herein. Unless otherwise specified, the issues are those cited in the solicitation.

DRAWINGS

US ARMY ARMAMENT RESEARCH DEVELOPMENT AND ENGINEERING CENTER (ARDEC)

PRODUCT AND PACKAGING DRAWINGS

9337402 - Clip, Sensor Locating.
9337403 - Wiring, Printed, Flexible.
9337404 - Bracket, Sensor.
9337405 - Manifold.
9337407 - Plug, Manifold.
9337417 - Manifold Assembly.
9337418 - Preform and Sensors Assembly.
9337419 - Housing, Molded.

(Copies of specifications, standards, handbooks, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer).

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

2.2 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein (except for associated detail specifications, specification sheets or MS standards), the text of this specification shall take precedence. Nothing in this specification, however, shall supersede applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 Materials. Materials and parts shall be in accordance with applicable drawings and specifications.

3.2 Parts. The parts shall comply with all requirements specified on applicable drawings, associated drawings, and with all requirements specified in applicable specifications and standards.

3.3 Housing function. The Housing, Molded 9337419 shall deploy sensors when given a voltage of 1.6 volts discharged from a 100 microfarad capacitor. The housing shall deploy sensors on the top side with either the three-sensor side up or the four-sensor side up. For First Article samples all sensors on the top side shall deploy and no sensors on the bottom side shall deploy. For Lot Acceptance samples sensors on the top side and the bottom side shall deploy in accordance with accept/reject criteria given in 4.5.1.

3.4 Soldering. All soldered electrical connections shall comply with MIL-S-45743.

3.4.1 Solderability. Electronic and electric assembly parts that are to be soldered shall comply with the solderability requirements of MIL-S-45743 except the flexible printed wiring shall comply with the solderability requirements of MIL-P-50884.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

3.4.2 Surveillance. The contractor shall provide for surveillance quantities of Housing, Molded Dwg. 9337419 from each months production. A total quantity of 2 housings per month shall be supplied in accordance with 4.5.2.

3.5 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.6 Workmanship. All parts and assemblies shall be fabricated and finished in a thorough workmanship manner, and all manufacturing processing, and assembly operations shall be correctly performed. Metal parts shall be free of burrs, chips, cracks, crazes, porosity, warpage, burn marks, checks, chipped edges, blisters, excess flash, dirt, grease, rust, salt deposits, corrosion products, and other defects or foreign matter which would affect their serviceability. The cleaning method used shall not be injurious to any part or assembly, nor shall the parts be contaminated by the cleaning agent. All required markings shall be neat, legible and sharply defined.

4 QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.1.1 Responsibility for compliance. All items must meet all requirements of sections 3 and 5. The inspection set forth in this specification shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the specification shall not relieve the contractor of the responsibility of assuring that all products or supplies submitted to the Government for acceptance comply with all requirement of the contract. Sampling in quality conformance does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to acceptance of defective material.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First article inspection

b. Quality conformance inspection

4.3 First article inspection.

4.3.1 Submission. The contractor shall submit a first article as designated by the contracting officer for evaluation in accordance with provisions of 4.3.2 and 4.3.3. The first article sample shall consist of the following items in sample quantities as indicated:

Part Description	Drawing	Quantity
Housing Molded	9337419	25

A sample of 10 for other components listed in Table I.

4.3.2 Inspections to be performed. See MIL-A-48078 and paragraphs 4.4.2, testing per paragraph 4.4.3, and Table I specified herein.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-H-64033A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
	M131 AP Mine System Molded Housing Components				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Housing, Molded (Dwg. 9337419)				
	Examination for defects	25	-	3.2	4.4.2.1
	Function test	25	-	3.3	4.5.1
	Preform & Sensors Assembly (Dwg.9337418)				
	Examination for defects	10	-	3.2	4.4.2.2
	Bracket Sensor (Dwg. 9337404)				
	Examination for defects	10	-	3.2	4.4.2.3
	Wiring, Printed, Flexible (Dwg. 9337403)				
	Examination for defects	10	-	3.2	4.4.2.4
	Clip, Sensor Locating (Dwg. 9337402)				
	Examination for defects	10	-	3.2	4.4.2.5

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-02-23T03:11Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection

CLASSIFICATION OF DEFECTS & TESTS MIL-H-64033A(AR)

PARAGRAPH	TITLE: M131 AP Mine System Molded Housing Components		SHEET 2 OF 2		DRAWING NUMBER: See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Plug Manifold (Dwg. 9337407)				
	Examination for defects	10	-	3.2	4.4.2.6
	Manifold (Dwg. 9337405)				
	Examination for defects	10	-	3.2	4.4.2.7
	Manifold Assembly (Dwg. 9337417)				
	Examination for defects	10	-	3.2	4.4.2.7

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-02-23T03:11Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation of MIL-A-48078. In addition, inspection lots of housing assemblies shall contain tripline sensors, extended range (9292972) of one lot interfix from one manufactured.

Maximum lot size shall be no more than one (1) months production (30 calender day period).

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans and procedures for major and minor defects shall be in accordnce with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-H-64033A(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.1	Housing, Molded	1 OF 2	9337419
			NEXT HIGHER ASSEMBLY 9337430

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None				
Major					
101	Housing, nonfunctioning of sensor		1.0% 1/	3.3	4.5.1
102	Pressure cartridge circuit resistance improper		100%	3.2	Ohm meter
103	Tripline circuit resistance improper		100%	3.2	Ohm meter
104	Unrepaired potting voids in excess of .025 on surfaces "X" and "Y" within .25" of sensor opening		.40%	3.2	Visual
105	Evidence of potting material on open end of triplines		.40%	3.2	Visual
106	Density of potting material improper		.40%	3.2	Certificate of Conformance
107	True position of lead holes improper		.40%	3.2	Gage
108	True position of S&A cavity improper		.40%	3.2	Gage
109	Diameter of small S&A cavity improper		.40%	3.2	Gage
110	Distance from center to S&A locating boss improper		.40%	3.2	Gage
111	Depth from surface "X" to centerline of explosive lead holes improper		.40%	3.2	Gage
112	True position of rectangular locating recess improper		.40%	3.2	Gage
113	Length of rectangular locating recess improper		.40%	3.2	Gage

NOTES: 1/ Sample as per MIL-STD-105 General Inspection Level 1, single sample, normal inspection.

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-02-23T03:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.1	Housing, Molded	2 OF 2	9337419
			NEXT HIGHER ASSEMBLY 9337430

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
114	Diameter of round locating recess improper		.40%	3.2	Gage
115	Outside Diameter improper		.40%	3.2	Gage
116	True position of outside diameter improper		.40%	3.2	Gage
117	Width of locating slot improper		.40%	3.2	Gage
118	True position of locating slot improper		.40%	3.2	Gage
119	True position of trip line outside diameter (7 places) improper		.40%	3.2	Gage
Minor					
201	Potting bulges above surface "X" and "Y" in center area of housing		.65%	3.2	Gage
202	Height of housing improper		.65%	3.2	Gage
203	Width of rectangular locating recess improper		.65%	3.2	Gage
204	Spacing from housing to edge of flex circuit		.65%	3.2	Gage
205	Material improper		.65%	3.2	Certification
206	Poor workmanship		.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-H-64033A(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.2	Preform and Sensors Assembly	1 OF 1	9337418
			NEXT HIGHER ASSEMBLY 9337419

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None				
Major					
101	Heat Shrunk tubing length improper (7 places)		-	3.2	4.4.3.2/Gage
102	Heat shrink tubing kinked improperly shrunk, improperly assembled (7 tubes)			.40%	3.2
Visual					
103	Wires routed improperly (16 places)		.40%	3.2	Visual
104	Diaphragm sealed both sides around crimp improper		.40%	3.2	Visual
105	Wires lengths improper		.40%	3.2	Visual
106	Poor Solder workmanship		.40%	3.2	Visual
107	Wires or tubing extending beyond envelope diameter		.40%	3.2	Visual
108	Insulation of wires improper		.40%	3.2	Visual
Minor					
201	Location of manifold tubing to pressure cartridge improper		.65%	3.2	Gage
202	Protrusion of sensor from sensor clip		.65%	3.2	Gage
203	Adhesive improper		.65%	3.2	Certification
204	Tube material improper		.65%	3.2	Certification
205	Poor workmanship		.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-H-64033A(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.3	Bracket, Sensor	1 OF 1	9337404
			NEXT HIGHER ASSEMBLY: 9337418

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None Defined				
Major					
101	Tabs twisted improper		.40%	3.2	Visual
102	Overall width (after formed) improper		.40%	3.2	Gage
103	Overall length (after formed) improper		.40%	3.2	Gage
104	Diameter of sensor clip holes improper		.40%	3.2	Gage
105	Position of sensor clip locating holes (7 places) improper		.40%	3.2	Gage
106	Position of explosive lead holes (4 places) improper		.40%	3.2	Gage
107	Bend radius improper		.40%	3.2	Gage
Minor					
201	Material improper		.65%	3.2	Certification of Conformance
202	Finish improper & incomplete		.65%	3.2	Visual
203	Overall Height (after forming) improper		.65%	3.2	Gage
204	Poor workmanship		.65%	3.6	Visual

NOTES:

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026/10-23T03:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-H-64033A(AR)

PARAGRAPH 4.4.2.4	TITLE Wiring, Printed, Flexible		SHEET 1 OF 1		DRAWING NUMBER 9337403
					NEXT HIGHER ASSEMBLY 9337418
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None Defined				
Major					
101	Visual and Dimensional Examination		.40%	3.2	MIL-P-50884 1/
102	Missing or improperly mounted terminals		.40%	3.2	Visual
103	Hole Locations and dimensions improper		.40%	3.2	Gage
104	Solderability improper	20 2/	-	3.4.1	MIL-P-50884
Minor					
201	Material improper		.65%	3.2	Certification
202	Poor workmanship		.65%	3.6	Visual

NOTES:
1/ Paragraph 4.5 Methods of Inspection.
2/ Reject for one or more defective.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-H-64033A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.5	Clip, Sensor Locating				9337402
					NEXT HIGHER ASSEMBLY 9337418
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None Defined				
Major					
101	True position of the sensor holding boss improper		.40%	3.2	Gage
102	Inside Diameter of the Clip Mounting Hole improper		.40%	3.2	Gage
103	Angle of clip board improper		.40%	3.2	Gage
104	True position of clip smallest width improper		.40%	3.2	Gage
105	Height of sensor hole improper		.40%	3.2	Gage
Minor					
201	Thickness improper		.65%	3.2	Gage
202	Material improper		.65%	3.2	Certification
203	True Position of Sensor Hole improper		.65%	3.2	Gage
204	Poor workmanship		.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2022640-23T03:11Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-H-64033A(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.6	Plug Manifold	1 1	9337407
			NEXT HIGHER ASSEMBLY 9337417

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None Defined				
Major					
101	True position of locating tab improper		.40%	3.2	Gage
102	True position of tripline tube holes improper		.40%	3.2	Gage
Minor					
201	Presence of mold flash		.65%	3.2	Visual
201	Material improper		.65%	3.2	Certification
203	Poor workmanship		.65%	3.6	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-02-23T03:11Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-H-64033A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.7	Manifold				9337405
					NEXT HIGHER ASSEMBLY 9337417
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None Defined				
Major					
101	Plugged tube holes		.40%	3.2	Visual
102	Outside diameter of tube retaining lip improper		.40%	3.2	Gage
103	True position of the four right tube holes improper		.40%	3.2	Gage
104	Outside diameter of the gas generator port improper		.40%	3.2	Gage
105	True position of the manifold plug locating slot improper		.40%	3.2	Gage
106	Inside diameter of the manifold plug cavity improper		.40%	3.2	Gage
107	Depth of the manifold plug cavity improper		.40%	3.2	Gage
Minor					
201	Height of tripline tube ports improper		.65%	3.2	Gage
202	Presence of molded flash		.65%	3.2	Visual
203	Material improper		.65%	3.2	Certification
204	Poor workmanship		.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-04-23T03:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-H-64033A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9337417
4.4.2.8	Manifold Assembly				NEXT HIGHER ASSEMBLY 9337418
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None Defined				
Major					
101	Verify open ports per Note 2		.40%	3.2	Visual
102	Verify coverage of adhesive between manifold and manifold plug per Note 5		.40%	3.2	Visual
103	Verify free ball movement per Note 6		.40%	3.2	Visual
Minor					
201	Poor workmanship		.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-02-23T03:11Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First Article Tables and Quality Conformance Inspection.

4.4.3.1 Dimensional control of molded or plastic parts. This paragraph applies to the following parts:

Plug, Manifold	9337407	Ref Para 4.4.2.6
Manifold	9337405	Ref Para 4.4.2.7

In place of normal sampling and inspections associated with the Classification of Defects, and after a curing time for the parts has been approved (see Note 1) a sample of three (3) parts (as molded) from each cavity shall be fully inspected dimensionally to qualify a new or reworked cavity for use in production. When multiple cavity dies are used, the molded parts shall carry the individual cavity identification. As a control of each cavity during production, the above quantity of parts from each cavity shall be inspected for at least the defects listed in the reference paragraphs for the above parts after continuous production of each 5,000 parts or at the end of each week, whichever occurs first. Of the three (3) samples, one (1) sample shall be the last part produced. If any defective parts are found during qualification of the cavity, the cavity producing the defective part will not be used in production. If any defective parts are found when inspection is performed for the control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for inspection for each separate type of defect according to MIL-STD-105, using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. All cavities removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of ispection frequency providing he presents objective evidence to the contracting officer to substantiate the request.

NOTE 1: In establishing a curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g. every 30, 60, etc. reins.) until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. If there is a change in material, or in the cycle time, or if a cavity is reworked, or a new cavity is used, a new curing time shall be established and approved.

4.4.3.2 Dimensional control of heat shrink tubing. To provide proper tubing lengths after heat shrink for assembly 9337418, each roll of unshrunk tubing MIL-I-23053 must be qualified for use. Five (5) unshrunk samples of each of the seven tubing lengths to be used in the assembly must be cut from each roll of tubing. Then after subjecting the samples to the same heating environment as the 9337418, tubing lengths must conform to the referenced length dimensions on dwg. 9337418.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed in this specification is identified either directly or by reference, in the "paragraph reference/inspection method" column of the First Article Table or Quality Conformance Inspection herein. The contractor shall submit inspection equipment designs to the Government for approval in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.4 herein.

4.5 Methods of inspection.

4.5.1 Housing function. A 100 microfarad (± 5%) capacitor charged to 1.6 volts (± 0.1 volt) shall be applied across terminals A and B of the flexible cable. One-half of the sensors shall be tested with the three (3) sensor side up and one-half shall be tested with the four (4) sensor side up.

First Article samples shall have all sensors on the top side release and deploy with no bottom side sensor releases.

Lot acceptance samples as per MIL-STD-105 shall be tested for sensors releasing using an AQL of 1.0% and based on the total number of sensors being tested on the top side of the housings. Of the housings selected, using an AQL of 1.0% for sample size, the number of sensors being tested on the top side now becomes the sample size for determining the acceptance/rejection criteria in an AQL of 1.0%. Also, of the allowable failures above, there can be no more than one sensor release failure per housing on the top side. Total bottom side sensor release failures can not exceed a 4.0% AQL where one or more bottom sensor release(s) per housing is considered one failure.

Sensor (trip line) circuit resistance shall be monitored continuously during deployment. Failure to maintain continuity of the circuit shall be cause to classify the housing assembly defective.

4.5.2 Surveillance units. The housings designated for surveillance shall be stored at the contractors facility until contract completion and disposition is made. The units shall be identified in a manner to provide traceability to the lot number, month, and year of manufacture. Monthly verifications of circuit resistances of pressure cartridge and trip lines shall be recorded and reported when increases are noted.

5. PACKAGING

5.1 Packaging.

5.1.1 Level A. Level A packaging shall have the same requirements as for Level C.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

5.1.2 Level B. Level B packaging shall have the same requirements as for Level C.

5.1.3 Level C. Level C packaging shall be in accordance with Dwg. 12598451.

5.2 Packing.

5.2.1 Level A. Level A packing shall have the same requirements as for Level C.

5.2.2 Level B. Level B packing shall have the same requirements as for Level C.

5.2.3 Level C. Level C packing shall be in accordance with Dwg. 1202705.

5.3 Marking.

5.3.1 Level A. Level A marking shall have the same requirements as for Level C.

5.3.2 Level B. Level B marking shall have the same requirements as for Level C.

5.3.3 Level C. Level C marking shall be in accordance with Dwgs 12598451 and 12902705.

6. NOTES

6.1 Intended use. These parts are designed for use in the M131 Mine System Antipersonnel Mine.

6.2 Acquisition requirements. See MIL-A-48078.

6.3 Submission of inspection equipment designs for approval. See MIL-A-48078. Submit equipment designs as required to Commander: USARDEC, ATTN: AMSMC-QAT-I(D), Picatinny Arsenal, New Jersey 07806-5000. This address will be specified on the Contract Data Requirements List, DD Form 1423 in the contract. Unless otherwise specified, data item DI-R-1714 will apply.

6.4 Data submissions. Results of all tests performed by the contractor shall be submitted in accordance with Data Item DI-R-1721 on the DD Form 1423 for the contract. Distribution shall include the following:

Commander
ARDEC
ATTN: AMSMC-QAT-M(D)
Picatinny Arsenal, NJ 07806-5000

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

6.5 Distribution of ammunition data cards, inspection and test results. Distribution of ammunition data cards, inspection, and test results shall include Commander: ARDEC, Picatinny Arsenal, NJ 07806-5000, ATTN: AMSMC-QAT-M(D).

6.6 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research Development and Engineering Center (ARDEC) may also include drawings prepared by and identified as, US Army Armament Research and Development Command, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal, or Picatinny Arsenal drawings. Technical data originally prepared by these activities is now under the cognizance of ARDEC.

6.7 Definition of packaging and packing levels.

6.7.1 Level A. Full military protection for unrestricted (OCONUS) shipment and storage.

6.7.2 Level B. Limited military protection for limited shipment and storage.

6.7.3 Level C. For interplant shipment and very limited storage.

6.8 Subject term (key word) listing.

Mine, Anti-Personnel
Molded Housing

6.9 Changes from previous issue. Asterisks (or vertical lines) are not used in this revision to identify changes with respect to the previous issue due to the extensiveness of the changes:

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1345-A505)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

INSTRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in submitting comments and suggestions for improvements. All users of military standardization documents are invited to provide suggestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and mailed. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was too rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the problems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an acknowledgement will be mailed to you within 30 days to let you know that your comments were received and are being considered.

NOTE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

DEPARTMENT OF THE ARMY

NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO 12062 WASHINGTON D C
POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
US Army ARDEC
ATTN: SMCAR-FSM
Picatinny Arsenal, NJ 07806-5000

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-H-64033A (AR)	

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ USER
	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:11Z
Check the source to verify that this is the current version before use.