MIL-P-60321 (PA)
AMENDMENT 1
26 October 1976

MILITARY SPECIFICATION

PRIMER, STAB, T103E1
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-P-60321, dated 1 March 1965.

Para. 2.1: Delete drawings 7548103, 7548104 and 7548118 and titles and substitute as follows:

9258182 - Box, Set-up, Packing, Ammunition, Inner for Small Explosive Components

9258183 - Box, Set-up, Packing, Ammunition, Outer for Small Explosive Components

9258184 - Box, Packing, Ammunition, for Small Explosive Components

Para. 4.2.2.3: Delete entire paragraph and substitute as follows:

4.2.2.3 Box, set-up, inner, after loading and prior to closing slide cover (see dwg. 9258182)

FSC: 1375

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection	Code No.
Critical:			
1.	Filler and cushion assembly missing	Visual	03001
2.	Filler and cushion assembly improperly assembled	Visual	03002
3.	Stiffener missing	Visual	03003
4.	Slide cover assembled improperly	Visual	03004
Major:	AQL 0.40 Percent		
101	Release paper missing	Visual	03005
Minor:	AQL 1.00 Percent		
201	Marking missing, incomplete or illegible	Visual	03006
202	Evidence of poor workmanship (see 3.5)	Visual	03007

Para. 4.2.2.4 Delete entire paragraph and substitute as follows:

4.2.2.4 Box, set-up, outer, with inner set-up boxes assembled and prior to assembling top and sealing strips (see dwg. 9258183)

Categories	Defects	Method of Inspection	Code No.
Critical:			
1.	Red surfaces on inner set-up boxes do not alternate on same side of outer set-up box	Visual	04001
2.	Stiffener not facing one direction	Visual	04002

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

Major:	None defined		
Minor:	AQL 1.00 Percent		
201	Marking missing, incomplete or illegible	Visual	04003
202	Evidence of poor workmanship (see 3.5)	Visual	04004

Para. 4.2.2.5 Delete entire paragraph and substitute as follows:

4.2.2.5 Box, packing, ammunition prior to assembling cover and strapping (see dwg. 9258184)

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 Percent		
101	Bags containing set-up boxes damaged	Visual	05001
102	Cushioning material incomplete or missing from outer set-up boxes	Visual	05002
103	Marking missing, misleading or illegible	Visual	05003
104	Barrier bag seal incomplete or improperly positioned	Visual	05004
Minor:	AQL 0.65 Percent		
201	Evidence of poor workmanship (see 3.5)	Visual	05005

Source: https://assist.dla.mil -- Downloaded: 20261O-23T00:28Z
Check the source to verify that this is the current version before use.

Para. 4.2.2.6 Delete entire paragraph and substitute as follows:

4.4.2.6 Box, packing ammunition (see dwg. 9258184)

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:	AQL 0.65 Percent		
101	Strapping missing, broken, loose or improperly fastened	Visual/Manual	06001
102	Box damaged	Visual	06002
103	Marking missing, incomplete or illegible	Visual	06003
Minor:	AQL 0.65% Percent		
201	Evidence of poor workmanship (see 3.5)	Visual	06004

Para. 4.2.3.3 Delete (see dwg. 7548103) and substitute (see dwg. 9258183). Delete Code No. 05004 and substitute Code No. 04005.

Para. 5.1.1 Delete 7548104 and substitute 9258182.

Para. 5.1.2 Delete 7548103 and substitute 9258183.

Para. 5.2.1. Delete 7548118 and substitute 9258184.

Para. 5.3 Delete 7548103, 7548104 and 7548118 and substitute 9258182, 9258183, 9258184.

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number: 1375-A187

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.