MILITARY SPECIFICATION

TENT, HEXAGONAL, LIGHTWEIGHT, M-1950

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This document covers a pole-supported pyramidal tent with a fire-resistant treated liner. A cover is provided to protect the tent and liner.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

* 2.1.1 Specifications, standards, and handbooks. The following specifications, standards, and handbooks form a part of this specification to the extent specified herein. Unless otherwise specified, the issues of these documents shall be those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation.

SPECIFICATIONS

FEDERAL

A-A-203	-	Paper, Kraft, Untreated
A-A-883	-	Tape, Pressure Sensitive Adhesive, Masking
T-C-571	-	Cords, Cotton; General and Special Purpose, Sash and Venetian Blind
T-T-871	-	Twine, Cotton, Wrapping
T-T-911	-	Twine, Fibrous, Jute

* Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: U.S. Army Natick Research, Development, and Engineering Center, Natick, MA 01760-5014 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A FSC 8340

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

V-F-106	-	Fasteners, Slide, Interlocking
V-T-285	-	Thread, Polyester
QQ-W-321	-	Wire, Copper Alloy
TT-P-595	-	Preservative Coating, Canvas
CCC-C-429	-	Cloth, Osnaburg, Cotton
CCC-C-467	-	Cloth, Burlap, Jute (or Kenaf)
DDD-L-20	-	Label: for Clothing, Equipage, and Tentage (General Use)
* GGG-N-202	-	Needle, Sailmaker's
PPP-B-601	-	Boxes, Wood, Cleated-Plywood

MILITARY

MIL-F-495	-	Finish, Chemical, Black, for Copper Alloys
MIL-C-496	-	Clips, End, Strap
MIL-P-501	-	Pins, Tent, Metal
MIL-W-530	-	Webbing, Textile, Cotton, General Purpose, Natural or in Colors
MIL-L-1709	-	Lines, Tent
MIL-P-1716	-	Poles, Tent, Telescopic, Adjustable, 5 Feet to 9 Feet, Magnesium
MIL-S-1734	-	Slips, Tent Line
MIL-R-2327	-	Rings, Connecting, Round
MIL-C-2399	-	Cement, Liquid, Tent Patching
MIL-R-3390	-	Rings, Dee
MIL-C-3395	-	Cloth, Netting, Nylon or Polyester
MIL-C-10859	-	Cloth, Oxford, Cotton (Permeable)
MIL-F-10884	-	Fasteners, Snap
MIL-L-11075	-	Loops, Strap Fastener
MIL-C-12095	-	Cloth, Wind-Resistant Sateen, Cotton; Fire and Water Resistant
MIL-G-16491	-	Grommet, Metallic
MIL-S-43002	-	Shield, Stovepipe, Tent, Nonmetallic
MIL-C-43256	-	Cord, Polyester, Solid Braid
MIL-T-43566	-	Tape, Textile, Cotton or Polyester, General Purpose, Natural or in Colors
MIL-C-43627	-	Cloth, Duck, Cotton, Plied Yarns, Fire, Water, Weather and Mildew Resistant Treated, Lightdry Finish
MIL-W-43638	-	Webbing, Textile, Woven, for Tent Framing
MIL-S-43770/10-		Snap Hooks, Cast Body, Fixed Loop Eye W/O Roller, Flat Spring Closure, Wide Mouth
MIL-W-44049	-	Webbing, Textile and Tape, Textile, Polypropylene, General Purpose, Natural or in Colors

Source: https://assist.dla.mil -- Downloaded: 202610-17T13:21Z
Check the source to verify that this is the currentversion before use.

STANDARDS

FEDERAL

FED-STD-751 - Stitches, Seams, and Stitchings

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-129 - Marking for Shipment and Storage

* (Copies of specifications, standards, and handbooks required by contractors in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting activity.)

* 2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this specification to the extent specified herein. Unless otherwise specified, the issues shall be those in effect on the date of solicitation.

Department of the Army Field Manual FM 10-16 -
General Repair of Tents, Canvas and Webbing

(Copies may be obtained from the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.)

DRAWINGS

* US ARMY NATICK RESEARCH, DEVELOPMENT AND ENGINEERING CENTER

5-4-221 - Tent, Hexagonal, Lightweight, M-1950; Illustration and List of Parts
5-4-222 - Assembly, View and Details
5-4-223 - Views and Details
5-4-224 - Front Details
5-4-225 - Assembled Front and Details
5-4-226 - Side
5-4-227 - Ventilator
5-4-229 - Liner Assembly
5-4-230 - Liner Details
5-4-231 - Cover
5-4-580 - Repair Kit
5-4-1052 - Erection Instructions

* (Copies of drawings, publications, and other Government documents required by contractors in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting activity.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

* 2.2 Other publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise specified, the issues of the documents which are DOD adopted shall be those listed in the issue of the DODISS specified in the solicitation. Unless otherwise specified, the issues of documents not listed in the DODISS shall be the issues of the nongovernment documents which are current on the date of solicitation.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

* D 2016 - Standard Test Method for Moisture Content of Wood
D 3951 - Standard Practice for Commercial Packaging

(Copies may be obtained from the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103.)

(Nongovernment standards and other publications are normally available from the organizations which prepare or which distribute the documents. These documents also may be available in or through libraries or other informational services.)

* 2.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence. Nothing in this specification, however, shall supersede applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 First article. When specified in the contract or purchase order, a sample shall be subjected to first article inspection (see 4.3, 6.2, and 6.5).

3.2 Materials and components. Materials and components shall be as specified herein (see 6.6).

3.2.1 Cloth, wind-resistant sateen, cotton. The cloth for the tent shall be dyed Olive Green 107 and shall conform to MIL-C-12095.

* 3.2.2 Cloth, cotton duck. The cloth for the cover and peak reinforcement shall conform to MIL-C-43627 and the color shall be Olive Drab 7. Requirements for colorfastness to weathering shall not apply for tent cover and peak reinforcement.

* 3.2.3 Cloth, cotton, oxford. The cloth for the liner shall conform to type I, class 2 of MIL-C-10859.

3.2.4 Cloth, netting, nylon. The nylon netting for the ventilator opening shall conform to type I or II of MIL-C-3395.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

3.2.5 Shield, stovepipe, tent. The flexible, silicone rubber coated stovepipe shield shall conform to MIL-S-43002.

* 3.2.6 Tape, textile, cotton. The tape shall be dyed Olive Drab 7 and shall conform to type I, class 4, 1/2 inch, 3/4 inch, 1 inch and 2 inch widths of MIL-T-43566. Alternatively, the tape shall be polypropylene conforming to type I, class 3 or 4, 3/4 inch and 2 inch of MIL-W-44049 for covers and liners only.

* 3.2.7 Webbing, textile, cotton. The webbing shall by dyed Olive Drab 7 and shall conform to type IIb, class 4, 1 inch width and type III, class 4, 5/8 inch and 1-1/2 inch widths of MIL-W-530. Alternatively, the webbing shall be polypropylene conforming to type IIb 1 inch width, class 4 of MIL-W-44049 for covers and liners only.

3.2.8 Webbing, textile, woven, low elongation. The webbing shall be 1 inch width conforming to type I of MIL-W-43638.

3.2.9 Thread, polyester.

3.2.9.1 Tent and cover. The thread shall conform to type I, class 1, subclass B, Olive Drab S-1 (C. A. 66022) of V-T-285. The dyed thread shall show fastness to weathering equal to or better than the standard shade sample. When no standard shade sample is available, the dyed thread shall show good fastness to weathering.

3.2.9.2 Liner. The thread shall be color natural and shall conform to type I or II, Class 1 of V-T-285.

* 3.2.9.3 Sizes. Thread sizes shall be as follows:

For all stitching on tent except zig-zag stitching, bartacking and stitching indicated by "Z" on drawings	- Size F for needle and bobbin
For zig-zag stitching and bartacking	- Size E for needle and bobbin
For stitching on tent indicated by "Z" on drawings	- Size F for needle, size E for looper
For all stitching on liner, except stitching indicated by "Z" on drawings	- Size E for needle and bobbin
For stitching on liner indicated by "Z" on drawings	- Size E for needle, size B for looper

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

For all stitching on cover except stitching indicated by "Z" on drawing	- Size FF for needle and bobbin
For stitching on cover indicated by "Z" on drawing	- Size FF for needle, size F for looper

3.2.10 Lines, tent. The tent lines shall conform to class D or class G of MIL-L-1709 in the types specified on the applicable drawings.

3.2.11 Stiffener, cord. The cord for the drip cap stiffener shall conform to type I, class 3, size No. 7 of T-C-571.

3.2.12 Toggle loops. The cord for the toggle loops shall conform to polyester, 1/8 inch diameter, OD-7 of MIL-C-43256.

3.2.13 Toggles, wood. The wood toggles shall be of the design and dimensions shown on Drawing 5-4-225. The wood for the toggles shall be straight-grained, sound and smooth lumber, kiln dried to not more than 15 percent moisture content when tested as specified in 4.4.1.1. The toggles shall be free from knots, shakes, checks, splits, or splintery surface. Any of the following woods may be used:

Hickory	Beech	Pecan	Maple, hard
Red or White Oak	Birch	Rock Elm	Ash

3.2.14 Toggles, metal. The metal toggles shall be of the design and dimensions shown on Drawing 5-4-223 and shall be fabricated from copper alloy wire conforming to alloy number 270, half hard temper of QQ-W-321. The toggles shall be given a black chemical finish conforming to MIL-F-495.

3.2.15 Slips, tent line. The tent line slips shall conform to type II of MIL-S-1734.

* 3.2.16 Fasteners, slide, interlocking. The slide fasteners shall conform to type III, style I, size H, wire stirrup pulls of V-F-106. Slide fastener chain shall be fabricated of brass or polyester coil. The slider for the brass chain shall be brass and the slider for the polyester coil shall be die cast zinc alloy. The slide fastener tape shall be dyed to match Olive Drab shades S (CA 66519) and be water repellent and mildew-resistant. (Tapes made of 100 percent polyester need not be tested for mildew resistance.) The color of the tape after treatment will be considered acceptable. The tape shall show good fastness to weathering. Alternatively, the slide fastener chain shall be polyester continuous monofilament in a ladder or coil type configuration. Color of the chain shall be Olive Drab or natural finish brass and the sliders shall be brass.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

3.2.17 Rings, dee. The dee rings shall conform to class 1 or 2, configuration K, size 1 inch by 3/4 inch of MIL-R-3390.

3.2.18 Rings, connecting. The connecting rings shall conform to class 2 or 5, size 2 and 6 of MIL-R-2327.

3.2.19 Grommets, metallic. The Nos. 3 and 5 grommets shall conform to type III, class 3 and the No. 2 grommets shall conform to type II, class 3 of MIL-G-16491.

3.2.20 Fasteners, snap. The snap fasteners shall conform to style 2, finish 2, button 24 line size, size 1 and eyelet size 1 of MIL-F-10884.

3.2.21 Clips, end. The end clips shall conform to type I, class 1 or 2, size 1 inch of MIL-C-496.

3.2.22 Loops, strap fastener. The strap fastener loops shall conform to type III, style B of MIL-L-11075.

3.2.23 Snaphook. The snaphooks shall conform to MIL-S-43770/10.

3.2.24 Pins, tent, metal. When required (see 6.2), the tent pins shall be type I, conforming to MIL-P-501.

3.2.25 Pole, tent, telescopic. When required (see 6.2), the magnesium, adjustable telescopic tent poles shall conform to MIL-P-1716.

3.2.26 Kit, repair. The repair kit bag shall be fabricated from the material specified in 3.2.1 and of the design and dimensions shown on Drawing 5-4-580. The snap fastener on the pocket shall be as specified in 3.2.20. The bag containing the repair kit components, shall be securely tied and placed in the repair kit pocket of each completed tent.

3.2.26.1 Components, repair. Components for each kit shall consist of the items listed in table I.

TABLE I. Repair kit components

Item	Quantity	Specification or reference
Cloth, wind-resistant sateen, cotton	1/2 yard full width	3.2.1
Thread, polyester, type I, class 1, sub-class B, size FF, shade S-1	1 spool (2-ounce)	3.2.9

Source: https://assist.dla.mil -- Downloaded: 202610-17T13:21Z
Check the source to verify that this is the currentversion before use.

TABLE I. Repair kit components (cont'd)

Item	Quantity	Specification or reference
Needle, sailmaker's size 16	3	GGG-N-202
Pusher, needle	1	Drawing 5-4-580 and wood specified in 3.2.13
Sleeve, lock retaining	2	Drawing 5-4-1075 Item 10 MIL-P-1716
Lock, upper	1	Drawing 5-4-1075 Item 7 MIL-P-1716
Lock, lower	1	Drawing 5-4-1075 Item 8 MIL-P-1716

3.3 Construction. The construction shall conform to the drawings listed in Section 2 and as specified herein.

3.3.1 Stitching, machine.

* 3.3.1.1 Types of stitching. All stitch types, except bartacking, shall conform to FED-STD-751 as follows:

For tent, screens and cover:

For all stitching except stitching indicated by "Z" on drawings	- Type 301, 5 to 7 stitches per inch
For stitching indicated by "Z" on drawings and for attachments of slide fasteners	- Type 401, 5 to 7 stitches per inch. Chain portion of stitching shall not appear on outside of tent, screens, or cover.
For zig-zag stitching	- Type 304, 10 to 16 stitches per inch

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

For liner:

For all stitching, except stitching indicated by "Z" on drawings	- Type 301, 6 to 8 stitches per inch
For stitching indicated by "Z" on drawings and for attachments of slide fasteners	- Type 401, 6 to 8 stitches per inch. Chain portion of stitching shall not appear on outside of liner.
For bartacking	- Bartack, 3/8 ± 1/16 inch long with 1/8 ± 1/32 inch bight and shall contain 28 stitches

* 3.3.1.2 Type 301 stitching. Ends of all stitching shall be backstitched or overstitched 1/2 inch minimum except when caught in other stitching or turned under in the hem. Thread tension shall be maintained so that there will be no loose stitching resulting in puckering of material sewn. The lock shall be imbedded in the material sewn.

* 3.3.1.2.1 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of one inch behind the end of the stitching. 1/

b. Thread breaks, two or more consecutive skipped stitches or run-off stitches noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of one inch before the defective area (1/2 inch on Box, Box and Cross and W-W stitching) and continue a minimum of one inch beyond the defective area onto the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching, without damaging the materials, and restitching in the required manner. 1/

1/ When making the above repairs, the ends of the stitching are not required to be backstitched.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

* 3.3.1.3 Type 401 stitching. Thread tension shall be maintained so that there will be no loose stitching. Both ends of all seams or stitching produced with a 401 stitch type, when not turned under in a hem or held down by other stitching, shall have a 1/2 to 3/4 inch chain extending beyond each end. The looper (under thread) shall always be on the inside of the tent or cover. All repairs shall be made in accordance with 3.3.1.2.1a or 3.3.1.2.1b. Repairs may be made using a 301 stitch type.

* 3.3.1.4 Type 304 stitching. For type 304 stitching, thread tension shall be maintained so that there will be no loose or excessively tight stitching. Repairs shall be in accordance with 3.3.1.2.1a or 3.3.1.2.1b except that the stitching shall over stitch the defective stitching area a minimum of three stitches onto the existing stitching. At least 1/4 inch of backstitching, overstitching or an increased number of stitches per inch shall be used to secure the ends of stitching.

* 3.3.1.5 Automatic stitching. Automatic stitching machines may be used to perform any of the required stitch patterns provided the requirements of the stitch pattern, stitches per inch, size and type of thread are met, and at least three or more tying, overlapping or backstitches are used to secure the ends of the stitching.

* 3.3.1.6 Thread ends. All thread ends that are visible on the finished item shall be trimmed to a length of not more than 1/4 inch.

* 3.3.1.7 Bartacking. Bartacking shall be free of thread breaks or loose stitching.

* 3.3.1.8 Lubrication of thread. The addition of any lubricant to the polyester sewing thread prior to or during the sewing operation is prohibited.

* 3.3.1.9 Stitching margins. Unless otherwise specified, all stitch margins shall be 1/8, +1/16 -0 inch.

* 3.3.2 Attachment of wood toggles. Wood toggles shall be attached as shown on Drawing 5-4-225.

* 3.3.3 Setting of grommets. Holes punched to receive the grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the materials. Roll of the clinched grommet shall not contain splits.

3.3.4 Setting of snap fasteners. If a hole is punched before inserting the male or female part of the fastener, it shall be smaller than the outside diameter of the fastener tube so that the tube must be forced through the hole. The fasteners shall be securely clinched. Roll of the clinched eyelet of the assembled fastener component shall not contain more than three scores (splits).

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

3.3.5 Setting of end clips. The webbing shall be inserted the full depth of the clips. The clips shall be securely attached without cutting the webbing and the webbing shall lie flat at the point of entry.

* 3.3.6 Repairs. Any necessary repairs shall be effected in accordance with Department of the Army Field Manual FM 10-16 except that hand-sewn patches, or cemented patches other than as specified herein, will not be acceptable. Cemented patches on holes, cuts or tears not more than 1 inch in diameter or length, using cement specified in MIL-C-2399, shall be permitted. A maximum of three cemented patches per tent will be allowed without prior authorization. All other repairs shall require contracting officer authorization. Repairs required as a result of failure to meet the requirements of the cup test and when authorized by the contracting officer shall be performed by treating with a compound conforming to type I, class 1, shade Olive Drab of TT-P-595 prior to retesting (see 6.4).

* 3.3.7 Wicking of sewing thread (cup test). There shall be no dripping of water through the tent stitching when the tent is tested as specified in 4.5.1. The cup test is intended to insure that non-wicking thread has been utilized and that no lubrication has been added to the polyester thread prior to or during the sewing operation.

* 3.3.8 Splicing of cloth. There shall be no splicing of roof, wall or tent cover panels. Splicing of reinforcements and snow cloth sections will be permitted and, if performed, shall conform to the following requirements:

a. Eight feet or less in length - One splice permitted;
More than 8 feet but not more than 12 feet in length - Two splices permitted;
More than 12 feet in length - Three splices permitted.

b. The shortest length of any spliced piece shall be not less than 2 feet.

c. Pieces shall be joined as shown on Drawing 5-4-226, section C-C.

* 3.3.9 Splicing of webbing. If required, the webbing shall be spliced as shown on Drawing 5-4-225. A maximum of one splice per gore will be permitted. The minimum distance between splices in the remainder of the tent shall be five feet.

* 3.3.10 Attachment of slide fasteners. Care shall be exercised to maintain specified distances between edges of fabric attached to slide fastener tape so that there will be no interference with the operation of the slider. The length of the slide fastener shall be such that after the slide fastener is sewed on, the tape shall not be puckered and the slider shall operate freely.

* 3.3.11 Replacement of defective components. During the spreading, cutting and manufacturing process, components of the tent having material defects or damages that are classified as defects in 4.4.2 or 4.4.3 shall be removed from production and replaced with non-defective and properly matched components.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

* 3.3.12 Fusing of ends of synthetic webbing and tape. All ends of synthetic webbing, and tape shall be fused. The apparatus used to fuse the ends shall be capable of providing sufficient heat to provide a smooth edge and with the cut ends of the yarns all fused together. Fusing of the ends shall be accomplished prior to being assembled for stitching.

3.4 Marking. All marking and labels shall conform to DDD-L-20.

3.4.1 Special marking. The application of the letters "US" on the tent and cover, the instructions on the door and the nomenclature on the cover shall conform to type IV, class 9 in the size characters and in the locations shown on the drawings. Class 9 markings shall be clearly legible after subjection to accelerated weathering.

3.4.2 Identification label. The identification labels shall be stitched to the tent, liner and cover in the locations shown on the drawings and shall conform to type VI, class 6 and shall be 3-1/2 inches by 5-1/2 inches minimum and a blank space of at least 1-1/4 inches shall be provided on the bottom of the label for the Department of Defense inspector's stamp.

* 3.4.3 Erection instruction label. Instruction labels shall conform to type VI, class 7 and shall be stitched to the tent, liner and cover in the locations shown on the drawings. The label shall be a proportionate copy of Drawing 5-4-1052 as reproduced from a glossy print of the drawing furnished by the contracting officer. The size of the label shall be borderline to borderline, 15 $\pm$ 1/4 inches in the longer dimension with a minimum 1/2 inch margin outside of the borderline on all sides.

* 3.5 Workmanship. The tent shall conform to the quality of product established by this document and the occurrence of defects shall not exceed the applicable acceptable quality levels.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in this document where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

* 4.1.1 Responsibility for compliance. All items must meet all requirements of sections 3 and 5. The inspection set forth in this document shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the document shall not relieve the contractor of the responsibility of assuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling in quality conformance does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to acceptance of defective material.

* 4.1.2 Responsibility for dimensional requirements. Unless otherwise specified in the contract or purchase order, the contractor is responsible for assuring that all specified dimensions have been met. When dimensions cannot be examined on the end item, inspection shall be made at any point, or at all points in the manufacturing process necessary to assure compliance with all dimensional requirements.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).
b. Quality conformance inspection (see 4.4).

* 4.3 First article inspection. When a first article is required (see 6.2), it shall be examined for the defects specified in 4.4.3 and 4.4.4, and tested for the characteristics specified in 4.4.5. The presence of any defect or failure to pass any test shall be cause for rejection of the first article.

4.4 Quality conformance inspection. Unless otherwise specified, sampling for inspection shall be performed in accordance with MIL-STD-105.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced documents unless otherwise excluded, amended, modified, or qualified in this document or applicable purchase document.

* 4.4.1.1 Wood toggle moisture content testing. In addition to the quality assurance provisions of the subsidiary documents, the wood toggles shall be tested for conformance to the moisture content requirements in 3.2.13. The moisture content shall be determined in accordance with the oven-drying or the electrical meter method reference ASTM D 2016. The results shall be reported to the nearest 0.1 percent for each toggle tested. The lot size shall be expressed in toggles. The sample unit shall be one toggle. The inspection level shall be S-1 and the AQL, expressed in terms of defects per hundred units, shall be 4.0.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

* 4.4.2 In-process inspection. Inspection shall be made of the following operations or assemblies to establish conformance to specified requirements. Whenever nonconformance is noted, correction shall be made to the items affected and to the operation. Items which cannot be corrected shall be removed from production.

a. Holes punched to receive grommets are in compliance with 3.3.3.

b. There shall be no lubrication of polyester thread prior to or during sewing operations in compliance with 3.3.1.8.

c. Holes punched to receive male or female parts of snap fasteners are in compliance with 3.3.4.

4.4.3 End item visual examination.

* 4.4.3.1 Tent with liner and cover. The end item shall be in an erected position so that both the inside and outside of the tent can be examined, along with its cover and liner, for defects listed in table II. The lot size shall be expressed in units of tents with liners and covers. The sample unit shall be one tent with liner and cover. The inspection level shall be I, and the acceptable quality level (AQL), expressed in terms of defects per hundred units, shall be 40 for major defects, 150 for major and minor A combined defects and 250 for total (major and minor combined) defects.

* 4.4.3.2 Tent liner, only. The end item shall be examined for the applicable defects listed in table II. The lot size shall be expressed in units of liners. The sample unit shall be one liner. The inspection level shall be I and the AQL, expressed in terms of defects per hundred inits, shall be 10 for major defects, 25 for major and minor A combined defects, and 100 for total (major, minor A and minor B combined) defects.

* 4.4.3.3 Tent cover, only. The end item shall be examined for the applicable defects listed in table II. The lot size shall be expressed in units of covers. The sample unit shall be one cover. The inspection level shall be I and the AQL, expressed in terms of defects per hundred units, shall be 6.5 for major defects, 15 for major and minor A combined defects, and 40 for total (major, minor A and minor B combined) defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects

	Examine	Defect	Classification Major	Minor A	Minor B
	Fabric	Cut, tear, or hole (including exposed drill hole) greater than 1/8 inch in length or diameter:			
		- on tent	X		
		- on cover or snow cloth		X	
		Cut, tear, or hole (including exposed drill hole) 1/8 inch or less in length or diameter:			
		- more than 20:			
		- on tent	X		
		- on cover or snow cloth		X	
		- more than 10 but not more than 20:			
		- on tent		X	
		- on cover or snow cloth			X
		- more than 5 but not more than 10:			
		- on tent			X
*	Fabric, liner	Cut, tear hole (including exposed drill hole):			
		- greater than 1/4 inch in length or diameter on liner	X		
		- greater than 1/8 inch but not greater than 1/4 inch in length or diameter on liner		X	
		- more than 5 holes 1/8 inch or less in length or diameter on liner			X
		Broken or missing yarns; multiple floats clearly visible at normal inspection distance (approximately 3 feet)		X	
	Cloth netting	Cut or tear:			
		- more than 2 inches in length	X		
		- more than 1/4 inch but not more than 2 inches in length		X	
		- 1/4 inch or less in length			

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Tape and webbing	Frayed or scalloped edge		X	
* Splicing of webbing	Splicing (when necessary) not as indicated on Drawing 5-4-225;		X	
	More than one splice per gore on seams joining panels of tent or liner		X	
* Cloth splicing	Splice in roof, wall, or tent cover panels	X		
	Number of splices per reinforcement or snow cloth section more than specified (see 3.3.8)		X	
	Spliced pieces not joined as shown on Drawing 5-4-226			X
Cord components	Cut or abrasion		X	
	Eave lines, corner lines, or foot-stops improperly knotted; free ends of lines not finished as specified			X
Hardware	Broken	X		
	Malformed:			
	- fails to perform intended function	X		
	- but will perform intended function		X	
	Corroded area			X
	Burr or sharp edge which may cause injury in handling or damage to fabric	X		
Grommets	Improperly set; two or more teeth exposed (except where grommet is set as specified but is in an area of unequal thickness which prevents uniform clinching)			X
	Clinched loosely allowing grommet to rotate in hole			X
	Clinched excessively tight cutting fabric	X		
	Insecurely clinched, i.e. grommet or washer may become disengaged	X		

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Grommets (cont'd)	Roll of a grommet contains one or more splits			X
End clips	Improperly clinched, i.e. webbing not flat at point of entrance into clip			X
	Clinched excessively tight cutting webbing or loosely clinched, i.e. clip becomes disengaged from webbing		X	
Snap fasteners	Female components used in location where male components are required; fasteners fail to snap in a closed position or to remain firmly closed		X	
Wood toggles	Contain knots, shakes, splits, or splintery surface		X	
Tent pins	Not type specified	X		
Tent poles	Not as specified	X		
Seams and stitching	Open seam on stitch type 301:			
	- for more than 1/4 inch but not more than 1 inch			X
	- for more than 1 inch		X	
	Open seam on stitch type 401:			
	- one row of stitching open for 1 inch or less on tent, liner, or cover			X
	- one row of stitching open for more than 1 inch:			
	- on tent roof or liner		X	
	- on tent wall or cover			X
	- Both rows of stitching open (not necessarily at same location):			
	- on tent roof or liner	X		
	- on tent wall or cover		X	

Source: https://assist.dla.mil -- Downloaded: 202610-17T13:21Z
Check the source to verify that this is the currentversion before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)	NOTE: A seam shall be classified as open when one or more stitches joining a seam are broken or when two or more skipped or run-off stitches occur. On double stitched seams, a seam shall be considered open when either one or both sides of a seam are open.			
	Raw edges caught in stitching:			
	- More than 1 inch, but not more than 3 inches			X
	- more than 3 inches		X	
	Thread breaks:			
	- overstitched less than 1 inch on stitch type 301			X
	- overstitched less than 3 stitches on stitch type 304			X
	- overstitched less than 1 inch on stitch type 401			X
	NOTE: Thread breaks not overstitched shall be classified as open seams.			
	Skipped stitches overstitched less than 1 inch on stitch type 401 or 301; less than 3 stitches on type 304 (when two or more skipped stitches occur)			X
	NOTE: Skipped stitches not overstitched shall be classified as open seams.			
	Needle chew resulting in cut, tear, or hole (see cut, tear, or hole)			
	One or more required rows of stitching omitted (except on boxstitching)	X		

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and Stitching (cont'd)				
Boxstitching	Incomplete:			
	- one row of stitching omitted			X
	- two or more rows of stitching omitted		X	
	Any boxstitching less than specified length by more than 1/8 inch			X
Bartacking	Any bartacking less than specified length by more than 1/8 inch			X
Stitching ends	Overstitched less than 1/2 inch on stitch type 301 (except where ends are held down by other stitching, turned under in a hem, or where stitching is performed automatically)			X
	Secured with less than three tying, overlapping or backstitches when automatic stitching is performed			X
	Secured with less than 1/4 inch of backstitching, overstitching or an increased number of stitches per inch at the end of stitch type 304			X
Seams	Pleated:			
	- on tent roof		X	
	- at tent eave or on tent wall, on liner or cover			X
Seam type	Wrong seam type	X		
Stitch type	Wrong stitch type	X		
Stitch tension	Loose, resulting in an exposed bobbin or top thread, for more than 6 inches		X	
	Tight, as evidenced by puckering on fabric, for more than 6 inches		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and Stitching (cont'd)				
Stitches per inch	Less than minimum specified (except panel joining seams):			
	- one stitch			X
	- two or more stitches		X	
	Less than minimum specified on panel joining seam		X	
	More than maximum specified:			
	- one stitch			X
	- two or more stitches		X	
	NOTE: Variation in the number of stitches per inch, caused by the operator speeding up the machine and pulling the fabric in order to sew over heavy places or heavy seams or in turning corners, shall be classified as follows:			
	a. Within the minor "B" defect classification - no defect			
	b. Within the minor "A" defect classification - minor "B" defect			
Stitching gage	Not as specified		X	
Stitching margin	Larger than specified:			
	- for more than 2 inches but not more than 4 inches in length			X
	- for more than 4 inches in length		X	
	Less than specified:			
	- for more than 2 inches but not more than 4 inches in length			X
	- for more than 4 inches in length		X	
Stitching indicated by "Z" on drawings	Chain portion of stitching shows on outside of tent, cover, or liner		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and Stitching (cont'd)				
Mends, darns, or patches	Repairs not in accordance with Department of the Army field Manual FM 10-16 or not authorized by the contracting officer (see 3.3.6)	X		
Component and assembly	Any component part omitted	X		
	Any component part not fabricated of applicable referenced material	X		
Hems	Constructed with partial turnunder when double turnunder is required		X	
	Twisted or pleated			X
Reinforcements	Improperly applied causing excessive fullness on reinforcement or reinforced part			X
Binding	Improperly or loosely applied, ends not finished as specified			X
* Slide Fasteners	Slider jams or fails to interlock chain	X		
	Any tape improperly assembled causing failure of chain to effect a smooth and secure closure	X		
	Wrong length	X		
	Width not as specified	X		
	Puckering of tape	X		
	Broken or missing scoops	X		
	Thong omitted	X		
	NOTE: The inspector shall pull slide fasteners three or four times to an open and closed position to determine proper function and effectiveness or each fastener			

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

	Examine	Defect	Classification Major	Minor A	Minor B
	Repair kit	Not as specified		X	
	Construction detail				
	Tent line lugs	Any lug stitched through roof only instead of through reinforcement webbing and roof reinforcement	X		
*		Any part of lug single ply construction		X	
		Piece "B" improperly set causing fullness on tent or distortion of corners		X	
	Doorway flaps	Turned-under edge of flap not stitched through door opening tape reinforcement		X	
		Top end of flap not stitched through wall, eave bank, and tape reinforcement		X	
		Facing improperly applied causing fullness on flap			X
	Toggle loops	Ends of loops exposed, i.e. not turned under or not caught in stitching attaching flap to wall			X
*	Toggles	Held in place with single turn of rope around groove or double turn not over hand knotted			X
	Stovepipe shield	Set to roof with oval opening in a horizontal position instead of vertical	X		
		Exposed stitching or needle holes			X
	General	Any other construction detail not performed as specified		X	
	Labels	Omitted, incorrect, illegible, or misplaced:			
		- erection instructions		X	
		- identification			X

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

	Examine	Defect	Classification Major	Minor A	Minor B
	Marking "US" and identification	Omitted, incorrect, illegible, or misplaced			X
	Cleanness	Grease or oil stains			X
*		Thread ends not trimmed to 1/4 inch or less (except in slide fastener area)			X
*		Thread ends not trimmed to 1/4 inch or less in slide fastener area		X	

4.4.4 End item dimension examination.

* 4.4.4.1 Tent with liner and cover. The end item shall be examined for the defects listed in table III. The lot size shall be expressed in units of tents with liners and covers. The sample unit shall be one tent with liner and cover. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 6.5 for major defects, 15 for major and minor A combined defects, and 65 for total (major, minor A and minor B) combined defects.

* 4.4.4.2 Tent liner, only. The end item shall be examined for the applicable defects listed in table III. The lot size shall be expressed in units of liners. The sample unit shall be one liner. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 2.5 for major defects, 10 for major and minor A combined defects, and 40 for total (major, minor A and minor B combined) defects.

* 4.4.4.3 Tent cover, only. The end item shall be examined for the applicable defects listed in table III. The lot size shall be expressed in units of covers. The sample unit shall be one cover. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 4.0 for major defects, 10 for major and minor A combined defects, and 25 for total (major, minor A, and minor B combined) defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE III. End item dimensional defects

Examine	Defect	Classification Major	Minor A	Minor B
Overall dimensions				
Tent and liner	Smaller than specified dimensions less applicable minus tolerance	X		
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			X
Cover	Smaller than specified dimensions less applicable minus tolerance indicated on drawing, but not smaller than specified dimensions less twice the applicable minus tolerance			X
	Smaller than specified dimensions less twice the applicable minus tolerance indicated on drawing		X	
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			X
Component dimensions				
* Webbing, tie tapes	Finished length less than specified by more than 1 inch			X
Reinforcements	Finished dimensions less than specified by more than 1/2 inch			X
	Any spliced piece less than 2 feet in length			X
Snow cloths	Less than specified width by more than 1 inch			X
Toggle loops	Free ends of loop extending less than 3/4 inch beyond edge of flap			X
Ventilator duct opening	Under or over specified dimensions by more than 1/2 inch			X

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE III. End item dimensional defects (Cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Location dimensions (unless otherwise specified)	Not within the specified tolerance		X	
Webbing and tie tapes	Out of specified location:			
	-by more than 1/4 inch but not more than 1/2 inch		X	
	-by more than 1/2 inch	X		
	Distance between splices on all reinforced places on tent and liner less than 5 feet			X

4.4.5 End item testing. Tent samples shall be tested as specified in 4.5.1 for compliance with 3.3.7. The lot shall consist of all completely fabricated tents offered for inspection at one time. The sample unit shall be one completely fabricated tent. The inspection level shall be S-3. Failure in any area shall be cause for rejection of the lot.

* 4.4.6 Packaging examination. The fully packaged end items shall be examined for the defects listed below. The lot size shall be expressed in units of shipping containers. The sample unit shall be one shipping container fully packaged. The inspection level shall be S-2 and the AQL, expressed in terms of defects per hundred units, shall be 2.5.

Examine	Defect
Marking (exterior and interior)	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application.
Materials	Any component missing, damaged, or not as specified.
Workmanship	Inadequate application of components, such as: incomplete sealing or closure of flap, improper taping, loose strapping or inadequate stapling. Bulged or distorted container.
Content	Number per container is more or less than required.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

4.5 Methods of inspection.

* 4.5.1 Wicking of sewing thread (cup test). The tent shall be tested in each of three areas as follows: at the peak, ridge or joining seam abutting the peaks or ridge; at an intersection of a horizontal and vertical seam such as at an intersection of a side wall and roof; and on a roof panel seam. Suspend the seamed section of the test fabric in the center of a 6 ± 1/8 inch diameter hoop and form a depression with the seamed fabric in the hoop to a depth of 1 ± 1/4 inch. Slowly pour 500 mL of water at 77°F ± 4°F into the cupped area (depression) and observe the under surface of the fabric for water penetration. Any wicking of water in any test area along the sewing thread, identified by a discoloration or darkening of the thread within 5 minutes after water is poured, shall constitute a test failure. Water leakage through the needle holes or between the plies of the lapped seamed fabric shall not be considered a failure.

5. PACKAGING

5.1 Preservation. Preservation shall be level A or Commercial as specified (see 6.2).

5.1.1 Level A.

5.1.1.1 Tent, with liner and cover. Each tent, with the liner attached by means of the toggles, shall be laid flat. The sock lines shall be threaded through the toggles and the door slide fastener closed. The six panels (5 sides and 1 front) of the tent shall then be folded in accordion pleat fashion extending from the apex of the roof to the bottom of the snow cloth. All lines shall be coiled or laid extended between the folds and on top of the folded panels. The snow cloth shall be folded over on top of the tent and the roof peak then folded down to the snow cloth edge. The tent ends and sides shall be folded toward the middle to form a compact bundle. The completely folded tent shall be placed within its cover and the cover closed with the securing straps.

* 5.1.1.1.1 Tent, with liner, tent pole, tent pins, and cover. Each tent shall be folded as specified in 5.1.1.1. Twenty tent pins (see 3.2.24) and one tent pole (see 3.2.25) shall be inserted into the pocket in the tent cover. Prior to insertion, the tent pole shall be reduced to the shortest length and the tent pins shall be grouped into units of four. Each unit of four pins shall be neatly and completely wrapped in 50 pound basis weight kraft paper conforming to A-A-203 and secured with minimum 1 inch wide tape conforming to A-A-883. The completely folded tent shall be placed within its cover and the cover closed with the securing straps.

Source: https://assist.dla.mil -- Downloaded: 202610-17T13:21Z
Check the source to verify that this is the currentversion before use.

5.1.1.2 Components.

5.1.1.2.1 Liner, tent. Each tent liner, with door slide fastener closed, shall be laid out flat. The six panels (5 sides and 1 front) of the liner shall be folded in accordion pleat fashion. The slide fastener, stovepipe and ventilator openings shall be within the folds. The roof peak shall be folded down to the bottom edge of the liner. The tent liner shall then be folded into a compact bundle measuring approximately 30 by 15 inches.

5.1.1.2.2 Cover, tent. Each tent cover shall be folded, with straps placed between the folds, to measure approximately 14-1/2 by 14-1/2 inches. Five folded tent covers shall be neatly stacked in a bundle and cross tied with cotton tape or twine.

5.1.2 Commercial. Tents with liner and cover or tents with liner or tent pole, tent pins and cover or tent liners or tent covers shall be preserved in accordance with ASTM D 3951.

5.2 Packing. Packing shall be level A, B or Commercial as specified (see 6.2).

5.2.1 Level A packing. Two tents with liners and covers or two tents with liners, tent poles, tent pins and covers; five tent liners; or thirty tent covers, preserved as specified in 5.1, shall be packed in a close-fitting plywood box conforming to overseas type, style A of PPP-B-601. Each box shall be closed and strapped with flat steel strapping in accordance with the box specification.

5.2.2 Level B packing. Two tents with liners and covers or two tents with liners, tent poles, tent pins and covers or five tent liners, or thirty tent covers, preserved as specified in 5.1, shall be wrapped in cotton osnaburg cloth conforming to class 2 of CCC-C-429, or burlap cloth conforming to class 3 of CCC-C-467. The wrapping shall be securely handsewn with type I or II, 16 ply cotton twine conforming to T-T-871, or type I, size No. 2 jute twine conforming to T-T-911, with approximately one stitch to the inch and every third stitch knotted, or alternatively, the seams of the wrap may be machine-sewn. A minimum of 5 inches of wrapping material or tubing shall be gathered together on each of the four corners and securely sewn into ears for handles. The polyester thread used to manufacture the tent may be used for effecting the machine sewn closure of the wrapping or tubing.

5.2.3 Commercial packing. Tents with liner and cover or tents with liner, tent pole, tent pins, and cover or tent liners, or tent covers, preserved as specified in 5.1, shall be packed in accordance with ASTM D 3951.

* 5.3 Marking. In addition to any special marking required by the contract or purchase order, shipping containers and cloth covered bundles shall be marked in accordance with MIL-STD-129 or ASTM D 3951, as applicable.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

5.3.1 Special marking. The following shall be stenciled or imprinted on each cloth covered bundle or box of complete tents in characters not less than 3/4 inch high:

"SEE ERECTION INSTRUCTIONS SEWED
TO INSIDE OF TENT COVER"

6. NOTES

6.1 Intended use. The tent with liner is used to provide shelter for troops operating in extremely cold-dry or cold-wet areas. The tent will normally accommodate five men and their duffel.

6.2 Ordering data. Acquisition documents should specify the following:

a. Title, number, and date of this document.
b. When a first article is required (see 3.1, 4.3, and 6.5).
c. Selection of applicable levels of preservation and packing (see 5.1 and and 5.2) and which of the following items are to be purchased:
   1. Tent with liner and cover, or
   2. Tent with liner, tent poles, tent pins and cover, or
   3. Liner only, or
   4. Cover only
d. When pins and poles are required (see 3.2.24 and 3.2.25).

6.3 Erection components. The following components are required for erection of the tent:

1 each - Pole, Tent, Telescopic, Adjustable 5 feet to 9 feet, Magnesium
For erection on hard ground, unfrozen
20 each - Pin, Tent, Aluminum, 9 inches

6.4 Seam retreatment. A satisfactory method of applying the textile compound for the repair of leaking seams is as follows:

a. A Suitable volume of textile compound conforming to type I, class 1, shade Olive Drab of TT-P-595 shall be thoroughly stirred and diluted with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir the mixture again before use.

b. Prior to application of the compound, the tent must be dry. Special attention must be taken to insure adequate ventilation and that proper fire preventative measures are taken since the compound is flammable.

c. Two coats of the compound shall then be applied to the seams (on the outside of the tent only). A four-inch wide stiff brush is recommended for use. The first coat shall be air dried for a minimum of four hours prior to application of the second coat. Elapsed time between coats may

Source: https://assist.dla.mil -- Downloaded: 202610-17T13:21Z
Check the source to verify that this is the currentversion before use.

be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, a second coat may be applied as soon as the first coat is dry to the touch. After the application of the second coat, the treated tent shall be allowed to air dry for a period of at least 24 hours.

6.4.1 Seams to be treated. Seams which have failed the test specified in 4.5.1 shall be treated as follows:

a. Failure at roof panel lap seams - treat all roof panel lap seams.

b. Failure at peak reinforcement - paint all peak reinforcement stitching.

c. Failure at eave - paint all stitching at eave and webbing reinforced roof joining seams.

* 6.5 First article. When a first article is required, it shall be inspected and approved under the appropriate provisions of FAR 52.209. The first article should be a preproduction sample. The contracting officer should specify the appropriate type of first article and the number of units to be furnished. The contracting officer should include specific instructions in all acquisition instruments regarding arrangements for selection, inspection, and approval of the first article.

6.6 Recycled material. It is encouraged that recycled material be used when practical as long as it meets the requirements of this document (see 3.2).

6.7 International standardization agreements. Certain provisions of this document are the subject of international standardization agreement as cited in NATO, STANAG No. 2882, relative to camouflage requirements for tents, shelters and subsidiary components. When amendment, revision, or cancellation of this document is proposed which will affect or violate the international agreement concerned, the preparing activity will take appropriate reconciliation action through international standardization channels including departmental standardization offices, if required.

* 6.8 Subject term (key word) listing.

Shelter
Tent, Hexagonal

6.9 Changes from previous issue. The margins of this document are marked with an asterisk (*) to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content, irrespective of the marginal notations and relationship to the previous issue.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

Custodians:

Army - GL
Navy - NU
Air Force - 99

Review activities:

Army - MD
Air Force - 82
DLA - CT

User activities:

Navy - MC
Air Force - 45

Preparing Activity:

Army - GL

Project No. 8340-0508

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

INSTRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in submitting comments and suggestions for improvements. All users of military standardization documents are invited to provide suggestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and mailed. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was too rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the problems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an acknowledgement will be mailed to you within 30 days to let you know that your comments were received and are being considered.

NOTE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document*(s)* or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

DEPARTMENT OF THE ARMY

US ARMY NATICK RESEARCH
and DEVELOPMENT CENTER
ATTN: STRNC-ES
Natick, MA 01760-5014

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

STRNC-ES

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.
POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
US Army Natick Research
and Development Center
ATTN: STRNC-ES
Natick, MA 01760-5014

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATE

Source: https://assist.dla.mil -- Downloaded: 202610-17T13:21Z
Check the source to verify that this is the currentversion before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-T-10035K	Tent, Hexagonal, Lightweight, M-1950

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ USER
	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

DD FORM 82 MAR 1426 PREVIOUS EDITION IS OBSOLETE.

NATICK OP, 20 Nov 84

Source: https://assist.dla.mil -- Downloaded: 202610-17T13:21Z
Check the source to verify that this is the current version before use.