INCH-POUND

MIL-DTL-10035L
01 January 2001
SUPERSEDING
MIL-T-10035K
25 March 1988

DETAILED SPECIFICATION

TENT, HEXAGONAL, LIGHTWEIGHT, M-1950

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers a pole-supported pyramidal tent with a fire-resistant treated liner. A cover is provided to protect the tent and liner.

2. APPLICABLE DOCUMENTS

* 2.1 General. The documents listed in this section are specified in sections 3 and 4 of this specification. This section does not include documents cited in other sections of this specification or recommended for additional information or as examples. While every effort has been made to ensure the completeness of this list, document users are cautioned that they must meet all specified requirements of the documents cited in sections 3 and 4 of this specification, whether or not they are listed in this section.

2.2 Government documents.

Beneficial comments (recommendations, additions, deletions, clarifications) and any pertinent data which may be of use in improving this document should be addressed to: Defense Supply Center Philadelphia, Clothing and Textiles Directorate, Attn: DSCP-CNR, 700 Robbins Avenue, Bldg 6, Area D, Philadelphia, PA 19111-5096 by using the Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A FSC 8340

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

* 2.2.1 Specifications, standards, and handbooks. The following specifications, standards, and handbooks form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents are those listed in the issue of the Department of Defense Index Specifications and Standards (DoDISS) and supplement thereto, cited in the solicitation (see 6.2).

SPECIFICATIONS

FEDERAL

A-A-55622	- Cord, Cotton, General and Special Purpose, Sash and Venetian Blind
V-F-106	- Fasteners, Slide, Interlocking
V-T-285	- Thread, Polyester
TT-P-595	- Preservative Coating, Canvas
DDD-L-20	- Label: for Clothing, Equipage, and Tentage (General Use)
GGG-N-202	- Needle, Sailmaker's

MILITARY

MIL-F-495	- Finish, Chemical, Black, for Copper Alloys
MIL-C-496	- Clip, End, Strap
MIL-P-501	- Pins, Tent, Metal
MIL-W-530	- Webbing, Textile, Cotton, General Purpose, Natural or in Colors
MIL-L-1709	- Lines, Tent
MIL-DTL-1716	- Poles, Tent, Telescopic, Adjustable 5 Feet to 9 Feet, Magnesium
MIL-S-1734	- Slips, Tent Line
MIL-R-3390	- Rings, Dee
MIL-C-3395	- Cloth, Netting, Nylon or Polyester
MIL-C-10859	- Cloth, Oxford, Cotton (Permeable)
MIL-F-10884	- Fasteners, Snap
MIL-L-11075	- Loops, Strap Fastener
MIL-C-12095	- Cloth, Wind-Resistant Sateen, Cotton; Fire and Water Resistant
MIL-DTL-43002	- Shield, Stovepipe, Tent, Nonmetalic
MIL-C-43256	- Cord, Polyester, Solid Braid
MIL-T-43566	- Tape, Textile, Cotton or Polyester, General Purpose, Natural or in Colors
MIL-C-43627	- Cloth, Duck, Cotton, Plied Yarns, Fire, Water, Weather and Mildew Resistant Treated, Lightdry Finish
MIL-W-44049	- Webbing, Textile and Tape, Textile, Polypropylene, General Purpose, Natural or in Colors

*(Unless otherwise indicated, copies of federal and military specifications, standards, and handbooks are available from the Defense Automated Printing Service, Bldg 4D (DPM-DODSSP), 700 Robbins Avenue, Philadelphia, PA 19111-5094.)

* 2.2.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this document to the extent specified herein. Unless otherwise specified, the issues are those cited in the solicitation.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

DRAWINGS

U.S. ARMY BIOLOGICAL AND CHEMICAL COMMAND

4-1-206	- Rings, Connecting, Round
5-4-221	- Tent, Hexagonal, Lightweight, M-1950; Illustration and List of Parts
5-4-222	- Assembly, View and Details
5-4-223	- Views and Details
5-4-224	- Front Details
5-4-225	- Assembled Front and Details
5-4-226	- Side
5-4-227	- Ventilator
5-4-229	- Liner Assembly
5-4-230	- Liner Details
5-4-231	- Cover
5-4-580	- Repair Kit
5-4-1052	- Erection Instructions

(Copies of drawings are available from the U. S. Army Biological and Chemical Command, ATTN: SSCNC-EMSS, NATICK, MA 01760-5057.)

* 2.3 Non-Government Publications. The following documents form a part of this document to the extent specified herein. Unless otherwise specified, the issues of the documents which are DoD adopted are those listed in the issue of the DoDISS cited in the solicitation. Unless otherwise specified, the issues of documents not listed in the DoDISS are the issues of the documents cited in the solicitation (see 6.2).

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

A47	- Standard Specification for Ferritic Malleable Iron Castings
A818	- Standard Specification for Coppered Carbon Steel Wire
A853	- Standard Specification for Steel Wire, Carbon, for General Use
B134	- Standard Specification for Brass Wire
B159	- Standard Specification for Phosphor Bronze Wire
B159M	- Standard Specification for Phosphor Bronze Wire (Metric)
B206	- Standard Specification for Copper-Nickel-Zinc Alloy (Nickel Silver) Wire and Copper
B206M	- Standard Specification for Copper-Nickel-Zinc Alloy (Nickel Silver) Wire and Copper
D6193	- Stitches, Seams and Sewing
D2016	- Standard Test Method for Determination of Moisture Content Of Particulate Wood Fuels

(Copies can be obtained from the American Society for Testing and Materials, 100 Barr Harbor drive, West Conshohocken, PA 19428.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

NAVAL LOGISTICS LIBRARY (NLL) NASM 16491
NATIONAL AEROSPACE STANDARDS COMMITTEE (NA/NAS)

NASM16491 - Grommet, Metallic, General Specification For

(Copies may be obtained from the Naval Logistics Library, 5450 Carlisle Pike, Mechanicsburg, PA. (717) 813-8387).

AMERICAN NATIONAL STANDARDS INSTITUTE (ANSI) ANSI / ASQC Z1.4
SAMPLING PROCEDURES AND TABLES FOR INSPECTION BY ATTRIBUTES

(Applications for copies should be obtained from: American Society for Quality Control, 611 East Wisconsin Avenue, Milwaukee, WI 53202).

* 2.4 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification takes precedence. Nothing in this specification, however, supersedes applicable laws and regulations unless a specific exemption has been obtained.

3. **REQUIREMENTS**

* 3.1 First article. When specified (see 6.2), a sample shall be subjected to first article inspection (see 4.3).

* 3.2 Materials and components. Materials and components shall be as specified herein and in referenced documents. Materials not definitely specified shall be of the quality normally used by the manufacturer provided the complete item complies with all provisions of this document. It is encouraged that recycled materials be used when practical as long as it meets the requirements of this document.

* 3.2.1 Cloth, wind- resistant sateen, cotton. The cloth for the tent shall be dyed Camouflage Green 483 and shall conform to MIL-C-12095.

* 3.2.2 Cloth, cotton duck. The cloth for the peak reinforcement shall conform to MIL-C-43627 and the color shall be Camouflage Green 483. Requirements for colorfastness to weathering shall not apply for peak reinforcement.

3.2.3 Cloth, cotton, oxford. The cloth for the liner shall conform to type I, class 2 of MIL-C-10859.

3.2.4 Cloth, netting, nylon. The nylon netting for the ventilator opening shall conform to type I or II of MIL-C-3395.

3.2.5 Shield, stovepipe, tent. The flexible, silicone rubber coated stovepipe shield shall conform to MIL-DTL-43002.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

3.2.6 Tape textile, cotton. The tape shall be dyed Camouflage Green 483 and shall conform to type I, class 4, ½ inch, ¾ inch, 1 inch and 2 inch width of MIL- T-43566. Alternatively, the tape shall be polypropylene conforming to type I, class 3 or 4, ¾ inch and 2 inch of MIL-W-44049 for covers and liners only.

3.2.7 Webbing, textile, cotton. The webbing shall be dyed Camouflage Green 483 and shall conform to type IIb, class 4, 1inch width and type III, class 4, 5/8 inch and 1-1/2 inch width of MIL-W-530. Alternatively, the webbing shall be polypropylene conforming to type IIb, 1 inch width, class 4 of MIL-W-44049 for covers.

3.2.8 Thread, polyester.

3.2.8.1 Tent and cover. The thread shall conform to type I, class 1, sub-class B, Camouflage Green 483 of V-T-285. The dyed thread shall show fastness to weathering equal to or better than the standard shade sample. When no standard shade sample is available, the dyed thread shall show good fastness to weathering.

3.2.8.2 Liner. The thread shall be color natural and shall conform to type I or II, Class 1 of V-T-285.

3.2.8.3 Sizes. Thread sizes shall be as follows:

For all stitching on tent except zig-zag stitching, bartacking and stitching indicated by "Z" on drawings	- Size F for needle and bobbin
For zig-zag stitching and bartacking	- Size E for needle and bobbin
For stitching on tent indicated by "Z" on drawings	- Size F for needle, size E for looper
For all stitching on liner, except stitching indicated by "Z" on drawings	- Size E for needle and bobbin
For stitching on liner indicated by "Z" on drawings	- Size E for needle, size B for looper

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

For stitching on cover indicated by "Z" on drawing	- Size FF for needle, size F for looper

3.2.9 Lines, tent. The tent lines shall conform to class D or class G of MIL-L-1709 in the types specified on the applicable drawings.

3.2.10 Stiffener, cord. The cord for the drip cap stiffener shall conform to type I, class 3, size No. 7 of T-C-571.

3.2.11 Toggle loops. The cord for the toggle loops shall conform to polyester, 1/8 inch diameter, Camouflage Green 483 of MIL-C- 43256.

3.2.12 Toggles, wood. The wood toggles shall be of the design and dimensions shown on Drawing 5-4-225. The wood for the toggles shall be straight-grained, sound and smooth lumber, kiln dried to not more than 15 percent moisture content when tested as specified in 4.3.1.1. The toggles shall be free from knots, shakes, checks, splits, or splintery surface. Any of the following woods may be used:

Hickory	Beech	Pecan	Maple, hard
Red or White Oak	Birch	Rock Elm	Ash

3.2.13 Toggles, metal. The metal toggles shall be of the design and dimensions shown on Drawing 5-4-223 and shall be fabricated from copper alloy wire conforming to alloy number 270, half hard temper in accordance with ASTM-B134, 159, 159M, 206 and 206M. The toggles shall be given a black chemical finish conforming to MIL-F-495.

3.2.14 Slip, tent line. The tent line slips shall conform to type II of MIL-S-1734.

3.2.15 Fasteners, slide, interlocking. The slide fasteners shall conform to type III, style I, size H, wire stirrup pulls of V-F-106. Slide fastener chain shall be fabricated of brass or polyester coil. The slider for the brass chain shall be brass and the slider for the polyester coil shall be die cast zinc alloy. The slide fastener tape shall be dyed to match Camouflage Green 483 and be water repellent and mildew-resistant. (Tapes made of 100 percent polyester need not be tested for mildew resistance.) The color of the tape after treatment will be considered acceptable. The tape shall show good fastness to weathering. Alternatively, the slide fastener chain shall be polyester continuous monofilament in a ladder or coil type configuration. Color of the chain shall be Camouflage Green 483 or natural finish brass and the sliders shall be brass.

3.2.16 Ring dee. The dee ring shall conform to class 1 or 2, configuration K, size 1 inch by ¾ inch of MIL-R-3390.

* 3.2.17 Ring, connecting. The connecting rings shall be of steel wire or cast malleable iron, black enamel, phosphate treated, zinc plate finished, size 2 or 5 in accordance with Drawing 4-1-206.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

* 3.2.17.1 Steel wire. The steel wire shall conform to steel numbers 1006 to 1020 in accordance with ASTM A853, ASTM A818, ASTM A641 or ASTM A809.

* 3.2.17.2 Steel tube. The steel tube shall be seamless, round in accordance with ASTM A513 and ASTM A519.

* 3.2.17.3 Malleable iron. The malleable iron shall be grade I (35018) – Black, ungalvanized or grade II (32510)- Black, ungalvanized in accordance with ASTM A47. The first three digits of the grade designations indicate the minimum yield strength (x 100 p.s.i.). The last two digits indicate the minimum elongation (percent in 2 inches).

3.2.18 Grommet, metallic. The Nos. 3 and 5 grommets shall conform to type III, class 3 and No.2 grommets shall conform to type II, class 3 of NASM 16491.

3.2.19 Fasteners, snap. The snap fasteners shall conform to style 2, finish 2, button 24 line size, size 1 and eyelet size 1 of MIL-F-10884.

3.2.20 Clip, end. The end clips shall conform to type I, class 1 or 2, size 1 inch of MIL-C-496.

3.2.21 Loops, strap fastener. The strap fastener loops shall conform to type III, style B of MIL-L-11075.

3.2.22 Snaphook. The snaphooks shall conform to MIL-S-43770/10 or equal.

3.2.23 Pins, tent, metal. When required (see 6.2), the tent pins shall be type I, conforming to MIL-P-501.

3.2.24 Pole, tent, telescope. When required (see 6.2), the magnesium, adjustable telescopic tent poles shall conform to MIL-P-1716.

3.2.25 Kit, repair. The repair kit bag shall be fabricated from the material specified in 3.2.1 and of the design and dimensions shown on Drawing 5-4-580. The snap fastener on the pocket shall be as specified in 3.2.19. The bag containing the repair kit components, shall be securely tied and placed in the repair kit pocket of each completed tent.

3.2.25.1 Components, repair. Components for each kit shall consist of the items listed in table I.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE I. Repair kit components

Item	Quantity	Specification or reference
Cloth, wind-resistant sateen, cotton	½ yard full width	3.2.1
Thread, polyester, type I, class 1, sub-class B, size FF, shade S-1	1 spool (2-ounce)	3.2.8
Needle, sailmaker's Size 16	3	GGG-N-202
Pusher, needle	1	Drawing 5-4-580 and wood specified in 3.2.12
Sleeve, lock retaining	2	Drawing 5-4-1075 Item 10 MIL-P-1716
Lock, upper	1	Drawing 5-4-1075 Item 7 MIL-P-1716
Lock, lower	1	Drawing 5-4-1075 Item 8 MIL-P-1716

3.3 Construction. The construction shall conform to the drawings listed in Section 2 and as specified herein.

3.3.1 Stitching, machine.

3.3.1.1 Types of stitching. All stitch types, except bartacking, shall conform to ASTM-D6193 as follows:

For tent, screens and cover:

For all stitching except stitching indicated by "Z" on drawings	- Type 301, 5 to 7 stitches per inch
For stitching indicated by "Z" on drawings and for attachments of slide fasteners	- Type 401, 5 to 7 stitches per inch. Chain portion of stitching shall not appear on outside of tent, screen, or cover.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

For zig-zag stitching	- Type 304, 10 to 16 stitches per inch

For liner:

For all stitching, except stitching indicated by "Z" on drawing	- Type 301, 6 to 8 stitches per inch
For stitching indicated by "Z" on drawing and for attachments of slide fasteners	- Type 401, 6 to 8 stitches per inch. Chain portion of stitching shall not appear on outside of liner.
For bartacking	- Bartack, 3/8 ± 1/16 inch long with 1/8 ± 1/32 inch bight and shall contain 28 stitches.

3.3.1.2 Type 301 stitching. Ends of all stitching shall be backstitched or overstitched ½ inch minimum except when caught in other stitching or turned under in the hem. Thread tension shall be maintained so that there will be no loose stitching resulting in puckering of material sewn. The lock shall be imbedded in the material sewn.

3.3.1.2.1 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of one inch behind the end of the stitching. 1/

b. Thread breaks, two or more consecutively skipped stitches or run-off stitches noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of one inch before the defective area (1/2 inch on Box, Box and Cross and W-W stitching) and continue a minimum of one inch beyond the defective area onto the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching, without damaging the materials, and restitching in the required manner. 1/

1/ When making the above repairs, the ends of the stitching are not required to be backstitched.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

3.3.1.3 Type 401 stitching. Thread tension shall be maintained so that there will be no loose stitching. Both ends of all seams or stitching produced with a 401 stitch type, when not turned under in a hem or held down by other stitching, shall have a ½ to ¾ inch chain extending beyond each end. The looper (under thread) shall always be on the inside of the tent or cover. All repairs shall be made in accordance with 3.3.1.2.1a or 3.3.1.2.1b. Repairs may be made using a 301 stitch type.

3.3.1.4 Type 304 stitching. For type 304 stitching, thread tension shall be maintained so that there will be no loose or excessively tight stitching. Repairs shall be in accordance with 3.3.1.2.1a or 3.3.1.2.1b except that the stitching shall over stitch the defective stitching area a minimum of three stitches onto the existing stitching. At least ¼ inch of backstitching,
overstitching or an increased number of stitches per inch shall be used to secure the ends of the stitching.

3.3.1.5 Automatic stitching. Automatic stitching machines may be used to perform any of the required stitch patterns provided the requirements of the stitch pattern, stitches per inch, size and type of thread are met, and at least three or more tying, overlapping or backstitches are used to secure the ends of the stitching.

3.3.1.6 Threads ends. All thread ends that are visible on the finished item shall be trimmed to a length of not more than ¼ inch.

3.3.1.7 Bartacking. Bartacking shall be free of thread breaks or loose stitching.

3.3.1.8 Lubrication of thread. The addition of any lubricant to the polyester sewing thread prior to or during the sewing operation is prohibited.

3.3.1.9 Stitching margins. Unless otherwise specified, all stitch margins shall be 1/8,
+1/16 -0 inch.

3.3.2 Attachment of wood toggles. Wood toggles shall be attached as shown on
Drawing 5-4-225.

3.3.3 Setting of grommets. Holes punched to receive the grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the materials. Roll of the clinched grommet shall not contain splits.

3.3.4 Setting of snap fasteners. If a hole is punched before inserting the male or female part of the fastener, it shall be smaller than the outside diameter of the fastener tube so that the tube must be forced through the hole. The fasteners shall be securely clinched. Roll of the clinched eyelet of the assembled fastener component shall not contain more that three scores (splits).

3.3.5 Setting of end clips. The webbing shall be inserted the full depth of the clips. The clips shall be securely attached without cutting the webbing and the webbing shall lie flat at the point of entry.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

3.3.6 Repairs. Any necessary repairs shall be effected in accordance with Department of the Army Field Manual FM 10-16 except that hand-sewn patches, or cemented patches other than as specified herein, will not be acceptable. Cemented patches on holes, cuts or tears not more than 1 inch in diameter or length, using an approved cement shall be permitted. A maximum of three cemented patches per tent will be allowed without prior authorization. Repairs required as a result of failure to meet the requirements of the cup test and when authorized by the contracting officer shall be performed by treating with a compound conforming to type I, class 1, shade Olive Drab of TT-P-595 prior to retesting (see 6.4).

3.3.7 Wicking of sewing thread (cup test). There shall be no dripping of water through the tent stitching when the tent is tested as specified in 4.5.1. The cup test is intended to ensure that non-wicking thread has been utilized and that no lubrication has been added to the polyester thread prior to or during the sewing operation.

3.3.8 Splicing of cloth. There shall be no splicing of roof, wall or tent cover panels. Splicing of reinforcements and snow cloth sections will be permitted and, if performed, shall conform to the following requirements:

a. Eight feet or less in length – One splice permitted;
   More than 8 feet but not more than 12 feet in length – Two splices permitted.
   More than 12 feet in length – Three splices permitted.

b. The shortest length of any spliced piece shall be not less than 2 feet.

c. Pieces shall be joined as shown on Drawing 5-4-226, section C-C.

3.3.9 Splicing of webbing. If required, the webbing shall be spliced as shown on Drawing 5-4-225. A maximum of one splice per gore will be permitted. The minimum distance between splices in the remainder of the tent shall be five feet.

3.3.10 Attachment of slide fasteners. Care shall be exercised to maintain specified distances between edges of fabric attached to slide fastener tape so that there will be no interference with the operation of the slider. The length of the slide fastener shall be such that after the slide fastener is sewed on, the tape shall not be puckered and the slider shall operate freely.

3.3.11 Replacement of defective components. During the spreading, cutting and manufacturing process, components of the tent having material defects or damages that are classified as defects in 4.3.2 or 4.3.3 shall be removed from production and replaced with non-defective and properly matched components.

3.3.12 Fusing of ends of synthetic webbing and tape. All ends of synthetic webbing, and tape shall be fused. The apparatus used to fuse the ends shall be capable of providing sufficient heat to provide a

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

smooth edge and with the cut ends of the yarns all fused together. Fusing of the ends shall be accomplished prior to being assembled for stitching.

3.4 Marking. All marking and labels shall conform to DDD-L-20.

3.4.1 Special marking. The application of the letters "US" on the tent and cover, the instructions on the door and the nomenclature on the cover shall conform to type IV, class 9 in the size characters and in the locations shown on the drawings. Class 9 markings shall be clearly legible after subjection to accelerated weathering.

3.4.2 Identification label. The identification labels shall be stitched to the tent, liner and cover in the locations shown on the drawings and shall conform to type VI, class 6 and shall be 3-1/2 inches by 5-1/2 inches minimum and a blank space of at least 1-1/4 inches shall be provided on the bottom of the label for the Department of Defense inspector's stamp.

3.4.3 Erection instruction label. Instruction labels shall conform to type VI, class 7 and shall be stitched to the tent, liner and cover in the locations shown on the drawings. The label shall be a proportionate copy of Drawing 5-4-1052 as reproduced from a glassy print of the drawing furnished by the contracting officer. The size of the label shall be borderline to borderline, 15+1/4 inches in the longer dimension with a minimum ½ inch margin outside of the borderline on all sides.

3.5 Workmanship. The end item shall conform to the quality of product established by this specification.

* 4. VERIFICATION

* 4.1 Classification of inspection. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.2).
b. Conformance inspection (see 4.3).

* 4.2 First article inspection. When a first article is required (see 3.1 and 6.2) it shall be examined for the defects specified in 4.4.2. Any nonconformance shall be cause for rejection of the first article.

* 4.3 Conformance inspection. Sampling for inspection shall be as specified in the contract or purchase order.

* 4.3.1 Component and material inspection. Components and materials shall be inspected in accordance with all the requirements of referenced documents unless otherwise excluded, amended, modified or qualified in this specification or applicable purchase document.

* 4.3.1.1 Wood toggle moisture content testing. In addition to the quality assurance provisions of the subsidiary documents, the wood toggles shall be tested for conformance to the moisture content requirements in 3.2.12. The moisture content shall be determined in accordance with the oven-drying or the electrical meter method reference ASTM D 2016. The results shall be reported to the nearest 0.1 percent for each toggle tested. The lot size shall be expressed in toggles. The sample unit shall be one toggle.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

4.3.2 In-process inspection. Inspection shall be made of the following operations or assemblies to establish conformance to specified requirements. Whenever nonconformance is noted, correction shall be made to the items affected and to the operation. Items which cannot be corrected shall be removed from production. The inspection level shall be S-1.

a. Holes punched to receive grommets are in compliance with 3.3.3.

b. There shall be no lubrication of polyester thread prior to or during sewing operations in compliance with 3.3.1.8.

c. Holes punched to receive male or female parts of snap fasteners are in compliance with 3.3.4.

4.3.3 End item visual examination.

4.3.3.1 Tent with liner and cover. The end item shall be in an erected position so that both the inside and outside of the tent can be examined, along with its cover and liner, for defects listed in table II. The lot size shall be expressed in units of tents with liners and covers. The sample unit shall be one tent with liner and cover. The inspection level shall be I.

4.3.3.2 Tent liner, only. The end item shall be examined for the applicable defects listed in table II. The lot size shall be expressed in units of liners. The sample unit shall be one liner and the inspection level shall be I.

4.3.3.3 Tent cover, only. The end item shall be examined for the applicable defects listed in table II. The lot size shall be expressed in units of covers. The sample unit shall be one cover. The inspection level shall be I.

TABLE II. End item visual defects

Examine	Defect	Classification		
		Major	Minor	
			A	B
Fabric	Cut, tear, or hole (including exposed drill hole) greater than 1/8 inch in length or diameter:			
	- on tent	101		
	- on cover or snow cloth		201	
	Cut , tear, or hole (including exposed drill hole) 1/8 inch or less in length or diameter:			
	- more than 20:			
	- on tent	102		
	- on cover or snow cloth		202	
	- more than 10 but not more than 20:			
	- on tent		203	
	- on cover or snow cloth			301
	- more than 5 but not more than 10:			
	- on tent			302
Fabric, liner	Cut, tear, hole (including exposed drill hole):			
	- greater than ¼ inch in length or diameter on liner	103		

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
	- greater than 1/8 inch but not greater than ¼ inch in length or diameter on liner		204	
	- more than 5 holes 1/8 inch or less in length or diameter on liner			303
	Broken or missing yarns; multiple floats clearly visible at normal inspection distance (approximately 3 feet)		205	
Cloth netting	Cut or tear:			
	- more than 2 inches in length	104		
	- more than ¼ inch but not more than 2 inches in length		206	
	- ¼ inch or less in length			304
Tape and webbing	Frayed or scalloped edge		207	
Splicing of webbing	Splicing (when necessary) not as indicated on Drawing 5-4-225;		208	
	More than one splice per gore on seams joining panels of tent or liner		209	
Cloth splicing	Splice in roof, wall, or tent cover panels	105		
	Number of splices per reinforcement or snow cloth section more than specified (see 3.3.8)		210	
	Spliced pieces not joined as shown on Drawing 5-4-226			305
Cord components	Cut or abrasion		211	
	Eave lines, corner lines, or foot-stops improperly knotted; free ends of lines not finished as specified			306
Hardware	Broken	106		
	Malformed:			
	- fails to perform intended function	107		
	- but will perform intended function		212	
	Corroded area			307
	Burr or sharp edge which may cause injury in handling or damage to fabric	108		
Grommets	Improperly set; two or more teeth exposed (except where grommet is set as specified but is in an area of			

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Grommets (cont'd)	unequal thickness which prevents uniform clinching)			308
	Clinched loosely allowing grommet to rotate in a hole			309
	Clinched excessively tight cutting fabric	109		
	Insecurely clinched, i.e. grommet or washer may become disengaged	110		
	Roll of a grommet contains one or more splits			310
End clips	Improperly clinched, i.e. webbing not flat at point of entrance into clip			311
	Clinched excessively tight cutting webbing or loosely clinched, i.e. clip becomes disengaged from webbing		213	
Snap fasteners	Female components used in location where male components are required; fasteners fail to snap is a closed position or to remain firmly closed		214	
Wood toggles	Contain knots, shakes, splits, or splintery surface		215	
Tent pins	Not as specified	111		
Tent poles	Not type specified	112		
Seams and stitching	Open seam on stitch type 301:			
	- for more than ¼ inch but not more than 1 inch			312
	- for more than 1 inch		216	
	open seam on stitch type 401:			
	- one row of stitching open for 1 inch or less on tent, liner, or cover			313
	- one row of stitching open for more than 1 inch:			

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and Stitching (cont'd)	- on tent roof or liner		217	
	- on tent wall or cover			314
	- Both rows of stitching open (not necessarily at same location):			
	- on tent roof or liner	113		
	- on tent wall or cover		218	
	NOTE: A seam shall be classified as open when one or more stitches joining a seam are broken or when two or more skipped or run-off stitches occur. on double stitched seams, a seam shall be considered open when either one or both sides of a seam are open.			
	Raw edges caught in stitching:			
	- more than 1 inch, but not more than 3 inches			315
	-more than 3 inches		219	
	Thread breaks:			
	- overstitched less than 1 inch on stitch type 301			316
	- overstitched less than 3 stitches on stitch type 304			317
	- overstitched less than 1 inch on stitch type 401			318
	NOTE: Thread breaks not overstitched shall be classified as open seams.			
	Skipped stitches overstitched less than 1 inch on stitch type 401 or 301; less than 3 stitches on type 304 (when two or more skipped stitches occur)			319
	NOTE: Skipped stitches not overstitched shall be classified as open seams.			
	Needle chew resulting in cut, tear or hole (see cut, tear, or hole)			
	One or more required rows of stitching omitted (except on boxstitching)	114		

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Boxstitching	Incomplete:			
	- one row of stitching omitted			320
	- two or more rows of stitching omitted		220	
	Any boxstitching less than specified length by more than 1/8 inch			321
Bartacking	Any bartacking less than specified length by more than 1/8 inch			322
Stitching ends	Overstitched less than ½ inch on stitch type 301 (except where ends are held down by other stitching, turned under in a hem, or where stitching is performed automatically)			323
	Secured with less than three tying, overlapping or backstitches when Stitching ends automatic stitching is performed			324
	Secured with less than ¼ inch of backstitching, overstitching or an increased number of stitches per inch at the end of stitch type 304			325
Seams	Pleated:			
	- on tent roof		221	
	- at tent eave or on tent wall, on liner or cover			326
Seam type	Wrong seam type	115		
Stitch type	Wrong stitch type	116		
Stitch tension	Loose, resulting in an exposed bobbin or top thread, for more than 6 inches		222	
	Tight, as evidenced by puckering on fabric, for more than 6 inches		223	
Stitches per inch	Less than minimum specified (except panel joining seams):			
	- one stitch			327
	- two or more stitches		224	
	Less than minimum specified on panel joining seam		225	
	More than maximum specified:			
	- one stitch			328

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Stitches per inch (cont'd)	- two or more stitches		226	
	NOTE: Variation in the number of stitches per inch, caused by the operator speeding up the machine and pulling the fabric in order to sew over heavy places or heavy seams or in turning corners, shall be classified as follows: a. Within the minor "B" defect classification – no defect b. Within the minor "A" defect classification – minor "B" defect			
Stitching gage	Not as specified		227	
Stitching margin	Larger than specified: - for more than 2 inches but not more than 4 inches in length			329
	- for more than 4 inches in length		228	
	Less than specified: - for more than 2 inches but not more than 4 inches in length in length			330
	- for more than 4 inches in length		229	
Stitching indicated By "Z" on drawing	Chain portion of stitching shows on outside of tent, cover, or liner		230	
Mends, darns, or Patches	Repairs not in accordance with Department of the Army field Manual FM 10-16 or not authorized by the contracting officer (see 3.3.6)	117		
Component and	Any component part omitted	118		
	Any component part not fabricated of applicable referenced material	119		
Hems	Constructed with partial turnunder when double turnunder is required		231	
	Twisted or pleated			331
Reinforcements	Improperly applied causing excessive fullness on reinforcement or reinforced part			332
Binding	Improperly or loosely applied, ends not finished as specified			333

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Slide Fasteners	Slider jams or fails to interlock chain	120		
	Any tape improperly assembled causing failure of chain to effect a smooth and secure closure	121		
	Wrong length			
	Width not as specified	122		
	Puckering of tape	123		
	Broken or missing scoops	124		
	Thongs omitted	125		
	NOTE: The inspector shall pull slide fasteners three or four times to an open and closed position to determine proper function and effectiveness or each fastener			
Repair kit	Not as specified		232	
Construction detail				
Tent line lugs	Any lug stitched through roof only instead of through reinforcement webbing and roof reinforcement	126		
	Any part of lug single ply construction		233	
	Piece "B" improperly set causing fullness on tent or distortion of corners		234	
Doorway flaps	Turned-under edge of flap not stitched through door opening tape reinforcement		235	
	Top end of flap not stitched through wall, eave bank, and tape reinforcement		236	
	Facing improperly applied causing fullness on flap			334
Toggle loops	Ends of loops exposed, i.e. not turned under or not caught in stitching attaching flap to wall			335
Toggles	Held in place with single turn of rope around groove or double turn not over hand knotted			336
Stovepipe shield	Set to roof with oval opening in a horizontal position instead of vertical	127		
	Exposed stitching or needle holes			337

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
General	Any other construction detail not performed as specified		237	
Labels	Omitted, incorrect, illegible, or misplaced:			
	- erection instructions		238	
	- identification			338
Marking "US" and Identification	Omitted, incorrect, illegible, or misplaced			339
Cleanliness	Grease or oil stains			340
	Thread ends not trimmed to ¼ inch or less (except in slide fastener area)			341
	Thread ends not trimmed to ¼ inch or less in slide fastener area		239	

4.4.4 End item dimension examination.

* 4.4.4.1 Tent with liner and cover. The end item shall be examined for the defects listed in table III. The lot size shall be expressed in units of tents with liners and covers. The sample unit shall unit be one tent with liner and cover. The inspection level shall be S-2.

* 4.4.4.2 Tent liner, only. The end item shall be examined for the applicable defects listed in table III. The lot size shall be expressed in units of liners. The sample unit shall be one liner. The inspection level shall be S-2.

* 4.4.4.3 Tent cover, only. The end item shall be examined for the applicable defects listed listed in table III. The lot size shall be expressed in units of covers. The sample unit shall be one cover. The inspection level shall be S-2.

TABLE III. End item dimensional defects

Examine	Defect	Classification Major	Minor A	Minor B
Overall dimensions				
Tent and liner	Smaller than specified dimensions less applicable minus tolerance	101		
	Larger than specified dimensions and applicable plus tolerance indicated on drawings		301	
Cover	Smaller than specified dimensions less applicable minus tolerance indicated			

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

TABLE III. End item dimensional defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Cover (cont'd)	on drawing, but not smaller than specified dimensions less twice the applicable minus tolerance			302
	Smaller than specified dimensions less twice the applicable minus tolerance indicated on drawing		201	
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			303
Component dimensions				
Webbing, tie tapes	Finished length less than specified by more than 1 inch			304
Reinforcements	Finished dimensions less than specified by more than ½ inch			305
	Any spliced piece less than 2 feet in length			306
Snow cloths	Less than specified width by more than 1 inch			307
Toggle loops	Free ends of loop extending less than ¾ inch beyond edge of flap			308
Ventilator duct opening	Under or over specified dimensions by more than ½ inch			309
Location dimensions (unless otherwise specified)	Not within the specified tolerance		202	
Webbing and tie tapes	Out of specified location:			
	-by more than ¼ inch but not more than ½ inch		203	
	-by more than ½ inch	102		
	Distance between splices on all reinforced places on tent and liner less than 5 feet			310

4.4.5 End item testing. Tent samples shall be tested as specified in 4.5.1 for compliance with 3.3.7. The lot shall consist of all completely fabricated tents offered for inspection at one time. The sample unit shall be one completely fabricated tent. The inspection level shall be S-3. Failure in any area shall be rejection of the lot.

4.4.6 Packaging examination. The fully packaged end items shall be examined for marking, materials, workmanship and content defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

4.5 Methods of inspection.

4.5.1 Wicking of sewing thread (cup test). The tent shall be tested in each of three areas as follows: at the peak, ridge or joining seam abutting the peaks or ridge; at an intersection of a horizontal and vertical seam such as at an intersection of a side wall and roof; and on a roof panel seam. Suspend the seamed section of the test fabric in the center of a 6 ± 1/8 inch diameter hoop and form a depression with the seamed fabric in the hoop to a depth of 1 ± ¼ inch. Slowly pour 500 mL of water at 77°F ± 4°F into the cupped area (depression) and observe the under surface of the fabric for water penetration. Any wicking of water in any test area along the sewing thread, identified by a discoloration or darkening of the thread within 5 minutes after water is poured, shall constitute a test failure. Water leakage through the needle holes or between the plies of the lapped seamed fabric shall not be considered a failure.

* 4.5.1.1 Seams to be treated. Seams which have failed the test specified in 4.5.1 shall be treated as follows (see 6.4):

a. Failure at roof panel lap seams – treat all roof panel lap seams.

b. Failure at peak reinforcement – paint all peak reinforcement stitching.

c. Failure at eave – paint all stitching at eave and webbing reinforced roof joining seams.

5. PACKAGING

* 5.1 Packaging. For acquisition purposes, the packaging requirements shall be as specified in the contract or order (see 6.2). When actual packaging of materiel is to be performed by DoD personnel, these personnel need to contact the responsible packaging activity to ascertain requisite packaging requirements. Packaging requirements are maintained by the Inventory Control Point's packaging activity within the Military Department or Defense Agency, or within the Military Department's System Command. Packaging data retrieval is available from the managing Military Department's or Defense Agency's automated packaging files, CD-ROM products, or by contacting the responsible packaging activity.

* 5.1.1 Special marking. The following shall be stenciled or imprinted on each bundle or box of complete tents in characters not less than ¾ inch high:

"SEE ERECTION INSTRUCTIONS SEWED
TO INSIDE OF TENT COVER"

6. NOTES

* (This section contains information of a general or explanatory nature that may be helpful, but is not mandatory.)

6.1 Intended use. The tent with liner is used to provide shelter for troops operating in extremely cold-dry or cold-wet areas. The tent will normally accommodate five men and their duffel.

* 6.2 Acquisition requirements. Acquisition documents must specify the following:

a. Title, number, and date of this specification.
b. Issue of DODISS to be cited in the solicitation, and if required, the specific issue of individual documents referenced (see 2.2 and 2.2.1).
c. When first article is required (see 3.1 and 4.3).

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

d. Which of the following items to be purchased:
   1. Tent with liner and cover, or
   2. Tent with liner, tent poles, tent pins and cover, or
   3. Liner only, or
   4. Cover only

e. When pins and poles are required (see 3.2.23 and 3.2.24).

6.3 Erection components. The following components are required for erection of the tent:

1 each – Pole, Tent, Telescopic, Adjustable 5 feet to 9 feet, Magnesium For erection on hard ground
20 each – Pin, Tent, Aluminum, 9 inches

6.4 Seam treatment. A satisfactory method of applying the textile compound for the repair of leaking seams is as follows:

a. A suitable volume of textile compound conforming to type I, class 1, shade Olive Drab of TT-P-595 must be thoroughly stirred and diluted with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir the mixture again before use.

b. Prior to application of the compound, the tent must be dry. Special attention must be taken to ensure adequate ventilation and that proper fire preventative measures are taken since the compound is flammable.

c. Two coats of the compound must be applied to the seams (on the outside of the tent only). A four-inch wide stiff brush is recommended for use. The first coat must be air dried for a minimum of four hours prior to application of the second coat. Elapsed time between coats may be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, a second coat may be applied as soon as the first coat is dry to the touch. After the application of the second coat, the treated tent must be allowed to air dry for a period of at least 24 hours.

6.5 International standardization agreements. Certain provisions of this document are the subject of international standardization agreement as cited in NATO, STANAG No. 2882, relative to camouflage requirements for tents, shelters and subsidiary components. When amendment, revision, or cancellation of this document is proposed which will affect or violate the international agreement concerned, the preparing activity will take appropriate reconciliation action through international standardization channels including departmental standardization offices, if required.

6.6 Subject term (key word) listing.
Shelter
Pyramidal
5-man

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

* 6.7 Changes from previous issue. The margins of this document have been marked with asterisks (or vertical lines) to indicate where changes from the previous issue were made. This was done as a convenience only and the Government assumed no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content, as written, irrespective of the marginal notations and relationship to the last previous issue.

Custodians:
Army – GL
Air Force - 11

Preparing activity
DLA-CT

Review activities:
Army – MD
Air Force – 11.6

Project No: 8340-0579

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7 and send to preparing activity.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

I RECOMMEND A CHANGE:	**1. DOCUMENT NUMBER** MIL-DTL-10035L	**2. DOCUMENT DATE** ***(YYYYMMDD)*** 2001JAN01

3. DOCUMENT TITLE

TENT, HEXAGONAL, LIGHTWEIGHT, M-1950

4. NATURE OF CHANGE *(Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets as needed.)*

REASON FOR RECOMMENDATION

6. SUBMITTER

a. NAME *(Last, First, Middle Initial)*	b. ORGANIZATION	
c. ADDRESS *(Include Zip Code)*	d. TELEPHONE *(Include Area Code)* (1) Commercial (2) DSN *(If applicable)*	7. DATE SUBMITTED *(YYYYMMDD)*

8. PREPARING ACTIVITY

a. NAME DEFENSE SUPPLY CENTER PHILADELPHIA DSCP-CNRP	b. TELEPHONE *(Include Area Code)* (1) Commercial (2) DSN (215) 737-5653 444-5653
c. ADDRESS *(Include Zip Code)* 700 Robbins Ave (Bldg 6, C&T) PHILADELPHIA, PA 19111-5092	**IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT:** Defense Standardization Program Office (DLSC-LM) 8725 John J. Kingman Road, Suite 2533 Fort Belvoir, Virginia 22060-6221 Telephone (703) 767-6888 DSN 427-6888

DD Form 1426, FEB 1999 (EG) PREVIOUS EDITION IS OBSOLETE WHS/DIOR, Feb 99

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:21Z
Check the source to verify that this is the current version before use.