INCH-POUND

MIL-T-10009H
29 October 1991
SUPERSEDING
MIL-T-10009G
27 March 1987

MILITARY SPECIFICATION

TENT, KITCHEN, FLYPROOF, M-1948

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This document covers one type of a rectangular, "A" type, square-end M-1948 flyproof kitchen tent with the back portion forming a stack higher than the rest of the tent. Dimensions of the tent are as follows: Length overall, 18 feet; width, 12 feet; ridge height, 9 feet; side wall height, 6 feet; length of stack, 6 feet; stack ridge height, 12 feet; stack side wall height, 9 feet. A cover is provided for protection during transport.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications, standards, and handbooks. The following specifications, standards, and handbooks form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents are those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation (see 6.2).

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be used in improving this document should be addressed to: U.S. Army Natick Research, Development, and Engineering Center, Natick, MA 01760-5017 by using the Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A

FSC 8340

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

SPECIFICATIONS

FEDERAL

L-S-125	- Screening, Insect, Nonmetallic
T-T-871	- Twine, Cotton, Wrapping
T-T-911	- Twine, Fibrous, Jute
V-F-106	- Fastener, Slide, Interlocking
V-T-285	- Thread, Polyester
QQ-B-613	- Brass, Leaded and Nonleaded: Flat Products (Plate, Bar, Sheet, and Strip)
TT-P-595	- Preservative Coating, Canvas
CCC-C-429	- Cloth, Osnaburg, Cotton
CCC-C-467	- Cloth, Burlap, Jute (or Kenaf)
DDD-L-20	- Label: For Clothing, Equipage, and Tentage, (General Use)
PPP-B-601	- Boxes, Wood, Cleated-Plywood
PPP-B-640	- Box, Fiberboard, Corrugated, Triple-Wall
PPP-F-320	- Fiberboard; Corrugated and Solid, Sheet Stock (Container Grade) and Cut Shapes

MILITARY

MIL-P-500	- Plates, Tent, Peak and Ridge
MIL-P-549	- Poles, Tent, Upright and Ridge
MIL-H-1608	- Hooks, Tent
MIL-L-1709	- Lines, Tent
MIL-S-1734	- Slips, Tent Line
MIL-P-2383	- Pins, Tent, Wood
MIL-C-2399	- Cement, Liquid, Tent Patching
MIL-R-3390	- Rings, Dee
MIL-F-10884	- Fasteners, Snap
MIL-G-16491	- Grommet, Metallic, General Specification for
MIL-R-30500	- Rope, Polyester
MIL-T-40625	- Tubing, Bias Sewn (Burlap or Osnaburg), Cloth
MIL-T-43566	- Tape, Textile, Cotton or Polyester, General Purpose, Natural or in Colors
MIL-C-43627	- Cloth, Duck, Cotton, Plied Yarns, Fire, Water, Weather and Mildew Resistant Treated, Lightdry Finish
MIL-W-43638	- Webbing, Textile, Woven, for Tent Framing

STANDARDS

FEDERAL

FED-STD-751	- Stitches, Seams and Stitchings

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

When specified [illegible] Source Control drawing approval request

MILITARY

MIL-STD-105	-	Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-129	-	Marking for Shipment and Storage
MIL-STD-147	-	Palletized Unit Loads

(Unless otherwise indicated, copies of federal and military specifications, standards, and handbooks are available from the Standardization Documents Order Desk, Building 4D, 700 Robbins Avenue, Philadelphia, PA 19111-5094.)

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this document to the extent specified herein. Unless otherwise specified, the issues are those cited in the solicitation.

DEPARTMENT OF THE ARMY FIELD MANUAL

FM 10-16 - General Repair of Tents, Canvas and Webbing

(Copies are available from the contracting activity or as directed by the contracting activity.)

DRAWINGS

U.S. ARMY NATICK RESEARCH, DEVELOPMENT, AND ENGINEERING CENTER

5-4-189	- Tent, Kitchen, Flyproof, M-1948; Illustration, Assembly and Sections
5-4-190	- Enlarged Views and Assembly Details
5-4-191	- Front Wall and Rear Wall Details
5-4-192	- Roof and Stack Details and Screen Lugs
5-4-193	- Screen Wall
5-4-3359	- Cover, Tent
5-4-506	- Erection Instructions

(Copies of drawings are available from the U.S. Army Natick Research, Development, and Engineering Center, ATTN: STRNC-UX, Natick, MA 01760-5017.)

2.2 Non-Government publications. The following documents form a part of this document to the extent specified herein. Unless otherwise specified, the issues of the documents which are DOD adopted are those listed in the issue of the DODISS cited in the solicitation. Unless otherwise specified, the issues of documents not listed in the DODISS are the issues of the documents cited in the solicitation (see 6.2).

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

COLOR ASSOCIATION OF THE UNITED STATES (CAUS)

DOD Color Card

(Application for copies should be obtained from the activity offering the contract, or from the contracting officer. The CAUS no longer produces copies of the color card.)

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

D 3951 - Standard Practice for Commercial Packaging

(Application for copies should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103-1187.)

(Non-Government standards and other publications are normally available from the organizations that prepare or distribute the documents. These documents also may be available in or through libraries or other informational services.)

2.3 Order of precedence. In the event of a conflict between the text of this document and the references cited herein, the text of this document takes precedence. Nothing in this document, however, supersedes applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 First article. When specified (see 6.2), a sample shall be subjected to first article inspection (see 6.3) in accordance with 4.3.

3.2 Materials and components. Materials and components shall be as specified herein and on the applicable drawings. It is encouraged that recycled material be used when practical as long as it meets the requirements of this specification.

3.2.1 Cloth, duck, cotton. Cloth for the tent shall be Olive Drab 7 and shall conform to MIL-C-43627.

3.2.2 Tape, textile, cotton. Tape shall be Olive Drab 7 and shall conform to type I, class 4 of MIL-T-43566, 3/4 inch, 1-1/2 inch, and 2 inch widths.

3.2.3 Webbing, low elongation. Webbing shall conform to type II of MIL-W-43638.

3.2.4 Thread, polyester. The thread shall conform to type I, class I, subclass B, shade S-1 (CA 66022) of V-T-285. The dyed thread shall show colorfastness to weathering equal to or better than the standard shade sample (see 6.4). If no standard shade sample is available, the thread shall show "good" colorfastness to weathering. Thread sizes shall be as follows:

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

a. For all stitching except stitching indicated by "Z" on drawings and bartacking - size FF for needle and bobbin.

b. For stitching indicated by "Z" on drawings - size FF for needle and size F for looper.

c. For bartacking - size F for needle and bobbin.

3.2.5 Screening, insect. Screening shall conform to type II, class 2, size 18 by 18 of L-S-125 and the color shall be Olive Green 14036.

3.2.6 Lines, tent. Tent lines shall conform to MIL-L-1709 in the following types:

Type	Use
I	Footstop
V	Screen wall tie line
X	Jumper line, JL-2
XVI	Hood line
XVII	Jumper line, JL-1
XIX	Body eave line
XXI	Cover tie line
XXVIII	Stack eave line

3.2.7 Twine, cotton. Twine shall conform to type II, class 1, 5-ply of T-T-871.

3.2.8 Hooks, tent. Tent hooks shall conform to type I, size 1-1/2 inch of MIL-H-1608.

3.2.9 Fasteners, slide. Slide fasteners shall conform to size H, brass chain, with double wire stirrup pulls in the types and styles specified (see 3.2.9.1) of V-F-106. The length of the chains shall be such that, after the slide fastener is sewed on, the tape shall not be puckered and the slider shall operate freely. The slide fastener tape shall be dyed to match Olive Drab S (CA 66519) and shall be water repellent and mildew-resistant treated. The color of the tape after treatment will be considered acceptable. The tape shall show good fastness to weathering. Alternatively, for the type III slide fastener, the slide fastener chain shall be polyester monofilament in a ladder or coil type configuration. Color of the chain, slider, pull, and stops shall approximately match the tape color.

3.2.9.1 Type and style. Entrance, serving window ends, and tent wall corner slide fasteners shall conform to type III, style 1; serving window bottoms and side wall slide fasteners shall conform to type V, style 1 or 3.

3.2.10 Fasteners, snap. Snap fasteners shall conform to style 1, finish 2, stud, eyelet base, sizes 1 and 2 of MIL-F-10884.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

3.2.11 Grommets, metallic. Metallic grommets shall conform to type III, class 3, size No.s 1, 3, 4, and 6 of MIL-G-16491.

3.2.12 Plate, ridge. Ridge plates shall conform to type XVI of MIL-P-500.

3.2.13 Ring, dee. Dee rings shall conform to class 1 or 2, configuration "A", size 3/4 inch of MIL-R-3390.

3.2.14 Slip, tent line. Tent line slips shall conform to type II of MIL-S-1734.

3.2.15 Rope clamp. The material for the brass rope clamp shall be copper alloy No. 260, sheet or strip conforming to QQ-B-613 (see 6.5). The design and dimensions shall be as shown on Drawing 5-4-190.

3.2.16 Rope, polyester. Polyester rope shall be of the sizes specified in the drawings and shall conform to MIL-R-30500. The color shall be Olive Drab 7.

3.2.17 Pins and poles. The following pins and poles are required for complete tent assemblies.

Pins, MIL-P-2383

Quantity	Classification
32	Size 1
31	Size 2

Poles, MIL-P-549

1	type II, class 2, size 11 feet 10 inches
1	type II, class 1, size 5 feet 11-1/4 inches
1	type II, class 1, size 7 feet
16	type I, class 1, size 6 feet 2 inches
2	type I, class 2, size 12 feet 3 inches
5	type I, class 2, size 9 feet

3.3 Construction. The construction of the kitchen tent shall conform in all respects to Drawing 5-4-189 and all subsidiary drawings listed in section 2 pertaining thereto, and as specified herein.

3.3.1 Stitching, machine.

3.3.1.1 Types of stitching. Stitch types, except bartacking, shall conform to FED-STD-751 as follows:

a. For all stitching except stitching indicated by "Z" on drawings and bartacking - type 301, 5 to 7 stitches per inch.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

b. For stitching indicated by "Z" on drawings and alternatively for attachment of slide fasteners - type 401, 5 to 7 stitches per inch. Chain portion of stitching shall not appear on outside of tent, screen or cover.

c. For bartacking - bartack, 5/8 ± 1/16 inch long, 1/8 inch wide (bight), and shall contain 28 stitches.

3.3.1.2 Thread breaks. Thread breaks in stitching shall be overstitched not less than 1 inch at each break on type 301 stitching and not less than 1-1/2 inches at each break on type 401 stitching. Thread breaks in type 401 stitching may be overstitched with stitch type 301. Bartacks shall be free of thread breaks. Thread breaks in type 301 stitching detected during inspection shall be repaired by overstitching the existing stitching in the affected area, starting 1 inch before the break and continuing 1 inch beyond the break (use 1-1/2 inch distances for type 401 stitching repairs).

3.3.1.3 Stitching ends, type 301. Stitching ends shall be overstitched not less than 1 inch on type 301 stitching except where ends are turned under in a hem or held down by other stitching. Where 301 stitching is performed automatically on stitch patterns such as box, box with cross-stitch, "W" stitching, or straight-line tacking, at least 3 or more tying, overlapping, or back stitches shall be used to secure the ends of stitching.

3.3.1.4 Skipped stitches. Two or more consecutively skipped stitches occurring in type 301 stitching shall be overstitched not less than 1 inch. Any skipped stitches in type 401 stitching shall be overstitched not less than 1-1/2 inches. Skipped stitches in 401 stitching may be overstitched with type 301 stitching. Skipped stitches noted during inspection shall be repaired as specified for thread breaks (see 3.3.1.2).

3.3.1.5 Lubrication. The addition of any lubricant to the polyester sewing thread prior to or during the sewing operation is prohibited.

3.3.2 Stitching, hand. Hand stitching shall be accomplished with the twine specified in 3.2.7 using four strands twisted together. Each stitch shall be pulled tight and all ends of stitching secured.

3.3.3 Attachment of slide fasteners. Care shall be exercised to trim all thread ends to 1/2 inch or less and to maintain specified distances between edges of fabric attached to slide fastener tape so that there will be no interference with the operation of the slider. The length of the slide fastener chain shall be such that, after the slide fastener is sewed on, the tape shall not be puckered and the slider shall operate freely.

3.3.4 Setting of grommets. Holes punched to receive grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the materials.

Source: https://assist.dla.mil -- Downloaded: 202610-17T13:20Z
Check the source to verify that this is the current version before use.

3.3.5 Setting of snap fasteners. If a hole is punched before inserting the male or female part of the fastener, it shall be smaller than the outside diameter of the fastener tube so that the tube must be forced through the hole. The fasteners shall be securely clinched.

3.3.6 Splicing of webbing or tape. If required, low elongation webbing, 1-1/2 inch or 2 inch width tapes shall be spliced as shown on Drawing 5-4-190. A maximum of one splice in webbing or tape in lengths of 5 feet or less will be permitted. More than one splice will be permitted in webbing or tape in lengths of more than 5 feet, but the minimum distance allowed between splices shall be 5 feet.

3.3.7 Splicing of fabric components. Splicing of roof, wall, or tent cover panels is prohibited. Splicing of screen bands, eave, ridge, and wall bands will be permitted and, if performed, shall conform to the following requirements:

a. For 8 feet or less in length, 1 splice is permitted.

b. For more than 8 feet but not more than 12 feet in length, 2 splices are permitted.

c. For more than 12 feet in length, 3 splices are permitted.

d. The shortest length of any spliced piece shall be not less than 2 feet.

e. Pieces shall be joined as shown on Drawing 5-4-193.

3.3.8 Compliance with cup test. There shall be no seepage of water through the tent stitching when the tent is tested as specified in 4.5.1. The cup test is intended to ensure that nonwicking thread has been utilized and that no lubrication has been added to the polyester thread during the sewing operation.

3.3.9 Repairs. All necessary repairs shall be effected in accordance with Department of the Army Field Manual FM 10-16, except that hand sewn patches or cemented patches other than as specified herein will not be acceptable. Cemented patches on holes, cuts, or tears not more than 1 inch in diameter or length, using cement specified in MIL-C-2399, shall be permitted. A maximum of three cemented patches per tent shall be allowable without prior contracting officer authorization. All other repairs shall require authorization by the contracting officer. Repairs required as a result of failure of the cup test and when authorized by the contracting officer shall be performed by treating with a compound conforming to type I, class 1, shade Olive Drab of TT-P-595 prior to retesting (see 6.7).

3.4 Marking and labels.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

3.4.1 Special marking. The letters "US" on the tent and cover and the nomenclature on the cover shall conform to type IV, class 9 of DDD-L-20, in the size characters and in the location shown on Drawings 5-4-191 and 5-4-3359. Class 9 markings shall be clearly legible after subjection to accelerated weathering.

3.4.2 Identification labels. Identification labels shall conform to type VI, class 6 or DDD-L-20 and shall be a minimum of 3-1/2 inches by 5-1/2 inches. A blank space of at least 1-1/4 inches shall be provided on the bottom of the label for the Department of Defense inspector's stamp. Identification labels shall be stitched to the tent, screen wall, and cover in the locations shown on Drawings 5-4-192, 5-4-193, and 5-4-3359.

3.4.3 Erection instruction labels. Labels of erection instructions shall conform to type VI, class 7 of DDD-L-20 and shall be stitched to the tent and cover in the locations shown on the drawings. The label shall be a proportionate copy of Drawing 5-4-506 as reproduced from a glossy print of this drawing furnished by the contracting officer (see 6.6). The size of the label shall be, borderline to borderline, 15 inches (± 1/4 inch) in the longer dimension, with a minimum 1/2 inch margin outside of the borderline on all sides.

3.5 Workmanship. Cloth components shall be clean and free of holes, cuts, tears, or cloth defects such as multiple floats or broken or missing yarns. Webbing and tape shall not have frayed or scalloped edges, and rope components shall be free of cuts or breaks. Thread tension shall be maintained so that there will be no loose or tight stitching, and seam allowances shall be maintained with seams properly sewed so that no run-offs, twists, pleats, or open seams shall result. Care shall be taken in sewing to see that no needle chews occur. All thread ends shall be trimmed to 1/2 inch or less. Metal components shall be free of burrs, sharp edges, or corroded areas and shall not be broken or malformed. The end item shall conform to the quality of product established by this specification and the occurrence of defects shall not exceed the applicable acceptable quality levels.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements (examinations and tests) as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in this specification where such inspections are deemed necessary to ensure supplies and services conform to prescribed requirements.

4.1.1 Responsibility for compliance. All items shall meet all requirements of sections 3 and 5. The inspection set forth in this specification shall become a part of the contractor's overall inspection system or quality program.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

The absence of any inspection requirements in the specification shall not relieve the contractor of the responsibility of ensuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling inspection, as part of manufacturing operations, is an acceptable practice to ascertain conformance to requirements, however, this does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to accept defective material.

4.1.2 Responsibility for dimensional requirements. Unless otherwise specified in the contract or purchase order, the contractor is responsible for ensuring that all specified dimensions have been met. When dimensions cannot be examined on the end item, inspection shall be made at any point, or at all points in the manufacturing process necessary to ensure compliance with all dimensional requirements.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).
b. Quality conformance inspection (see 4.4).

4.3 First article inspection. When a first article is required (see 3.1 and 6.2), a complete kitchen tent shall be examined for the defects specified in 4.4.3 and 4.4.4 and tested for the characteristics specified in 4.4.5. The presence of any defect or failure to pass any test shall be cause for rejection of the first article.

4.4 Quality conformance inspection. Unless otherwise specified, sampling for inspection shall be performed in accordance with MIL-STD-105.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced documents unless otherwise excluded, amended, modified, or qualified in this specification or applicable purchase document.

4.4.2 In-process inspection. Inspection shall be made to determine that the following are as specified:

a. There shall be no lubrication of polyester thread prior to or during the sewing operations for compliance with 3.3.1.5.

b. Holes punched to receive grommets are in compliance with 3.3.4.

c. Holes punched to receive snap fasteners are in compliance with 3.3.5.

Whenever nonconformance is noted, correction shall be made to the affected items and to the process. Items that cannot be corrected shall be removed from production.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

4.4.3 End item visual examination. The end items shall be examined for the defects listed in table I. The lot size shall be expressed in units of completely fabricated kitchen tents with covers. The sample unit shall be one completely fabricated tent with cover. The tent shall be inspected in an erected position so that the interior is easily accessible for examination. The inspection level shall be I and the acceptable quality level (AQL), expressed in terms of defects per hundred units, shall be 40 for major defects, 100 for combined major and minor A defects, and 250 for total (combined major, minor A, and minor B) defects.

TABLE I. End item visual defects

Examine	Defect	Classification		
		Major	Minor A	Minor B
Fabric	Cut, tear, or hole (including exposed drill hole) greater than 1/8 inch in length or diameter:			
	- on tent	101		
	- on cover or sod cloth		201	
	Cut, tear, or hole (including exposed drill hole) 1/8 inch or less in length or diameter:			
	- more than 20 holes:			
	- on tent	102		
	- on cover or sod cloth		202	
	- more than 10 but not more than 20 holes:			
	- on tent		203	
	- on cover or sod cloth			301
	- more than 5 but not more than 10 holes on tent			302
	Broken or missing yarn, multiple floats clearly visible at normal inspection distance (approximately 3 feet)		204	
	Untreated area on either side of cloth for more than 1 inch in length or diameter		205	
Screening	Cut or tear:			
	- more than 2 inches in length	103		
	- more than 1/4 inch but not more then 2 inches in length		206	
	- 1/4 inch or less in length			303

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification		
		Major	Minor A	Minor B
Webbing, tape	Edge frayed or scalloped			304
	Splices (when necessary) not spliced as indicated on Drawing 5-4-190			305
Rope components	Any cut; any break:			
	- on eave guy line		207	
	- on any other line			306
Hardware	Broken	104		
	Malformed:			
	- fails to perform intended function	105		
	- but will perform intended function		208	
	Corroded area	106		
	Burr or sharp edge that may cause injury in handling or damage to fabric	107		
Grommets	Improperly set, two or more teeth exposed (except where grommet is set as specified but is in an area of uneven thickness that prevents uniform clinching)			307
	Clinched loosely, allowing grommet to rotate around hole			308
	Clinched excessively tight (i.e., cutting fabric):			
	- on tent	108		
	- on cover		209	
	Insecurely clinched (i.e., grommets or washers become disengaged):			
	- on tent	109		
	- on cover		210	
	Misaligned with eye of tent hook, obstructing passage of pole spindle	110		
	Set with barrel inserted from outside in lieu of inside:			
	- on eave or ridge		211	
	- on any other location			309

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification		
		Major	Minor A	Minor B
Hardware (cont'd)				
Hooks, tent	Not set as specified		212	
	Not sufficiently closed, allowing connecting hardware to become disengaged		213	
Ridge plate	Misplaced so that center hole of plate fails to correspond with grommet on ridge resulting in obstruction of pole spindle	111		
Snap fasteners	Female components used where male components are required or vice versa; fasteners fail to snap in a closed position or fail to remain firmly closed	112		
Connecting rings	Misplaced (i.e., handstitched through a single thickness of body roof)		214	
	Not securely handstitched to body roof		215	
Seams and stitching	Open seam on stitch type 301:			
	- for more than 1/4 inch but not more than 1 inch			310
	- for more than 1 inch		216	
	Open seam on stitch type 401:			
	- one row of stitching open for 1 inch or less on tent or cover			311
	- one row of stitching open for more than 1 inch:			
	- on roof		217	
	- on wall or cover			312
	- both rows of stitching open (not necessarily at same location):			
	- on roof	113		
	- on wall or cover		218	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification		
		Major	Minor A	Minor B
Seams and stitching (cont'd)				
	NOTE: A seam shall be classified as open when one or more skipped or run-off stitches occur. On double stitched seams, a seam shall be considered open when either one or both sides of a seam are open.			
	Raw edges caught in stitching:			
	- more than 1 inch, but not more than 3 inches			313
	- more than 3 inches		219	
	Thread breaks:			
	- overstitched less than one inch on stitch type 301			314
	- overstitched less than 1-1/2 inches on stitch type 401			315
	NOTE: Thread breaks not overstitched shall be classified as open seams.			
	Skipped stitches overstitched less than 1-1/2 inches on stitch type 401; less than 1 inch on type 301			316
	NOTE: Skipped stitches not overstitched shall be classified as open seams.			
	Needle chew resulting in cut, tear, or hole (see Cut, tear, or hole under Fabric examination)			
	One or more required rows of stitching omitted	114		
Boxstitching	Incomplete:			
	- one row of stitching omitted			317
	- two or more rows of stitching omitted		220	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification		
		Major	Minor A	Minor B
Seams and stitching (cont'd)				
Boxstitching (cont'd)	Any boxstitching less than specified length by more than 1/8 inch			318
"W" stitching	Incomplete: - two or more rows of stitching omitted	115		
	- one row of stitching omitted		221	
	Any "W" stitching less than specified length by more than 1 inch			319
Bartacking	Any bartack more or less than specified length and tolerance			320
Stitching ends	Overstitched less than 1 inch on stitch type 301 (except where ends are held down by other stitching, turned under in hem, or where stitching is performed automatically			321
	Secured with less than 3 tying, overlapping, or back stitches when automatic stitching is performed			322
Seams	Pleated: - on roof		222	
	- at eave or on wall			323
Seam type	Wrong seam type	116		
Stitch type	Wrong stitch type	117		
Stitch tension	Loose, resulting in an exposed bobbin or top thread, for more than 6 inches		223	
	Tight, as evidenced by puckering on fabric, for more than 6 inches		224	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification		
		Major	Minor A	Minor B
Seams and stitching (cont'd)				
Stitches per inch	Less than minimum specified (except panel joining seams):			
	- one stitch			324
	- two or more stitches		225	
	Less than minimum specified on panel joining seams		226	
	More than maximum specified:			
	- one stitch			325
	- two or more stitches		227	
NOTE:	Variation in the number of stitches per inch, caused by the operator speeding up the machine and pulling the fabric in order to sew over heavy places or heavy seams or in turning corners, shall be classified as follows:			
	a. With the minor B defect classification - no defect			
	b. Within the minor A defect classification - minor B			
Stitching gage	Not as specified		228	
Stitching margin	Larger than specified by more than 3/16 inch:			
	- for more than 2 inches but not more than 4 inches in length			326
	- for more than 4 inches in length		229	
	Less than specified:			
	- for more than 2 inches but not more than 4 inches in length			327
	- for more than 4 inches in length		230	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification		
		Major	Minor A	Minor B
Seams and stitching (cont'd)				
Stitching indicated by "Z" on drawings	Chain portion of stitching shows on outside of tent, cover or screen	118		
Handstitching	Less than 4 strands of 5-ply twine used		231	
Mends, darns, or patches	Repair not in accordance with Department of the Army Field Manual FM 10-16 or not authorized by the contracting officer (see 3.3.9)	119		
Components and assembly	Any component part not fabricated ofapplicable referenced material	120		
Hems	Twisted or pleated			328
	Constructed with partial turnunder when double turnunder is required		232	
Reinforcements	Improperly applied causing excessive fullness on reinforcement or reinforced parts			329
Binding	Improperly or loosely applied			330
Cloth splicing	Splice in roof, wall, or tent cover panels	121		
	Number of splices per reinforcement section more than specified		233	
Slide fastener tapes	Slider jams or fails to interlock chain	122		
	Any tape improperly assembled, causing failure of chain to effect a smooth and secure closure	123		

Source: https://assist.dla.mil -- Downloaded: 202610-17T13:20Z
Check the source to verify that this is the currentversion before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification		
		Major	Minor A	Minor B
Components and assembly (cont'd)				
Points of stress	Webbing loops engaging hardware at each stress area set loose, failing to relieve stress from canvas:			
	- on one loop			331
	- on two or more loops	124		
NOTE:	When the proper tension between the webbing and the hardware and between the webbing and the tent body has been attained, only slight fullness of fabric at stress point will result.			
Construction details	Any detail of construction not as specified		234	
Pole cutouts	Misplaced, failing to provide clearance for upright poles			332
Ventilators	Flaps or hoods fail to cover openings fully when in a closed position		235	
Stack side flaps	Upper corners of flaps caught in stitching joining front and rear stack ventilator screens to side ventilator screens, preventing flaps from hanging evenly		236	
	No. 4 grommets on upper corners not set through stack side flaps		237	
Front stack ventilator	Bottom end of center screen frame reinforcement webbing (front) not extending into body ridge		238	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification		
		Major	Minor A	Minor B
Construction details (cont'd)				
Screen wall	Grommets on screen wall fail to correspond with snap fasteners on lugs, causing failure of screen wall to fit inside of tent	125		
	Female components of snap fasteners on screen wall ends fail to correspond with male components on rear wall	126		
NOTE:	The screen wall shall be attached to the tent lugs and to the rear wall of the tent to determine proper fit.			
Labels	Omitted, misplaced, incorrect, or illegible:			
	- erection instruction		239	
	- identification			333
Markings: "US" on tent and cover	Omitted, incorrect, illegible, or misplaced			334
Cleanness	Grease or oil stains			335
	Thread ends not trimmed to 1/2 inch or less (except in slide fastener area)			336
	Thread ends not trimmed to 1/2 inch or less in slide fastener area		240	
	Metal staples (when used) not removed			337

4.4.4 End item dimensional examination. The end items shall be examined for the defects listed in table II. Only those dimensions that can be evaluated without damaging or disassembling the end items shall be examined. The lot size shall be expressed in units of completely fabricated kitchen tents with covers. The sample unit shall be one completely fabricated tent with one cover. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 2.5 for major defects and 25 for combined major and minor A defects, and 100 for total (combined major, minor A and minor B) defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

TABLE II. End item dimensional defects

Examine	Defect	Classification		
		Major	Minor A	Minor B
Overall dimensions on tent; screen wall	Smaller than specified dimensions less applicable minus tolerance indicated on drawings	101		
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			301
Overall dimensions of cover	Not within the specified tolerances			302
Location dimensions (unless otherwise specified)	Not within the specified tolerances: - not exceeding twice the applicable tolerance			303
	- exceeding twice the applicable tolerance		201	
Grommets	Set beyond specified location by more than 1/2 inch (unless otherwise specified)			304
	Ridge grommets set off center of ridge line of body or stack: - by more than 1/2 inch but not more than 1 inch			305
	- by more than 1 inch		202	
	Ridge grommets set less than 2 inches from ridge end of body or stacl		203	
Sod cloths	Less than specified width by more than 1 inch			306
Reinforcements	Finished dimensions less than specified by more than 1/2 inch			307
	Any spliced piece less than 2 feet in length			308
Webbing and tapes	Finished length of tie tapes less than specified by more than 1 inch			309
	Turnunder at ends of webbing engaging hardware less than specified: - by more than 1 inch but not more than 1-1/2 inches			310
	- by more than 1-1/2 inches		204	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

4.4.5 End item testing. Tent samples shall be tested as specified in 4.5.1 for compliance with 3.3.8. The lot shall consist of all completely fabricated tents offered for inspection, and the inspection level shall be S-3. The sample unit shall be one completely fabricated kitchen tent. Failure in any area on any sample unit shall be cause for rejection of the lot.

4.4.6 Packaging examination. The fully packaged end items shall be examined for the defects listed below. The lot size shall be expressed in units of shipping containers. The sample unit shall be one shipping container fully packaged. The inspection level shall be S-2 and the AQL, expressed in terms of defects per hundred units, shall be 2.5.

Examine	Defect
Marking (exterior and interior)	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application
Materials	Any component missing, damaged, or not as specified
Workmanship	Inadequate application of components, such as: incomplete sealing or closure of flap, improper taping, loose strapping, or inadequate stapling Bulged or distorted container
Content	Number per container is more or less than required

4.4.7 Palletization examination. The fully packaged and palletized end items shall be examined for the defects listed below. The lot size shall be expressed in units of palletized unit loads. The sample unit shall be one palletized unit load, fully packaged. The inspection level shall be S-1 and the AQL, expressed in terms of defects per hundred units, shall be 6.5.

Examine	Defect
Finished dimensions	Length, width, or height exceeds specified maximum requirement
Palletization	Pallet pattern not as specified Load not bonded as specified
Weight	Exceeds maximum load limits
Marking	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application

4.5 Methods of inspection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

4.5.1 Wicking of sewing thread (cup test). The tent shall be tested in three areas as follows: at the peaks, ridge, or joining seam abutting the peaks or ridge; at an intersection of a horizontal and vertical seam such as at an intersection of a side wall and roof; and on a roof panel seam. Suspend the seamed section of the test fabric in the center of a 6 ± 1/8 inch diameter hoop and form a depression with the seamed fabric in the hoop to a depth of 1 ± 1/4 inch. Slowly pour 500 mL of water at 77°F ± 4°F into the cupped area (depression) and observe the under surface of the fabric for water penetration. Any wicking of water in any test area along the sewing thread, identified by a discoloration or darkening of the thread within 5 minutes after water is poured, shall constitute a failure. Water leakage through the needle holes or between the plies of the lapped seamed fabric shall not be considered a failure.

5. PACKAGING

5.1 Preservation. Preservation shall be level A or Commercial, as specified (see 6.2).

5.1.1 Level A preservation.

5.1.1.1 Screen wall. The screen with all slide fasteners closed shall be laid out full length. The peak and sod cloth shall be folded over to form a straight line. The screen shall be folded in the length starting with a 32 inch fold at one end and continuing until the folded screen results in a bundle measuring approximately 35 inches by 72 inches.

5.1.1.2 Tent. The tent shall be spread out flat, outside up, with corner slide fasteners open and sides, rear wall, and front wall (awning) extended. The guy lines shall be laid toward the center of the tent. The stack part of the tent shall be arranged as neatly as possible. The rear wall shall be folded over and laid on the stack roof. The front wall (awning) shall then be brought over and laid on the deck body. The side walls shall be folded toward the center of the tent up to the eave. The stack shall then be folded over and laid on the deck body. Care shall be exercised when tucking in the exposed stack screen. The folded screen wall (see 5.1.1.1) shall be laid full length on the stack next to and along one side wall. The stack and that part of the deck underneath shall then be folded over to the center completely covering the screen wall. The front portion of the deck shall be folded over in half to the center and then folded over on top of the first folded part of the tent. Each end of the tent shall be folded over to within six inches of the center. The tent shall then be folded in half, placing one end on top of the other, completing the folding pattern. The folded tent bundle shall be secured by cross-tying with tent line rope. During the folding operation, care should be taken to expel entrapped air (see Drawing 5-4-506). The completely folded tent shall be placed within the cover provided and the cover securely closed with the tie lines. All cover ends or flaps shall be neatly folded within the package.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

5.1.2 Commercial preservation. Screen walls and tents shall be preserved in accordance with ASTM D 3951.

5.2 Packing. Packing shall be level A, B, or Commercial, as specified (see 6.2).

5.2.1 Level A Packing.

5.2.1.1 Fabric component. One tent, preserved as specified in 5.1, shall be packed in a close-fitting, cleated-plywood box conforming to overseas type, style A of PPP-B-601. Each box shall be provided with skids. Box and skids shall be fabricated in accordance with load type and gross weight requirements of PPP-B-601. Each shipping container shall be closed and reinforced with flat steel strapping in accordance with the appendix of PPP-B-601.

5.2.1.2 Complete assemblies. One tent and screen wall, preserved as specified in 5.1, complete with pins and poles as specified (see 3.2.17), with tent cover, shall be packed in a close-fitting, cleated-plywood box conforming to overseas type, style A of PPP-B-601. Each box shall be provided with skids. Box and skids shall be fabricated in accordance with load type and gross weight requirements of PPP-B-601. Each shipping container shall be closed and reinforced with flat steel strapping in accordance with the appendix of PPP-B-601.

5.2.2 Level B Packing.

5.2.2.1 Fabric component. One tent, preserved as specified in 5.1, shall be wrapped and sewn in cotton osnaburg cloth conforming to class 2 any type, any color of CCC-C-429 or burlap cloth conforming to class 3 of CCC-C-467. The wrapping shall be securely hand sewn with type I or II, 16-ply cotton twine of any class conforming to T-T-871, or type I, size No. 2 jute twine conforming to T-T-911, with approximately one stitch to the inch and every third stitch overhand knotted. Alternatively, the bottom and side may be machine-sewn. A minimum of five inches of wrapping material shall be gathered together on each of the four corners and securely hand sewn into ears for handles. In lieu of the sewn wrapping indicated above, bias-sewn tubing conforming to MIL-T-40625 may be used. One end of the tubing may be machine-sewn. The formation of handles shall be effected by hand sewing in conformance with the method as described above. Wherever machine sewing is used, the thread type, stitch type, and number of stitches per inch shall conform to the requirements specified in MIL-T-40625. Alternatively, when specified (see 6.2), one tent, preserved as specified in 5.1, shall be packed in a close-fitting, class 1, style G, corrugated fiberboard box conforming to PPP-B-640. Approximate outside dimensions of the box shall be 48 inches in length, 40 inches in width, and 14 inches in depth. The box cover may be constructed of a domestic, grade 350, double-wall fiberboard conforming to PPP-F-320.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

5.2.2.2 Complete assemblies. One tent and screen wall, preserved as specified in 5.1, complete with pins and poles as specified in 3.2.17, with tent cover, shall be packed in a close-fitting, cleated-plywood box conforming to domestic type, style optional, of PPP-B-601. Each box shall be provided with skids. Box and skids shall be fabricated in accordance with load type and weight requirements of PPP-B-601. Each container shall be closed and reinforced in accordance with the appendix of PPP-B-601.

5.2.3 Commercial packing. Tents preserved as specified in 5.1 or complete assemblies (see 5.2.1.2), which includes screen walls (see 5.1), shall be packed in accordance with ASTM D 3951.

5.3 Palletization. When specified (see 6.2), one tent, packed in a fiberboard box as specified in 5.2.2 or 5.2.3, shall be palletized on a 4-way entry pallet according to MIL-STD-147. Each tent shall be bonded to the pallet by method D and in accordance with MIL-STD-147.

5.4 Marking. In addition to any special marking required by the contract or purchase order, shipping containers, and palletized unit loads shall be marked in accordance with MIL-STD-129 or ASTM D 3951, as applicable.

6. NOTES

(This section contains information of a general or explanatory nature that may be helpful, but is not mandatory.)

6.1 Intended use. The tent is used in the tropics to provide shelter while cooking and serving food. A wall screen, equipped with a serving window, snaps to the tent and provides an insect-proof closure on sides and front when the walls are raised or guyed out to form awnings.

6.2 Acquisition requirements. Acquisition documents must specify the following:

a. Title, number, and date of this specification.
b. Issue of DODISS to be cited in the solicitation, and if required, the specific issue of individual documents referenced (see 2.1.1 and 2.2).
c. When a first article is required (see 3.1, 4.3, and 6.3).
d. Levels of preservation and packing (see 5.1 and 5.2).
e. When tent only is required (see 5.2.2.1).
f. When palletization is required (see 5.3).

6.3 First article. When a first article is required, it shall be inspected and approved under the appropriate provisions of Federal Acquisition Regulation (FAR) 52.209. The first article should be preproduction sample. The contracting officer should specify the appropriate type of first article and the number of units to be furnished. The contracting officer should also include specific instructions in acquisition documents regarding arrangements for selection, inspection, and approval of the first article.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

6.4 Standard sample. For access to samples, address the contracting activity issuing the invitation for bids or request for proposal.

6.5 Commercial products. The Astrup Co., Cleveland, Ohio, brass rope clamp No. 225 has been found to meet the requirements of 3.2.15.

6.6 Print. For access to glossy print of Drawing 5-4-506 (see 3.4.3), address the contracting activity issuing the invitation for bids.

6.7 Repair of leaking seams. A satisfactory method of applying the textile compound for the repair of leaking seams is as follows:

a. A suitable volume of textile compound conforming to type I, class 1, shade Olive Drab of TT-P-595, shall be thoroughly stirred and diluted with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir the mixture again before use.

b. Prior to application of the compound, the tents must be dry. Special attention must be taken to insure adequate ventilation and that proper fire preventive measures are taken since the compound is flammable.

c. Two coats of the textile compound shall then be applied to the seams (on the outside of the tent only). A four-inch wide stiff brush is recommended. The first coat shall be air dried for a minimum of four hours prior to application of the second coat. Elapsed time between coats may be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, a second coat may be applied as soon as the first coat is dry to the touch. After the application of the second coat, the treated tent shall be allowed to air dry for a period of at least 24 hours.

6.7.1 Seams to be treated. Seams which have failed the test specified in 4.5.1 can be treated as follows:

a. Failure at panel lap seam - treat all panel lap seams.

b. Failure at roof reinforcement seam - treat all stitching of fabric reinforcements on roof and eave.

6.8 Subject term (key word) listing.

Cooking and serving food
Insect-proof
Screened shelter
Shelter, tropical

6.8 Changes from previous issue. Marginal notations are not used in this revision to identify changes with respect to the previous issue due to the extensiveness of the changes.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

Drawing number assignment report.

Custodians:

Army - GL
Air Force - 99

Review activities:

Army - MD
Air Force - 82
DLA - CT

User activity:

Air Force - 45

Preparing activity:

Army - GL

(Project 8340-0553)

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.

Application for copies of DOD Manual 5220.22-M should be addressed

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

I RECOMMEND A CHANGE:	1. DOCUMENT NUMBER MIL-T-10009H	2. DOCUMENT DATE (YYMMDD) 91-10-29

3. DOCUMENT TITLE: TENT, KITCHEN, FLYPROOF, M-1948

4. NATURE OF CHANGE (*Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets as needed.*)

5. REASON FOR RECOMMENDATION

6. SUBMITTER		
a. NAME (Last, First, Middle Initial)	b. ORGANIZATION	
c. ADDRESS (Include Zip Code)	d. TELEPHONE (Include Area Code) (1) Commercial (2) AUTOVON	7. DATE SUBMITTED (YYMMDD)

8. PREPARING ACTIVITY		
a. NAME U.S. Army Natick RD&E Center	b. TELEPHONE (Include Area Code) (1) Commercial 508-651-4531	(2) AUTOVON 256-4531
c. ADDRESS (Include Zip Code) Commander, U.S. Army Natick RD&E Center ATTN: STRNC-UXT Natick, MA 01760-5017	IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT: Defense Quality and Standardization Office 5203 Leesburg Pike, Suite 1403, Falls Church, VA 22041-3466 Telephone (703) 756-2340 AUTOVON 289-2340	

Source: https://assist.dla.mil - Downloaded: 2026-10-17T13:20Z
Check the source to verify that this is the current version before use.